

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418b3",
    "email": "vrunda.sawant@cosmosbank.in",
    "firstName": "Vrunda Sawant",
    "mobileNo": "9819868668",
    "workMobileNo": "9819868668",
    "lastName": "Sawant"
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
  }
}
```

```
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
```

```
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": "",
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.17109630840686",
  "longitude": "72.87098287181128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87098287181128,
    19.17109630840686
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-09T07:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dindoshi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "12",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "D G Woods CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gokuldham ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "654b5fd0637db60f88b65876",
"ownerName": "Vijay Raghunath Vivalkar ",
"ownerPhoneNo": "9820308441",
"appAddress": "Dindoshi, goregaon East 1203, 12th floor, ",
"remark": ""
```



```
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/654b5fd0637db60f88b65876/document_1699438541451_53475.pdf",
    "fileName": "document_1699438541451_53475.pdf",
    "displayStatus": false,
    "id": "541978",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Nov 08 2023 15:45:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1699524714662_127998.pdf",
    "path": "cases/654b5fd0637db60f88b65876/
document_1699524714662_127998.pdf",
    "id": "332536",
    "uploadedBy": "62691c48afd7d55eddecfd3",
    "createdAt": "Thu Nov 09 2023 15:41:54 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004962",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "914704",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 08 2023 15:45:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vijay Raghunath Vivalkar ",
    "phone": "9820308441",
    "ownershipShare": "",
    "email": "",
    "id": "852030"
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8603d",
    "name":
"externallmg_1699524569646_WhatsApp_Image_20231109_at_33227_PM_1.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569646_WhatsApp_Image_20231109_at_33227_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8603e",
    "name":
"externallmg_1699524569649_WhatsApp_Image_20231109_at_33227_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569649_WhatsApp_Image_20231109_at_33227_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8603f",
    "name":
"externallmg_1699524569651_WhatsApp_Image_20231109_at_33756_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569651_WhatsApp_Image_20231109_at_33756_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86040",
    "name":
"externallmg_1699524569654_WhatsApp_Image_20231109_at_33757_PM_1.jpeg",
```

```
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569654_WhatsApp_Image_20231109_at_33757_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86041",
    "name":
"externallmg_1699524569656_WhatsApp_Image_20231109_at_33757_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569656_WhatsApp_Image_20231109_at_33757_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86042",
    "name":
"externallmg_1699524569659_WhatsApp_Image_20231109_at_32813_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569659_WhatsApp_Image_20231109_at_32813_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86043",
    "name":
"externallmg_1699524569662_WhatsApp_Image_20231109_at_32814_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569662_WhatsApp_Image_20231109_at_32814_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86044",
    "name":
"externallmg_1699524569665_WhatsApp_Image_20231109_at_32825_PM_1.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569665_WhatsApp_Image_20231109_at_32825_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "654cafd9637db60f88b86045",
    "name":
"externallmg_1699524569667_WhatsApp_Image_20231109_at_32825_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569667_WhatsApp_Image_20231109_at_32825_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86046",
    "name":
"externallmg_1699524569671_WhatsApp_Image_20231109_at_32826_PM_1.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569671_WhatsApp_Image_20231109_at_32826_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86047",
    "name":
"externallmg_1699524569674_WhatsApp_Image_20231109_at_32826_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569674_WhatsApp_Image_20231109_at_32826_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86048",
    "name":
"externallmg_1699524569676_WhatsApp_Image_20231109_at_32827_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569676_WhatsApp_Image_20231109_at_32827_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b86049",
    "name":
"externallmg_1699524569679_WhatsApp_Image_20231109_at_32906_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569679_WhatsApp_Image_20231109_at_32906_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8604a",
    "name":
"externallmg_1699524569681_WhatsApp_Image_20231109_at_32914_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569681_WhatsApp_Image_20231109_at_32914_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8604b",
    "name":
"externallmg_1699524569683_WhatsApp_Image_20231109_at_32915_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569683_WhatsApp_Image_20231109_at_32915_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8604c",
    "name":
"externallmg_1699524569686_WhatsApp_Image_20231109_at_32916_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569686_WhatsApp_Image_20231109_at_32916_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8604d",
    "name":
"externallmg_1699524569688_WhatsApp_Image_20231109_at_32919_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569688_WhatsApp_Image_20231109_at_32919_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafd9637db60f88b8604e",
```

```
    "name":
"externallmg_1699524569692_WhatsApp_Image_20231109_at_32920_PM_1.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569692_WhatsApp_Image_20231109_at_32920_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafd9637db60f88b8604f",
  "name":
"externallmg_1699524569693_WhatsApp_Image_20231109_at_32920_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569693_WhatsApp_Image_20231109_at_32920_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafd9637db60f88b86050",
  "name":
"externallmg_1699524569695_WhatsApp_Image_20231109_at_32921_PM_1.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524569695_WhatsApp_Image_20231109_at_32921_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86123",
  "name":
"externallmg_1699524586175_WhatsApp_Image_20231109_at_32921_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586175_WhatsApp_Image_20231109_at_32921_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86124",
  "name":
"externallmg_1699524586177_WhatsApp_Image_20231109_at_32923_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586177_WhatsApp_Image_20231109_at_32923_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86125",
  "name":
"externallmg_1699524586180_WhatsApp_Image_20231109_at_32924_PM_1.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586180_WhatsApp_Image_20231109_at_32924_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86126",
  "name":
"externallmg_1699524586183_WhatsApp_Image_20231109_at_32924_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586183_WhatsApp_Image_20231109_at_32924_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86127",
  "name":
"externallmg_1699524586186_WhatsApp_Image_20231109_at_32926_PM_1.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586186_WhatsApp_Image_20231109_at_32926_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86128",
  "name":
"externallmg_1699524586188_WhatsApp_Image_20231109_at_32926_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586188_WhatsApp_Image_20231109_at_32926_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b86129",
  "name":
"externallmg_1699524586191_WhatsApp_Image_20231109_at_32927_PM_1.jpeg",
```

```
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586191_WhatsApp_Image_20231109_at_32927_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafea637db60f88b8612a",
    "name":
"externallmg_1699524586196_WhatsApp_Image_20231109_at_32927_PM_2.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586196_WhatsApp_Image_20231109_at_32927_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafea637db60f88b8612b",
    "name":
"externallmg_1699524586199_WhatsApp_Image_20231109_at_32927_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586199_WhatsApp_Image_20231109_at_32927_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafea637db60f88b8612c",
    "name":
"externallmg_1699524586202_WhatsApp_Image_20231109_at_32928_PM.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586202_WhatsApp_Image_20231109_at_32928_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654cafea637db60f88b8612d",
    "name":
"externallmg_1699524586206_WhatsApp_Image_20231109_at_33226_PM_1.jpeg",
    "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586206_WhatsApp_Image_20231109_at_33226_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "654cafea637db60f88b8612e",
  "name":
"externallmg_1699524586212_WhatsApp_Image_20231109_at_33226_PM_2.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586212_WhatsApp_Image_20231109_at_33226_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cafea637db60f88b8612f",
  "name":
"externallmg_1699524586215_WhatsApp_Image_20231109_at_33226_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699524586215_WhatsApp_Image_20231109_at_33226_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cb71d637db60f88b88170",
  "name":
"externallmg_1699526429584_WhatsApp_Image_20231109_at_41036_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699526429584_WhatsApp_Image_20231109_at_41036_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654cb71d637db60f88b88171",
  "name":
"externallmg_1699526429587_WhatsApp_Image_20231109_at_41035_PM.jpeg",
  "path": "cases/654b5fd0637db60f88b65876/
externallmg_1699526429587_WhatsApp_Image_20231109_at_41035_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1699095795764_1696911325333_1694858329226_Calculation_123_2_2.xlsx",
    "filename": "1699515879428_1699095795764_1696911325333_1694858329226_C
alculation_123_2_2.xlsx",
```

```
    "path": "cases/654b5fd0637db60f88b65876/processingDocuments/1699515879428
_1699095795764_1696911325333_1694858329226_Calculation_123_2_2.xlsx",
    "size": "2369761",
    "createdAt": "Thu Nov 09 2023 13:14:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "654c734d637db60f88b78ef4",
    "note": "Rate verification Done - 3.75 Cr.",
    "taskId": "654b5fd0637db60f88b6588d",
    "createdAt": "2023-11-09T05:51:09.200Z"
  }
],
"createdAt": "2023-11-08T10:15:44.016Z",
"updatedAt": "2023-11-09T10:40:29.651Z",
"__v": 0,
"invoiceId": "654b5fd0637db60f88b6587c",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": " Flat No. 1203, 12th Floor, Wing - C, D G Woods CHSL, Gokuldhm ,
Village - Dindoshi, Goregaon East, Mumbai",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Vijay Raghunath Vivalkar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9820308441"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
