

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7b55191f7b344b003bce"
    },
    "type": "CREDITOFFICER",
    "_id": "655b464b5586e008158de0d0",
    "firstName": "Kundan",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9031620745",
    "email": "kundan.kumar3@unionbankofindia.bank"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "20000000",
    "discussWithPerson": "Kundan",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7b55191f7b344b003bce",
  "name": "UBI-Mid Corporate Branch",
  "branchCode": "",
  "mobileNo": "7219107800",
  "alternateMobileNo": "",
  "email": "cb0024@corpbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Veena Chambers 21,Dalal Street,Fort-Mumbai"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
```

```
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": ""
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    }
  },

```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.084134027216574",
  "longitude": "72.83598829060793"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83598829060793,
    19.084134027216574
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-23",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shalaka CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Juhu Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Santacruz West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```

```
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "21.33333333333332",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "20",
  "buildingServicesDepreciatedRate": "597.3333333333333",
  "depreciatedCostOfConstruction": "44402.67",
  "depreciatedBuildingRate": "2202.666666666667"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "364560",
  "landRate": "183640",
  "igrImage": "cases/655b86975586e008158e1472/igr_1700724071502_Image.png",
  "squareMeterGuideLineRate": "364560.00",
  "squareFeetGuideLineRate": "33869.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "rate": "31180.00",
  "squareMeterGuideLineRate": "335613.00",
  "squareFeetGuideLineRate": "31180.00",
  "depreciationPercentage": "84"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2007",
    "date": "1",
    "month": "1",
    "year": "2007"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_occupancy_certificate",
    "label": "As per occupancy certificate"
  }
},
```

```
"isSiteVisitAllowed": true,
"ageOfBuilding": "16",
"totalLifeBuilding": "60",
"estimatedAge": "44",
"noOfLifts": "1"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "30119880.00",
  "selectedBuildUpValue": "966.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "37132",
    "max": "47291"
  },
  "builtUpRateRange": {
    "min": "30944",
    "max": "39409"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "805.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "655b86975586e008158e1472",
"audioRemarks": [],
"ownerName": "Talib And Shamsi Construction Pvt Ltd ",
"ownerPhoneNo": "9892040259",
"appAddress": "Flat No 202\n2nd floor\nsalakha co operative Housing society Ltd
\nJhu Road\nSantacruz w\nMumbai 400 O54",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/655b86975586e008158e1472/document_1700497022057_17004970
80149_Tallb_and_shamsi_constructions_Pvt_Ubi_mid_cop_fort.pdf",
    "fileName": "document_1700497022057_1700497080149_Tallb_and_shamsi_constr
uctions_Pvt_Ubi_mid_cop_fort.pdf",
    "displayStatus": false,
    "id": "845442",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Mon Nov 20 2023 21:47:26 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005140",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "412944",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 20 2023 21:47:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Talib And Shamsi Construction Pvt Ltd ",
    "phone": "9892040259",
    "ownershipShare": ""
  }
]
```

```
"email": "",
"id": "278804"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "74.79",
  "totalAreaDocument": "805",
  "docBuiltpUpPercentage": "20",
  "docFinalBuiltpUp": "966.00",
  "docFinalBuiltpUpSquareMeter": "89.74",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "108589"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "655efd8fcabee4333991eb7f",
  "property": "Residential Flat ",
  "area": "1218",
  "builtpUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "57600000",
  "expectedRate": "47290.64",
```

```
    "builtUpExpectedRate": "39408.87",
    "image": "cases/655b86975586e008158e1472/
indicator_1700723665895_Image.png",
    "squareMeter": "113.16",
    "id": "455729"
  },
  {
    "printlnReport": true,
    "_id": "655efd8fcabee4333991eb80",
    "property": "Residential Flat ",
    "area": "394",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "16300000",
    "expectedRate": "41370.56",
    "builtUpExpectedRate": "34475.47",
    "image": "cases/655b86975586e008158e1472/
indicator_1700723827347_Image.png",
    "squareMeter": "36.60",
    "id": "909996"
  },
  {
    "printlnReport": true,
    "_id": "655efd8fcabee4333991eb81",
    "property": "Residential Flat ",
    "area": "680",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "source": "Index_no.2",
    "expectedPrice": "21041750",
    "expectedRate": "30943.75",
    "builtUpExpectedRate": "0.00",
    "image": "cases/655b86975586e008158e1472/
indicator_1700723976137_Image.png",
    "squareMeter": "63.17",
    "id": "690728"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "655ec379cabee43339913007",
    "name": "externallmg_1700709009110_1700709072926_image_0.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709009110_1700709072926_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913008",
    "name": "externallmg_1700709009443_1700709072926_image_1.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709009443_1700709072926_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913009",
    "name": "externallmg_1700709010646_1700709072926_image_2.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709010646_1700709072926_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991300a",
    "name": "externallmg_1700709011006_1700709072926_image_3.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709011006_1700709072926_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991300b",
    "name": "externallmg_1700709011987_1700709072926_image_4.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709011987_1700709072926_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "655ec379cabee4333991300c",
    "name": "externallmg_1700709012289_1700709072926_image_5.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709012289_1700709072926_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991300d",
    "name": "externallmg_1700709012684_1700709072926_image_6.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709012684_1700709072926_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991300e",
    "name": "externallmg_1700709013026_1700709072926_image_7.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709013026_1700709072926_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991300f",
    "name": "externallmg_1700709058188_1700709121696_image_0.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709058188_1700709121696_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913010",
    "name": "externallmg_1700709058600_1700709121696_image_1.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709058600_1700709121696_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913011",
```

```
    "name": "externallmg_1700709058924_1700709121696_image_2.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709058924_1700709121696_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913012",
    "name": "externallmg_1700709059233_1700709121696_image_3.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709059233_1700709121696_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913013",
    "name": "externallmg_1700709059613_1700709121696_image_4.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709059613_1700709121696_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913014",
    "name": "externallmg_1700709059915_1700709121696_image_5.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709059915_1700709121696_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913015",
    "name": "externallmg_1700709060047_1700709121696_image_6.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709060047_1700709121696_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913016",
    "name": "externallmg_1700709060310_1700709121696_image_7.jpeg",
```

```
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709060310_1700709121696_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913017",
    "name": "externallmg_1700709060770_1700709121696_image_8.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709060770_1700709121696_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913018",
    "name": "externallmg_1700709061063_1700709121696_image_9.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709061063_1700709121696_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee43339913019",
    "name": "externallmg_1700709061403_1700709121696_image_10.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709061403_1700709121696_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991301a",
    "name": "externallmg_1700709062033_1700709121696_image_11.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709062033_1700709121696_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655ec379cabee4333991301b",
    "name": "externallmg_1700709062269_1700709121696_image_12.jpeg",
    "path": "cases/655b86975586e008158e1472/
externallmg_1700709062269_1700709121696_image_12.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "655ec379cabee4333991301c",
  "name": "externallmg_1700708952782_1700709017621_image_0.jpeg",
  "path": "cases/655b86975586e008158e1472/
externallmg_1700708952782_1700709017621_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "655ec379cabee4333991301d",
  "name": "externallmg_1700708952966_1700709017621_image_1.jpeg",
  "path": "cases/655b86975586e008158e1472/
externallmg_1700708952966_1700709017621_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "TALIB AND SHAMSI CONSTRUCTION PVT LTD - Flat No. 202 &
302 -UBI-Mid Corporate Branch.xlsx",
    "filename": "1700724178049_TALIB_AND_SHAMSI_CONSTRUCTION_PVT_LTD_
_Flat_No_202__302__UBIMid_Corporate_Branch.xlsx",
    "path": "cases/655b86975586e008158e1472/processingDocuments/170072417804
9_TALIB_AND_SHAMSI_CONSTRUCTION_PVT_LTD__Flat_No_202__302__UBIMid_
Corporate_Branch.xlsx",
    "size": "3684636",
    "createdAt": "Thu Nov 23 2023 12:52:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
```

```

    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "655d95ed5586e00815902983",
    "note": "Value given for confirmation",
    "taskId": "655c63d95586e008158f061c",
    "createdAt": "2023-11-22T05:47:25.431Z"
  }
],
"createdAt": "2023-11-20T16:17:27.072Z",
"updatedAt": "2023-11-23T07:57:59.169Z",
"__v": 0,
"invoiceId": "655b86975586e008158e1478",
"fullAddress": "Residential Flat No. 202, 2nd Floor, Shalaka CHSL, Juhu Road,
Santacruz West, Mumbai, State - Maharashtra, India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Talib And Shamsi Construction Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892040259",
"siteVisitDate": "2023-11-23",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Any Other Document",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 805.00",
"flatRate": "45000",
"landOtherRate": "42200"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
