

```

{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8d5"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418f5",
    "email": "prasnat.sawant@cosmosbank.in",
    "firstName": "Prashant Sawant",
    "mobileNo": "9867065325",
    "workMobileNo": "9867065325",
    "lastName": "Sawant"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Prashant Sawant",
    "expectedFees": 5000,
    "quotedAmount": "10000"
  },
  "organization": {

```

```
{
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8d5",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Mulund (West) Branch",
  "email": "cosmos@mulundwestgmail.com",
  "mobileNo": "022-21640621",
  "alternateMobileNo": "022-21646370",
  "address": "Apurva Co-Op. Housing Society, Govardhan Nagar, L.B.S. Road, Mulund
(West), Mumbai - 400 080, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_& Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```

    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62ea09ea4e679b264caf07d7",
    "role": "SITEENGINEER",
    "firstName": "Suraj",
    "email": "suraj@vastukala.org",
    "lastName": "Zore",
    "mobileNo": "8652448654",
    "designation": "",
    "shortName": "SZ",
    "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
    "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",

```

```
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
```

```

      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.179000",
  "longitude": "72.952472"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.952472,
    19.179
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-23",
      "remark": ""
    }
  ]
}
],
},

```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "545",
  "rate": "10910",
  "yearOfConstruction": "1980",
  "compositionOfBuilding": "Ground + 3 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",

```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ramgopal Industrial Estate",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",  
"key": "selectArea",  
"value": "",  
"label": true  
},  
"street1": {  
  "status": true,  
  "name": "Street 1",  
  "key": "street1",  
  "value": "Dr Rajendra Prasad Road",  
  "label": false  
},  
"street2": {  
  "status": false,  
  "name": "Street 2",  
  "key": "street2",  
  "value": "",  
  "label": false  
},  
"landmark": {  
  "status": false,  
  "name": "Landmark",  
  "key": "landmark",  
  "value": "",  
  "label": false  
},  
"wing": {  
  "status": false,  
  "name": "Wing",  
  "key": "wing",  
  "value": "",  
  "label": true  
},  
"projectName": {  
  "status": false,  
  "name": "Project Name",  
  "key": "projectName",  
  "value": "",  
  "label": false  
},  
"oldSurveyNumber": {  
  "status": false,  
  "name": "Old Survey No.",  
  "key": "oldSurveyNumber",  
  "value": "",  
  "label": true  
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit No 204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund West",
  "label": false
}
```

```
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```



```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "655dd5705586e0081590f5ed",
"audioRemarks": [],
"ownerName": "Dilip Dattatray Pishawikar",
"ownerPhoneNo": "9223354070",
"appAddress": "Industrial Unit no. 214, 2nd floor, Ramgopal Industrial estate, Dr.
Rajendra Prasad Road, Mulund West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Re-Sale",
      "value": "60ae1294aa6d152c1801b44b"
    },
    "isHardCopy": false,
    "path": "cases/655dd5705586e0081590f5ed/
document_1700648285771_85886.pdf",
    "fileName": "document_1700648285771_85886.pdf",
    "displayStatus": false,
    "id": "714301",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Wed Nov 22 2023 15:48:24 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "from": {
      "value": "Developers",
```

```
    "label": "Developers"
  },
  "Developers": "-",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "-",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-",
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1702014926867_90600.pdf",
"path": "cases/655dd5705586e0081590f5ed/
document_1702014926867_90600.pdf",
"id": "333320",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Dec 08 2023 11:25:26 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005188",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "289645",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 22 2023 15:48:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Dilip Dattatray Pishawikar",
    "phone": "9223354070",
    "ownershipShare": "",
    "email": "",
    "id": "473902"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d45e",
    "name": "externallmg_r_1700753532901_1700753594899_image_1.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753532901_1700753594899_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d45f",
    "name": "externallmg_r_1700753531865_1700753594899_image_0.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753531865_1700753594899_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d460",
    "name": "externallmg_r_1700753533798_1700753594899_image_2.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753533798_1700753594899_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d461",
    "name": "externallmg_r_1700753534877_1700753594899_image_3.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753534877_1700753594899_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d462",
```

```
    "name": "externallmg_r_1700753535985_1700753594899_image_4.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753535985_1700753594899_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d463",
    "name": "externallmg_r_1700753542216_1700753594899_image_6.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753542216_1700753594899_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d464",
    "name": "externallmg_r_1700753536778_1700753594899_image_5.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753536778_1700753594899_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d465",
    "name": "externallmg_r_1700753543806_1700753594899_image_7.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753543806_1700753594899_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d466",
    "name": "externallmg_r_1700753546774_1700753594899_image_9.jpg",
    "path": "cases/655dd5705586e0081590f5ed/
externallmg_r_1700753546774_1700753594899_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655f70e9cabee4333992d467",
    "name": "externallmg_r_1700753545091_1700753594899_image_8.jpg",
```

```
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753545091_1700753594899_image_8.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "655f70e9cabee4333992d468",  
    "name": "externallmg_r_1700753548497_1700753594899_image_10.jpg",  
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753548497_1700753594899_image_10.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "655f70e9cabee4333992d469",  
    "name": "externallmg_r_1700753550426_1700753594899_image_11.jpg",  
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753550426_1700753594899_image_11.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "655f70e9cabee4333992d46a",  
    "name": "externallmg_r_1700753552197_1700753594899_image_12.jpg",  
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753552197_1700753594899_image_12.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "655f70e9cabee4333992d46b",  
    "name": "externallmg_r_1700753498350_1700753561244_image_2.png",  
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753498350_1700753561244_image_2.png",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "655f70e9cabee4333992d46c",  
    "name": "externallmg_r_1700753497027_1700753561244_image_1.jpg",  
    "path": "cases/655dd5705586e0081590f5ed/  
externallmg_r_1700753497027_1700753561244_image_1.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "655f70e9cabee4333992d46d",
  "name": "externalimg_r_1700753495838_1700753561244_image_0.jpg",
  "path": "cases/655dd5705586e0081590f5ed/
externalimg_r_1700753495838_1700753561244_image_0.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Lalit Manakchand Kothari.doc",
    "filename": "1702014650165_Lalit_Manakchand_Kothari.doc",
    "path": "cases/655dd5705586e0081590f5ed/
externalDocuments/1702014650165_Lalit_Manakchand_Kothari.doc",
    "size": "23702016",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Fri Dec 08 2023 11:20:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"processingDocuments": [
  {
    "originalname": "DILIP DATTATRAY PISHAWIKAR- Cosmos Bank ( Mulund (West)
Branch ).xlsx",
    "filename": "1701948112246_DILIP_DATTATRAY_PISHAWIKAR_Cosmos_Bank__
Mulund_West_Branch_.xlsx",
    "path": "cases/655dd5705586e0081590f5ed/processingDocuments/1701948112246
_DILIP_DATTATRAY_PISHAWIKAR_Cosmos_Bank__Mulund_West_Branch_.xlsx",
    "size": "1033025",
    "createdAt": "Thu Dec 07 2023 16:51:52 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
```

```

    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65602f11cabee43339930411",
  "note": "Area details not available in the documents",
  "taskId": "655dd9d25586e0081591080f",
  "createdAt": "2023-11-24T05:05:21.074Z"
}
],
"createdAt": "2023-11-22T10:18:24.934Z",
"updatedAt": "2023-12-08T05:55:26.977Z",
"__v": 0,
"invoiceId": "655dd5715586e0081590f5f6",
"fullAddress": "Industrial Unit No. Unit No 204, 2nd Floor, Ramgopal Industrial Estate,
Dr Rajendra Prasad Road, Mulund West, Mumbai, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Dilip Dattatray Pishawikar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9223354070",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"siteVisitDate": "2023-11-23"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			