

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b883"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230b72",
    "firstName": "Mr. Sandeep bhatnagar",
    "email": "b06668@pnb.co.in",
    "mobileNo": null,
    "workMobileNo": "9004071747"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",

```

```
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b883",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "APMC Vashi Branch",
  "email": "bo3864@pnb.co.in",
  "mobileNo": "022-27651957 ",
  "alternateMobileNo": "27652890",
  "address": "Central Facility Building No. 2, Sector - 19, Vashi, Navi Mumbai - 400
705, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "PUNJAB NATIONAL BANK - APMC VASHI ",
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62720e52afd7d55eddedc887",
"role": "PICKUPPERSON",
"firstName": "Harshad",
"email": "harshad@vastukala.org",
"lastName": "Panchal",
"mobileNo": "9029575553",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
```

```
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.034153802587905",
  "longitude": "73.0674525192814"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "25/11/2023 12:00 am"
    },
    {
      "dateTime": "25/11/2023 12:00 am"
    },
    {
      "dateTime": "25/11/2023 12:00 am"
    },
    {
      "dateTime": "25/11/2023 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Navi Mumbai",
    "label": true
  },
  "city": {
    "status": false,
```

```
"name": "City",
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "2",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "SS/II",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "8",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Koparkhairane",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```



```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "65619b23cabee43339958344",
"ownerName": "Mr. Vishwas Dinkar Patil",
"ownerPhoneNo": "9892352669",
"fullAddress": "Residential Flat No. 106, Ground Floor, SS/II, Koparkhairane, Plot No.
2, Sector 8, District - Navi Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/07/2010",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Pinjari Bholinath Ramu",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Vishwas Dinkar Patil",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "6731/2010"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "561174",
    "path": "cases/65619b23cabee43339958344/
document_1700895512296_Ramu_bholenath_pinjari_PnbVashi_sector1_4.pdf",
    "fileName":
"document_1700895512296_Ramu_bholenath_pinjari_PnbVashi_sector1_4.pdf"
  },
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
```



```
"label": "Deed of Apartment"
},
"inputs": {
  "documentDate": "12/10/2010",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Pinjari Bholinath Ramu",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Vishwas Dinkar Patil",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  }
},
"file": {
  "isHardCopy": false,
  "displayStatus": true,
  "fileName":
"document_1701088136667_Ramu_bholenath_pinjari_PnbVashi_sector1_4.pdf",
  "path": "cases/65619b23cabee43339958344/
document_1701088136667_Ramu_bholenath_pinjari_PnbVashi_sector1_4.pdf",
  "id": "280575",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Nov 27 2023 18:01:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30a",
    "label": "Floor Plan"
  },
  "inputs": {
    "documentDate": "27/07/1990",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1701088262699_101108.pdf",
  "path": "cases/65619b23cabee43339958344/
document_1701088262699_101108.pdf",
```

```
"id": "150565",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Nov 27 2023 18:01:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1255aa6d152c1801b329",
    "label": "Possession Receipt"
  },
  "inputs": {
    "documentDate": "20/10/1993",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  }
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1701146460481_201681.pdf",
"path": "cases/65619b23cabee43339958344/
document_1701146460481_201681.pdf",
"id": "223975",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Nov 28 2023 10:19:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "inputs": {
    "documentDate": "22/10/1993",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  }
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1701146496482_130706.pdf",
"path": "cases/65619b23cabee43339958344/
document_1701146496482_130706.pdf",
"id": "782042",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Nov 28 2023 10:19:09 GMT+0530 (India Standard Time)"
},
}
```

```
{
  "documentType": {
    "value": "60ae1296aa6d152c1801b457",
    "label": "Letter"
  },
  "inputs": {
    "documentDate": "09/05/2000",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1701146860487_128176.pdf",
  "path": "cases/65619b23cabee43339958344/
document_1701146860487_128176.pdf",
  "id": "130668",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Nov 28 2023 10:19:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1296aa6d152c1801b457",
    "label": "Letter"
  },
  "inputs": {
    "documentDate": "28/07/2010",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1701146949817_111247.pdf",
  "path": "cases/65619b23cabee43339958344/
document_1701146949817_111247.pdf",
  "id": "551412",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Nov 28 2023 10:19:09 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005256",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
```

```
{
  "id": "403386",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Nov 25 2023 12:28:43 GMT+0530 (India Standard Time)"
},
"owners": [
  {
    "name": "Mr. Vishwas Dinkar Patil",
    "phone": "9892352669",
    "ownershipShare": "",
    "email": "",
    "id": "769911"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6562d959cabee433399791b6",
    "name": "externalimg_1700976985031_Screenshot_20231126_105535.jpg",
    "path": "cases/65619b23cabee43339958344/externalimg_1700976985031_Screenshot_20231126_105535.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6562d959cabee433399791b7",
    "name": "externalimg_r_1700976985050_JKFantasy____20231125Sat_103423AM____hnbm_lmjn____org.jpg",
    "path": "cases/65619b23cabee43339958344/externalimg_r_1700976985050_JKFantasy____20231125Sat_103423AM____hnbm_lmjn____org.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6562d959cabee433399791b8",
  "name": "externalImg_r_1700976985025_JKFantasy___20231125Sat_103420AM___
_____hnbm_lmjn___org.jpg",
  "path": "cases/65619b23cabee43339958344/externalImg_r_1700976985025_JKFan
tasy___20231125Sat_103420AM_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6562d959cabee433399791b9",
  "name": "externalImg_r_1700976985020_JKFantasy___20231125Sat_103418AM___
_____hnbm_lmjn___org.jpg",
  "path": "cases/65619b23cabee43339958344/externalImg_r_1700976985020_JKFan
tasy___20231125Sat_103418AM_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "IGR-01.pdf",
    "filename": "1701071578763_IGR01.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578763_IGR01.pdf",
    "size": "146132",
    "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1701071578769_IGR02.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578769_IGR02.pdf",
    "size": "141191",
    "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1701071578776_IGR03.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578776_IGR03.pdf",
    "size": "142156",
    "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1701071578780_IGR04.pdf",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578780_IGR04.pdf",
  "size": "144057",
  "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-05.pdf",
  "filename": "1701071578783_IGR05.pdf",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578783_IGR05.pdf",
  "size": "145463",
  "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-06.pdf",
  "filename": "1701071578788_IGR06.pdf",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578788_IGR06.pdf",
  "size": "141003",
  "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-07.pdf",
  "filename": "1701071578791_IGR07.pdf",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578791_IGR07.pdf",
  "size": "150795",
  "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-08.pdf",
  "filename": "1701071578795_IGR08.pdf",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578795_IGR08.pdf",
  "size": "139426",
  "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
  },
  {
    "originalname": "IGR-09.pdf",
    "filename": "1701071578801_IGR09.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578801_IGR09.pdf",
    "size": "142250",
    "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-10.pdf",
    "filename": "1701071578806_IGR10.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071578806_IGR10.pdf",
    "size": "146484",
    "createdAt": "Mon Nov 27 2023 13:22:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR.pdf",
    "filename": "1701071586488_AGR.pdf",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071586488_AGR.pdf",
    "size": "49926987",
    "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG_20231126_105938.jpg",
    "filename": "1701071587578_IMG_20231126_105938.jpg",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071587578_IMG_20231126_105938.jpg",
    "size": "3946961",
    "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG_20231126_105946.jpg",
    "filename": "1701071587697_IMG_20231126_105946.jpg",
    "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071587697_IMG_20231126_105946.jpg",
    "size": "3815167",
    "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
}
```

```
{
  "originalname": "IMG_20231126_105949.jpg",
  "filename": "1701071587790_IMG_20231126_105949.jpg",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071587790_IMG_20231126_105949.jpg",
  "size": "3469912",
  "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Screenshot_20231126_105535.jpg",
  "filename": "1701071587879_Screenshot_20231126_105535.jpg",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071587879_Screenshot_20231126_105535.jpg",
  "size": "1266629",
  "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=Vishwas.xlsx",
  "filename": "1701071587909_Summary_NewVishwas.xlsx",
  "path": "cases/65619b23cabee43339958344/
processingDocuments/1701071587909_Summary_NewVishwas.xlsx",
  "size": "1870230",
  "createdAt": "Mon Nov 27 2023 13:23:07 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65631e85cabee43339984444",
    "note": "Pending for value confirmation",
    "taskId": "65619b3acabee4333995841e",
  }
]
```



```

    "createdAt": "2023-11-26T10:31:33.306Z"
  }
],
"createdAt": "2023-11-25T06:58:43.514Z",
"updatedAt": "2023-11-28T04:49:09.906Z",
"__v": 0,
"invoiceId": "65619b23cabee4333995834d",
"updatedAt": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Vishwas Dinkar Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892352669"
}

```

| Name          | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : |        |       |       |
| Other         |        |       |       |
| Composition : |        |       |       |