

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.23848151266863",
  "longitude": "72.85463755092232"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85463755092232,
    19.23848151266863
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "26/11/2023 11:00 am"
  },
  {
    "dateTime": "26/11/2023 12:00 am"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-11-27",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Eksar",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
}
```

```
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Arkade Crown",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sardar Vallabhbhai Patel Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
```



```
"key": "wing",
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "226, 198",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "5",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1430",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "703",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 103",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (West), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
```

```
"general": {
  "ownership": {
    "value": "Proposed_Purchaser_-_Joint_Ownership",
    "label": "Proposed Purchaser - Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Pluto Apartment",
    "west": "Ami Prabha Residency",
    "south": "Chandra Apartment",
    "east": "Sardar Vallabhbai Patel Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
}
```

```
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal Site Inspection,
Measurement & Photographs of the property. Details about the work progress status
has been provided by Sales Manager - Mr. Subhash Rane (Contact No. 9819817269).",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "159700",
  "landRate": "70730",
  "igrImage": "cases/6562c017cabee433399765b4/igr_1700980092877_Image.png",
  "squareMeterGuideLineRate": "167685.00",
  "squareFeetGuideLineRate": "15578.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "159700.00",
  "squareMeterGuideLineRate": "167685.00",
  "squareFeetGuideLineRate": "15578.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
}
```

```
},
"monthlyRent": "53000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed 1 S at P1 Level Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
},
```

```
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_RCC_Slab",
  "label": "Proposed RCC Slab"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
```

```
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "7",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "792.00",
```



```
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6562c017cabee433399765b4/
routeMap_1701078196943_Image.png",
    "routeLat": "19.238261",
    "routeLng": "72.854594",
    "stationName": "Borivali",
    "routeDistance": "1.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "l8fh8",
      "name": "l8fh8",
      "image": "cases/6562c017cabee433399765b4/
routeMap_1701078127464_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
```

```
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "1",
"othersRate": "1000000",
"totalothersRate": "1000000",
"finaltotal": "26200000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "25200000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Nov 27 2023 17:40:31 GMT+0530 (India Standard Time)",
  "number": "2303687",
  "dayCount": "13",
  "monthCount": "383",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "Complete",
"percentage": "5",
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "20",
  "percentage": "33.333333333333336",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "14",
  "percentage": "4.08",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "14",
  "percentage": "4.08",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "12",
  "percentage": "1.75",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "12",
  "percentage": "1.75",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "54.99",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12337776.00",
  "selectedBuildUpValue": "792.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65645d0ecabee433399a0bca",
      "name":
"externalImg_1701076238123_WhatsApp_Image_20231127_at_22946_PM_1.jpeg",
      "path": "cases/6562c017cabee433399765b4/
externalImg_1701076238123_WhatsApp_Image_20231127_at_22946_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65645d0ecabee433399a0bd7",
      "name":
"externalImg_1701076238162_WhatsApp_Image_20231127_at_22944_PM_2.jpeg",
      "path": "cases/6562c017cabee433399765b4/
externalImg_1701076238162_WhatsApp_Image_20231127_at_22944_PM_2.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65645d0ecabee433399a0bcd",
    "name":
"externallmg_1701076238136_WhatsApp_Image_20231127_at_22947_PM_2.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238136_WhatsApp_Image_20231127_at_22947_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65645d0ecabee433399a0bda",
    "name":
"externallmg_1701076238170_WhatsApp_Image_20231127_at_22945_PM_2.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238170_WhatsApp_Image_20231127_at_22945_PM_2.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "33932",
    "max": "36371"
  },
  "builtUpRateRange": {
    "min": "30848",
    "max": "33065"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "720.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORDELIVERY",
"paymentId": [],
"_id": "6562c017cabee433399765b4",
"ownerName": "Arkade Developers Pvt. Ltd.",
"ownerPhoneNo": "8082645878",
"appAddress": "Flat no 703 7 th floor A- Wing Project Arkade Crown Borivali West
400103",
"remark": "SSL Prasan Rinku Gupta - 7021444942",
"documents": [
  {
    "documentType": {
      "value": "656489dfcabee433399a9a61",
      "label": "Cost Sheet"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "632864",
    "path": "cases/6562c017cabee433399765b4/
document_1700970479862_1700970548002_Jinesh_ViraCost_Sheet.pdf",
    "fileName":
"document_1700970479862_1700970548002_Jinesh_ViraCost_Sheet.pdf"
  },
  {
    "documentType": {
      "value": "60ae1259aa6d152c1801b33f",
      "label": "Builder Letter"
    },
    "inputs": {
      "documentDate": "08/11/2023",
      "remark": "issued by Arkade Developers Ltd."
    }
  },
  "isHardCopy": false,
```

```
    "displayStatus": true,
    "id": "685485",
    "path": "cases/6562c017cabee433399765b4/
document_1700970495548_1700970563463_Jinesh_ViraNOC.pdf",
    "fileName": "document_1700970495548_1700970563463_Jinesh_ViraNOC.pdf"
  }
],
"caseNumber": "005261",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "348263",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Nov 26 2023 09:18:39 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Arkade Developers Pvt. Ltd.",
    "phone": "8082645878",
    "ownershipShare": "",
    "email": "",
    "id": "634370"
  }
],
"proposePurchasers": [
  {
    "name": "Mr. Jinesh Manilal Vira & Mrs. Queenjal Premji Gogri",
    "phone": "",
    "email": "",
    "ownershipShare": ""
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "656489dfcabee433399a9a61",
      "label": "Cost Sheet"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```

    "label": "Square Feet"
  },
  "id": "154230",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "720",
  "squareMeterArea": "66.89",
  "docFinalBuiltUp": "792",
  "docFinalBuiltUpSquareMeter": "73.57900000000001",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6562e581cabee4333997d690",
    "property": "2 BHK Flat For Sale Arkade Crown, Mandapeshwar, Mumbai",
    "area": "734",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "26500000.00",
    "expectedRate": "36103.54",
    "builtUpExpectedRate": "32821.40",
    "image": "cases/6562c017cabee433399765b4/indicator_1700979382623_Image.png",
    "squareMeter": "68.19",
    "id": "191227"
  },
  {
    "printlnReport": true,
    "_id": "6562e581cabee4333997d691",
    "property": "3 BHK Flat For Sale Borivali West, Mumbai",
    "area": "1240.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "45100000.00",
    "expectedRate": "36370.97",
  }
]

```

```
    "builtUpExpectedRate": "33064.52",
    "image": "cases/6562c017cabee433399765b4/
indicator_1700979446814_Image.png",
    "squareMeter": "115.20",
    "id": "871082"
  },
  {
    "printlnReport": true,
    "_id": "6562e581cabee4333997d692",
    "property": "3 BHK Flat For Sale Arkade Crown Borivali West, Mumbai",
    "area": "1290.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "45100000.00",
    "expectedRate": "34961.24",
    "builtUpExpectedRate": "31782.95",
    "image": "cases/6562c017cabee433399765b4/
indicator_1700979492830_Image.png",
    "squareMeter": "119.85",
    "id": "215502"
  },
  {
    "printlnReport": true,
    "_id": "6562e581cabee4333997d693",
    "property": "Arkade Crown Borivali West, Mumbai",
    "area": "1114.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "37800000",
    "expectedRate": "33931.78",
    "builtUpExpectedRate": "30847.07",
    "image": "cases/6562c017cabee433399765b4/
indicator_1700979584874_Image.png",
    "squareMeter": "103.49",
    "id": "552533"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65645d0ecabee433399a0bca",
  "name":
"externallmg_1701076238123_WhatsApp_Image_20231127_at_22946_PM_1.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238123_WhatsApp_Image_20231127_at_22946_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bcb",
  "name":
"externallmg_1701076238128_WhatsApp_Image_20231127_at_22946_PM_2.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238128_WhatsApp_Image_20231127_at_22946_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bcc",
  "name":
"externallmg_1701076238132_WhatsApp_Image_20231127_at_22947_PM_1.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238132_WhatsApp_Image_20231127_at_22947_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bcd",
  "name":
"externallmg_1701076238136_WhatsApp_Image_20231127_at_22947_PM_2.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238136_WhatsApp_Image_20231127_at_22947_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bce",
  "name":
"externallmg_1701076238139_WhatsApp_Image_20231127_at_22947_PM.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238139_WhatsApp_Image_20231127_at_22947_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65645d0ecabee433399a0bcf",
    "name":
"externallmg_1701076238143_WhatsApp_Image_20231127_at_22948_PM_1.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238143_WhatsApp_Image_20231127_at_22948_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65645d0ecabee433399a0bd0",
    "name":
"externallmg_1701076238145_WhatsApp_Image_20231127_at_22948_PM_2.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238145_WhatsApp_Image_20231127_at_22948_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65645d0ecabee433399a0bd1",
    "name":
"externallmg_1701076238148_WhatsApp_Image_20231127_at_22948_PM.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238148_WhatsApp_Image_20231127_at_22948_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65645d0ecabee433399a0bd2",
    "name":
"externallmg_1701076238151_WhatsApp_Image_20231127_at_22949_PM_1.jpeg",
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238151_WhatsApp_Image_20231127_at_22949_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65645d0ecabee433399a0bd3",
```

```
    "name":
"externallmg_1701076238153_WhatsApp_Image_20231127_at_22949_PM_2.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238153_WhatsApp_Image_20231127_at_22949_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd4",
  "name":
"externallmg_1701076238155_WhatsApp_Image_20231127_at_22949_PM.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238155_WhatsApp_Image_20231127_at_22949_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd5",
  "name":
"externallmg_1701076238157_WhatsApp_Image_20231127_at_22950_PM.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238157_WhatsApp_Image_20231127_at_22950_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd6",
  "name":
"externallmg_1701076238159_WhatsApp_Image_20231127_at_22944_PM_1.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238159_WhatsApp_Image_20231127_at_22944_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd7",
  "name":
"externallmg_1701076238162_WhatsApp_Image_20231127_at_22944_PM_2.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238162_WhatsApp_Image_20231127_at_22944_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd8",
  "name":
"externallmg_1701076238165_WhatsApp_Image_20231127_at_22944_PM.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238165_WhatsApp_Image_20231127_at_22944_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bd9",
  "name":
"externallmg_1701076238167_WhatsApp_Image_20231127_at_22945_PM_1.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238167_WhatsApp_Image_20231127_at_22945_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bda",
  "name":
"externallmg_1701076238170_WhatsApp_Image_20231127_at_22945_PM_2.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238170_WhatsApp_Image_20231127_at_22945_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bdb",
  "name":
"externallmg_1701076238174_WhatsApp_Image_20231127_at_22945_PM.jpeg",
  "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238174_WhatsApp_Image_20231127_at_22945_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65645d0ecabee433399a0bdc",
  "name":
"externallmg_1701076238176_WhatsApp_Image_20231127_at_22946_PM.jpeg",
```



```
    "path": "cases/6562c017cabee433399765b4/
externallmg_1701076238176_WhatsApp_Image_20231127_at_22946_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
    "originalname": "Valuation_report_Arkade Developers Pvt. Ltd.pdf",
    "filename": "1701157416766_Valuation_report_Arkade_Developers_Pvt_Ltd.pdf",
    "path": "cases/6562c017cabee433399765b4/externalDocuments/1701157416766_Valuation_report_Arkade_Developers_Pvt_Ltd.pdf",
    "size": "999287",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Tue Nov 28 2023 13:13:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  }
],
"processingDocuments": [
  {
    "originalname": "5261.xlsx",
    "filename": "1701081858128_5261.xlsx",
    "path": "cases/6562c017cabee433399765b4/processingDocuments/1701081858128_5261.xlsx",
    "size": "8123",
    "createdAt": "Mon Nov 27 2023 16:14:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "SBI - Arkade Developers Pvt. Ltd..pdf",
    "filename": "1701087889271_SBI__Arkade_Developers_Pvt_Ltd.pdf",
    "path": "cases/6562c017cabee433399765b4/processingDocuments/1701087889271_SBI__Arkade_Developers_Pvt_Ltd.pdf",
    "size": "8005664",
    "createdAt": "Mon Nov 27 2023 17:54:49 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "62691c48afd7d55eddecfda3",
```

```
    "role": "ADMIN",
    "firstName": "Bhavika",
    "lastName": "chavan",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "6565c86a5996860c23017bcb",
  "note": "Parking Details (Task Reopen)",
  "taskId": "6562e588cabee4333997d69d",
  "createdAt": "2023-11-28T11:00:58.109Z"
}
],
"createdAt": "2023-11-26T03:48:39.605Z",
"updatedAt": "2023-11-28T11:29:13.869Z",
"__v": 0,
"invoiceId": "6562c017cabee433399765bf",
"fullAddress": "Residential Flat No. 703, 7th Floor, Wing - A, Arkade Crown, Sardar
Vallabhbhai Patel Road, Village - Eksar, Borivali (West), Mumbai, Taluka - Borivali,
District - Mumbai suburban, PIN Code - 400 103, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60af6ae2ffdf65bcd65861d",
"contactPersonName": "Mr. Subhash Rane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Manager",
"siteVisitContactNo": "9819817269",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Cost_Inflation_Index",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 720.00",
"flatRate": "35000",
"landOtherRate": "32000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
```

```

},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
},
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Mon Nov 27 2023 15:51:49 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-27"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			