

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": ""
  },
  "fees": {
    "type": "quoted",
    "propertyValue": "0",
    "discussWithPerson": "Mrs. Mona Mehta",
    "expectedFees": null,
    "quotedAmount": "7500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.12046284106089",
  "longitude": "72.84992294525564"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/12/2023 04:30 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gundavli ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Shiv Chhaya Co-Op. Hsg. Soc. Ltd. ",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "33, Sir M.V.Road ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Green Bungalow",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "658, 658/1, 659, 660",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 069",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/ _Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
}
```

```
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Binu Apartment ",
  "west": "Mittal Industrial Estate ",
  "south": "Sir Mathuradas VasANJI Road ",
  "east": "Ganesh Mandir"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Approved Building plans were not provided and not
verified.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
}
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_Purpose",
    "label": "Commercial Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1966",
  "fullDate": "1/1/1966"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
```

```
"estimatedAge": "3",
"ageOfBuilding": "57",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "Basement",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "1"
},
"finalPlinthArea": {
  "area": "1900.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/657961be3fcadc6777678d55/
routeMap_1702621787879_Image.png",
    "routeLat": "19.120306",
    "routeLng": "72.850056",
    "stationName": "Andheri ",
    "routeDistance": "180 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "wtok4",
      "name": "wtok4",
      "image": "cases/657961be3fcadc6777678d55/
routeMap_1702621699663_Image.png"
    }
  ]
}
```



```
]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "1900.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "657be0833fcadc67776a9fef",
    "name":
"externalImg_1702617219789_WhatsApp_Image_20231215_at_104256_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externalImg_1702617219789_WhatsApp_Image_20231215_at_104256_AM.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "1900.00",
empanelmentNo": [],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "657961be3fcadc6777678d55",
"ownerName": "Mrs. Pooja Chirag Shah & Mr. Chirag Ashok Shah ",
"ownerPhoneNo": "9967771932",
"fullAddress": "Commercial Office No. Basement Floor, Wing - B, Shiv Chhaya Co-Op.
Hsg. Soc. Ltd. , CTS No. 658, 658/1, 659, 660, 33, Sir M.V.Road , Green Bungalow,
Village - Gundavli , Taluka - Andheri, District - Mumbai Suburban, Andheri (East), PIN -
400 069, State - Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "03/04/2006",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Dhirajlal N. Kamdar ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mrs. Pooja Chirag Shah & Mr. Chirag Ashok Shah ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "2694 / 2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1702619470477_Agreement_For_sale.pdf",
    "path": "cases/657961be3fcadc6777678d55/
document_1702619470477_Agreement_For_sale.pdf",
    "id": "515607",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Fri Dec 15 2023 11:21:10 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae1247aa6d152c1801b2ea",
  "label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "26/02/1996",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "GBK / 518 / A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1702619567690_239736.pdf",
"path": "cases/657961be3fcadc6777678d55/
document_1702619567690_239736.pdf",
"id": "532250",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Dec 15 2023 11:22:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "remark": " transferred dated 13.04.2007 issued by Shiv - Chhaya Co-Op. Hsg.
Soc. Ltd",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mrs. Pooja Chirag Shah & Mr. Chirag Ashok Shah ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "25"
  },
  "isHardCopy": false,
  "displayStatus": false,
```



```
    "fileName": "document_1702619662027_Document_.pdf",
    "path": "cases/657961be3fcadc6777678d55/
document_1702619662027_Document_.pdf",
    "id": "294812",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Fri Dec 15 2023 11:24:22 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "02/11/2021",
      "remark": " in the name of Mrs. Pooja Chirag Shah & Mr. Chirag Ashok Shah
issued by Vastukala consultant's Pvt. Ltd. "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1702619747790_document_1702453683159_Valuation_Re
port_Pooja_Chirag_Shah.pdf",
    "path": "cases/657961be3fcadc6777678d55/document_1702619747790_document_
1702453683159_Valuation_Report_Pooja_Chirag_Shah.pdf",
    "id": "428689",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Fri Dec 15 2023 11:25:47 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "005587",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "830795",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Dec 13 2023 13:18:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Pooja Chirag Shah & Mr. Chirag Ashok Shah ",
    "phone": "9967771932",
```

```
"ownershipShare": "",
"email": "",
"id": "671174"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "256003",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "1900",
  "squareMeterArea": "176.51",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0833fcadc67776a9feb",
  "name":
"externalImg_1702617219760_WhatsApp_Image_20231215_at_104254_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externalImg_1702617219760_WhatsApp_Image_20231215_at_104254_AM_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9fec",
    "name":
"externallmg_1702617219765_WhatsApp_Image_20231215_at_104255_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219765_WhatsApp_Image_20231215_at_104255_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9fed",
    "name":
"externallmg_1702617219772_WhatsApp_Image_20231215_at_104255_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219772_WhatsApp_Image_20231215_at_104255_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9fee",
    "name":
"externallmg_1702617219783_WhatsApp_Image_20231215_at_104256_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219783_WhatsApp_Image_20231215_at_104256_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9fef",
    "name":
"externallmg_1702617219789_WhatsApp_Image_20231215_at_104256_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219789_WhatsApp_Image_20231215_at_104256_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff0",
    "name":
"externallmg_1702617219794_WhatsApp_Image_20231215_at_104257_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219794_WhatsApp_Image_20231215_at_104257_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff1",
    "name":
"externallmg_1702617219803_WhatsApp_Image_20231215_at_104247_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219803_WhatsApp_Image_20231215_at_104247_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff2",
    "name":
"externallmg_1702617219810_WhatsApp_Image_20231215_at_104247_AM_2.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219810_WhatsApp_Image_20231215_at_104247_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff3",
    "name":
"externallmg_1702617219812_WhatsApp_Image_20231215_at_104248_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219812_WhatsApp_Image_20231215_at_104248_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff4",
    "name":
"externallmg_1702617219814_WhatsApp_Image_20231215_at_104248_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219814_WhatsApp_Image_20231215_at_104248_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0833fcadc67776a9ff5",
```

```
    "name":
"externallmg_1702617219817_WhatsApp_Image_20231215_at_104249_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219817_WhatsApp_Image_20231215_at_104249_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0833fcadc67776a9ff6",
  "name":
"externallmg_1702617219819_WhatsApp_Image_20231215_at_104249_AM_2.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219819_WhatsApp_Image_20231215_at_104249_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0833fcadc67776a9ff7",
  "name":
"externallmg_1702617219822_WhatsApp_Image_20231215_at_104249_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219822_WhatsApp_Image_20231215_at_104249_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0833fcadc67776a9ff8",
  "name":
"externallmg_1702617219825_WhatsApp_Image_20231215_at_104250_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219825_WhatsApp_Image_20231215_at_104250_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0833fcadc67776a9ff9",
  "name":
"externallmg_1702617219827_WhatsApp_Image_20231215_at_104250_AM_2.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617219827_WhatsApp_Image_20231215_at_104250_AM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0ab",
  "name":
"externallmg_1702617234535_WhatsApp_Image_20231215_at_104250_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234535_WhatsApp_Image_20231215_at_104250_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0ac",
  "name":
"externallmg_1702617234538_WhatsApp_Image_20231215_at_104251_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234538_WhatsApp_Image_20231215_at_104251_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0ad",
  "name":
"externallmg_1702617234542_WhatsApp_Image_20231215_at_104251_AM_2.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234542_WhatsApp_Image_20231215_at_104251_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0ae",
  "name":
"externallmg_1702617234547_WhatsApp_Image_20231215_at_104251_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234547_WhatsApp_Image_20231215_at_104251_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0af",
  "name":
"externallmg_1702617234549_WhatsApp_Image_20231215_at_104252_AM_1.jpeg",
```

```
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234549_WhatsApp_Image_20231215_at_104252_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0923fcadc67776aa0b0",
    "name":
"externallmg_1702617234552_WhatsApp_Image_20231215_at_104252_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234552_WhatsApp_Image_20231215_at_104252_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0923fcadc67776aa0b1",
    "name":
"externallmg_1702617234556_WhatsApp_Image_20231215_at_104253_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234556_WhatsApp_Image_20231215_at_104253_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0923fcadc67776aa0b2",
    "name":
"externallmg_1702617234558_WhatsApp_Image_20231215_at_104253_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234558_WhatsApp_Image_20231215_at_104253_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0923fcadc67776aa0b3",
    "name":
"externallmg_1702617234561_WhatsApp_Image_20231215_at_104254_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234561_WhatsApp_Image_20231215_at_104254_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "657be0923fcadc67776aa0b4",
  "name":
"externallmg_1702617234563_WhatsApp_Image_20231215_at_104226_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234563_WhatsApp_Image_20231215_at_104226_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0b5",
  "name":
"externallmg_1702617234566_WhatsApp_Image_20231215_at_104226_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234566_WhatsApp_Image_20231215_at_104226_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0b6",
  "name":
"externallmg_1702617234568_WhatsApp_Image_20231215_at_104232_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234568_WhatsApp_Image_20231215_at_104232_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0b7",
  "name":
"externallmg_1702617234571_WhatsApp_Image_20231215_at_104232_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234571_WhatsApp_Image_20231215_at_104232_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be0923fcadc67776aa0b8",
  "name":
"externallmg_1702617234574_WhatsApp_Image_20231215_at_104233_AM_1.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234574_WhatsApp_Image_20231215_at_104233_AM_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be0923fcadc67776aa0b9",
    "name":
    "externallmg_1702617234577_WhatsApp_Image_20231215_at_104233_AM_2.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617234577_WhatsApp_Image_20231215_at_104233_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be09c3fcadc67776aa10b",
    "name":
    "externallmg_1702617244794_WhatsApp_Image_20231215_at_104233_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617244794_WhatsApp_Image_20231215_at_104233_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be09c3fcadc67776aa10c",
    "name":
    "externallmg_1702617244798_WhatsApp_Image_20231215_at_104234_AM_1.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617244798_WhatsApp_Image_20231215_at_104234_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be09c3fcadc67776aa10d",
    "name":
    "externallmg_1702617244800_WhatsApp_Image_20231215_at_104234_AM.jpeg",
    "path": "cases/657961be3fcadc6777678d55/
externallmg_1702617244800_WhatsApp_Image_20231215_at_104234_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657be09c3fcadc67776aa10e",
```

```
"name":
"externalImg_1702617244802_WhatsApp_Image_20231215_at_104236_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externalImg_1702617244802_WhatsApp_Image_20231215_at_104236_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657be09c3fcadc67776aa10f",
  "name":
"externalImg_1702617244804_WhatsApp_Image_20231215_at_104247_AM.jpeg",
  "path": "cases/657961be3fcadc6777678d55/
externalImg_1702617244804_WhatsApp_Image_20231215_at_104247_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-13T07:48:14.980Z",
"updatedAt": "2023-12-15T06:30:19.832Z",
"__v": 0,
"invoiceId": "657961bf3fcadc6777678d5e",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Mr. Rakesh Mhade",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Representative ",
"siteVisitContactNo": "9967771932",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
```

"toBeAdded": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1900.00"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			