

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "6403359b80a50a302f6acd52",
    "firstName": "Suraj Barge",
    "lastName": "Barge",
    "mobileNo": "",
    "workMobileNo": "9920273024",
    "email": "suresh.barge@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "Suraj Barge",
    "expectedFees": 10000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiroi Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.022548339336343",
  "longitude": "72.86771982908249"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86771982908249,
```

```
19.022548339336343
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-26",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
```

```
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Main",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dosti Wave",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Antop Hill",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Vidhya Alankar College Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
```



```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Dosti Eastern Bay Phase-2",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2A/116(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "804",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "F/North Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400037",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Wadala (East), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Dosti Blossom",
  "west": "Open Space",
  "south": "Vidhya Alankar College Road",
  "east": "Lloyds Estate A and B wing"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
```

```
    },
    "extraDetailOfProperty": "As per agreement sale plan, the composition of flat is 2
Bedrooms + Living Room + Dining + 2 Toilets.",
    "dateOfIssusApprovePlan": "Copy of approved plan were not provided and not
verified.",
    "approvePlanVerified": "N.A.",
    "empanelledOfApprovePlan": "N.A."
  },
  "compositeRate": {
    "remark": "Internal visit not allowed at site. The details about the work progress
status has been provided by CRM Amita Pawar (Contact No. 7506444511)",
    "depreciationPercentage": "",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "depreciatedCostOfConstruction": "",
    "depreciatedBuildingRate": ""
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "103570",
    "landRate": "47210",
    "igrImage": "cases/658a6401b7b4df714dab4d9f/igr_1703667441590_Image.png",
    "squareMeterGuideLineRate": "108749.00",
    "squareFeetGuideLineRate": "10103.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "5",
    "depreciationPercentage": "0",
    "rate": "103570.00",
    "squareMeterGuideLineRate": "108749.00",
    "squareFeetGuideLineRate": "10103.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "I_Class",
      "label": "I Class"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Building_Under_Construction",
      "label": "Building Under Construction"
    }
  },
  "monthlyRent": "58000",
```

```
"assessmentNo": "Building under construction",
"taxPaidHolderName": "Building under construction",
"taxAmount": "Building under construction",
"electricityServiceConnectionNo": "Building under construction",
"meterCardHolderName": "Building under construction",
"undividedAreaOfLandAsPerSaleDeed": "N.A.",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Alongwith 1 Car Parking on P3 Podium Level",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
```

```
"month": "1",
"year": "2027",
"fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
```

```
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "4",
"noOfPodium": "4",
"noOfAmenityFloors": "",
"noOfFloors": "44",
"flatFloorNo": "8",
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "783.20",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
}
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/658a6401b7b4df714dab4d9f/
routeMap_1703667678366_Image.png",
    "routeLat": "19.022264",
    "routeLng": "72.867819",
    "stationName": "Wadala",
    "routeDistance": "1.6 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "63myc4",
      "name": "63myc4",
      "image": "cases/658a6401b7b4df714dab4d9f/
routeMap_1703667494276_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "23140000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "23140000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Dec 27 2023 14:53:06 GMT+0530 (India Standard Time)",
  "number": "2304217",
  "dayCount": "15",
  "monthCount": "446",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
```

```
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "54",
  "percentage": "40",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "54",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "54",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "54",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "54",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "71.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7912670.00",
  "selectedBuildUpValue": "783.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "658b113cb7b4df714dacb41c",
      "name": "externalimg_1703612684007_1703612779821_image_2.jpeg",
      "path": "cases/658a6401b7b4df714dab4d9f/
externalimg_1703612684007_1703612779821_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "658b113cb7b4df714dacb423",
      "name": "externalimg_1703612687968_1703612779821_image_9.jpeg",
      "path": "cases/658a6401b7b4df714dab4d9f/
externalimg_1703612687968_1703612779821_image_9.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
```

```
    "_id": "658b113cb7b4df714dacb41a",
    "name": "externallmg_1703612683023_1703612779821_image_0.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612683023_1703612779821_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658b113cb7b4df714dacb41b",
    "name": "externallmg_1703612683402_1703612779821_image_1.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612683402_1703612779821_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658b113cb7b4df714dacb41f",
    "name": "externallmg_1703612686187_1703612779821_image_5.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612686187_1703612779821_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658b113cb7b4df714dacb41c",
    "name": "externallmg_1703612684007_1703612779821_image_2.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612684007_1703612779821_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658b113cb7b4df714dacb421",
    "name": "externallmg_1703612687430_1703612779821_image_7.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612687430_1703612779821_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658b113cb7b4df714dacb422",
    "name": "externallmg_1703612687674_1703612779821_image_8.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612687674_1703612779821_image_8.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "658b113cb7b4df714dacb41d",
  "name": "externallmg_1703612684806_1703612779821_image_3.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612684806_1703612779821_image_3.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
  "label": "Lead",
  "value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": false,
finalValuationArea": "712.00",
empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "658a6401b7b4df714dab4d9f",
"ownerName": "Abhishek Ramkrishna & Priyamvada Ramkrishna",
"ownerPhoneNo": "9892522880",
"appAddress": "Flat no. 804, 8th Floor, Dosti Wave, Wing - C, Dosti Eastern bay Phase
2, Antop Hill, Wadala E",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "inputs": {
      "documentDate": "30/03/2022",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Dosti Realty Ltd.",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Abhishek Ramkrishna & Priyamvada Ramkrishna",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "6805/2022"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "162594",
    "path": "cases/658a6401b7b4df714dab4d9f/
document_1703568337338_1703568434271_PROPERTY_PAPERS.pdf",
    "fileName":
"document_1703568337338_1703568434271_PROPERTY_PAPERS.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    }
  }
]
```

```
},
"inputs": {
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51900030769"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1703662252637_P51900030769.pdf",
"path": "cases/658a6401b7b4df714dab4d9f/
document_1703662252637_P51900030769.pdf",
"id": "959677",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Dec 27 2023 13:00:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE/CTY/0953/F/N/337(NEW)/FCC/6/Amend"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1703662280254_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "path": "cases/658a6401b7b4df714dab4d9f/document_1703662280254_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "id": "669693",
  "uploadedBy": "60eeaeddf3dd69653a581316",
```

```
    "createdAt": "Wed Dec 27 2023 13:01:20 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005884",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "861728",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 26 2023 10:56:25 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Abhishek Ramkrishna & Priyamvada Ramkrishna",
    "phone": "9892522880",
    "ownershipShare": "",
    "email": "",
    "id": "291807"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "678098",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "712",
    "squareMeterArea": "66.15",
    "docFinalBuiltUp": "783.2",
    "docFinalBuiltUpSquareMeter": "72.765",
    "docBultupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
```

```
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "658be695c71d833b9178fa2b",
    "property": "Residential Flat",
    "area": "725",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "22800000",
    "expectedRate": "31448.28",
    "builtUpExpectedRate": "28589.34",
    "image": "cases/658a6401b7b4df714dab4d9f/
indicator_1703667229735_Image.png",
    "squareMeter": "67.35",
    "id": "770824"
  },
  {
    "printlnReport": false,
    "_id": "658be695c71d833b9178fa2c",
    "property": "Residential Flat",
    "area": "666",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "23000000",
    "expectedRate": "34534.53",
    "builtUpExpectedRate": "31395.03",
    "image": "cases/658a6401b7b4df714dab4d9f/
indicator_1703667248155_Image.png",
    "squareMeter": "61.87",
    "id": "996060"
  },
  {
    "printlnReport": false,
    "_id": "658be695c71d833b9178fa2d",
    "property": "Residential Flat",
    "area": "712",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"source": "Index_no.2",
"expectedPrice": "22919000",
"expectedRate": "32189.61",
"builtUpExpectedRate": "29263.28",
"image": "cases/658a6401b7b4df714dab4d9f/
indicator_1703667290615_Image.jpeg",
"squareMeter": "66.15",
"id": "828577"
},
{
  "printlnReport": false,
  "_id": "658be695c71d833b9178fa2e",
  "property": "Residential Flat",
  "area": "712",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "21776000",
  "expectedRate": "30584.27",
  "builtUpExpectedRate": "27803.88",
  "image": "cases/658a6401b7b4df714dab4d9f/
indicator_1703667349379_Image.jpeg",
  "squareMeter": "66.15",
  "id": "151776"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41a",
    "name": "externalImg_1703612683023_1703612779821_image_0.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externalImg_1703612683023_1703612779821_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41b",
```

```
    "name": "externallmg_1703612683402_1703612779821_image_1.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612683402_1703612779821_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41c",
    "name": "externallmg_1703612684007_1703612779821_image_2.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612684007_1703612779821_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41d",
    "name": "externallmg_1703612684806_1703612779821_image_3.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612684806_1703612779821_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41e",
    "name": "externallmg_1703612685477_1703612779821_image_4.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612685477_1703612779821_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb41f",
    "name": "externallmg_1703612686187_1703612779821_image_5.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612686187_1703612779821_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb420",
    "name": "externallmg_1703612686850_1703612779821_image_6.jpeg",
```

```
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612686850_1703612779821_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb421",
    "name": "externallmg_1703612687430_1703612779821_image_7.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612687430_1703612779821_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb422",
    "name": "externallmg_1703612687674_1703612779821_image_8.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612687674_1703612779821_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658b113cb7b4df714dacb423",
    "name": "externallmg_1703612687968_1703612779821_image_9.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612687968_1703612779821_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "658b113cb7b4df714dacb424",
    "name": "externallmg_1703612644503_1703612741398_image_0.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612644503_1703612741398_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "658b113cb7b4df714dacb425",
    "name": "externallmg_1703612645060_1703612741398_image_1.jpeg",
    "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612645060_1703612741398_image_1.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658b113cb7b4df714dacb426",
  "name": "externallmg_1703612645625_1703612741398_image_2.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612645625_1703612741398_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658b113cb7b4df714dacb427",
  "name": "externallmg_1703612646052_1703612741398_image_3.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612646052_1703612741398_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658b113cb7b4df714dacb428",
  "name": "externallmg_1703612646489_1703612741398_image_4.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612646489_1703612741398_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658b113cb7b4df714dacb429",
  "name": "externallmg_1703612646716_1703612741398_image_5.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612646716_1703612741398_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658b113cb7b4df714dacb42a",
  "name": "externallmg_1703612647374_1703612741398_image_6.jpeg",
  "path": "cases/658a6401b7b4df714dab4d9f/
externallmg_1703612647374_1703612741398_image_6.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "658b113cb7b4df714dacb42b",
      "name": "externalImg_1703612647830_1703612741398_image_7.jpeg",
      "path": "cases/658a6401b7b4df714dab4d9f/
externalImg_1703612647830_1703612741398_image_7.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "AGR.pdf",
      "filename": "1703593660698_AGR.pdf",
      "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593660698_AGR.pdf",
      "size": "15303016",
      "createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-01.pdf",
      "filename": "1703593661063_IGR01.pdf",
      "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593661063_IGR01.pdf",
      "size": "183294",
      "createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-02.pdf",
      "filename": "1703593661072_IGR02.pdf",
      "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593661072_IGR02.pdf",
      "size": "181915",
      "createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-03.pdf",
      "filename": "1703593661079_IGR03.pdf",
      "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593661079_IGR03.pdf",
      "size": "180580",
```

```
"createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1703593661083_IGR04.pdf",
  "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593661083_IGR04.pdf",
  "size": "161451",
  "createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=ABHISHEK.xlsx",
  "filename": "1703593661088_Summary_NewABHISHEK.xlsx",
  "path": "cases/658a6401b7b4df714dab4d9f/
processingDocuments/1703593661088_Summary_NewABHISHEK.xlsx",
  "size": "2749787",
  "createdAt": "Tue Dec 26 2023 17:57:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-26T05:26:25.578Z",
"updatedAt": "2023-12-27T09:33:07.389Z",
"__v": 0,
"invoiceId": "658a6401b7b4df714dab4da8",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 804, 8th Floor, Wing - C, Dosti Wave, Dosti Eastern
Bay Phase-2, Antop Hill, Vidhya Alankar College Road, Municipality Ward No. F/North
Ward, Wadala (East), Mumbai, District - Mumbai Main, 400037, State - Maharashtra,
India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Amit Pawar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": ""
```

```
"relationWithOwner": "CRM",
"siteVisitContactNo": "7506444511",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 696.00\nUtility Area in Sq. Ft.
= 16.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 712.00",
"buildingServicesRate": "3000",
"flatRate": "32500",
"landOtherRate": "29500",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Wed Dec 27 2023 12:48:11 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-26"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			