

```
{
  "typeOfReport": {
    "value": "Structural_Report",
    "label": "Structural Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64353bf7a99b2228209dbc5f"
    },
    "type": "CREDITOFFICER",
    "_id": "64353bf7a99b2228209dbc61",
    "firstName": "Vaijayanti ",
    "lastName": "Khade",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "vjbhiw@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64353bf7a99b2228209dbc5f",
  "name": "old Jakatnaka Branch\t",
  "branchCode": "",
  "mobileNo": "02522252724\t",
  "alternateMobileNo": "",
  "email": "vjbhiw@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Old Jakatnaka Branch , SHop No 1 & 2, Konark Arcade, Near Bhiwandi
Municipal Corporation, Bhiwandi, 4211302"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  }
]
```

```
],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.230410470659518",
  "longitude": "73.11385003834482"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],

```

```
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamatghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Suryashakti Co.- Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Above Yash Nursing Home, Kaneri",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```

```
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "15/3/1, 16 (P), 43/7 (P) & 152/4/1",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "8643, 8656 (P), 8632 (P) & 8644 (P)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```



```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
```

```
"unitBoundaries": {
  "isDisplay": false
},
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6593b444440d8733f0ab3ddd",
"ownerName": "Smt. Laxmiben Khetaram Patel",
"ownerPhoneNo": "8530382604",
"fullAddress": "Residential Structural Report No. 3, 2nd Floor, Wing - C, Suryashakti
Co.- Op. Hsg. Soc. Ltd., Above Yash Nursing Home, Kaneri, New/Current Survey No.
15/3/1, 16 (P), 43/7 (P) & 152/4/1, CTS No. 8643, 8656 (P), 8632 (P) & 8644 (P),
Village - Kamatghar, Taluka - Bhiwandi, District - Thane, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "22/07/2005",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "Shri. Dahyabhai Mahijibhai Patel, Smt. Madhuben Dahyabhai Patel,
Shri. Jasbhai Prabhubhai Patel & Smt. Shantaben Ranchodbhai Patel",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Smt. Laxmiben Khetaram Patel",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "3089/2005"
```



```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1704178676273_DocScanner_28_Dec_2023_301_pm.pdf",
    "path": "cases/6593b444440d8733f0ab3ddd/
document_1704178676273_DocScanner_28_Dec_2023_301_pm.pdf",
    "id": "441593",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Tue Jan 02 2024 12:29:16 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1704178723901_146135.pdf",
  "path": "cases/6593b444440d8733f0ab3ddd/
document_1704178723901_146135.pdf",
  "id": "592224",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Tue Jan 02 2024 12:29:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "06/07/1998",
    "nameOfApprovingAuthority": {
      "value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
      "label": "Bhiwandi Nizampur City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "TP / 457 "
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1704180144573_146135.pdf",
    "path": "cases/6593b444440d8733f0ab3ddd/
document_1704180144573_146135.pdf",
    "id": "301495",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Tue Jan 02 2024 12:56:24 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "12/08/1999",
      "nameOfApprovingAuthority": {
        "value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
        "label": "Bhiwandi Nizampur City Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "TP / 667 "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1704180187727_145939.pdf",
    "path": "cases/6593b444440d8733f0ab3ddd/
document_1704180187727_145939.pdf",
    "id": "659336",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Tue Jan 02 2024 12:56:24 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "12/09/2018",
      "remark": "issued by Suryashakti Co-Op. Hsg. Soc. Ltd.",
      "to": {
        "value": "purchaser",
```

```
    "label": "purchaser"
  },
  "purchaser": "Smt. Laxmiben Khetaram Patel",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "008"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1704180288634_174758.pdf",
"path": "cases/6593b444440d8733f0ab3ddd/
document_1704180288634_174758.pdf",
"id": "933557",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Jan 02 2024 12:56:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b306",
    "label": "Property Tax"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "BNCMC232443900211 issued by Bhiwandi Nizampur Municipal Council."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1704180334549_212589.pdf",
  "path": "cases/6593b444440d8733f0ab3ddd/
document_1704180334549_212589.pdf",
  "id": "289084",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Jan 02 2024 12:56:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
```

```
"documentDate": "09/11/2023",
"number": {
  "value": "No",
  "label": "No"
},
"No": "13011677783 issued by Torrent Power Limited."
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1704180384793_209977.pdf",
"path": "cases/6593b444440d8733f0ab3ddd/
document_1704180384793_209977.pdf",
"id": "607990",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Jan 02 2024 12:56:24 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006048",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "534125",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 02 2024 12:29:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt. Laxmiben Khetaram Patel",
    "phone": "8530382604",
    "ownershipShare": "",
    "email": "",
    "id": "890685"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
```

```

"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-02T06:59:16.728Z",
"updatedAt": "2024-01-02T07:26:24.893Z",
"__v": 0,
"invoiceId": "6593b444440d8733f0ab3de6",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Smt. Laxmiben Khetaram Patel",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8530382604"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			