PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd PG-4135/23-24 B1-001, U/B FLOOR, 5-Jan-24 BOOMERANG, CHANDIVALI FARM ROAD, Delivery Note Mode/Terms of Payment ANDHERI-EAST 400072 **AGAINST REPORT** GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA - RACPC ANDHERI Dispatch Doc No. Delivery Note Date RACPC - Andheri 006143/2304356 1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Dispatched through Destination Behind Tunga Paradise Hotel, Andheri (East), Mumbai - 400 093 GSTIN/UIN : 27AAACS8577K2ZO Terms of Delivery : Maharashtra, Code: 27 State Name SI **Particulars** HSN/SAC GST Amount Rate No. 1 STRUCTURAL REPORT FEE 997224 18 % 1,500.00 (Technical Inspection and Certification Services) **CGST** 135.00 SGST 135.00 Total 1,770.00 Amount Chargeable (in words) E. & O.E Indian Rupee One Thousand Seven Hundred Seventy Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Amount Rate Amount Tax Amount 997224 1,500.00 9% 135.00 9% 135.00 270.00 Total 1,500.00 135.00 135.00 270.00 Tax Amount (in words): Indian Rupee Two Hundred Seventy Only Company's Bank Details Remarks: Bank Name State Bank of India 006143/2304356 Mr Pradeep Parshuram A/c No. 32632562114 ManeResidential Flat No. 002, Ground Floor, Wing -Branch & IFS Code: MIDC Andheri (E) & SBIN0007074 B, "Kishor Kunj No. 3 Co-op. Hsg. Soc. Ltd.", Behind Viva College, Y. K. Nagar, Village - Bolinj, Virar (West) , Taluka - Vasai, District - Palgahr, PIN Code - 401 303, State - Maharashtra, India. Company's PAN : AADCV4303R Declaration NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137 UPI Virtual ID : vastukala@icici Customer's Seal and Signature for Vastukala Consultants (I) Pvt Ltd

This is a Computer Generated Invoice





ASMITA JAYSING RATHOD

Authorised Signatory

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RACPC Andhen (East) / Mr. Pradeep Parshuram Mane (6143/2304356)

Page 1 of 3

Vastu/Mumbai/01/2024/6143/2304356 05/11-58-NI Date: 05.01.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 002, Ground Floor, Wing - B, "Kishor Kunj No. 3 Co-op. Hsg. Soc. Ltd.", Behind Viva College, Y. K. Nagar, Village - Bolinj, Virar (West), Taluka - Vasai, District - Palgahr, PIN Code - 401 303, State - Maharashtra, India.

Name of Owner: Mr. Pradeep Parshuram Mane.

This is to certify that on visual inspection, it appears that the structure of the at "Kishor Kunj No. 3 Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under normal condition and with proper periodic repairs & maintenance is about 41 years.

General Information:

A.		Introduction
1	Name of Building	Kishor Kunj No. 3 Co-op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 002, Ground Floor, Wing - B, "Kishor Kunj No. 3 Co-op. Hsg. Soc. Ltd.", Behind Viva College, Y. K. Nagar, Village - Bolinj, Virar (West), Taluka - Vasai, District - Palgahr, PIN Code - 401 303, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2004 (Approx)
11	Present age of building	19 years
12	Residual age of the building	41 years Subject to proper, preventive periodic maintenance & structural repairs
13	No. of flats (Per Floor)	Ground Floor is having 3 Flats
14	Methodology adopted	As per visual site inspection







Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24
mumbai@vastukala.org

B.	External O	bservation of the Building	
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	
3	Plumbing	Normal Condition	
4	Cracks on the external walls	Not Found	
5	Filling cracks on the external walls	Found	
6	Cracks on columns & beams	Found	
7	Vegetation	Not Found	
8	Leakages of water in the drainage pipes	Not Found	
	or water pipes		
9	Dampness external in the wall due to	Found	
	leakages		
10	Any other observation about the	The external condition is Normal	
	condition of external side of the building	<u> </u>	
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Good Condition	
2	Columns (Cracks & Leakages)	Good Condition	
3	Ceiling (Cracks & Leakages)	Good Condition	
4	Leakages inside the property	Not Found	
5	Painting inside the property	Good	
6	Maintenance of staircase & cracks	Good	

D	Common Observation		
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws	
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit	
	(Co-Operative Societies Act / Rules)	of the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal	

E Conclusion

The captioned building is having Ground + 4 Upper Floors which are constructed in year 2004 (Approx.). Estimated future life under present circumstances is about 41 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 07.12.2023 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Manoj Chalikwar Digitally signed by Manoj Chalikwar DN: cn=Manoj Chalikwar, o=Vastukal Consultants (I) Pvt. Ltd., ou=Mumbai, email=manoj@vastukala.org, c=IN Date: 2024.01.05 16:14:49 +05'30'

Director

Auth. Sign.

Manoj Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2018/10366

State Bank of India Empanelment No.: SME/TCC/2021-22/86/3





Actual Site Photographs























