

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```
    "designation": "",
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.434170",
  "longitude": "72.811512"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.811512,
    19.43417
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "6/01/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-06",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nilemore",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "1",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Palghar",
    "label": true
  },
  "city": {
    "status": false,
```

```
"name": "City",
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Anant Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Yashwant Gaurav Road",
  "label": false
}
```

```
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Fun Fiesta",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "226/2 part, 266/4, 266/5",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "307",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```



```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 203",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
```

```
"value": "Proposed_Teak_wood_door_frame_with_flush_doors",
"label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
"value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
"label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
"value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Vasai_Virar_City_Municipal_Corporation",
"label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building \"Vimal Residency\"",
"west": "Building \"Vimal Classic\"",
"south": "Internal Road",
"east": "Zero Yashwant Gaurav Road"
},
"asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living Room + Kitchen + Bedroom + 2 Toilets + Passage (i.e. 1 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Plan No. VP-0198 & 4033 / 803 / 2021-22 (No) dated 05.01.2022 issued by Vasai Virar City Municipal Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "8000.00",
  "depreciatedBuildingRate": "2700"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "68700",
  "landRate": "18000",
  "igrImage": "cases/6598f7c38f39506e83453709/igr_1704538209232_Image.png",
  "squareMeterGuideLineRate": "68700.00",
  "squareFeetGuideLineRate": "6382.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "68700.00",
  "squareMeterGuideLineRate": "68700.00",
  "squareFeetGuideLineRate": "6382.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "9,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
```

```
"label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Stilt Car Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Proposed_Standard",
"label": "Proposed Standard"
},
"structuralSafety": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenancelssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
```

```
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "3",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "480.70",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6598f7c38f39506e83453709/
routeMap_1704695879938_Image.png",
    "routeLat": "19.427872",
    "routeLng": "72.810188",
    "stationName": "Nalasopara",
    "routeDistance": "2 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  }
}
```

```
},
"locationMapImg": [
  {
    "id": "ux4py",
    "name": "ux4py",
    "image": "cases/6598f7c38f39506e83453709/
routeMap_1704695768844_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3496000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "3496000.00"
},
"outward": {
  "status": false,
```



```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "1",
    "percentage": "2.5",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "12.50",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3067827.00",
  "selectedBuildUpValue": "480.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659b8ba48f39506e8346b7d4",
      "name":
"externalImg_1704692644086_WhatsApp_Image_20240107_at_124415.jpeg",
```

```
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644086_WhatsApp_Image_20240107_at_124415.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "659b8ba48f39506e8346b7ca",
    "name":
"externallmg_1704692643984_WhatsApp_Image_20240107_at_124420.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643984_WhatsApp_Image_20240107_at_124420.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659b8ba48f39506e8346b7ce",
    "name":
"externallmg_1704692644054_WhatsApp_Image_20240107_at_124425.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644054_WhatsApp_Image_20240107_at_124425.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7739",
    "max": "8939"
  },
  "builtUpRateRange": {
    "min": "7036",
    "max": "8127"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "437.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "6598f7c38f39506e83453709",
"ownerName": "Mr. Narendra Ravindra Bakshi",
"ownerPhoneNo": "8983714754",
"appAddress": "Flat no. 307, 3rd Floor, Wing - D, Building no. 1, Shri Anant Tower,
Village - Nilemore, Vasai",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "22/12/2003",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Shantinath Enterprises",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Narendra Ravindra Bakshi & Mr. Karan Ravindra Bakshi",
      "number": {
        "value": "Registration_No",
```

```
    "label": "Registration No"
  },
  "Registration_No": "19972/2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "323693",
"path": "cases/6598f7c38f39506e83453709/document_1704523682266_170452379
0972_Racpc_GHatkopar_Narendra_Bakshi.pdf",
"fileName": "document_1704523682266_1704523790972_Racpc_GHatkopar_Nare
ndra_Bakshi.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "26/01/2024",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P99000046995"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1704697612862_P99000046995.pdf",
"path": "cases/6598f7c38f39506e83453709/
document_1704697612862_P99000046995.pdf",
"id": "192670",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Jan 08 2024 12:36:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1268aa6d152c1801b383",
    "label": "Revised Development Permission"
  },
  "inputs": {
    "documentDate": "05/01/2022",
    "nameOfApprovingAuthority": {
```



```
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "remark": "NO. VVCMC / TP / RDP / VP-0198 & 4033 / 803 / 20210-22"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1704697874200_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/6598f7c38f39506e83453709/document_1704697874200_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "189062",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Jan 08 2024 12:41:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "05/01/2022",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "remark": "(Downloaded from Rera)",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VP-0198 & 4033 / 803 / 2021-22"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "193759",
  "path": "cases/6598f7c38f39506e83453709/document_1704699065112_1_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "fileName": "document_1704699065112_1_Building_Plan_Approval___NA_Order_for_plotted_development.pdf"
}
],
"caseNumber": "006168",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
```

```
"id": "325515",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Sat Jan 06 2024 12:18:35 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Narendra Ravindra Bakshi",
"phone": "8983714754",
"ownershipShare": "",
"email": "",
"id": "365899"
},
{
"name": "Mr. Karan Ravindra Bakshi",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "191894"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "550910",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "437",
"squareMeterArea": "40.6",
"docFinalBuiltUp": "480.7",
"docFinalBuiltUpSquareMeter": "44.660000000000004",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
```

```
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "659930e88f39506e8345ef0b",
    "property": "Shree Anant Tower, Nallasopara West",
    "area": "440",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "3500000",
    "expectedRate": "7954.55",
    "builtUpExpectedRate": "7231.40",
    "image": "cases/6598f7c38f39506e83453709/
indicator_1704538086028_Image.png",
    "squareMeter": "40.88",
    "id": "298415"
  },
  {
    "printlnReport": true,
    "_id": "659930e88f39506e8345ef0c",
    "property": "Shree Anant Tower, Nallasopara West",
    "area": "575",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "8",
    "source": "magic_bricks",
    "expectedPrice": "4450000",
    "expectedRate": "7739.13",
    "builtUpExpectedRate": "7035.57",
    "image": "cases/6598f7c38f39506e83453709/
indicator_1704538125090_Image.png",
    "squareMeter": "53.42",
    "id": "144979"
  },
  {
    "printlnReport": true,
    "_id": "659930e88f39506e8345ef0d",
```

```
"property": "Shree Anant Tower, Nallasopara West",
"area": "437",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "7",
"source": "Index_no.2",
"expectedPrice": "3450000",
"expectedRate": "7894.74",
"builtUpExpectedRate": "7177.03",
"image": "cases/6598f7c38f39506e83453709/
indicator_1704538177816_Image.png",
"squareMeter": "40.60",
"id": "548324"
},
{
  "printlnReport": true,
  "_id": "659930e88f39506e8345ef0e",
  "property": "Shree Anant Tower, Nallasopara West",
  "area": "522",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "4666000",
  "expectedRate": "8938.70",
  "builtUpExpectedRate": "8126.09",
  "image": "cases/6598f7c38f39506e83453709/
indicator_1704538331988_Image.png",
  "squareMeter": "48.50",
  "id": "767992"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7c7",
    "name":
"externallmg_1704692643303_WhatsApp_Image_20240107_at_124419_1.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643303_WhatsApp_Image_20240107_at_124419_1.jpeg",
    "orientation": "landscape"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659b8ba48f39506e8346b7c8",
      "name":
"externallmg_1704692643937_WhatsApp_Image_20240107_at_124419.jpeg",
      "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643937_WhatsApp_Image_20240107_at_124419.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659b8ba48f39506e8346b7c9",
      "name":
"externallmg_1704692643962_WhatsApp_Image_20240107_at_124420_1.jpeg",
      "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643962_WhatsApp_Image_20240107_at_124420_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659b8ba48f39506e8346b7ca",
      "name":
"externallmg_1704692643984_WhatsApp_Image_20240107_at_124420.jpeg",
      "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643984_WhatsApp_Image_20240107_at_124420.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659b8ba48f39506e8346b7cb",
      "name":
"externallmg_1704692643993_WhatsApp_Image_20240107_at_124424_1.jpeg",
      "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692643993_WhatsApp_Image_20240107_at_124424_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659b8ba48f39506e8346b7cc",
      "name":
"externallmg_1704692644043_WhatsApp_Image_20240107_at_124424.jpeg",
```

```
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644043_WhatsApp_Image_20240107_at_124424.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7cd",
    "name":
"externallmg_1704692644049_WhatsApp_Image_20240107_at_124425_1.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644049_WhatsApp_Image_20240107_at_124425_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7ce",
    "name":
"externallmg_1704692644054_WhatsApp_Image_20240107_at_124425.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644054_WhatsApp_Image_20240107_at_124425.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7cf",
    "name":
"externallmg_1704692644057_WhatsApp_Image_20240107_at_124555.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644057_WhatsApp_Image_20240107_at_124555.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7d0",
    "name":
"externallmg_1704692644061_WhatsApp_Image_20240107_at_124412.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644061_WhatsApp_Image_20240107_at_124412.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659b8ba48f39506e8346b7d1",
    "name":
"externallmg_1704692644068_WhatsApp_Image_20240107_at_124413.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644068_WhatsApp_Image_20240107_at_124413.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7d2",
    "name":
"externallmg_1704692644071_WhatsApp_Image_20240107_at_124415_1.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644071_WhatsApp_Image_20240107_at_124415_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7d3",
    "name":
"externallmg_1704692644076_WhatsApp_Image_20240107_at_124415_2.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644076_WhatsApp_Image_20240107_at_124415_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7d4",
    "name":
"externallmg_1704692644086_WhatsApp_Image_20240107_at_124415.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644086_WhatsApp_Image_20240107_at_124415.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b8ba48f39506e8346b7d5",
    "name":
"externallmg_1704692644090_WhatsApp_Image_20240107_at_124417.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644090_WhatsApp_Image_20240107_at_124417.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b8ba48f39506e8346b7d6",
  "name":
  "externallmg_1704692644096_WhatsApp_Image_20240107_at_124418_1.jpeg",
  "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644096_WhatsApp_Image_20240107_at_124418_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b8ba48f39506e8346b7d7",
  "name":
  "externallmg_1704692644101_WhatsApp_Image_20240107_at_124418_2.jpeg",
  "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644101_WhatsApp_Image_20240107_at_124418_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b8ba48f39506e8346b7d8",
  "name":
  "externallmg_1704692644105_WhatsApp_Image_20240107_at_124418.jpeg",
  "path": "cases/6598f7c38f39506e83453709/
externallmg_1704692644105_WhatsApp_Image_20240107_at_124418.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1703490159519_1701953547274_1698233439717_16977182111
73_1696854326515_Calculation_1.xlsx",
    "filename": "1704538357050_1703490159519_1701953547274_1698233439717_1
697718211173_1696854326515_Calculation_1.xlsx",
    "path": "cases/6598f7c38f39506e83453709/processingDocuments/1704538357050
_1703490159519_1701953547274_1698233439717_1697718211173_1696854326515
_Calculation_1.xlsx",
    "size": "1069402",
    "createdAt": "Sat Jan 06 2024 16:22:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
```



```
},
{
  "originalname": "1 Building Plan Approval _ NA Order for plotted development.pdf",
  "filename": "1704699266860_1_Building_Plan_Approval__NA_Order_for_plotted_
development.pdf",
  "path": "cases/6598f7c38f39506e83453709/processingDocuments/1704699266860
_1_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "size": "337743",
  "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "1 Commencement Certificates _ NA Order for plotted
development.pdf",
  "filename": "1704699266869_1_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
  "path": "cases/6598f7c38f39506e83453709/processingDocuments/1704699266869
_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
  "size": "538979",
  "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "document_1704523682266_1704523790972_Racpc_GHatkopar_N
arendra_Bakshi.pdf",
  "filename": "1704699266878_document_1704523682266_1704523790972_Racpc_
GHatkopar_Narendra_Bakshi.pdf",
  "path": "cases/6598f7c38f39506e83453709/processingDocuments/1704699266878
_document_1704523682266_1704523790972_Racpc_GHatkopar_Narendra_Bakshi.pdf",
  "size": "10042565",
  "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname":
"externallmg_1704692644049_WhatsApp_Image_20240107_at_124425_1.jpeg",
  "filename": "1704699267012_externallmg_1704692644049_WhatsApp_Image_202
40107_at_124425_1.jpeg",
  "path": "cases/6598f7c38f39506e83453709/processingDocuments/1704699267012
_externallmg_1704692644049_WhatsApp_Image_20240107_at_124425_1.jpeg",
  "size": "165156",
  "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
```

```
    "originalname": "Google Location.jpeg",
    "filename": "1704699267016_Google_Location.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
processingDocuments/1704699267016_Google_Location.jpeg",
    "size": "135600",
    "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1704699267020_Site_Details.jpeg",
    "path": "cases/6598f7c38f39506e83453709/
processingDocuments/1704699267020_Site_Details.jpeg",
    "size": "207932",
    "createdAt": "Mon Jan 08 2024 13:04:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "659931048f39506e8345ef39",
    "note": "Rate Verification Done, Visit pending",
    "taskId": "6598fd5f8f39506e83454f9c",
    "createdAt": "2024-01-06T10:52:52.526Z"
  }
],
"createdAt": "2024-01-06T06:48:35.925Z",
"updatedAt": "2024-01-08T07:47:02.595Z",
"__v": 0,
"invoiceId": "6598f7c48f39506e8345370f",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
}
```

```
},
"fullAddress": "Residential Flat No. 307, 3rd Floor, Building No 1, Wing - D, Shree
Anant Tower, Yashwant Gaurav Road, Near Fun Fiesta, Village - Nilemore, Nalasopara
(West), Taluka - Vasai, District - Palghar, PIN - 401 203, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Santosh Gupta",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"siteVisitContactNo": "9309908035",
"buildingServicesRate": "2700.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 437.00",
"flatRate": "8000",
"landOtherRate": "5300",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
```

```
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Mon Jan 08 2024 12:44:02 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-06"
}
```

Name	Length	Width	Total
Composition :			
Other Composition :			