

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3446562",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 1723.281,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6401b61f0e28255fb44e636a",
"role": "SITEENGINEER",
"firstName": "Sanket",
"email": "ksanket7414@yahoo.com",
"lastName": "Karalkar",
"mobileNo": "8080582858",
"designation": "",
"shortName": "SAK",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.405422",
  "longitude": "72.831064"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.831064,
    19.405422
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "9/01/2024 09:30 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "478.80",
  "rate": "7195.00",
  "yearOfConstruction": "2008",
  "compositionOfBuilding": "Ground + 4 upper floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Achole",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Saikrupa Complex Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vasant Nagari",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "2(2), H. No. 4 & 5, S. No. 3(3), H. No. 7, 10, 11, 12, 14 & 15, S. No. 4(4), H.
No. 10 & 12",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai (East)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```



```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "659cc47c8f39506e834881b9",
"ownerName": "Mahindra Purohit ",
"ownerPhoneNo": "9082469158",
"appAddress": "Flat no 204 2 nd floor Wing -B Saikurpa Co-op HSG Soc Ltd Village
Achole Vasai East -401208",
"remark": "Structural report required Today ",
"documents": [
  {
    "documentType": {
      "label": "Valuation Report",
      "value": "60ae1255aa6d152c1801b32b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/659cc47c8f39506e834881b9/
document_1704772700975_1704772811943_20240109_0919.pdf",
    "fileName": "document_1704772700975_1704772811943_20240109_0919.pdf",
    "id": "748089",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jan 09 2024 09:28:52 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"caseNumber": "006211",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "324567",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 09 2024 09:28:52 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mahindra Purohit ",
    "phone": "9082469158",
    "ownershipShare": "",
    "email": "",
    "id": "405280"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d414",
    "name": "externalImg_1704778481108_externallmg_1701401278103_WhatsApp_I
mage_20231130_at_210439_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalmg_1704778481108_externall
mg_1701401278103_WhatsApp_Image_20231130_at_210439_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d415",
    "name": "externalImg_1704778481110_externallmg_1701401278107_WhatsApp_I
mage_20231130_at_210439_2.jpeg",
```

```
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481110_externallmg_1701401278107_WhatsApp_Image_20231130_at_210439_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d416",
    "name": "externallmg_1704778481113_externallmg_1701401278112_WhatsApp_Image_20231130_at_210439_3.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481113_externallmg_1701401278112_WhatsApp_Image_20231130_at_210439_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d417",
    "name": "externallmg_1704778481116_externallmg_1701401278115_WhatsApp_Image_20231130_at_210440_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481116_externallmg_1701401278115_WhatsApp_Image_20231130_at_210440_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d418",
    "name": "externallmg_1704778481118_externallmg_1701401278117_WhatsApp_Image_20231130_at_210440.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481118_externallmg_1701401278117_WhatsApp_Image_20231130_at_210440.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaf18f39506e8348d419",
    "name": "externallmg_1704778481120_externallmg_1701401278119_WhatsApp_Image_20231130_at_210441_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481120_externallmg_1701401278119_WhatsApp_Image_20231130_at_210441_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659cdaf18f39506e8348d41a",
    "name": "externallmg_1704778481121_externallmg_1701401278120_WhatsApp_I
mage_20231130_at_210441_2.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778481121_externall
mg_1701401278120_WhatsApp_Image_20231130_at_210441_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaff8f39506e8348d4ac",
    "name": "externallmg_1704778495459_externallmg_1701401278123_WhatsApp_I
mage_20231130_at_210441.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495459_externall
mg_1701401278123_WhatsApp_Image_20231130_at_210441.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaff8f39506e8348d4ad",
    "name": "externallmg_1704778495460_externallmg_1701401278125_WhatsApp_I
mage_20231130_at_210442_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495460_externall
mg_1701401278125_WhatsApp_Image_20231130_at_210442_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaff8f39506e8348d4ae",
    "name": "externallmg_1704778495462_externallmg_1701401278126_WhatsApp_I
mage_20231130_at_210442_2.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495462_externall
mg_1701401278126_WhatsApp_Image_20231130_at_210442_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdaff8f39506e8348d4af",
    "name": "externallmg_1704778495465_externallmg_1701401278128_WhatsApp_I
mage_20231130_at_210442.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495465_externall
mg_1701401278128_WhatsApp_Image_20231130_at_210442.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdaff8f39506e8348d4b0",
  "name": "externallmg_1704778495466_externallmg_1701401278129_WhatsApp_I
mage_20231130_at_210443_1.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495466_externall
mg_1701401278129_WhatsApp_Image_20231130_at_210443_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdaff8f39506e8348d4b1",
  "name": "externallmg_1704778495467_externallmg_1701401291675_WhatsApp_I
mage_20231130_at_210443_1.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495467_externall
mg_1701401291675_WhatsApp_Image_20231130_at_210443_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdaff8f39506e8348d4b2",
  "name": "externallmg_1704778495470_externallmg_1701401291677_WhatsApp_I
mage_20231130_at_210443_2.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778495470_externall
mg_1701401291677_WhatsApp_Image_20231130_at_210443_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb108f39506e8348d587",
  "name": "externallmg_1704778510439_externallmg_1701401291681_WhatsApp_I
mage_20231130_at_210443_3.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778510439_externall
mg_1701401291681_WhatsApp_Image_20231130_at_210443_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb108f39506e8348d588",
```

```
    "name": "externalimg_1704778510440_externalimg_1701401291684_WhatsApp_I
mage_20231130_at_210443.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalimg_1704778510440_external
mg_1701401291684_WhatsApp_Image_20231130_at_210443.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb108f39506e8348d589",
    "name": "externalimg_1704778510441_externalimg_1701401291686_WhatsApp_I
mage_20231130_at_210444_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalimg_1704778510441_external
mg_1701401291686_WhatsApp_Image_20231130_at_210444_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb108f39506e8348d58a",
    "name": "externalimg_1704778510443_externalimg_1701401291690_WhatsApp_I
mage_20231130_at_210444_2.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalimg_1704778510443_external
mg_1701401291690_WhatsApp_Image_20231130_at_210444_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb108f39506e8348d58b",
    "name": "externalimg_1704778510446_externalimg_1701401291692_WhatsApp_I
mage_20231130_at_210444.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalimg_1704778510446_external
mg_1701401291692_WhatsApp_Image_20231130_at_210444.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb108f39506e8348d58c",
    "name": "externalimg_1704778510447_externalimg_1701401291695_WhatsApp_I
mage_20231130_at_210445_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externalimg_1704778510447_external
mg_1701401291695_WhatsApp_Image_20231130_at_210445_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb108f39506e8348d58d",
  "name": "externallmg_1704778511997_externallmg_1701401291698_WhatsApp_I
mage_20231130_at_210445_2.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778511997_externall
mg_1701401291698_WhatsApp_Image_20231130_at_210445_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb1b8f39506e8348d614",
  "name": "externallmg_1704778523368_externallmg_1701401291703_WhatsApp_I
mage_20231130_at_210445.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523368_externall
mg_1701401291703_WhatsApp_Image_20231130_at_210445.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb1b8f39506e8348d615",
  "name": "externallmg_1704778523374_externallmg_1701401291718_WhatsApp_I
mage_20231130_at_210436.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523374_externall
mg_1701401291718_WhatsApp_Image_20231130_at_210436.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb1b8f39506e8348d616",
  "name": "externallmg_1704778523377_externallmg_1701401291721_WhatsApp_I
mage_20231130_at_210437_1.jpeg",
  "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523377_externall
mg_1701401291721_WhatsApp_Image_20231130_at_210437_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659cdb1b8f39506e8348d617",
  "name": "externallmg_1704778523380_externallmg_1701401291724_WhatsApp_I
mage_20231130_at_210437_2.jpeg",
```

```
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523380_externallmg_1701401291724_WhatsApp_Image_20231130_at_210437_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb1b8f39506e8348d618",
    "name": "externallmg_1704778523384_externallmg_1701401291727_WhatsApp_Image_20231130_at_210437.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523384_externallmg_1701401291727_WhatsApp_Image_20231130_at_210437.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb1b8f39506e8348d619",
    "name": "externallmg_1704778523387_externallmg_1701401291730_WhatsApp_Image_20231130_at_210438_1.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523387_externallmg_1701401291730_WhatsApp_Image_20231130_at_210438_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb1b8f39506e8348d61a",
    "name": "externallmg_1704778523391_externallmg_1701401291734_WhatsApp_Image_20231130_at_210438.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523391_externallmg_1701401291734_WhatsApp_Image_20231130_at_210438.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659cdb1b8f39506e8348d61b",
    "name": "externallmg_1704778523395_externallmg_1701401291738_WhatsApp_Image_20231130_at_210439.jpeg",
    "path": "cases/659cc47c8f39506e834881b9/externallmg_1704778523395_externallmg_1701401291738_WhatsApp_Image_20231130_at_210439.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
```



```
{
  "originalname": "Structural Stability Report - Mr. Mahendra Purohit.docx",
  "filename":
"1704778413956_Structural_Stability_Report__Mr_Mahendra_Purohit.docx",
  "path": "cases/659cc47c8f39506e834881b9/externalDocuments/1704778413956_St
ructural_Stability_Report__Mr_Mahendra_Purohit.docx",
  "size": "587541",
  "documentType": {
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Tue Jan 09 2024 11:03:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"processingDocuments": [
  {
    "originalname": "1701510335381_Valuation_Report_Mahendra_Purohit.pdf",
    "filename":
"1704778461773_1701510335381_Valuation_Report_Mahendra_Purohit.pdf",
    "path": "cases/659cc47c8f39506e834881b9/processingDocuments/1704778461773
_1701510335381_Valuation_Report_Mahendra_Purohit.pdf",
    "size": "1020135",
    "createdAt": "Tue Jan 09 2024 11:04:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-09T03:58:52.882Z",
"updatedAt": "2024-01-09T05:35:23.469Z",
"__v": 0,
"invoiceId": "659cc47c8f39506e834881c2",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": " Structural Report No. 204, 2nd Floor, Wing - B, Saikrupa Complex Co-
op. Hsg. Soc. Ltd., New/Current Survey No. 2(2), H. No. 4 & 5, S. No. 3(3), H. No. 7, 10,
11, 12, 14 & 15, S. No. 4(4), H. No. 10 & 12, Vasant Nagari, Village - Achole, Vasai
(East), Taluka - Vasai, District - Palghar, PIN - 401 208",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mahindra Purohit ",
```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9082469158"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
