

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64f2efcceb1f822256e0cc7b"
    },
    "type": "CREDITOFFICER",
    "_id": "64f2efcceb1f822256e0cc7d",
    "firstName": "Chandan",
    "lastName": "Kishore",
    "mobileNo": "",
    "workMobileNo": "7030544490",
    "email": "brmgr353@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64f2efcceb1f822256e0cc7b",
  "name": "Vashi Turbhe Branch",
  "branchCode": "",
  "mobileNo": "9699789032",
  "alternateMobileNo": "",
  "email": "brmgr353@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "P-17, Sector 1, Cldco Old Admin Building, Vashi, Navi Mumbai, 400703"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
```

```
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.035833",
  "longitude": "72.876333"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.876333,
    19.035833
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
```

```
"area": "355.00",
"rate": "14717.00",
"yearOfConstruction": "2017",
"compositionOfBuilding": "Ground + 4 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Wadala Salt Plan",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Bombay Suburban",
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Wadala ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "B-5",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mumbai Pune Motar Malak Shramjeevan Premises Co.- Op. Hsg. Soc.
Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "W.T.T. Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Wadala Truck Terminal, Wadala Salt Plan, Near RTO, Antop Hill",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```

```
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "8",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit No. 227",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```



```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```

```
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "850.4999999999999",
  "depreciatedCostOfConstruction": "17649.50",
  "depreciatedBuildingRate": "1849.5"
},
"igrRate": {
  "propertyName": "Commercial",
  "rate": "236690",
  "landRate": "88690",
  "igrImage": "cases/659ce15a8f39506e8348ed7c/igr_1706707539068_Image.png",
  "squareMeterGuideLineRate": "0.00",
  "squareFeetGuideLineRate": "0.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "79",
  "rate": "1730.00",
  "squareFeetGuideLineRate": "1730.00",
  "squareMeterGuideLineRate": "18625.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2003",
"fullDate": "1/1/2003"
},
"planningArea": {
"value": "Commercial",
"label": "Commercial"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "Approx.",
"label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
```

```
"noOfFloors": "4",
"flatFloorNo": "2",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "36"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "614496.00",
  "selectedBuildUpValue": "355.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17000",
    "max": "167230"
  },
  "builtUpRateRange": {
    "min": "14167",
    "max": "139359"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
```

```
"finalValuationArea": "296.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "659ce15a8f39506e8348ed7c",
"ownerName": "M/s. BMSS Steel Industries Pvt. Ltd.",
"ownerPhoneNo": "0000000000",
"fullAddress": "Commercial Unit No. Unit No. 227, 2nd Floor, Mumbai Pune Motar
Malak Shramjeevan Premises Co.- Op. Hsg. Soc. Ltd., Wadala Truck Terminal, Wadala
Salt Plan, Near RTO, Antop Hill, Plot No. B-5, CTS No. 8, W.T.T. Road, Village - Wadala
Salt Plan, District - Bombay Suburban, Wadala , State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/07/2022",
      "from": {
        "value": "The_Assignor",
        "label": "The Assignor"
      },
      "The_Assignor": "MRS. USHA BABAN DONGARE & MUMBAI PUNE MOTAR
MALAK SHRAMJEEVAN PREMISES CO.- OP. HSG. SOC. LTD.,",
      "to": {
        "value": "The_Assignee",
        "label": "The Assignee"
      },
      "The_Assignee": "M/S. BMSS STEEL INDUSTRIES PVT. LTD",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "8658/2022"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1704779984865_Office_227.pdf",
    "path": "cases/659ce15a8f39506e8348ed7c/
document_1704779984865_Office_227.pdf",
    "id": "411895",
```

```
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Tue Jan 09 2024 11:32:01 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706767286562_482873.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
document_1706767286562_482873.pdf",
  "id": "758858",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Feb 01 2024 11:34:23 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706767308397_723712.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
document_1706767308397_723712.pdf",
  "id": "748502",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Feb 01 2024 11:34:23 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706767463082_98020.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
document_1706767463082_98020.pdf",
  "id": "604815",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Feb 01 2024 11:34:23 GMT+0530 (India Standard Time)"
}
],
```

```
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "006217",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "889539",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 09 2024 11:32:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. BMSS Steel Industries Pvt. Ltd.",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "187878"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "552383",
    "name": "Working Area",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "120.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "120.00"
  }
],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "27.50",
    "totalAreaDocument": "296",
    "docBultupPercentage": "20",
    "docFinalBultUp": "355.20",
    "docFinalBultUpSquareMeter": "33.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "266058"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65ba4a626635d840ef57999b",
    "property": "Commercial ",
    "area": "296",
    "bultUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "5300000",
    "expectedRate": "17905.41",
    "bultUpExpectedRate": "14921.17",
    "image": "cases/659ce15a8f39506e8348ed7c/
indicator_1706707353274_Image.jpeg",
    "squareMeter": "27.50",
    "id": "939832"
  },
  {
    "printlnReport": true,
    "_id": "65ba4a626635d840ef57999c",
```

```
"property": "Commercial",
"area": "296",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"source": "Index_no.2",
"expectedPrice": "49500000",
"expectedRate": "167229.73",
"builtUpExpectedRate": "139358.11",
"image": "cases/659ce15a8f39506e8348ed7c/
indicator_1706707375293_Image.jpeg",
"squareMeter": "27.50",
"id": "817865"
```

```
},
```

```
{
```

```
"printlnReport": true,
"_id": "65ba4a626635d840ef57999d",
"property": "Price Indicators",
"area": "300",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "5000000",
"expectedRate": "16666.67",
"builtUpExpectedRate": "5000000",
"image": "cases/659ce15a8f39506e8348ed7c/
indicator_1706707408139_Image.png",
"squareMeter": "27.87",
"id": "246293"
```

```
},
```

```
{
```

```
"printlnReport": true,
"_id": "65ba4a626635d840ef57999e",
"property": "Commercial",
"area": "370",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Housing.Com",
"expectedPrice": "7000000",
"expectedRate": "18918.92",
"builtUpExpectedRate": "15765.77",
```

```
    "image": "cases/659ce15a8f39506e8348ed7c/
indicator_1706707430762_Image.png",
    "squareMeter": "34.37",
    "id": "407135"
  },
  {
    "printlnReport": true,
    "_id": "65ba4a626635d840ef57999f",
    "property": "Commercial Office",
    "area": "600",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "8500000",
    "expectedRate": "14166.67",
    "builtUpExpectedRate": "8500000",
    "image": "cases/659ce15a8f39506e8348ed7c/
indicator_1706707452959_Image.png",
    "squareMeter": "55.74",
    "id": "368055"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada876",
    "name":
"externallmg_1704863187407_WhatsApp_Image_20240109_at_115855.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187407_WhatsApp_Image_20240109_at_115855.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada877",
    "name":
"externallmg_1704863187413_WhatsApp_Image_20240109_at_115856_1.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187413_WhatsApp_Image_20240109_at_115856_1.jpeg",
    "orientation": "portrait"
  },
  {

```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada878",
    "name":
"externallmg_1704863187416_WhatsApp_Image_20240109_at_115856_2.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187416_WhatsApp_Image_20240109_at_115856_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada879",
    "name":
"externallmg_1704863187420_WhatsApp_Image_20240109_at_115856.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187420_WhatsApp_Image_20240109_at_115856.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada87a",
    "name":
"externallmg_1704863187424_WhatsApp_Image_20240109_at_115857_1.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187424_WhatsApp_Image_20240109_at_115857_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada87b",
    "name":
"externallmg_1704863187425_WhatsApp_Image_20240109_at_115857.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187425_WhatsApp_Image_20240109_at_115857.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25d302c44c777bada87c",
    "name":
"externallmg_1704863187428_WhatsApp_Image_20240109_at_115844_1.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187428_WhatsApp_Image_20240109_at_115844_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25d302c44c777bada87d",
  "name":
  "externallmg_1704863187430_WhatsApp_Image_20240109_at_115844.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187430_WhatsApp_Image_20240109_at_115844.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25d302c44c777bada87e",
  "name":
  "externallmg_1704863187431_WhatsApp_Image_20240109_at_115845_1.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187431_WhatsApp_Image_20240109_at_115845_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25d302c44c777bada87f",
  "name":
  "externallmg_1704863187434_WhatsApp_Image_20240109_at_115845.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863187434_WhatsApp_Image_20240109_at_115845.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c1",
  "name":
  "externallmg_1704863200487_WhatsApp_Image_20240109_at_115846.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200487_WhatsApp_Image_20240109_at_115846.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c2",
```

```
    "name":
"externallmg_1704863200490_WhatsApp_Image_20240109_at_115847_1.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200490_WhatsApp_Image_20240109_at_115847_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c3",
  "name":
"externallmg_1704863200493_WhatsApp_Image_20240109_at_115847.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200493_WhatsApp_Image_20240109_at_115847.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c4",
  "name":
"externallmg_1704863200495_WhatsApp_Image_20240109_at_115848_1.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200495_WhatsApp_Image_20240109_at_115848_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c5",
  "name":
"externallmg_1704863200498_WhatsApp_Image_20240109_at_115848.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200498_WhatsApp_Image_20240109_at_115848.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c6",
  "name":
"externallmg_1704863200501_WhatsApp_Image_20240109_at_115849.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200501_WhatsApp_Image_20240109_at_115849.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c7",
  "name":
"externallmg_1704863200504_WhatsApp_Image_20240109_at_115850.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200504_WhatsApp_Image_20240109_at_115850.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c8",
  "name":
"externallmg_1704863200508_WhatsApp_Image_20240109_at_115852_1.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200508_WhatsApp_Image_20240109_at_115852_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8c9",
  "name":
"externallmg_1704863200511_WhatsApp_Image_20240109_at_115852_2.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200511_WhatsApp_Image_20240109_at_115852_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8ca",
  "name":
"externallmg_1704863200515_WhatsApp_Image_20240109_at_115852_3.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200515_WhatsApp_Image_20240109_at_115852_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e25e002c44c777bada8cb",
  "name":
"externallmg_1704863200518_WhatsApp_Image_20240109_at_115852.jpeg",
```

```
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200518_WhatsApp_Image_20240109_at_115852.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25e002c44c777bada8cc",
    "name":
"externallmg_1704863200521_WhatsApp_Image_20240109_at_115853_1.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200521_WhatsApp_Image_20240109_at_115853_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25e002c44c777bada8cd",
    "name":
"externallmg_1704863200524_WhatsApp_Image_20240109_at_115853_2.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200524_WhatsApp_Image_20240109_at_115853_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25e002c44c777bada8ce",
    "name":
"externallmg_1704863200526_WhatsApp_Image_20240109_at_115853_3.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200526_WhatsApp_Image_20240109_at_115853_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e25e002c44c777bada8cf",
    "name":
"externallmg_1704863200529_WhatsApp_Image_20240109_at_115853.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/
externallmg_1704863200529_WhatsApp_Image_20240109_at_115853.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
```

```
{
  "originalname": "BMSS Steel Industries.doc",
  "filename": "1706767138881_BMSS_Steel_Industries.doc",
  "path": "cases/659ce15a8f39506e8348ed7c/
externalDocuments/1706767138881_BMSS_Steel_Industries.doc",
  "size": "4924416",
  "documentType": {
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Thu Feb 01 2024 11:29:00 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
],
"processingDocuments": [
  {
    "originalname":
"externallmg_1704863187428_WhatsApp_Image_20240109_at_115844_1.jpeg",
    "filename": "1706707570690_externallmg_1704863187428_WhatsApp_Image_202
40109_at_115844_1.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706707570690
_externallmg_1704863187428_WhatsApp_Image_20240109_at_115844_1.jpeg",
    "size": "84378",
    "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1704863187430_WhatsApp_Image_20240109_at_115844.jpeg",
    "filename": "1706707570695_externallmg_1704863187430_WhatsApp_Image_202
40109_at_115844.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706707570695
_externallmg_1704863187430_WhatsApp_Image_20240109_at_115844.jpeg",
    "size": "41219",
    "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1704863187434_WhatsApp_Image_20240109_at_115845.jpeg",
    "filename": "1706707570698_externallmg_1704863187434_WhatsApp_Image_202
40109_at_115845.jpeg",
    "path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706707570698
_externallmg_1704863187434_WhatsApp_Image_20240109_at_115845.jpeg",
    "size": "102235",
    "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1706707570702_IGR01.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570702_IGR01.pdf",
  "size": "154144",
  "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1706707570710_IGR02.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570710_IGR02.pdf",
  "size": "146495",
  "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1706707570716_IGR03.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570716_IGR03.pdf",
  "size": "164204",
  "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1706707570723_IGR04.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570723_IGR04.pdf",
  "size": "158555",
  "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-05.pdf",
  "filename": "1706707570727_IGR05.pdf",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570727_IGR05.pdf",
  "size": "154934",
  "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
    },
    {
      "originalname": "OFFICE NO. 227.pdf",
      "filename": "1706707570730_OFFICE_NO_227.pdf",
      "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570730_OFFICE_NO_227.pdf",
      "size": "8016179",
      "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "OFFICE NO. 228.pdf",
      "filename": "1706707570877_OFFICE_NO_228.pdf",
      "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707570877_OFFICE_NO_228.pdf",
      "size": "7491968",
      "createdAt": "Wed Jan 31 2024 18:56:11 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Summary New=BMSS.xlsx",
      "filename": "1706707575901_Summary_NewBMSS.xlsx",
      "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706707575901_Summary_NewBMSS.xlsx",
      "size": "2597730",
      "createdAt": "Wed Jan 31 2024 18:56:15 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "CC_Page_1.jpg",
      "filename": "1706767121010_CC_Page_1.jpg",
      "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767121010_CC_Page_1.jpg",
      "size": "723712",
      "createdAt": "Thu Feb 01 2024 11:28:41 GMT+0530 (India Standard Time)",
      "uploadedBy": "627222afafd7d55eddeddd82"
    },
    {
      "originalname": "CC_Page_2.jpg",
      "filename": "1706767121167_CC_Page_2.jpg",
      "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767121167_CC_Page_2.jpg",
      "size": "456239",
      "createdAt": "Thu Feb 01 2024 11:28:41 GMT+0530 (India Standard Time)",
      "uploadedBy": "627222afafd7d55eddeddd82"
    },
  },
```



```
{
  "originalname": "CC_Page_4.jpg",
  "filename": "1706767121259_CC_Page_4.jpg",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767121259_CC_Page_4.jpg",
  "size": "367643",
  "createdAt": "Thu Feb 01 2024 11:28:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "OC_Page_1.jpg",
  "filename": "1706767121375_OC_Page_1.jpg",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767121375_OC_Page_1.jpg",
  "size": "482873",
  "createdAt": "Thu Feb 01 2024 11:28:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "OC_Page_2.jpg",
  "filename": "1706767121642_OC_Page_2.jpg",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767121642_OC_Page_2.jpg",
  "size": "432478",
  "createdAt": "Thu Feb 01 2024 11:28:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "allotment.jpeg",
  "filename": "1706767443710_allotment.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/
processingDocuments/1706767443710_allotment.jpeg",
  "size": "98020",
  "createdAt": "Thu Feb 01 2024 11:34:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "WhatsApp Image 2024-01-30 at 11.58.33 AM.jpeg",
  "filename": "1706767443736_WhatsApp_Image_20240130_at_115833_AM.jpeg",
  "path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706767443736
_WhatsApp_Image_20240130_at_115833_AM.jpeg",
  "size": "108930",
  "createdAt": "Thu Feb 01 2024 11:34:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
```

```
"originalname": "WhatsApp Image 2024-01-30 at 11.58.34 AM (1).jpeg",
"filename":
"1706767443775_WhatsApp_Image_20240130_at_115834_AM_1.jpeg",
"path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706767443775
_WhatsApp_Image_20240130_at_115834_AM_1.jpeg",
"size": "88896",
"createdAt": "Thu Feb 01 2024 11:34:03 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
},
{
"originalname": "WhatsApp Image 2024-01-30 at 11.58.35 AM.jpeg",
"filename": "1706767443807_WhatsApp_Image_20240130_at_115835_AM.jpeg",
"path": "cases/659ce15a8f39506e8348ed7c/processingDocuments/1706767443807
_WhatsApp_Image_20240130_at_115835_AM.jpeg",
"size": "131034",
"createdAt": "Thu Feb 01 2024 11:34:03 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"lastName": "Pawar"
},
"workType": "MAKER",
"display": true,
"status": true,
"_id": "65bb36716635d840ef57f8a4",
"note": "Report Making In App (Task Reopen)",
"taskId": "659e25e602c44c777bada914",
"createdAt": "2024-02-01T06:13:05.744Z"
}
],
"createdAt": "2024-01-09T06:02:02.054Z",
"updatedAt": "2024-02-01T06:35:45.378Z",
"__v": 0,
"invoiceId": "659ce15a8f39506e8348ed85",
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "M/s. BMSS Steel Industries Pvt. Ltd.",
```

```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 296.00",
"flatRate": "18500",
"landOtherRate": "15800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"proposePurchaserName": "",
"briefDescOfProperty": "Working Area",
"carpetTotal": "120.00",
"otherCarpetTotal": "0.00"

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Working Area	12'00"	10'00"	120.00
Other Composition :			