

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b94e"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418eb",
    "email": "sudhir.raut@cosmosbank.in",
    "firstName": "Sudhi Raut",
    "mobileNo": "8355848857",
    "workMobileNo": "8355848857",
    "lastName": "Raut"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sudhi Raut",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b94e",
  "branchCode": "000009",
  "type": "BRANCH",
  "name": "Santacruz (East) Branch",
  "email": "vidyadhar.rangnekar@cosmosbank.in",
  "mobileNo": "02226126971",
  "alternateMobileNo": "",
  "address": "Ground Floor, Uday Darshan Buidling, Jawaharlal Nehru Road, Golibar,
Santacruz (East), Mumbai - 400055, State -\r\nMaharashtra, Country - India ",
  "ledgerName": "COSMOS BANK- SANTACRUZ (EAST)",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.463185",
  "longitude": " 72.813114"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.813114,
    19.463185
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
```

```
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "virar East",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om varad Laxmi co operative housing society Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```

```
"status": false,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "9",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```

```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
```



```
"unitBoundaries": {
  "isDisplay": false
},
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "659e7a7e02c44c777baedd58",
"ownerName": "Mahesh mhadadalkar",
"ownerPhoneNo": "9226158401",
"appAddress": "Gala no 9, ground floor, Om varad Laxmi co operative housing society
Ltd, virar East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Index - II",
      "value": "60ae1287aa6d152c1801b415"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/659e7a7e02c44c777baedd58/
document_1704884852329_.1704884963634_Mahesh_",
    "fileName": "document_1704884852329_.1704884963634_Mahesh_",
    "id": "193603",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Jan 10 2024 16:37:42 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "006264",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "186328",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 10 2024 16:37:42 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mahesh mhadadalkar",
    "phone": "9226158401",
    "ownershipShare": "",
    "email": "",
    "id": "102334"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf038f",
    "name":
"externallmg_1704886997719_WhatsApp_Image_20240110_at_50831_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997719_WhatsApp_Image_20240110_at_50831_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0390",
    "name":
"externallmg_1704886997725_WhatsApp_Image_20240110_at_50832_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997725_WhatsApp_Image_20240110_at_50832_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0391",
    "name":
"externallmg_1704886997733_WhatsApp_Image_20240110_at_50832_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997733_WhatsApp_Image_20240110_at_50832_PM_2.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0392",
    "name":
"externallmg_1704886997742_WhatsApp_Image_20240110_at_50832_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997742_WhatsApp_Image_20240110_at_50832_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0393",
    "name":
"externallmg_1704886997744_WhatsApp_Image_20240110_at_50833_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997744_WhatsApp_Image_20240110_at_50833_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0394",
    "name":
"externallmg_1704886997747_WhatsApp_Image_20240110_at_50833_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997747_WhatsApp_Image_20240110_at_50833_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0395",
    "name":
"externallmg_1704886997750_WhatsApp_Image_20240110_at_50833_PM_3.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997750_WhatsApp_Image_20240110_at_50833_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0396",
```

```
    "name":
"externallmg_1704886997754_WhatsApp_Image_20240110_at_50833_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997754_WhatsApp_Image_20240110_at_50833_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82d502c44c777baf0397",
    "name":
"externallmg_1704886997756_WhatsApp_Image_20240110_at_50834_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704886997756_WhatsApp_Image_20240110_at_50834_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03d4",
    "name":
"externallmg_1704887012272_WhatsApp_Image_20240110_at_50838_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012272_WhatsApp_Image_20240110_at_50838_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03d5",
    "name":
"externallmg_1704887012277_WhatsApp_Image_20240110_at_50838_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012277_WhatsApp_Image_20240110_at_50838_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03d6",
    "name":
"externallmg_1704887012291_WhatsApp_Image_20240110_at_50838_PM_3.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012291_WhatsApp_Image_20240110_at_50838_PM_3.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e82e402c44c777baf03d7",
  "name":
"externallmg_1704887012297_WhatsApp_Image_20240110_at_50838_PM.jpeg",
  "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012297_WhatsApp_Image_20240110_at_50838_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e82e402c44c777baf03d8",
  "name":
"externallmg_1704887012303_WhatsApp_Image_20240110_at_50839_PM_1.jpeg",
  "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012303_WhatsApp_Image_20240110_at_50839_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e82e402c44c777baf03d9",
  "name":
"externallmg_1704887012308_WhatsApp_Image_20240110_at_50839_PM_2.jpeg",
  "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012308_WhatsApp_Image_20240110_at_50839_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e82e402c44c777baf03da",
  "name":
"externallmg_1704887012314_WhatsApp_Image_20240110_at_50839_PM.jpeg",
  "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012314_WhatsApp_Image_20240110_at_50839_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659e82e402c44c777baf03db",
  "name":
"externallmg_1704887012319_WhatsApp_Image_20240110_at_50834_PM_1.jpeg",
```

```
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012319_WhatsApp_Image_20240110_at_50834_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03dc",
    "name":
"externallmg_1704887012324_WhatsApp_Image_20240110_at_50834_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012324_WhatsApp_Image_20240110_at_50834_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03dd",
    "name":
"externallmg_1704887012329_WhatsApp_Image_20240110_at_50835_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012329_WhatsApp_Image_20240110_at_50835_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03de",
    "name":
"externallmg_1704887012335_WhatsApp_Image_20240110_at_50835_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012335_WhatsApp_Image_20240110_at_50835_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03df",
    "name":
"externallmg_1704887012341_WhatsApp_Image_20240110_at_50835_PM_3.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012341_WhatsApp_Image_20240110_at_50835_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659e82e402c44c777baf03e0",
    "name":
"externallmg_1704887012346_WhatsApp_Image_20240110_at_50835_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012346_WhatsApp_Image_20240110_at_50835_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e1",
    "name":
"externallmg_1704887012349_WhatsApp_Image_20240110_at_50836_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012349_WhatsApp_Image_20240110_at_50836_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e2",
    "name":
"externallmg_1704887012353_WhatsApp_Image_20240110_at_50836_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012353_WhatsApp_Image_20240110_at_50836_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e3",
    "name":
"externallmg_1704887012358_WhatsApp_Image_20240110_at_50836_PM_3.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012358_WhatsApp_Image_20240110_at_50836_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e4",
    "name":
"externallmg_1704887012363_WhatsApp_Image_20240110_at_50836_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012363_WhatsApp_Image_20240110_at_50836_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e5",
    "name":
"externallmg_1704887012367_WhatsApp_Image_20240110_at_50837_PM_1.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012367_WhatsApp_Image_20240110_at_50837_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e6",
    "name":
"externallmg_1704887012372_WhatsApp_Image_20240110_at_50837_PM_2.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012372_WhatsApp_Image_20240110_at_50837_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659e82e402c44c777baf03e7",
    "name":
"externallmg_1704887012377_WhatsApp_Image_20240110_at_50837_PM.jpeg",
    "path": "cases/659e7a7e02c44c777baedd58/
externallmg_1704887012377_WhatsApp_Image_20240110_at_50837_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-10T11:07:42.179Z",
"updatedAt": "2024-01-10T11:43:32.488Z",
"__v": 0,
"invoiceId": "659e7a7e02c44c777baedd66",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
}
```

"fullAddress": " Unit No. 9, Ground Floor, Om varad Laxmi co operative housing society Ltd, virar East",  
"updatedBy": "64cde526dc9f3034f3fefa49",  
"addressForMap": "",  
"caseReferredBy": "",  
"contactPersonName": "Mahesh mhadadalkar",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9226158401"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			