

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b31",
    "email": "resham.kulkarni@cosmosbank.in",
    "firstName": "Resham ",
    "mobileNo": "9987780572",
    "workMobileNo": "9987780572",
    "lastName": "Kulkarni"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.253747942511804",
  "longitude": "73.1017023"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kongaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": false,
```

```
"name": "City",
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "MIDC",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Additional Kalyan Bhiwandi Industrial Area",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Asmeeta Texpa",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit 203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```



```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65a0d29302c44c777bb1c87f",
"ownerName": "Mr. Gavrav J. Jain",
"ownerPhoneNo": "9320753111",
"fullAddress": "Industrial Unit No. Unit 203, 2nd Floor, Wing - B, Additional Kalyan
Bhiwandi Industrial Area, Asmeeta Texpa, Plot No. MIDC, Village - Kongaon, Taluka -
Bhiwandi, District - Thane, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/11/2012",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "M/s. Asmeeta Infratech Limited",
      "to": {
        "value": "Lessee",
        "label": "Lessee"
      },
      "Lessee": "Mr. Gavrav J. Jain",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "10000/2012"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1705038465685_Rajguru_Creation_100002012_1.pdf",
    "path": "cases/65a0d29302c44c777bb1c87f/
document_1705038465685_Rajguru_Creation_100002012_1.pdf",
    "id": "943086",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Fri Jan 12 2024 11:18:02 GMT+0530 (India Standard Time)"
  },
]
```

```
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "documentDate": "27/07/2011",
    "remark": "Building Approval Plan Letter No. EE / SPA / DMB / 5343 / 2011 issued
by MIDC Dombivli Division"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1705383245761_110094.pdf",
  "path": "cases/65a0d29302c44c777bb1c87f/
document_1705383245761_110094.pdf",
  "id": "190932",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Jan 16 2024 11:04:05 GMT+0530 (India Standard Time)"
},
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "006304",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "741285",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 12 2024 11:18:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Gavrav J. Jain",
    "phone": "9320753111",
    "ownershipShare": "",
    "email": "",
    "id": "884266"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9ae02c44c777bb4bdef",
    "name":
"externallmg_1705294254829_WhatsApp_Image_20240115_at_101953_1.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294254829_WhatsApp_Image_20240115_at_101953_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9ae02c44c777bb4bdf0",
    "name":
"externallmg_1705294254841_WhatsApp_Image_20240115_at_101953_2.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294254841_WhatsApp_Image_20240115_at_101953_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9ae02c44c777bb4bdf1",
    "name":
"externallmg_1705294254845_WhatsApp_Image_20240115_at_101953_3.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294254845_WhatsApp_Image_20240115_at_101953_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be33",
    "name":
"externallmg_1705294264709_WhatsApp_Image_20240115_at_101953_4.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264709_WhatsApp_Image_20240115_at_101953_4.jpeg",
    "orientation": "portrait"
  },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be34",
  "name":
"externallmg_1705294264712_WhatsApp_Image_20240115_at_101953_5.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264712_WhatsApp_Image_20240115_at_101953_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be35",
  "name":
"externallmg_1705294264716_WhatsApp_Image_20240115_at_101953_6.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264716_WhatsApp_Image_20240115_at_101953_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be36",
  "name":
"externallmg_1705294264719_WhatsApp_Image_20240115_at_101953_7.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264719_WhatsApp_Image_20240115_at_101953_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be37",
  "name":
"externallmg_1705294264722_WhatsApp_Image_20240115_at_101953_8.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264722_WhatsApp_Image_20240115_at_101953_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be38",
  "name":
"externallmg_1705294264725_WhatsApp_Image_20240115_at_101953_9.jpeg",
```

```
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264725_WhatsApp_Image_20240115_at_101953_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be39",
    "name":
"externallmg_1705294264727_WhatsApp_Image_20240115_at_101953_10.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264727_WhatsApp_Image_20240115_at_101953_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be3a",
    "name":
"externallmg_1705294264732_WhatsApp_Image_20240115_at_101953_11.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264732_WhatsApp_Image_20240115_at_101953_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be3b",
    "name":
"externallmg_1705294264735_WhatsApp_Image_20240115_at_101953_12.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264735_WhatsApp_Image_20240115_at_101953_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be3c",
    "name":
"externallmg_1705294264738_WhatsApp_Image_20240115_at_101953_13.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264738_WhatsApp_Image_20240115_at_101953_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65a4b9b802c44c777bb4be3d",
  "name":
"externallmg_1705294264741_WhatsApp_Image_20240115_at_101953_14.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264741_WhatsApp_Image_20240115_at_101953_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be3e",
  "name":
"externallmg_1705294264743_WhatsApp_Image_20240115_at_101953_15.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264743_WhatsApp_Image_20240115_at_101953_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be3f",
  "name":
"externallmg_1705294264746_WhatsApp_Image_20240115_at_101953_16.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264746_WhatsApp_Image_20240115_at_101953_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be40",
  "name":
"externallmg_1705294264749_WhatsApp_Image_20240115_at_101953_17.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264749_WhatsApp_Image_20240115_at_101953_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a4b9b802c44c777bb4be41",
  "name":
"externallmg_1705294264751_WhatsApp_Image_20240115_at_101953_18.jpeg",
  "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264751_WhatsApp_Image_20240115_at_101953_18.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be42",
    "name":
"externallmg_1705294264754_WhatsApp_Image_20240115_at_101953_19.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264754_WhatsApp_Image_20240115_at_101953_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be43",
    "name":
"externallmg_1705294264756_WhatsApp_Image_20240115_at_101953.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264756_WhatsApp_Image_20240115_at_101953.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a4b9b802c44c777bb4be44",
    "name":
"externallmg_1705294264758_WhatsApp_Image_20240115_at_101954.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/
externallmg_1705294264758_WhatsApp_Image_20240115_at_101954.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1705308282895_AGR.pdf",
    "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308282895_AGR.pdf",
    "size": "31471030",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1705294254845_WhatsApp_Image_20240115_at_101953_3.jpeg",
```

```
    "filename": "1705308283523_externallmg_1705294254845_WhatsApp_Image_20240115_at_101953_3.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/processingDocuments/1705308283523_externallmg_1705294254845_WhatsApp_Image_20240115_at_101953_3.jpeg",
    "size": "57573",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1705294264758_WhatsApp_Image_20240115_at_101954.jpeg",
    "filename": "1705308283525_externallmg_1705294264758_WhatsApp_Image_20240115_at_101954.jpeg",
    "path": "cases/65a0d29302c44c777bb1c87f/processingDocuments/1705308283525_externallmg_1705294264758_WhatsApp_Image_20240115_at_101954.jpeg",
    "size": "53328",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1705308283527_IGR01.pdf",
    "path": "cases/65a0d29302c44c777bb1c87f/processingDocuments/1705308283527_IGR01.pdf",
    "size": "158679",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1705308283530_IGR02.pdf",
    "path": "cases/65a0d29302c44c777bb1c87f/processingDocuments/1705308283530_IGR02.pdf",
    "size": "154792",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1705308283532_IGR03.pdf",
    "path": "cases/65a0d29302c44c777bb1c87f/processingDocuments/1705308283532_IGR03.pdf",
    "size": "155865",
    "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
}
```



```
{
  "originalname": "IGR-04.pdf",
  "filename": "1705308283535_IGR04.pdf",
  "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308283535_IGR04.pdf",
  "size": "154496",
  "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-05.pdf",
  "filename": "1705308283537_IGR05.pdf",
  "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308283537_IGR05.pdf",
  "size": "154597",
  "createdAt": "Mon Jan 15 2024 14:14:43 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Index-II.pdf",
  "filename": "1705308294013_IndexII.pdf",
  "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308294013_IndexII.pdf",
  "size": "161882",
  "createdAt": "Mon Jan 15 2024 14:14:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "REf Repo-Dinesh Shah.pdf",
  "filename": "1705308294016_REf_RepoDinesh_Shah.pdf",
  "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308294016_REf_RepoDinesh_Shah.pdf",
  "size": "4007943",
  "createdAt": "Mon Jan 15 2024 14:14:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=GAURAV.xlsx",
  "filename": "1705308294120_Summary_NewGAURAV.xlsx",
  "path": "cases/65a0d29302c44c777bb1c87f/
processingDocuments/1705308294120_Summary_NewGAURAV.xlsx",
  "size": "2333266",
  "createdAt": "Mon Jan 15 2024 14:14:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
```

```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65a0dd4f02c44c777bb1e6cb",
    "note": "Given Approx Value Rs. 57 to Rs. 60 Lakhs\n",
    "taskId": "65a0d2c602c44c777bb1c934",
    "createdAt": "2024-01-12T06:33:51.381Z"
  },
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65a4c9e602c44c777bb4ec37",
    "note": "Pending for value confirmation",
    "taskId": "65a0d2c602c44c777bb1c934",
    "createdAt": "2024-01-15T06:00:06.926Z"
  }
],
"createdAt": "2024-01-12T05:48:03.124Z",
"updatedAt": "2024-01-16T05:34:05.840Z",
"__v": 0,
"invoiceId": "65a0d29302c44c777bb1c885",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Gavrav J. Jain",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9320753111",
"proposePurchaserName": ""
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			