

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64425b2d629ac20845e9f4bf"
    },
    "type": "CREDITOFFICER",
    "_id": "64425b2d629ac20845e9f4c1",
    "firstName": "shell",
    "lastName": "shell",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "12me@me.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64425b2d629ac20845e9f4bf",
  "name": "RACC Nashik Branch",
  "branchCode": "",
  "mobileNo": "02225923555",
  "alternateMobileNo": "",
  "email": "testjagdish.bhatt@vastukala.org",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RBO.2, The Wave Building Opposite Shell Petrol Pump, First Floor,
Pathardi Road Nashik.422010,\n\nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
```

```
},
```

```
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
```

```
},
```

```
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "647ed1960ab64c23c9fcf71d",
  "role": "FRONTDESK",
  "firstName": "Rishidatt",
  "email": "rishiyadav4444@gamil.com",
  "lastName": "Yadav",
  "mobileNo": "9404341081",
  "designation": "",
  "shortName": "RV",
  "workWithDocumentMaker": ""
```

```
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
```

```
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.20061237488537",
  "longitude": "73.82674863126861"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dindori",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Upper Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Dindori",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "47/2",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Narayan Row Houses",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Balaji Infotech Abacus Classes, Bhawani Nagar, Umarale Road",
```

```
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B - 08",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```



```
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "917",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422202",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
}
```

```
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65a1197e02c44c777bb29d16",
"ownerName": "Badaram Dewasi",
"ownerPhoneNo": "9896030382",
"fullAddress": " Row House No. B - 08,, Upper Ground Floor, Narayan Row Houses,
Behind Balaji Infotech Abacus Classes, Bhawani Nagar, Umarale Road, Plot No. 47/2,
Village - Dindori, Gut No. 917, Taluka - Dindori, District - Nashik, Nashik, 422202",
"remark": "",
```

```
"documents": [  
  {  
    "documentType": {  
      "value": "60ae124aaa6d152c1801b2f7",  
      "label": "Any Other Document"  
    },  
    "isHardCopy": false,  
    "displayStatus": false,  
    "fileName": "document_1705056595900_AnyScanner_01_03_2024.pdf",  
    "path": "cases/65a1197e02c44c777bb29d16/  
document_1705056595900_AnyScanner_01_03_2024.pdf",  
    "id": "227548",  
    "uploadedBy": "63f9ed37ce84bf289ba991ac",  
    "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"  
  },  
  {  
    "documentType": {  
      "value": "60ae124aaa6d152c1801b2f7",  
      "label": "Any Other Document"  
    },  
    "isHardCopy": false,  
    "displayStatus": false,  
    "fileName": "document_1705056604316_DocScanner_11Jan2024_128_pm_2.pdf",  
    "path": "cases/65a1197e02c44c777bb29d16/  
document_1705056604316_DocScanner_11Jan2024_128_pm_2.pdf",  
    "id": "217391",  
    "uploadedBy": "63f9ed37ce84bf289ba991ac",  
    "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"  
  },  
  {  
    "documentType": {  
      "value": "60ae124aaa6d152c1801b2f7",  
      "label": "Any Other Document"  
    },  
    "isHardCopy": false,  
    "displayStatus": false,  
    "fileName": "document_1705056610170_DocScanner_11Jan2024_128_pm.pdf",  
    "path": "cases/65a1197e02c44c777bb29d16/  
document_1705056610170_DocScanner_11Jan2024_128_pm.pdf",  
    "id": "776212",  
    "uploadedBy": "63f9ed37ce84bf289ba991ac",  
    "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"  
  },  
  {  
    "documentType": {  
      "value": "60ae124aaa6d152c1801b2f7",
```



```
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705056616822_New_Doc_01092024_1441.pdf",
  "path": "cases/65a1197e02c44c777bb29d16/
document_1705056616822_New_Doc_01092024_1441.pdf",
  "id": "490717",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705056624838_PLAN_.pdf",
  "path": "cases/65a1197e02c44c777bb29d16/
document_1705056624838_PLAN_.pdf",
  "id": "596363",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705056631335_SALE_DEED.pdf",
  "path": "cases/65a1197e02c44c777bb29d16/
document_1705056631335_SALE_DEED.pdf",
  "id": "759978",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1705056718658_126863.pdf",
    "path": "cases/65a1197e02c44c777bb29d16/
document_1705056718658_126863.pdf",
    "id": "621626",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Jan 12 2024 16:21:58 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006316",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "612718",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 12 2024 16:20:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Badaram Dewasi",
    "phone": "9896030382",
    "ownershipShare": "",
    "email": "",
    "id": "517569"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a054",
    "name":
"externallmg_1705056706638_WhatsApp_Image_20240111_at_115709_AM.jpeg",
```

```
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706638_WhatsApp_Image_20240111_at_115709_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a055",
    "name":
"externallmg_1705056706687_WhatsApp_Image_20240111_at_115710_AM_1.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706687_WhatsApp_Image_20240111_at_115710_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a056",
    "name":
"externallmg_1705056706729_WhatsApp_Image_20240111_at_115710_AM.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706729_WhatsApp_Image_20240111_at_115710_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a057",
    "name":
"externallmg_1705056706793_WhatsApp_Image_20240111_at_115711_AM_1.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706793_WhatsApp_Image_20240111_at_115711_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a058",
    "name":
"externallmg_1705056706857_WhatsApp_Image_20240111_at_115711_AM.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706857_WhatsApp_Image_20240111_at_115711_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65a119c302c44c777bb2a059",
  "name":
"externallmg_1705056706903_WhatsApp_Image_20240111_at_115712_AM_1.jpeg",
  "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706903_WhatsApp_Image_20240111_at_115712_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a119c302c44c777bb2a05a",
  "name":
"externallmg_1705056706930_WhatsApp_Image_20240111_at_115712_AM_2.jpeg",
  "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706930_WhatsApp_Image_20240111_at_115712_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a119c302c44c777bb2a05b",
  "name":
"externallmg_1705056706968_WhatsApp_Image_20240111_at_115712_AM.jpeg",
  "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056706968_WhatsApp_Image_20240111_at_115712_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a119c302c44c777bb2a05c",
  "name":
"externallmg_1705056707022_WhatsApp_Image_20240111_at_115713_AM_1.jpeg",
  "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707022_WhatsApp_Image_20240111_at_115713_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a119c302c44c777bb2a05d",
  "name":
"externallmg_1705056707047_WhatsApp_Image_20240111_at_115713_AM_2.jpeg",
  "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707047_WhatsApp_Image_20240111_at_115713_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a05e",
    "name":
"externallmg_1705056707096_WhatsApp_Image_20240111_at_115713_AM.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707096_WhatsApp_Image_20240111_at_115713_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a05f",
    "name":
"externallmg_1705056707122_WhatsApp_Image_20240111_at_115714_AM_1.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707122_WhatsApp_Image_20240111_at_115714_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a060",
    "name":
"externallmg_1705056707206_WhatsApp_Image_20240111_at_115714_AM_2.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707206_WhatsApp_Image_20240111_at_115714_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a061",
    "name":
"externallmg_1705056707258_WhatsApp_Image_20240111_at_115714_AM.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707258_WhatsApp_Image_20240111_at_115714_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a062",
```

```

    "name":
    "externallmg_1705056707320_WhatsApp_Image_20240111_at_115715_AM_1.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707320_WhatsApp_Image_20240111_at_115715_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a119c302c44c777bb2a063",
    "name":
    "externallmg_1705056707385_WhatsApp_Image_20240111_at_115715_AM.jpeg",
    "path": "cases/65a1197e02c44c777bb29d16/
externallmg_1705056707385_WhatsApp_Image_20240111_at_115715_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-12T10:50:38.463Z",
"updatedAt": "2024-01-12T10:51:58.790Z",
"__v": 0,
"invoiceId": "65a1197e02c44c777bb29d1f",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Badaram Dewasi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9896030382"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---