

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64425b2d629ac20845e9f4bf"
    },
    "type": "CREDITOFFICER",
    "_id": "64425b2d629ac20845e9f4c1",
    "firstName": "shell",
    "lastName": "shell",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "12me@me.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64425b2d629ac20845e9f4bf",
  "name": "RACC Nashik Branch",
  "branchCode": "",
  "mobileNo": "02225923555",
  "alternateMobileNo": "",
  "email": "testjagdish.bhatt@vastukala.org",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RBO.2, The Wave Building Opposite Shell Petrol Pump, First Floor,
Pathardi Road Nashik.422010,\n\nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": ""
```

```
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.010694076791335",
  "longitude": "73.80769255690562"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": ""Keshav"",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Hotel Palms Residency, Opp. Swami Narayan Mandir, Bappa Sitaram
Marg, Mumbai - Agra National Highway, Adgaon Naka, Panchavati",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Samraat Vrindavan Apartment",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "188/ 1A + 188/ 1B/ 1 + 188/ 1C/ 1",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "804",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```



```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65a228ed02c44c777bb37058",
"ownerName": "Nilam Kasar",
"ownerPhoneNo": "9730010055",
"fullAddress": " Flat No. 804, 8th Floor, Wing - C, "Keshav", Samraat Vrindavan
Apartment, Near Hotel Palms Residency, Opp. Swami Narayan Mandir, Bappa Sitaram
Marg, Mumbai - Agra National Highway, Adgaon Naka, Panchavati, Village - Nashik,
Taluka - Nashik, District - Nashik, Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1705126062133_Kaagaz_20240110_134730095330_2.pdf",
    "path": "cases/65a228ed02c44c777bb37058/
document_1705126062133_Kaagaz_20240110_134730095330_2.pdf",
    "id": "561926",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1705126090538_174576.pdf",
    "path": "cases/65a228ed02c44c777bb37058/
document_1705126090538_174576.pdf",
    "id": "608363",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
  },
}
```



```
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705126095814_Kaagaz_20240110_134730095330.pdf",
  "path": "cases/65a228ed02c44c777bb37058/
document_1705126095814_Kaagaz_20240110_134730095330.pdf",
  "id": "679557",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705126103814_Krishna_Patel_plan_3.pdf",
  "path": "cases/65a228ed02c44c777bb37058/
document_1705126103814_Krishna_Patel_plan_3.pdf",
  "id": "881020",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705126115560_Krishna_Patel_plan_4.pdf",
  "path": "cases/65a228ed02c44c777bb37058/
document_1705126115560_Krishna_Patel_plan_4.pdf",
  "id": "738140",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1705126122656_Krishna_Patel_plan1.pdf",
    "path": "cases/65a228ed02c44c777bb37058/
document_1705126122656_Krishna_Patel_plan1.pdf",
    "id": "425546",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006325",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "244573",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jan 13 2024 11:38:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nilam Kasar",
    "phone": "9730010055",
    "ownershipShare": "",
    "email": "",
    "id": "679639"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "65a229cc02c44c777bb375c5",
    "name":
"externallmg_1705126346680_WhatsApp_Image_20240111_at_52026_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126346680_WhatsApp_Image_20240111_at_52026_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375c6",
    "name":
"externallmg_1705126346783_WhatsApp_Image_20240111_at_52031_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126346783_WhatsApp_Image_20240111_at_52031_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375c7",
    "name":
"externallmg_1705126346799_WhatsApp_Image_20240111_at_52032_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126346799_WhatsApp_Image_20240111_at_52032_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375c8",
    "name":
"externallmg_1705126346836_WhatsApp_Image_20240111_at_52037_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126346836_WhatsApp_Image_20240111_at_52037_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375c9",
    "name":
"externallmg_1705126346936_WhatsApp_Image_20240111_at_52039_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126346936_WhatsApp_Image_20240111_at_52039_PM.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a229cc02c44c777bb375ca",
      "name":
"externallmg_1705126347025_WhatsApp_Image_20240111_at_52040_PM.jpeg",
      "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347025_WhatsApp_Image_20240111_at_52040_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a229cc02c44c777bb375cb",
      "name":
"externallmg_1705126347077_WhatsApp_Image_20240111_at_52042_PM_1.jpeg",
      "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347077_WhatsApp_Image_20240111_at_52042_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a229cc02c44c777bb375cc",
      "name":
"externallmg_1705126347128_WhatsApp_Image_20240111_at_52042_PM.jpeg",
      "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347128_WhatsApp_Image_20240111_at_52042_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a229cc02c44c777bb375cd",
      "name":
"externallmg_1705126347156_WhatsApp_Image_20240111_at_52045_PM.jpeg",
      "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347156_WhatsApp_Image_20240111_at_52045_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a229cc02c44c777bb375ce",
      "name":
"externallmg_1705126347208_WhatsApp_Image_20240111_at_52047_PM.jpeg",
```

```
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347208_WhatsApp_Image_20240111_at_52047_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375cf",
    "name":
"externallmg_1705126347261_WhatsApp_Image_20240111_at_52048_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347261_WhatsApp_Image_20240111_at_52048_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375d0",
    "name":
"externallmg_1705126347313_WhatsApp_Image_20240111_at_52049_PM_1.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347313_WhatsApp_Image_20240111_at_52049_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375d1",
    "name":
"externallmg_1705126347351_WhatsApp_Image_20240111_at_52049_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347351_WhatsApp_Image_20240111_at_52049_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375d2",
    "name":
"externallmg_1705126347377_WhatsApp_Image_20240111_at_52050_PM_1.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347377_WhatsApp_Image_20240111_at_52050_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65a229cc02c44c777bb375d3",
  "name":
"externallmg_1705126347418_WhatsApp_Image_20240111_at_52050_PM_2.jpeg",
  "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347418_WhatsApp_Image_20240111_at_52050_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a229cc02c44c777bb375d4",
  "name":
"externallmg_1705126347526_WhatsApp_Image_20240111_at_52050_PM.jpeg",
  "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347526_WhatsApp_Image_20240111_at_52050_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a229cc02c44c777bb375d5",
  "name":
"externallmg_1705126347647_WhatsApp_Image_20240111_at_52051_PM.jpeg",
  "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347647_WhatsApp_Image_20240111_at_52051_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a229cc02c44c777bb375d6",
  "name":
"externallmg_1705126347774_WhatsApp_Image_20240111_at_52052_PM_1.jpeg",
  "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347774_WhatsApp_Image_20240111_at_52052_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a229cc02c44c777bb375d7",
  "name":
"externallmg_1705126347857_WhatsApp_Image_20240111_at_52052_PM_2.jpeg",
  "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126347857_WhatsApp_Image_20240111_at_52052_PM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229cc02c44c777bb375d8",
    "name":
"externallmg_r_1705126347580_WhatsApp_Image_20240111_at_52051_PM_1.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_r_1705126347580_WhatsApp_Image_20240111_at_52051_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb37609",
    "name":
"externallmg_1705126355308_WhatsApp_Image_20240111_at_52053_PM_1.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126355308_WhatsApp_Image_20240111_at_52053_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb3760a",
    "name":
"externallmg_1705126355519_WhatsApp_Image_20240111_at_52053_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126355519_WhatsApp_Image_20240111_at_52053_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb3760b",
    "name":
"externallmg_1705126355717_WhatsApp_Image_20240111_at_52054_PM_1.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126355717_WhatsApp_Image_20240111_at_52054_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb3760c",
```

```
    "name":
"externallmg_1705126355924_WhatsApp_Image_20240111_at_52054_PM_2.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126355924_WhatsApp_Image_20240111_at_52054_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb3760d",
    "name":
"externallmg_1705126356135_WhatsApp_Image_20240111_at_52054_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_1705126356135_WhatsApp_Image_20240111_at_52054_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a229d402c44c777bb3760e",
    "name":
"externallmg_r_1705126355213_WhatsApp_Image_20240111_at_52052_PM.jpeg",
    "path": "cases/65a228ed02c44c777bb37058/
externallmg_r_1705126355213_WhatsApp_Image_20240111_at_52052_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-13T06:08:45.629Z",
"updatedAt": "2024-01-13T06:12:36.478Z",
"__v": 0,
"invoiceId": "65a228ed02c44c777bb3705e",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Nilam Kasar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
```


"relationWithOwner": "self",
"siteVisitContactNo": "9730010055"

}

Name

Length

Width

Total

Composition :

Other

Composition :
