CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: BOB / Regional Office Branch / Mr. Kaliprasad Jayraj Bhatt (006414/2304574)

Page 1 of 3

Vastu/Nashik/01/2024/006414/2304574

18/5-276-RYRJ Date: 18.01.2024

## Structural Stability Report

Residential Flat No. 13, Second Floor, " Sukhdham Co- Operative Housing Society Ltd. ", Survey No. 624/ 4+5A +5B/2, Plot No.16, T.P.S II, Final Plot No. 174, Near St. Francis High School, Tidke Colony, Golf Club Road, Village - Nashik, Taluka & District - Nashik, PIN Code - 422 002, State - Maharashtra, Country - India belongs to Name of Proposed Purchaser: Mr. Kaliprasad Jayraj Bhatt. Name of Owner: Dr. Dinesh Vishvanath Thakare.

This is to certify that on visual inspection, it appears that the structure of "Sukhdham Co- Operative Housing Society Ltd. "is in Normal condition and the future life can be reasonably takes under Average condition and with proper periodic repairs & maintenance is about 35years.

## General Information:

A.		Introduction
1	Name of Building	" Sukhdham Co- Operative Housing Society Ltd. "
2	Property Address	Residential Flat No. 13, Second Floor, " Sukhdham Co-Operative Housing Society Ltd.", Survey No. 624/ 4+5A +5B/ 2, Plot No.16, T.P.S II, Final Plot No. 174, Near St. Francis High School, Tidke Colony, Golf Club Road, Village – Nashik, Taluka & District - Nashik, PIN Code – 422 002, State – Maharashtra, Country – India.
3	Type of Building	Flat No. 13
4	No. of Floors	Ground + Stilt + 2 <sup>nd</sup> Uppers Floor
5	Whether stilt / podium / open parking provided	Covered Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1998 (As per Part Occupancy Certificate)
11	Present age of building	25 years
12	Residual age of the building	35 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of Flats	6 Flats on Second Floor
14	Methodology adopted	As per visual site inspection

Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra-Nandur Naka Link Road, Adgaon, Nashik - 422 003, (M.S.) E-mail: nashik@vastukala.org, Tel.: +91 253 4068262 / 9890380564

Our Pan India Presence at :

Mumbai Thane

P Aurangabad P Pune

Indore

Raikot Raipur

Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

Regd. Office: B1-001, U/B Floor, Boomerang,

TeleFax: +91 22 28371325/24 mumbai@vastukala.org