

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64461cc5629ac20845ebe414"
    },
    "type": "CREDITOFFICER",
    "_id": "64461cc5629ac20845ebe416",
    "firstName": "Sandeep ",
    "lastName": "Meshram",
    "mobileNo": "",
    "workMobileNo": "9975402060",
    "email": "pnbme@me.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Sandeep ",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64461cc5629ac20845ebe414",
  "name": "MCC 2 Fort P M Road Branch\t",
  "branchCode": "",
  "mobileNo": "02225923555",
  "alternateMobileNo": "",
  "email": "mcc8133@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "United Bank of India Building, 3rd Floor, 25 Sir P M Road, Opposite
Citibank, Fort,Mumbai - 400001, State – Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.116533068594233",
  "longitude": "72.86423463558239"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86423463558239,
    19.116533068594233
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-03",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-03",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulgaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Upper Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumabi Suburban",
    "label": true
  },
}
```

```
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mistry Industrial Complex Premises Co-op. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "M.I.D.C. Cross Road A",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off. Mahakali Caves Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "18(pt), 19 & 84, Hissa No. 4(pt) & 5(pt)",
  "label": true
},
"hisssaNo": {
```



```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "237",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "24",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K-East",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 093",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  }
}
```

```
},
"doors": {
  "value": "MS_Rolling_Shutter",
  "label": "MS Rolling Shutter"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
  "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Aptech Limited Company",
    "west": "Technopolis Knowledge Park",
    "south": "Slum Area",
    "east": "MIDC Cross Road A"
  },
  "asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "having Reception Area + 5 Cabins + MS Loft Area (Used
for Commercial Purpose)",
"dateOfIssusApprovePlan": "As Building Completion Certificate is received it may be
assumed that the construction is as per Sanctioned Plan.\n\n",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "73.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "1984.5",
  "depreciatedCostOfConstruction": "15015.50",
  "depreciatedBuildingRate": "715.5"
},
"igrRate": {
  "propertyName": "Industrial",
  "rate": "152440",
  "landRate": "61800",
  "igrImage": "cases/65bc97c76635d840ef59bb41/igr_1708083988848_Image.png",
  "squareMeterGuideLineRate": "152440.00",
  "squareFeetGuideLineRate": "14162.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "51",
  "rate": "10036.00",
  "squareFeetGuideLineRate": "10036.00",
  "squareMeterGuideLineRate": "108026.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_Purpose",
    "label": "Commercial Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "22,000/- Expected rental income per month",
  "assessmentNo": "As per Maintenance Bill No. 321",
  "taxPaidHolderName": " Mrs. Veenadevi Ganeshmal Jain",
  "taxAmount": "8,738/-",
  "electricityServiceConnectionNo": "Electricity Bill CA No. 152000614",
  "meterCardHolderName": " Mrs. Veenadevi Ganeshmal Jain",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
```

```
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1975",
  "fullDate": "1/1/1975"
},
"planningArea": {
  "value": "Industrial",
  "label": "Industrial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"groundStilt": {
"value": "Lower_Ground_+_Upper_Ground_Floor",
"label": "Lower Ground + Upper Ground Floor"
}
```

```
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "11",
"ageOfBuilding": "49",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "Upper Ground",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "18"
},
"finalPlinthArea": {
  "area": "702.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/65bc97c76635d840ef59bb41/
routeMap_1707117276869_Image.png",
    "routeLat": "19.115991",
    "routeLng": "72.864500",
    "stationName": "Western Express Highway ",
    "routeDistance": "1.2"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  }
}
```



```
},
"locationMapImg": [
  {
    "id": "aw4321",
    "name": "aw4321",
    "image": "cases/65bc97c76635d840ef59bb41/
routeMap_1707116836661_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "10541232.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "5965753",
  "finalValue": "10541232.00",
  "purchaseValueDocument": {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
```

```
    "label": "Sale Deed"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "108027",
  "path": "cases/65bc97c76635d840ef59bb41/
document_1706858425443_1706858559996_Mishtry_Industries_24.pdf",
  "fileName":
"document_1706858425443_1706858559996_Mishtry_Industries_24.pdf",
  "documentDate": "04/04/2014",
  "amount": "56,53,053/-",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Mansoor A. Chunawalla, Mr. Abbas M. Tinwala & Mrs. Sabera A.
Tinwala & Mr. Abbas M. Sarawala",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mrs. Veenadevi Ganeshmal Jain",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "2587/2014"
}
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Mar 02 2024 14:53:36 GMT+0530 (India Standard Time)",
  "number": "2305285",
  "dayCount": "18",
  "monthCount": "33",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7045272.00",
  "selectedBuildUpValue": "702.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65c05ce76635d840ef5c81c0",
      "name": "externallmg_r_1707105511655_TimePhoto_20240203_162132.jpg",
      "path": "cases/65bc97c76635d840ef59bb41/externallmg_r_1707105511655_TimePhoto_20240203_162132.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65c05cd66635d840ef5c8115",
      "name": "externallmg_r_1707105494274_IMG20240203161346.jpg",
      "path": "cases/65bc97c76635d840ef59bb41/externallmg_r_1707105494274_IMG20240203161346.jpg",
    }
  ]
}
```

```
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c8113",
    "name": "externallmg_r_1707105494262_TimePhoto_20240203_162015.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494262_TimePhoto_20240203_162015.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05ce76635d840ef5c81c1",
    "name": "externallmg_r_1707105511657_TimePhoto_20240203_162134.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511657_TimePhoto_20240203_162134.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c8116",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494279_TimePhoto_20240203_160338.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c8119",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494284_TimePhoto_20240203_160401.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c811a",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494286_TimePhoto_20240203_160414.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c811c",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494291_TimePhoto_20240203_160442.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c811d",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494293_TimePhoto_20240203_160454.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c811e",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494297_TimePhoto_20240203_160513.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c8120",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494298_TimePhoto_20240203_160705.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c05cd66635d840ef5c8118",
    "name": "Unit",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494282_TimePhoto_20240203_160343.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "13228",
"max": "22000"
},
"builtUpRateRange": {
  "min": "12026",
  "max": "20000"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "702.00",
"empanelmentNo": [
  "REF:ZO: SAMD:1138"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65bc97c76635d840ef59bb41",
"paymentId": [],
"ownerName": "Mrs. Veenadevi Ganeshmal Jain",
"ownerPhoneNo": "0000000000",
"appAddress": "Unit no 24, Mishtry Industrial Complex,MIDC, Cross Road A,Off
Mahakali Coves Road,Andheri East",
"remark": "Contact person Mr Mohan Jha 7738515841",
"documents": [
  {
    "documentType": {
```

```
"value": "60ae1245aa6d152c1801b2e3",
"label": "Sale Deed"
},
"inputs": {
  "documentDate": "04/04/2014",
  "amount": "56,53,053.00",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Mansoor A. Chunawalla, Mr. Abbas M. Tinwala & Mrs. Sabera A. Tinwala & Mr. Abbas M. Sarawala",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mrs. Veenadevi Ganeshmal Jain",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "2587/2014"
},
"isHardCopy": false,
"displayStatus": true,
"id": "108027",
"path": "cases/65bc97c76635d840ef59bb41/
document_1706858425443_1706858559996_Mishtry_Industries_24.pdf",
"fileName":
"document_1706858425443_1706858559996_Mishtry_Industries_24.pdf"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "12/06/1975",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
"No": "CE / 3341 / BSII / A / K"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1707121243568_BCC.pdf",
"path": "cases/65bc97c76635d840ef59bb41/document_1707121243568_BCC.pdf",
"id": "672922",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Feb 05 2024 13:50:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "remark": "bearing Nos. 821 to 825 having 5 Shares of Rs. 50/- each transferred dated 26.06.2014 in the name of Smt. Veenadevi Ganeshmal Jain issued by Mistry Industrial Complex Premises C-op. Society Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "165"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1707121394594_Share_Certificate.pdf",
  "path": "cases/65bc97c76635d840ef59bb41/document_1707121394594_Share_Certificate.pdf",
  "id": "226203",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Mon Feb 05 2024 13:53:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "18/01/2024",
    "number": {
      "value": "CA_No",
      "label": "CA No"
    },
    "CA_No": "152000614"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "521726",
    "path": "cases/65bc97c76635d840ef59bb41/
document_1707121556731_Electricity_Bill.pdf",
    "fileName": "document_1707121556731_Electricity_Bill.pdf"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f1",
      "label": "Society Maintenance Bill"
    },
    "inputs": {
      "documentDate": "01/01/2024",
      "remark": "in the name of Mrs. Veenadevi Ganeshmal Jain issued by Mistry
Industrial Complex Premises Co-op. Society Ltd.",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "321"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "791716",
    "path": "cases/65bc97c76635d840ef59bb41/
document_1707121816223_54365.pdf",
    "fileName": "document_1707121816223_54365.pdf"
  }
],
"caseNumber": "006700",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "649600",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 02 2024 12:50:39 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Veenadevi Ganeshmal Jain",
    "phone": "0000000000",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "557876"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Working Area",
    "length": "",
    "length1": "20",
    "length2": "7",
    "width": "",
    "width1": "31",
    "width2": "8",
    "totalArea": "651.80",
    "images": [],
    "finalArea": "651.80",
    "extraAreas": []
  }
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Loft",
      "value": "Loft"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "length1": "15",
    "length2": "6",
    "length": "",
    "width1": "8",
    "width2": "3",
```

```
"width": "",
"totalArea": "127.87",
"percentageBeforeTotal": "127.87",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "127.87"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "554323",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "702",
  "squareMeterArea": "65.22",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBUILTUPPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65cf4b1b19837c7e5fdddb97",
  "property": "Industrial Gala",
  "area": "790",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "9500000",
  "expectedRate": "12025.32",
```

```
    "builtUpExpectedRate": "9500000",
    "image": "cases/65bc97c76635d840ef59bb41/
indicator_1708083856967_Image.jpeg",
    "squareMeter": "73.39",
    "id": "706546"
  },
  {
    "printlnReport": true,
    "_id": "65cf4b1b19837c7e5fdddb98",
    "property": "Industrial",
    "area": "1350",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "27000000",
    "expectedRate": "20000.00",
    "builtUpExpectedRate": "27000000",
    "image": "cases/65bc97c76635d840ef59bb41/
indicator_1708083883358_Image.png",
    "squareMeter": "125.42",
    "id": "166771"
  },
  {
    "printlnReport": true,
    "_id": "65cf4b1b19837c7e5fdddb99",
    "property": "Industrial",
    "area": "1210",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "19400000",
    "expectedRate": "16033.06",
    "builtUpExpectedRate": "19400000",
    "image": "cases/65bc97c76635d840ef59bb41/
indicator_1708083897572_Image.png",
    "squareMeter": "112.41",
    "id": "689734"
  },
  {
    "printlnReport": true,
    "_id": "65cf4b1b19837c7e5fdddb9a",
    "property": "Industrial",
```



```
"area": "600",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "9000000",
"expectedRate": "15000.00",
"builtUpExpectedRate": "9000000",
"image": "cases/65bc97c76635d840ef59bb41/
indicator_1708083913884_Image.png",
"squareMeter": "55.74",
"id": "970213"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65c05cd66635d840ef5c8110",
"name": "externalImg_1707105494257_Screenshot_2024020316232301_3d9111e2
d3171bf4882369f490c087b4.jpg",
"path": "cases/65bc97c76635d840ef59bb41/externalImg_1707105494257_Screens
hot_2024020316232301_3d9111e2d3171bf4882369f490c087b4.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65c05cd66635d840ef5c8111",
"name": "externalImg_r_1707105494266_IMG20240203160003.jpg",
"path": "cases/65bc97c76635d840ef59bb41/
externalImg_r_1707105494266_IMG20240203160003.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65c05cd66635d840ef5c8112",
"name": "externalImg_r_1707105494271_IMG20240203160008.jpg",
"path": "cases/65bc97c76635d840ef59bb41/
externalImg_r_1707105494271_IMG20240203160008.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65c05cd66635d840ef5c8113",
  "name": "externalimg_r_1707105494262_TimePhoto_20240203_162015.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externalimg_r_1707105494262_TimePhoto_20240203_162015.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05cd66635d840ef5c8114",
  "name": "externalimg_r_1707105494269_IMG20240203160006.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externalimg_r_1707105494269_IMG20240203160006.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05cd66635d840ef5c8115",
  "name": "externalimg_r_1707105494274_IMG20240203161346.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externalimg_r_1707105494274_IMG20240203161346.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05cd66635d840ef5c8116",
  "name": "externalimg_r_1707105494279_TimePhoto_20240203_160338.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externalimg_r_1707105494279_TimePhoto_20240203_160338.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05cd66635d840ef5c8117",
  "name": "externalimg_r_1707105494276_TimePhoto_20240203_160328.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externalimg_r_1707105494276_TimePhoto_20240203_160328.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65c05cd66635d840ef5c8118",
    "name": "externallmg_r_1707105494282_TimePhoto_20240203_160343.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494282_TimePhoto_20240203_160343.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c8119",
    "name": "externallmg_r_1707105494284_TimePhoto_20240203_160401.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494284_TimePhoto_20240203_160401.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811a",
    "name": "externallmg_r_1707105494286_TimePhoto_20240203_160414.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494286_TimePhoto_20240203_160414.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811b",
    "name": "externallmg_r_1707105494290_TimePhoto_20240203_160434.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494290_TimePhoto_20240203_160434.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811c",
    "name": "externallmg_r_1707105494291_TimePhoto_20240203_160442.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494291_TimePhoto_20240203_160442.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811d",
```

```
    "name": "externallmg_r_1707105494293_TimePhoto_20240203_160454.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494293_TimePhoto_20240203_160454.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811e",
    "name": "externallmg_r_1707105494297_TimePhoto_20240203_160513.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494297_TimePhoto_20240203_160513.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c811f",
    "name": "externallmg_r_1707105494295_TimePhoto_20240203_160503.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494295_TimePhoto_20240203_160503.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c8120",
    "name": "externallmg_r_1707105494298_TimePhoto_20240203_160705.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494298_TimePhoto_20240203_160705.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c8121",
    "name": "externallmg_r_1707105494300_TimePhoto_20240203_160710.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494300_TimePhoto_20240203_160710.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c8122",
    "name": "externallmg_r_1707105494302_TimePhoto_20240203_160717.jpg",
```

```
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494302_TimePhoto_20240203_160717.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05cd66635d840ef5c8123",
    "name": "externallmg_r_1707105494304_TimePhoto_20240203_161218.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105494304_TimePhoto_20240203_161218.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81b8",
    "name": "externallmg_r_1707105511630_TimePhoto_20240203_161313.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511630_TimePhoto_20240203_161313.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81b9",
    "name": "externallmg_r_1707105511638_TimePhoto_20240203_162006.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511638_TimePhoto_20240203_162006.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81ba",
    "name": "externallmg_r_1707105511626_TimePhoto_20240203_161247.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511626_TimePhoto_20240203_161247.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81bb",
    "name": "externallmg_r_1707105511634_TimePhoto_20240203_161325.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511634_TimePhoto_20240203_161325.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81bc",
    "name": "externallmg_r_1707105511650_TimePhoto_20240203_162028.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511650_TimePhoto_20240203_162028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81bd",
    "name": "externallmg_r_1707105511647_TimePhoto_20240203_162011.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511647_TimePhoto_20240203_162011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81be",
    "name": "externallmg_r_1707105511642_TimePhoto_20240203_162009.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511642_TimePhoto_20240203_162009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81bf",
    "name": "externallmg_r_1707105511652_TimePhoto_20240203_162129.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511652_TimePhoto_20240203_162129.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c0",
    "name": "externallmg_r_1707105511655_TimePhoto_20240203_162132.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511655_TimePhoto_20240203_162132.jpg",
    "orientation": "portrait"
  }
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c1",
    "name": "externallmg_r_1707105511657_TimePhoto_20240203_162134.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511657_TimePhoto_20240203_162134.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c2",
    "name": "externallmg_r_1707105511660_TimePhoto_20240203_162156.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511660_TimePhoto_20240203_162156.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c3",
    "name": "externallmg_r_1707105511663_TimePhoto_20240203_162201.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511663_TimePhoto_20240203_162201.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c4",
    "name": "externallmg_r_1707105511665_TimePhoto_20240203_162212.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511665_TimePhoto_20240203_162212.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c05ce76635d840ef5c81c5",
    "name": "externallmg_r_1707105511668_TimePhoto_20240203_162246.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511668_TimePhoto_20240203_162246.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05ce76635d840ef5c81c6",
  "name": "externallmg_r_1707105511671_TimePhoto_20240203_162255.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511671_TimePhoto_20240203_162255.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05ce76635d840ef5c81c7",
  "name": "externallmg_r_1707105511673_TimePhoto_20240203_162257.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105511673_TimePhoto_20240203_162257.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05d486635d840ef5c8362",
  "name": "externallmg_r_1707105607738_IMG20240203214405.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105607738_IMG20240203214405.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c05d486635d840ef5c8363",
  "name": "externallmg_r_1707105607681_IMG20240203214354.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/
externallmg_r_1707105607681_IMG20240203214354.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1708084053463_AGR.pdf",
    "path": "cases/65bc97c76635d840ef59bb41/
processingDocuments/1708084053463_AGR.pdf",
    "size": "6497928",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
```



```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "BCC.pdf",
  "filename": "1708084053624_BCC.pdf",
  "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053624_BCC.pdf",
  "size": "303270",
  "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "EB.pdf",
  "filename": "1708084053632_EB.pdf",
  "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053632_EB.pdf",
  "size": "100818",
  "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_1707105494257_Screenshot_2024020316232301_3d9111e2d3171bf4882369f490c087b4.jpg",
  "filename": "1708084053636_externallmg_1707105494257_Screenshot_2024020316232301_3d9111e2d3171bf4882369f490c087b4.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053636_externallmg_1707105494257_Screenshot_2024020316232301_3d9111e2d3171bf4882369f490c087b4.jpg",
  "size": "189289",
  "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1707105494266_IMG20240203160003.jpg",
  "filename": "1708084053646_externallmg_r_1707105494266_IMG20240203160003.jpg",
  "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053646_externallmg_r_1707105494266_IMG20240203160003.jpg",
  "size": "54365",
  "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1707105494269_IMG20240203160006.jpg",
  "filename": "1708084053649_externallmg_r_1707105494269_IMG20240203160006.jpg",
```

```
    "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053649_externallmg_r_1707105494269_IMG20240203160006.jpg",
    "size": "53578",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1707105494271_IMG20240203160008.jpg",
    "filename":
"1708084053652_externallmg_r_1707105494271_IMG20240203160008.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053652_externallmg_r_1707105494271_IMG20240203160008.jpg",
    "size": "47677",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1707105607681_IMG20240203214354.jpg",
    "filename":
"1708084053655_externallmg_r_1707105607681_IMG20240203214354.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053655_externallmg_r_1707105607681_IMG20240203214354.jpg",
    "size": "2046258",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1707105607738_IMG20240203214405.jpg",
    "filename":
"1708084053710_externallmg_r_1707105607738_IMG20240203214405.jpg",
    "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053710_externallmg_r_1707105607738_IMG20240203214405.jpg",
    "size": "995311",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1708084053754_IGR01.pdf",
    "path": "cases/65bc97c76635d840ef59bb41/processingDocuments/1708084053754_IGR01.pdf",
    "size": "149767",
    "createdAt": "Fri Feb 16 2024 17:17:33 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
```

```
"originalname": "MB.pdf",
"filename": "1708084062726_MB.pdf",
"path": "cases/65bc97c76635d840ef59bb41/
processingDocuments/1708084062726_MB.pdf",
"size": "55621",
"createdAt": "Fri Feb 16 2024 17:17:42 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "SHARE.pdf",
"filename": "1708084062729_SHARE.pdf",
"path": "cases/65bc97c76635d840ef59bb41/
processingDocuments/1708084062729_SHARE.pdf",
"size": "911686",
"createdAt": "Fri Feb 16 2024 17:17:42 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=GALA.xlsx",
"filename": "1708084062745_Summary_NewGALA.xlsx",
"path": "cases/65bc97c76635d840ef59bb41/
processingDocuments/1708084062745_Summary_NewGALA.xlsx",
"size": "2094226",
"createdAt": "Fri Feb 16 2024 17:17:42 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "6006d4ce5080a310ac1fdfc2",
"role": "FRONTDESK",
"firstName": "Jagdish ",
"lastName": "Bhatt",
"profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"workType": "SITE_INSPECTION",
"display": true,
"status": true,
"_id": "65c05d246635d840ef5c82a4",
"note": "Photo Pending (Task Reopen)",
"taskId": "65bc9e586635d840ef59cd9d",
"createdAt": "2024-02-05T03:59:32.965Z"
```

```
    },
    {
      "createdBy": {
        "_id": "60f91b6f344e052188ffd1fc",
        "role": "MAKER",
        "firstName": "Jayaraja",
        "lastName": "Acharya",
        "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
      },
      "workType": "MAKER",
      "display": true,
      "status": true,
      "_id": "65d0883452bb6a0e76c6e1ab",
      "note": "Draft Report Shared to Sachin Joshi",
      "taskId": "65c05cf56635d840ef5c81e0",
      "createdAt": "2024-02-17T10:19:32.007Z"
    }
  ],
  "createdAt": "2024-02-02T07:20:39.636Z",
  "updatedAt": "2024-03-02T09:42:23.570Z",
  "__v": 0,
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "fullAddress": "Industrial Unit No. 24, Upper Ground Floor, Mistry Industrial Complex
Premises Co-op. Soc. Ltd., New/Current Survey No. 18(pt), 19 & 84, Hissa No. 4(pt) &
5(pt), CTS No. 237, M.I.D.C. Cross Road A, Off. Mahakali Caves Road, Village -
Mulgaon, Municipality Ward No. K-East, Andheri (East), Taluka - Andheri, District -
Mumabi Suburban, PIN - 400 093, State - Maharashtra, India",
  "updatedBy": "60eeaeddf3dd69653a581316",
  "addressForMap": "",
  "caseReferredBy": "",
  "contactPersonName": "Mr. Ramesh Rajawat",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Representative of owner",
  "siteVisitContactNo": "9975402060",
  "briefDescOfProperty": "Working Area",
  "carpetTotal": "651.8",
  "finalMeasurementType": "Sq. Ft.",
```

```
"otherCarpetTotal": "127.87",
"builtupPercentage": "20",
"finalBuiltupArea": "935.60",
"finalCarpetArea": "779.67",
"finalSalableArea": "935.60",
"salablePercentage": "0",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "127.87",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 651.80\nWooden Loft Area in
Sq. Ft. = 127.87\n<br />",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 702.00",
"buildingServicesRate": "2700",
"flatRate": "17000",
"landOtherRate": "14300",
"otherRateDetails": {
  "Loft": {
    "title": "Loft",
    "area": "127.87",
    "totalRate": "3951183.00",
    "rate": "30900.00",
    "percentage": "100.00"
  }
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Sat Mar 02 2024 17:38:06 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-02-03",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
```

```

    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			
Working Area	20'7"	31'8"	651.80
Other Composition :			
Loft	15'6"	8'3"	127.87