

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fdb72bce84bf289baaece8"
    },
    "type": "CREDITOFFICER",
    "_id": "63fdb72bce84bf289baaecea",
    "firstName": "Chaitanya",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "7011129647",
    "email": "chaitanya@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fdb72bce84bf289baaece8",
  "name": "Narsingh Nagar Branch",
  "branchCode": "",
  "mobileNo": "7011129647",
  "alternateMobileNo": "",
  "email": "abganga@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Sukhashanti heights Narsing Nagar, Gangapur Road, Nashik- 422013"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": ""
```

```
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.028094725324806",
  "longitude": "73.74619496179048"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chandashi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik ",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "195",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aaradhya Gauri-B",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Ashoka Center for Business and Computer Studies , Chandashi
Road,",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "62/1+62/2+63+64",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": " Flat No.06 ( as per Building Plan ) Family Unit as per Broacher Flat
No.202, ",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422013",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
"igrFinalRate": {
```

```
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65cc8857d93fe4510d4f563c",
"ownerName": ".Naresh Sirsath ",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. Flat No.06 ( as per Building Plan ) Family Unit as
per Broacher Flat No.202, , Basement Floor, Aaradhya Gauri-B, Near Ashoka Center
for Business and Computer Studies , Chandashi Road,, Plot No. 195, Village -
Chandashi, Taluka - Nashik , District - Nashik , Nashik , 422013",
"remark": "",
"documents": [
{
"documentType": {
"value": "60ae124aaa6d152c1801b2f7",
"label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707903033173_Naresh_Shirsath.pdf",
"path": "cases/65cc8857d93fe4510d4f563c/
document_1707903033173_Naresh_Shirsath.pdf",
"id": "736424",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Feb 14 2024 15:01:03 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae124aaa6d152c1801b2f7",
"label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707903041619_naresh_sirsath_.pdf",
"path": "cases/65cc8857d93fe4510d4f563c/
document_1707903041619_naresh_sirsath_.pdf",
"id": "496427",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Feb 14 2024 15:01:03 GMT+0530 (India Standard Time)"
}
```



```
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1707903061992_538198.pdf",
  "path": "cases/65cc8857d93fe4510d4f563c/
document_1707903061992_538198.pdf",
  "id": "775232",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Feb 14 2024 15:01:03 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006968",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "619549",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 14 2024 15:01:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": ".Naresh Sirsath ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "251498"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5846",
    "name":
"externalImg_1707903167974_WhatsApp_Image_20240208_at_24843_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externalImg_1707903167974_WhatsApp_Image_20240208_at_24843_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5847",
    "name":
"externalImg_1707903168010_WhatsApp_Image_20240208_at_24844_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externalImg_1707903168010_WhatsApp_Image_20240208_at_24844_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5848",
    "name":
"externalImg_1707903168211_WhatsApp_Image_20240208_at_24845_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externalImg_1707903168211_WhatsApp_Image_20240208_at_24845_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5849",
    "name":
"externalImg_1707903168305_WhatsApp_Image_20240208_at_24846_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externalImg_1707903168305_WhatsApp_Image_20240208_at_24846_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f584a",
```

```
    "name":
"externallmg_1707903168388_WhatsApp_Image_20240208_at_24847_PM_1.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168388_WhatsApp_Image_20240208_at_24847_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f584b",
  "name":
"externallmg_1707903168493_WhatsApp_Image_20240208_at_24847_PM_2.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168493_WhatsApp_Image_20240208_at_24847_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f584c",
  "name":
"externallmg_1707903168615_WhatsApp_Image_20240208_at_24847_PM.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168615_WhatsApp_Image_20240208_at_24847_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f584d",
  "name":
"externallmg_1707903168710_WhatsApp_Image_20240208_at_24848_PM_1.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168710_WhatsApp_Image_20240208_at_24848_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f584e",
  "name":
"externallmg_1707903168819_WhatsApp_Image_20240208_at_24848_PM_2.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168819_WhatsApp_Image_20240208_at_24848_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f584f",
  "name":
"externallmg_1707903168846_WhatsApp_Image_20240208_at_24848_PM.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903168846_WhatsApp_Image_20240208_at_24848_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f5850",
  "name":
"externallmg_1707903169004_WhatsApp_Image_20240208_at_24849_PM_1.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169004_WhatsApp_Image_20240208_at_24849_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f5851",
  "name":
"externallmg_1707903169170_WhatsApp_Image_20240208_at_24850_PM_1.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169170_WhatsApp_Image_20240208_at_24850_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f5852",
  "name":
"externallmg_1707903169254_WhatsApp_Image_20240208_at_24850_PM_2.jpeg",
  "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169254_WhatsApp_Image_20240208_at_24850_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cc88c1d93fe4510d4f5853",
  "name":
"externallmg_1707903169307_WhatsApp_Image_20240208_at_24850_PM.jpeg",
```

```
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169307_WhatsApp_Image_20240208_at_24850_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5854",
    "name":
"externallmg_1707903169359_WhatsApp_Image_20240208_at_24851_PM_1.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169359_WhatsApp_Image_20240208_at_24851_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5855",
    "name":
"externallmg_1707903169386_WhatsApp_Image_20240208_at_24851_PM_2.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169386_WhatsApp_Image_20240208_at_24851_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5856",
    "name":
"externallmg_1707903169500_WhatsApp_Image_20240208_at_24851_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903169500_WhatsApp_Image_20240208_at_24851_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5857",
    "name":
"externallmg_r_1707903169030_WhatsApp_Image_20240208_at_24849_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_r_1707903169030_WhatsApp_Image_20240208_at_24849_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5858",
    "name":
"externallmg_r_1707903168050_WhatsApp_Image_20240208_at_24845_PM_1.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_r_1707903168050_WhatsApp_Image_20240208_at_24845_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c1d93fe4510d4f5859",
    "name":
"externallmg_r_1707903169597_WhatsApp_Image_20240208_at_24852_PM_1.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_r_1707903169597_WhatsApp_Image_20240208_at_24852_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c9d93fe4510d4f58b7",
    "name":
"externallmg_1707903177221_WhatsApp_Image_20240208_at_24852_PM_2.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903177221_WhatsApp_Image_20240208_at_24852_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c9d93fe4510d4f58b8",
    "name":
"externallmg_1707903177225_WhatsApp_Image_20240208_at_24852_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903177225_WhatsApp_Image_20240208_at_24852_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c9d93fe4510d4f58b9",
    "name":
"externallmg_1707903177226_WhatsApp_Image_20240208_at_24853_PM_1.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903177226_WhatsApp_Image_20240208_at_24853_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c9d93fe4510d4f58ba",
    "name":
"externallmg_1707903177228_WhatsApp_Image_20240208_at_24853_PM_2.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903177228_WhatsApp_Image_20240208_at_24853_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cc88c9d93fe4510d4f58bb",
    "name":
"externallmg_1707903177230_WhatsApp_Image_20240208_at_24853_PM.jpeg",
    "path": "cases/65cc8857d93fe4510d4f563c/
externallmg_1707903177230_WhatsApp_Image_20240208_at_24853_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-14T09:31:03.934Z",
"updatedAt": "2024-02-14T09:32:57.877Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": ".Naresh Sirsath ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			