

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc5a"
    },
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc5d",
    "firstName": "Umesh Devchand ",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc5a",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
```

```
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.99027381610018",
  "longitude": "73.7521625305175"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  }
}
```

```
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
```

```
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shri Ram Kunj ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```



```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65d080fe52bb6a0e76c6be1c",
"ownerName": "Shri Ram Kunj",
"ownerPhoneNo": "9226502502",
"fullAddress": "Residential APF No. Basement Floor, Shri Ram Kunj , Village - Nashik,
Taluka - Nashik , District - Nashik, Nashik, 422005",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1708163232065_1_a_Details_of_encumbrances_concerned
_to_Finance.pdf",
    "path": "cases/65d080fe52bb6a0e76c6be1c/document_1708163232065_1_a_Detail
s_of_encumbrances_concerned_to_Finance.pdf",
    "id": "349086",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1708163253823_1_Annual_Audit_Report_of_Statutory_CA
_Form_5_FY_202223.pdf",
    "path": "cases/65d080fe52bb6a0e76c6be1c/document_1708163253823_1_Annual_
Audit_Report_of_Statutory_CA_Form_5_FY_202223.pdf",
    "id": "865315",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
  },
}
```



```
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1708163260131_1_Architects_Certificate_of_Percentage_of
_Completion_of_Work_Form_1.pdf",
  "path": "cases/65d080fe52bb6a0e76c6be1c/document_1708163260131_1_Architec
ts_Certificate_of_Percentage_of_Completion_of_Work_Form_1.pdf",
  "id": "131674",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1708163271790_cost_sheet.pdf",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
document_1708163271790_cost_sheet.pdf",
  "id": "553669",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "P51600049058"
},
  "isHardCopy": false,
```

```
"displayStatus": false,
"fileName": "document_1708163285030_P51600049058.pdf",
"path": "cases/65d080fe52bb6a0e76c6be1c/
document_1708163285030_P51600049058.pdf",
"id": "180336",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1708163303375_Shri_Ram_kunj__e_Brochure_.pdf",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
document_1708163303375_Shri_Ram_kunj__e_Brochure_.pdf",
  "id": "585099",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1708163320552_109526.pdf",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
document_1708163320552_109526.pdf",
  "id": "987668",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
```

```
"label": "Commercial"
},
"caseNumber": "007043",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "289711",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 17 2024 15:18:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri Ram Kunj",
    "phone": "9226502502",
    "ownershipShare": "",
    "email": "",
    "id": "339055"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2ba",
    "name":
"externalImg_1708163391795_WhatsApp_Image_20240217_at_25135_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externalImg_1708163391795_WhatsApp_Image_20240217_at_25135_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2bb",
    "name":
"externalImg_1708163391900_WhatsApp_Image_20240217_at_25136_PM_1.jpeg",
```

```
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163391900_WhatsApp_Image_20240217_at_25136_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2bc",
    "name":
"externallmg_1708163391999_WhatsApp_Image_20240217_at_25136_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163391999_WhatsApp_Image_20240217_at_25136_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2bd",
    "name":
"externallmg_1708163392122_WhatsApp_Image_20240217_at_25137_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392122_WhatsApp_Image_20240217_at_25137_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2be",
    "name":
"externallmg_1708163392175_WhatsApp_Image_20240217_at_25140_PM_1.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392175_WhatsApp_Image_20240217_at_25140_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2bf",
    "name":
"externallmg_1708163392435_WhatsApp_Image_20240217_at_25141_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392435_WhatsApp_Image_20240217_at_25141_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65d0814252bb6a0e76c6c2c0",
  "name":
"externallmg_1708163392558_WhatsApp_Image_20240217_at_25142_PM_1.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392558_WhatsApp_Image_20240217_at_25142_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0814252bb6a0e76c6c2c1",
  "name":
"externallmg_1708163392685_WhatsApp_Image_20240217_at_25142_PM.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392685_WhatsApp_Image_20240217_at_25142_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0814252bb6a0e76c6c2c2",
  "name":
"externallmg_1708163392797_WhatsApp_Image_20240217_at_25143_PM_1.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392797_WhatsApp_Image_20240217_at_25143_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0814252bb6a0e76c6c2c3",
  "name":
"externallmg_1708163392952_WhatsApp_Image_20240217_at_25143_PM.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163392952_WhatsApp_Image_20240217_at_25143_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0814252bb6a0e76c6c2c4",
  "name":
"externallmg_1708163393072_WhatsApp_Image_20240217_at_25144_PM_1.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163393072_WhatsApp_Image_20240217_at_25144_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2c5",
    "name":
"externallmg_1708163393141_WhatsApp_Image_20240217_at_25144_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163393141_WhatsApp_Image_20240217_at_25144_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2c6",
    "name":
"externallmg_1708163393220_WhatsApp_Image_20240217_at_25145_PM_1.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163393220_WhatsApp_Image_20240217_at_25145_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2c7",
    "name":
"externallmg_1708163393300_WhatsApp_Image_20240217_at_25145_PM.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163393300_WhatsApp_Image_20240217_at_25145_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2c8",
    "name":
"externallmg_1708163393464_WhatsApp_Image_20240217_at_25146_PM_1.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163393464_WhatsApp_Image_20240217_at_25146_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0814252bb6a0e76c6c2c9",
```

```
    "name":  
    "externallmg_1708163393576_WhatsApp_Image_20240217_at_25146_PM.jpeg",  
    "path": "cases/65d080fe52bb6a0e76c6be1c/  
externallmg_1708163393576_WhatsApp_Image_20240217_at_25146_PM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65d0814252bb6a0e76c6c2ca",  
    "name":  
    "externallmg_1708163393673_WhatsApp_Image_20240217_at_25147_PM_1.jpeg",  
    "path": "cases/65d080fe52bb6a0e76c6be1c/  
externallmg_1708163393673_WhatsApp_Image_20240217_at_25147_PM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65d0814252bb6a0e76c6c2cb",  
    "name":  
    "externallmg_1708163393840_WhatsApp_Image_20240217_at_25147_PM.jpeg",  
    "path": "cases/65d080fe52bb6a0e76c6be1c/  
externallmg_1708163393840_WhatsApp_Image_20240217_at_25147_PM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65d0814252bb6a0e76c6c2cc",  
    "name":  
    "externallmg_1708163393991_WhatsApp_Image_20240217_at_25148_PM_1.jpeg",  
    "path": "cases/65d080fe52bb6a0e76c6be1c/  
externallmg_1708163393991_WhatsApp_Image_20240217_at_25148_PM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65d0814252bb6a0e76c6c2cd",  
    "name":  
    "externallmg_r_1708163392312_WhatsApp_Image_20240217_at_25140_PM_2.jpeg",  
    "path": "cases/65d080fe52bb6a0e76c6be1c/  
externallmg_r_1708163392312_WhatsApp_Image_20240217_at_25140_PM_2.jpeg",  
    "orientation": "portrait"  
  },  
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0815252bb6a0e76c6c322",
  "name":
"externallmg_1708163408714_WhatsApp_Image_20240217_at_25136_PM_2.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163408714_WhatsApp_Image_20240217_at_25136_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0815252bb6a0e76c6c323",
  "name":
"externallmg_1708163408841_WhatsApp_Image_20240217_at_25139_PM.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163408841_WhatsApp_Image_20240217_at_25139_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0815252bb6a0e76c6c324",
  "name":
"externallmg_1708163408998_WhatsApp_Image_20240217_at_25140_PM.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163408998_WhatsApp_Image_20240217_at_25140_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0815252bb6a0e76c6c325",
  "name":
"externallmg_1708163409162_WhatsApp_Image_20240217_at_25142_PM_2.jpeg",
  "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409162_WhatsApp_Image_20240217_at_25142_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d0815252bb6a0e76c6c326",
  "name":
"externallmg_1708163409265_WhatsApp_Image_20240217_at_25143_PM_2.jpeg",
```



```
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409265_WhatsApp_Image_20240217_at_25143_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0815252bb6a0e76c6c327",
    "name":
"externallmg_1708163409365_WhatsApp_Image_20240217_at_25144_PM_2.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409365_WhatsApp_Image_20240217_at_25144_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0815252bb6a0e76c6c328",
    "name":
"externallmg_1708163409453_WhatsApp_Image_20240217_at_25145_PM_2.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409453_WhatsApp_Image_20240217_at_25145_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0815252bb6a0e76c6c329",
    "name":
"externallmg_1708163409581_WhatsApp_Image_20240217_at_25146_PM_2.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409581_WhatsApp_Image_20240217_at_25146_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0815252bb6a0e76c6c32a",
    "name":
"externallmg_1708163409738_WhatsApp_Image_20240217_at_25147_PM_2.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externallmg_1708163409738_WhatsApp_Image_20240217_at_25147_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "65d0815252bb6a0e76c6c32b",
    "name":
"externalImg_1708163409941_WhatsApp_Image_20240217_at_25148_PM_1.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externalImg_1708163409941_WhatsApp_Image_20240217_at_25148_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d0815252bb6a0e76c6c32c",
    "name":
"externalImg_1708163410093_WhatsApp_Image_20240217_at_25148_PM_2.jpeg",
    "path": "cases/65d080fe52bb6a0e76c6be1c/
externalImg_1708163410093_WhatsApp_Image_20240217_at_25148_PM_2.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-17T09:48:46.460Z",
"updatedAt": "2024-02-17T09:50:10.398Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Shri Ram Kunj",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9226502502"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---