

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "644bb5d9ba47a23af30ea5a9"
    },
    "type": "CREDITOFFICER",
    "_id": "64abe9a306d6ec17498752f3",
    "firstName": "Amit",
    "lastName": "Srivastava",
    "mobileNo": "",
    "workMobileNo": "9740297466",
    "email": "ubin0555843@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "63100000",
    "discussWithPerson": "Amit",
    "expectedFees": 31550,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "644bb5d9ba47a23af30ea5a9",
  "name": "Sakinaka Branch ",
  "branchCode": "",
  "mobileNo": "2228562040",
  "alternateMobileNo": "",
  "email": "ubin0555843@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Unit No. 8 & 9, Silver Satelite, Andheri Kurla Road, Near Marol Naka,
Metro Station, \nSakinaka, Andheri (East), Mumbai - 400059, State - Maharashtra,
Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        }
      },
    ]
  }
],
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.99689439313239",
  "longitude": "72.8251392177082"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8251392177082,
    18.99689439313239
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/02/2024 05:35 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Lower Parel",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "29",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
```

```
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Marathin Nexrt",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gen Veer Santaji Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2902",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Lower Parel",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```



```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65d32f3d4125726f9016209c",
"ownerName": "Parul Samir Rokadia ",
"ownerPhoneNo": "9987681274",
"appAddress": "Flat no 2902 29 th floor Marathon NextGen Veer Santaji Marg off
Ganpat Roa Kadam Marg Lower Parel 400013",
"remark": "DSA Amit Mahta CA contact no hey ",
"documents": [
{
"documentType": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/65d32f3d4125726f9016209c/
document_1708338889234_1708339040314_Agreement_2902.pdf",
"fileName": "document_1708338889234_1708339040314_Agreement_2902.pdf",
"id": "741659",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Feb 19 2024 16:06:45 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007060",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
{
"id": "388966",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Feb 19 2024 16:06:45 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
```

```
"name": "Parul Samir Rokadia ",
"phone": "9987681274",
"ownershipShare": "",
"email": "",
"id": "114502"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65d57beccf7ad63a0af87b47",
  "name": "externalImg_1708489699176_1708489850748_image_0.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externalImg_1708489699176_1708489850748_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65d57beccf7ad63a0af87b48",
  "name": "externalImg_1708489704787_1708489850748_image_1.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externalImg_1708489704787_1708489850748_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65d57beccf7ad63a0af87b49",
  "name": "externalImg_1708489705671_1708489850748_image_2.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externalImg_1708489705671_1708489850748_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65d57db1cf7ad63a0af8823c",
    "name": "externallmg_1708490137836_1708490287872_image_0.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490137836_1708490287872_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af8823d",
    "name": "externallmg_1708490137902_1708490287872_image_1.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490137902_1708490287872_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af8823e",
    "name": "externallmg_1708490138260_1708490287872_image_2.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490138260_1708490287872_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af8823f",
    "name": "externallmg_1708490138924_1708490287872_image_3.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490138924_1708490287872_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88240",
    "name": "externallmg_1708490139631_1708490287872_image_4.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490139631_1708490287872_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88241",
```

```
    "name": "externallmg_1708490140200_1708490287872_image_5.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490140200_1708490287872_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88242",
    "name": "externallmg_1708490140645_1708490287872_image_6.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490140645_1708490287872_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88243",
    "name": "externallmg_1708490141763_1708490287872_image_7.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490141763_1708490287872_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88244",
    "name": "externallmg_1708490143621_1708490287872_image_8.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490143621_1708490287872_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88245",
    "name": "externallmg_1708490147716_1708490287872_image_9.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490147716_1708490287872_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88246",
    "name": "externallmg_1708490147848_1708490287872_image_10.jpeg",
```

```
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490147848_1708490287872_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88247",
    "name": "externallmg_1708490148895_1708490287872_image_11.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490148895_1708490287872_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88248",
    "name": "externallmg_1708490149366_1708490287872_image_12.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490149366_1708490287872_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af88249",
    "name": "externallmg_1708490154051_1708490287872_image_13.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490154051_1708490287872_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af8824a",
    "name": "externallmg_1708490155009_1708490287872_image_14.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490155009_1708490287872_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d57db1cf7ad63a0af8824b",
    "name": "externallmg_1708490156353_1708490287872_image_15.jpeg",
    "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490156353_1708490287872_image_15.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57db1cf7ad63a0af8824c",
  "name": "externallmg_1708490156818_1708490287872_image_16.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490156818_1708490287872_image_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57db1cf7ad63a0af8824d",
  "name": "externallmg_1708490159396_1708490287872_image_17.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490159396_1708490287872_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57dfbcf7ad63a0af88340",
  "name": "externallmg_1708490229986_1708490381347_image_0.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490229986_1708490381347_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57dfbcf7ad63a0af88341",
  "name": "externallmg_1708490231540_1708490381347_image_1.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490231540_1708490381347_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57dfbcf7ad63a0af88342",
  "name": "externallmg_1708490231778_1708490381347_image_2.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490231778_1708490381347_image_2.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65d57dfbcf7ad63a0af88343",
      "name": "externallmg_1708490232251_1708490381347_image_3.jpeg",
      "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490232251_1708490381347_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65d57dfbcf7ad63a0af88344",
      "name": "externallmg_1708490232837_1708490381347_image_4.jpeg",
      "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490232837_1708490381347_image_4.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65d57dfbcf7ad63a0af88345",
      "name": "externallmg_1708490233514_1708490381347_image_5.jpeg",
      "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490233514_1708490381347_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65d57dfbcf7ad63a0af88346",
      "name": "externallmg_1708490233724_1708490381347_image_6.jpeg",
      "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490233724_1708490381347_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65d57dfbcf7ad63a0af88347",
      "name": "externallmg_1708490234081_1708490381347_image_7.jpeg",
      "path": "cases/65d32f3d4125726f9016209c/
externallmg_1708490234081_1708490381347_image_7.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65d57dfbcf7ad63a0af88348",
  "name": "externalImg_1708490234458_1708490381347_image_8.jpeg",
  "path": "cases/65d32f3d4125726f9016209c/
externalImg_1708490234458_1708490381347_image_8.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "IGR-01.pdf",
    "filename": "1708413220470_IGR01.pdf",
    "path": "cases/65d32f3d4125726f9016209c/
processingDocuments/1708413220470_IGR01.pdf",
    "size": "163400",
    "createdAt": "Tue Feb 20 2024 12:43:40 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1708413220476_IGR02.pdf",
    "path": "cases/65d32f3d4125726f9016209c/
processingDocuments/1708413220476_IGR02.pdf",
    "size": "160843",
    "createdAt": "Tue Feb 20 2024 12:43:40 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
  }
]
```



```

    "_id": "65d4519ecf7ad63a0af774e4",
    "note": "Given Approx Value",
    "taskId": "65d45128cf7ad63a0af77147",
    "createdAt": "2024-02-20T07:15:42.926Z"
  }
],
"createdAt": "2024-02-19T10:36:45.281Z",
"updatedAt": "2024-02-21T04:37:15.209Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 2902, 29th Floor, Marathin Nexrt, Gen Veer Santaji
Marg, Village - Lower Parel, Lower Parel, Mumbai",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Parul Samir Rokadia ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9987681274"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			