

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65d5a289cf7ad63a0af90ae7"
    },
    "type": "CREDITOFFICER",
    "_id": "65d5a289cf7ad63a0af90ae9",
    "firstName": "Sharad",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7303850049",
    "email": "bo123110@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20333330",
    "discussWithPerson": "Sharad",
    "expectedFees": 10166.665,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65d5a289cf7ad63a0af90ae7",
  "name": "Bangur Nagar Branch",
  "branchCode": "123110",
  "mobileNo": "02223843172",
  "alternateMobileNo": "",
  "email": "bo123110@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, Max Heal House, Opp Ayyappa Mandir Bangur Nagar Police
CHawk, Goregaon West Mumbai 400104"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc575ece84bf289ba9e82d",
    "role": "SITEENGINEER",
    "firstName": "Deepak ",
    "email": "daksh7831@gmail.com",
    "lastName": "Jain ",
    "mobileNo": "9022815908",
    "designation": "",
    "shortName": "DJ",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    }
  ]
}
```

```
],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.214119137196267",
  "longitude": "72.86224419074846"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86224419074846,
    19.214119137196267
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
```

```
{
  "dateTime": "21/02/2024 03:18 pm"
},
{
  "dateTime": "21/02/2024 12:00 am"
}
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Poisar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
},
```

```
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Vasant Smruti CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "90 Feet Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Thakur Complex",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```

```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "801",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```



```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
```

```
    "name": "Suburb",
    "key": "suburb",
    "value": "Kandivali East",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65d5a8ddcf7ad63a0af9212e",
"ownerName": "Master Vedant Nishant Wadwalkar ",
"ownerPhoneNo": "9930702073",
"appAddress": "Flat no 801 D Wing Vasant Smruti CHS Ltd 90 ft road Thanku Village
kandivali East 400101",
"remark": "9372391609 Rupa Singh ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
document_1708501098590_1708501249051_imgZ29141920_rotated.pdf",
    "fileName":
"document_1708501098590_1708501249051_imgZ29141920_rotated.pdf",
    "id": "798872",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Feb 21 2024 13:10:13 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007101",
```



```
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "320479",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Feb 21 2024 13:10:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Master Vedant Nishant Wadwalkar ",
    "phone": "9930702073",
    "ownershipShare": "",
    "email": "",
    "id": "482467"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e4797",
    "name": "externalImg_1708746896121_IMG20240224WA0002.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896121_IMG20240224WA0002.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e4798",
    "name": "externalImg_1708746896122_IMG20240224WA0004.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896122_IMG20240224WA0004.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e4799",
    "name": "externalImg_1708746896129_IMG20240224WA0005.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896129_IMG20240224WA0005.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e479a",
    "name": "externalImg_1708746896133_IMG20240224WA0006.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896133_IMG20240224WA0006.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e479b",
    "name": "externalImg_1708746896136_IMG20240224WA0008.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896136_IMG20240224WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e479c",
    "name": "externalImg_1708746896141_IMG20240224WA0009.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896141_IMG20240224WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e479d",
    "name": "externalImg_1708746896146_IMG20240224WA0010.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746896146_IMG20240224WA0010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65d96890df99cf0e735e479e",
    "name": "externalimg_1708746896151_IMG20240224WA0011.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746896151_IMG20240224WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e479f",
    "name": "externalimg_1708746896155_IMG20240224WA0012.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746896155_IMG20240224WA0012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d96890df99cf0e735e47a0",
    "name": "externalimg_1708746896159_IMG20240224WA0014.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746896159_IMG20240224WA0014.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e494c",
    "name": "externalimg_1708746909722_IMG20240224WA0015.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909722_IMG20240224WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e494d",
    "name": "externalimg_1708746909726_IMG20240224WA0016.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909726_IMG20240224WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65d9689edf99cf0e735e494e",
    "name": "externalimg_1708746909728_IMG20240224WA00172.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909728_IMG20240224WA00172.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e494f",
    "name": "externalimg_1708746909835_IMG20240224WA0017.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909835_IMG20240224WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4950",
    "name": "externalimg_1708746909837_IMG20240224WA0018.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909837_IMG20240224WA0018.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4951",
    "name": "externalimg_1708746909843_IMG20240224WA0021.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909843_IMG20240224WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4952",
    "name": "externalimg_1708746909844_IMG20240224WA0023.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalimg_1708746909844_IMG20240224WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4953",
```

```
    "name": "externalImg_1708746909855_IMG20240224WA0003.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746909855_IMG20240224WA0003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4954",
    "name": "externalImg_1708746909856_IMG20240224WA0019.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746909856_IMG20240224WA0019.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4955",
    "name": "externalImg_1708746909858_IMG20240224WA0022.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746909858_IMG20240224WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4956",
    "name": "externalImg_1708746909859_IMG20240224WA0024.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746909859_IMG20240224WA0024.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4957",
    "name": "externalImg_1708746909861_IMG20240224WA0025.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externalImg_1708746909861_IMG20240224WA0025.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4958",
    "name": "externalImg_1708746909861_IMG20240224WA0026.jpg",
```

```
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externallmg_1708746909861_IMG20240224WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e4959",
    "name": "externallmg_r_1708746909853_IMG20240224WA0028.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externallmg_r_1708746909853_IMG20240224WA0028.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65d9689edf99cf0e735e495a",
    "name": "externallmg_r_1708746909850_IMG20240224WA0027.jpg",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
externallmg_r_1708746909850_IMG20240224WA0027.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1708600048443_AGR.pdf",
    "path": "cases/65d5a8ddcf7ad63a0af9212e/
processingDocuments/1708600048443_AGR.pdf",
    "size": "59955147",
    "createdAt": "Thu Feb 22 2024 16:37:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
profilePhoto_1626255068979_Shymam_Photo.jpg"
```

```

    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65d72a8ccf7ad63a0afbbc3c",
    "note": "Given Approx Value Rs. 95 Lakhs",
    "taskId": "65d5c64fcf7ad63a0af95e44",
    "createdAt": "2024-02-22T11:05:48.318Z"
  }
],
"createdAt": "2024-02-21T07:40:13.346Z",
"updatedAt": "2024-02-24T03:55:10.001Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 801, 8th Floor, Wing - D, Vasant Smruti CHSL, 90 Feet Road, Thakur Complex, Village - Poisar, Kandivali East, Mumbai, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Master Vedant Nishant Wadwalkar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930702073"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			