

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f5a",
    "firstName": "Amruta ",
    "email": "amruta.pathak@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9769900929",
    "lastName": "Pathak"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
( East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720e52afd7d55eddedc887",
  "role": "PICKUPPERSON",
  "firstName": "Harshad",
  "email": "harshad@vastukala.org",
  "lastName": "Panchal",
  "mobileNo": "9029575553",
  "designation": "",
  "shortName": "HP",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.25741020155522",
  "longitude": "72.86010403069957"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chikanghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Kalyan (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sadguru Chhaya Co-Op. Hsg. Soc. Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
}
```

```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "93-A/1/1 Part",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```



```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "05",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```



```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65dc5357df99cf0e73611412",
"ownerName": "Mrs. Namita Nandkishor Borker & Mr. Nandkishor Yeshwant Borker",
"ownerPhoneNo": "9930804849",
"fullAddress": "Residential Flat No. 05, 2nd Floor, Sadguru Chhaya Co-Op. Hsg. Soc.
Ltd, Village - Chikanghar, Taluka - Kalyan, District - Thane, Kalyan (West), PIN Code -
421 301, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/05/2010",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Sadanand Appaji Deshmukh",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Namita Nandkishor Borker & Mr. Nandkishor Yeshwant Borker",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "4947/2010"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1708938060281_BORKAR_AGREEMENT.pdf",
    "path": "cases/65dc5357df99cf0e73611412/
document_1708938060281_BORKAR_AGREEMENT.pdf",
    "id": "359419",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Mon Feb 26 2024 14:31:11 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60af48bf2ffdf65bcd6585fa",
  "label": "Agreement for sale"
},
"inputs": {
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mrs. Namita Nandkishor Borker & Mr. Nandkishor Yeshwant Borker",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Shrikant Raghunath Dewlalkar, Mr. Kalpak Shrikant Dewlalkar &
Mrs. Dipali Kalpak Dewlalkar",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "0000"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709121399957_86311.pdf",
"path": "cases/65dc5357df99cf0e73611412/document_1709121399957_86311.pdf",
"id": "213183",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Wed Feb 28 2024 17:27:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1709121442900_109221.pdf",
  "path": "cases/65dc5357df99cf0e73611412/
document_1709121442900_109221.pdf",
```

```
"id": "670289",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Wed Feb 28 2024 17:27:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/04/1981",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Mahanagarpalika",
      "label": "Kalyan Mahanagarpalika"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "PWD / 22 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709188350512_150520.pdf",
  "path": "cases/65dc5357df99cf0e73611412/
document_1709188350512_150520.pdf",
  "id": "888433",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu Feb 29 2024 12:02:30 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007241",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "419066",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Feb 26 2024 14:31:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mrs. Namita Nandkishor Borker & Mr. Nandkishor Yeshwant Borker",
  "phone": "9930804849",
  "ownershipShare": "",
  "email": "",
  "id": "845515"
}
],
"proposePurchasers": [
  {
    "name": "Mr. Shrikant Raghunath Dewlalkar, Mr. Kalpak Shrikant Dewlalkar & Mrs.
Dipali Kalpak Dewlalkar"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87a9df99cf0e736206ae",
    "name":
"externallmg_1708951465271_WhatsApp_Image_20240226_at_61057_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465271_WhatsApp_Image_20240226_at_61057_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87a9df99cf0e736206af",
    "name":
"externallmg_1708951465325_WhatsApp_Image_20240226_at_61058_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465325_WhatsApp_Image_20240226_at_61058_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87a9df99cf0e736206b0",
```

```
"name":
"externallmg_1708951465385_WhatsApp_Image_20240226_at_61059_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465385_WhatsApp_Image_20240226_at_61059_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b1",
  "name":
"externallmg_1708951465445_WhatsApp_Image_20240226_at_61059_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465445_WhatsApp_Image_20240226_at_61059_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b2",
  "name":
"externallmg_1708951465510_WhatsApp_Image_20240226_at_61100_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465510_WhatsApp_Image_20240226_at_61100_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b3",
  "name":
"externallmg_1708951465572_WhatsApp_Image_20240226_at_61101_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465572_WhatsApp_Image_20240226_at_61101_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b4",
  "name":
"externallmg_1708951465619_WhatsApp_Image_20240226_at_61101_PM_2.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465619_WhatsApp_Image_20240226_at_61101_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b5",
  "name":
"externallmg_1708951465664_WhatsApp_Image_20240226_at_61101_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465664_WhatsApp_Image_20240226_at_61101_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b6",
  "name":
"externallmg_1708951465710_WhatsApp_Image_20240226_at_61103_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465710_WhatsApp_Image_20240226_at_61103_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b7",
  "name":
"externallmg_1708951465740_WhatsApp_Image_20240226_at_61103_PM_2.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465740_WhatsApp_Image_20240226_at_61103_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b8",
  "name":
"externallmg_1708951465754_WhatsApp_Image_20240226_at_61104_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465754_WhatsApp_Image_20240226_at_61104_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87a9df99cf0e736206b9",
  "name":
"externallmg_1708951465776_WhatsApp_Image_20240226_at_61105_PM.jpeg",
```

```
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465776_WhatsApp_Image_20240226_at_61105_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87a9df99cf0e736206ba",
    "name":
"externallmg_1708951465793_WhatsApp_Image_20240226_at_61106_PM_1.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951465793_WhatsApp_Image_20240226_at_61106_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87d1df99cf0e73620708",
    "name":
"externallmg_1708951505197_WhatsApp_Image_20240226_at_61106_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505197_WhatsApp_Image_20240226_at_61106_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87d1df99cf0e73620709",
    "name":
"externallmg_1708951505208_WhatsApp_Image_20240226_at_61107_PM_1.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505208_WhatsApp_Image_20240226_at_61107_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87d1df99cf0e7362070a",
    "name":
"externallmg_1708951505223_WhatsApp_Image_20240226_at_61107_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505223_WhatsApp_Image_20240226_at_61107_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65dc87d1df99cf0e7362070b",
  "name":
"externallmg_1708951505237_WhatsApp_Image_20240226_at_61108_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505237_WhatsApp_Image_20240226_at_61108_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e7362070c",
  "name":
"externallmg_1708951505250_WhatsApp_Image_20240226_at_61108_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505250_WhatsApp_Image_20240226_at_61108_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e7362070d",
  "name":
"externallmg_1708951505271_WhatsApp_Image_20240226_at_61109_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505271_WhatsApp_Image_20240226_at_61109_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e7362070e",
  "name":
"externallmg_1708951505286_WhatsApp_Image_20240226_at_61109_PM_2.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505286_WhatsApp_Image_20240226_at_61109_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e7362070f",
  "name":
"externallmg_1708951505305_WhatsApp_Image_20240226_at_61109_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505305_WhatsApp_Image_20240226_at_61109_PM.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620710",
  "name":
  "externallmg_1708951505317_WhatsApp_Image_20240226_at_61110_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505317_WhatsApp_Image_20240226_at_61110_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620711",
  "name":
  "externallmg_1708951505333_WhatsApp_Image_20240226_at_61110_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505333_WhatsApp_Image_20240226_at_61110_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620712",
  "name":
  "externallmg_1708951505345_WhatsApp_Image_20240226_at_61111_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505345_WhatsApp_Image_20240226_at_61111_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620713",
  "name":
  "externallmg_1708951505359_WhatsApp_Image_20240226_at_61111_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505359_WhatsApp_Image_20240226_at_61111_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620714",
```

```
    "name":
"externallmg_1708951505377_WhatsApp_Image_20240226_at_61112_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505377_WhatsApp_Image_20240226_at_61112_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620715",
  "name":
"externallmg_1708951505395_WhatsApp_Image_20240226_at_61112_PM_2.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505395_WhatsApp_Image_20240226_at_61112_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620716",
  "name":
"externallmg_1708951505411_WhatsApp_Image_20240226_at_61112_PM_3.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505411_WhatsApp_Image_20240226_at_61112_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87d1df99cf0e73620717",
  "name":
"externallmg_1708951505430_WhatsApp_Image_20240226_at_61112_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951505430_WhatsApp_Image_20240226_at_61112_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e7362078f",
  "name":
"externallmg_1708951531346_WhatsApp_Image_20240226_at_61113_PM_1.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531346_WhatsApp_Image_20240226_at_61113_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e73620790",
  "name":
"externallmg_1708951531382_WhatsApp_Image_20240226_at_61113_PM_2.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531382_WhatsApp_Image_20240226_at_61113_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e73620791",
  "name":
"externallmg_1708951531423_WhatsApp_Image_20240226_at_61113_PM_3.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531423_WhatsApp_Image_20240226_at_61113_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e73620792",
  "name":
"externallmg_1708951531445_WhatsApp_Image_20240226_at_61113_PM_4.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531445_WhatsApp_Image_20240226_at_61113_PM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e73620793",
  "name":
"externallmg_1708951531468_WhatsApp_Image_20240226_at_61113_PM.jpeg",
  "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531468_WhatsApp_Image_20240226_at_61113_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65dc87ebdf99cf0e73620794",
  "name":
"externallmg_1708951531507_WhatsApp_Image_20240226_at_61114_PM_1.jpeg",
```

```
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531507_WhatsApp_Image_20240226_at_61114_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87ebdf99cf0e73620795",
    "name":
"externallmg_1708951531534_WhatsApp_Image_20240226_at_61114_PM_2.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531534_WhatsApp_Image_20240226_at_61114_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87ebdf99cf0e73620796",
    "name":
"externallmg_1708951531562_WhatsApp_Image_20240226_at_61114_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531562_WhatsApp_Image_20240226_at_61114_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87ebdf99cf0e73620797",
    "name":
"externallmg_1708951531591_WhatsApp_Image_20240226_at_61306_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531591_WhatsApp_Image_20240226_at_61306_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65dc87ebdf99cf0e73620798",
    "name":
"externallmg_1708951531640_WhatsApp_Image_20240226_at_61307_PM.jpeg",
    "path": "cases/65dc5357df99cf0e73611412/
externallmg_1708951531640_WhatsApp_Image_20240226_at_61307_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [  
  {  
    "originalname": "cosmos - calculation - namita.xlsx",  
    "filename": "1709183687428_cosmos__calculation__namita.xlsx",  
    "path": "cases/65dc5357df99cf0e73611412/  
processingDocuments/1709183687428_cosmos__calculation__namita.xlsx",  
    "size": "16896",  
    "createdAt": "Thu Feb 29 2024 10:44:47 GMT+0530 (India Standard Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "igr1.pdf",  
    "filename": "1709183687430_igr1.pdf",  
    "path": "cases/65dc5357df99cf0e73611412/  
processingDocuments/1709183687430_igr1.pdf",  
    "size": "471892",  
    "createdAt": "Thu Feb 29 2024 10:44:47 GMT+0530 (India Standard Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "igr2.pdf",  
    "filename": "1709183687475_igr2.pdf",  
    "path": "cases/65dc5357df99cf0e73611412/  
processingDocuments/1709183687475_igr2.pdf",  
    "size": "497643",  
    "createdAt": "Thu Feb 29 2024 10:44:47 GMT+0530 (India Standard Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "igr3.pdf",  
    "filename": "1709183687515_igr3.pdf",  
    "path": "cases/65dc5357df99cf0e73611412/  
processingDocuments/1709183687515_igr3.pdf",  
    "size": "448886",  
    "createdAt": "Thu Feb 29 2024 10:44:47 GMT+0530 (India Standard Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  },  
  {  
    "originalname": "Summary - namita.xlsx",  
    "filename": "1709183687553_Summary__namita.xlsx",  
    "path": "cases/65dc5357df99cf0e73611412/  
processingDocuments/1709183687553_Summary__namita.xlsx",  
    "size": "2917180",  
    "createdAt": "Thu Feb 29 2024 10:44:47 GMT+0530 (India Standard Time)",  
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"  
  }  
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-26T09:01:11.647Z",
"updatedAt": "2024-02-29T06:32:30.612Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Namita Nandkishor Borker & Mr. Nandkishor Yeshwant
Borker",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mr. Shrikant Raghunath Dewlalkar, Mr. Kalpak Shrikant
Dewlalkar & Mrs. Dipali Kalpak Dewlalkar",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930804849"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			