

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64acf2bed9a15943959dd27d"
    },
    "type": "CREDITOFFICER",
    "_id": "65e5bff8f9222577acb9632c",
    "firstName": "Ravi Prakash ",
    "lastName": "Vishwakarma ",
    "mobileNo": "",
    "workMobileNo": "8605750880",
    "email": "ravi.vishwakarma@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "500000",
    "discussWithPerson": "Ravi Prakash ",
    "expectedFees": 250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64acf2bed9a15943959dd27d",
  "name": "SME Loan Factory MMWR (Head)",
  "branchCode": "",
  "mobileNo": "9425321969",
  "alternateMobileNo": "",
  "email": "cpc.sme.mmwr@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Sharda Bhavan, Opp. Mithibai Collage Juhu Vile Parle (West), Mumbai -
400 056"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af6ae22ffdf65bcd65861d",
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
```

```
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.232016792008427",
  "longitude": "72.85466925882423"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85466925882423,
    19.232016792008427
  ]
}
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "5/03/2024 10:55 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Borivali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "3",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krishna Nagar CHSL",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Chandavarkar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```

```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```



```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
```

```
    "key": "suburb",
    "value": "Borivali West",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65e69e26f9222577acb98e2b",
"ownerName": "Manjulaben Hansraj Shah ",
"ownerPhoneNo": "9619104010",
"appAddress": "Flat no 1 Ground floor Bldg no 3 Krishna Nagar CHS Ltd
Chandavarkar Road Borivali West 400092",
"remark": "O.c copy/Plan copy / C.C copy pending hey Engineer ko bolo visit time
leneko customer se ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65e69e26f9222577acb98e2b/document_1709612505425_17096126
62770_Bob_Manjulaben_H_Shah_Flat_no_1.pdf",
    "fileName": "document_1709612505425_1709612662770_Bob_Manjulaben_H_Sha
h_Flat_no_1.pdf",
    "id": "173811",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Mar 05 2024 09:53:02 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007437",
```



```
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "256969",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 05 2024 09:53:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Manjulaben Hansraj Shah ",
    "phone": "9619104010",
    "ownershipShare": "",
    "email": "",
    "id": "188449"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e909",
    "name":
"externallmg_1709617987255_WhatsApp_Image_20240305_at_112354_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987255_WhatsApp_Image_20240305_at_112354_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e90a",
    "name":
"externallmg_1709617987262_WhatsApp_Image_20240305_at_112355_AM_1.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987262_WhatsApp_Image_20240305_at_112355_AM_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e6b343f9222577acb9e90b",
      "name":
"externallmg_1709617987270_WhatsApp_Image_20240305_at_112355_AM.jpeg",
      "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987270_WhatsApp_Image_20240305_at_112355_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e6b343f9222577acb9e90c",
      "name":
"externallmg_1709617987277_WhatsApp_Image_20240305_at_112357_AM_1.jpeg",
      "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987277_WhatsApp_Image_20240305_at_112357_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e6b343f9222577acb9e90d",
      "name":
"externallmg_1709617987282_WhatsApp_Image_20240305_at_112357_AM_2.jpeg",
      "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987282_WhatsApp_Image_20240305_at_112357_AM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e6b343f9222577acb9e90e",
      "name":
"externallmg_1709617987285_WhatsApp_Image_20240305_at_112357_AM.jpeg",
      "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987285_WhatsApp_Image_20240305_at_112357_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e6b343f9222577acb9e90f",
      "name":
"externallmg_1709617987289_WhatsApp_Image_20240305_at_112358_AM.jpeg",
```

```
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987289_WhatsApp_Image_20240305_at_112358_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e910",
    "name":
"externallmg_1709617987294_WhatsApp_Image_20240305_at_112359_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987294_WhatsApp_Image_20240305_at_112359_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e911",
    "name":
"externallmg_1709617987296_WhatsApp_Image_20240305_at_112400_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987296_WhatsApp_Image_20240305_at_112400_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e912",
    "name":
"externallmg_1709617987300_WhatsApp_Image_20240305_at_112402_AM_1.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987300_WhatsApp_Image_20240305_at_112402_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e913",
    "name":
"externallmg_1709617987302_WhatsApp_Image_20240305_at_112402_AM_2.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987302_WhatsApp_Image_20240305_at_112402_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65e6b343f9222577acb9e914",
    "name":
"externallmg_1709617987305_WhatsApp_Image_20240305_at_112402_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987305_WhatsApp_Image_20240305_at_112402_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e915",
    "name":
"externallmg_1709617987309_WhatsApp_Image_20240305_at_112405_AM_1.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987309_WhatsApp_Image_20240305_at_112405_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e916",
    "name":
"externallmg_1709617987311_WhatsApp_Image_20240305_at_112405_AM_2.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987311_WhatsApp_Image_20240305_at_112405_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e917",
    "name":
"externallmg_1709617987314_WhatsApp_Image_20240305_at_112405_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987314_WhatsApp_Image_20240305_at_112405_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e918",
    "name":
"externallmg_1709617987318_WhatsApp_Image_20240305_at_112407_AM_1.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987318_WhatsApp_Image_20240305_at_112407_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e919",
    "name":
"externallmg_1709617987321_WhatsApp_Image_20240305_at_112407_AM_2.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987321_WhatsApp_Image_20240305_at_112407_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b343f9222577acb9e91a",
    "name":
"externallmg_1709617987327_WhatsApp_Image_20240305_at_112407_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617987327_WhatsApp_Image_20240305_at_112407_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9e1",
    "name":
"externallmg_1709617999042_WhatsApp_Image_20240305_at_112407_AM_2.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999042_WhatsApp_Image_20240305_at_112407_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9e2",
    "name":
"externallmg_1709617999046_WhatsApp_Image_20240305_at_112407_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999046_WhatsApp_Image_20240305_at_112407_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9e3",
```

```
"name":
"externallmg_1709617999051_WhatsApp_Image_20240305_at_112408_AM.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999051_WhatsApp_Image_20240305_at_112408_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e4",
  "name":
"externallmg_1709617999056_WhatsApp_Image_20240305_at_112409_AM_1.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999056_WhatsApp_Image_20240305_at_112409_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e5",
  "name":
"externallmg_1709617999060_WhatsApp_Image_20240305_at_112409_AM.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999060_WhatsApp_Image_20240305_at_112409_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e6",
  "name":
"externallmg_1709617999065_WhatsApp_Image_20240305_at_112410_AM_1.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999065_WhatsApp_Image_20240305_at_112410_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e7",
  "name":
"externallmg_1709617999070_WhatsApp_Image_20240305_at_112410_AM.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999070_WhatsApp_Image_20240305_at_112410_AM.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e8",
  "name":
"externallmg_1709617999075_WhatsApp_Image_20240305_at_112411_AM_1.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999075_WhatsApp_Image_20240305_at_112411_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9e9",
  "name":
"externallmg_1709617999080_WhatsApp_Image_20240305_at_112411_AM.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999080_WhatsApp_Image_20240305_at_112411_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9ea",
  "name":
"externallmg_1709617999084_WhatsApp_Image_20240305_at_112412_AM.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999084_WhatsApp_Image_20240305_at_112412_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9eb",
  "name":
"externallmg_1709617999091_WhatsApp_Image_20240305_at_112346_AM_1.jpeg",
  "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999091_WhatsApp_Image_20240305_at_112346_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e6b34ff9222577acb9e9ec",
  "name":
"externallmg_1709617999097_WhatsApp_Image_20240305_at_112346_AM.jpeg",
```

```
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999097_WhatsApp_Image_20240305_at_112346_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9ed",
    "name":
"externallmg_1709617999102_WhatsApp_Image_20240305_at_112347_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999102_WhatsApp_Image_20240305_at_112347_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9ee",
    "name":
"externallmg_1709617999108_WhatsApp_Image_20240305_at_112348_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999108_WhatsApp_Image_20240305_at_112348_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e6b34ff9222577acb9e9ef",
    "name":
"externallmg_1709617999114_WhatsApp_Image_20240305_at_112350_AM.jpeg",
    "path": "cases/65e69e26f9222577acb98e2b/
externallmg_1709617999114_WhatsApp_Image_20240305_at_112350_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-05T04:23:02.678Z",
"updatedAt": "2024-03-05T05:53:19.202Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
}
```



```
},
"fullAddress": "Residential Flat No. 1, Ground Floor, Building No 3, Wing - B, Krishna
Nagar CHSL, Chandavarkar Road, Village - Borivali, Borivali West, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Manjulaben Hansraj Shah ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9619104010"
}
```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				