

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65e979baf9222577acbe667a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312b5",
    "firstName": "Abhishek ",
    "email": "abk@sbi.co.in",
    "mobileNo": "0000000000",
    "workMobileNo": "9920665690",
    "lastName": "kumar"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Abhishek ",
    "expectedFees": null,
    "quotedAmount": "30000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65e979baf9222577acbe667a",
  "name": "SME Panvel Branch ",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "sbi.19254@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "MTNL Building, Ground Floor, Plot No 229, Near Shivaji Chouk, M G
ROad Panvel-410206"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "65829f7c65d49d78457ec7be",
"role": "SITEENGINEER",
"firstName": "Vaibhav",
"email": "vaib1234b@gmail.com",
"lastName": "Bhagat",
"mobileNo": "8779534609",
"designation": "Bachlore Of Engireeing",
"shortName": "Vaibhav",
"workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.019213835752996",
  "longitude": "73.03918812017316"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.03918812017316,
    19.019213835752996
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/03/2024 05:55 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "15000",
  "lumpsumValue": "1",
  "rateMax": "17000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Belapur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Navi Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": " Commercial Complex,",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
```

```
"label": "MS Rolling Shutter",
"value": "MS_Rolling_Shutter"
},
"windows": {
  "label": "Aluminium Sliding Window ",
  "value": "Aluminium_Sliding_Window_"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed ",
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "mes vidya mandir",
    "west": "road",
    "south": "road , open plot",
    "east": "income tax colony"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Vacant- Bank Possession",
    "value": "Vacant_Bank_Possession"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Open Parking",
```

```
"value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1998",
  "fullDate": "1/1/1998"
},
"propertyTypeList": {
  "label": "Commercial",
  "value": "Commercial"
},
"planningArea": {
  "label": "Commercial",
  "value": "Commercial"
},
"structureType": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
```

```
"value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "34",
"ageOfBuilding": "26",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "03",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "033"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```



```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65e9a62ef9222577acbf07b6",
"ownerName": "Amit Ashok Teckchandan ",
"ownerPhoneNo": "0000000000",
"appAddress": "Unit no 1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16,17,18,19,20,21,22,23,24
,25,26,27,28,29,30,31-1st floor,,15&16 Ground Floor, Commercial Complex, Plot no
07,Sector 22,CBD Belapur ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811273754_1709811435235_Office_no_20.pdf",
    "fileName": "document_1709811273754_1709811435235_Office_no_20.pdf",
    "id": "531267",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
```

```
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709811321545_1709811484745_Office_no_11.pdf",
"fileName": "document_1709811321545_1709811484745_Office_no_11.pdf",
"id": "833319",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811363266_1709811528227_Office_no_08.pdf",
"fileName": "document_1709811363266_1709811528227_Office_no_08.pdf",
"id": "430128",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811457341_1709811624983_Office_no_09.pdf",
"fileName": "document_1709811457341_1709811624983_Office_no_09.pdf",
"id": "581478",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811513284_1709811680278_Office_no_19.pdf",
"fileName": "document_1709811513284_1709811680278_Office_no_19.pdf",
"id": "122209",
```

```
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811544121_1709811711179_Office_no_10.pdf",
  "fileName": "document_1709811544121_1709811711179_Office_no_10.pdf",
  "id": "406267",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811577704_1709811741460_Office_no_12.pdf",
  "fileName": "document_1709811577704_1709811741460_Office_no_12.pdf",
  "id": "888287",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811639580_1709811803998_Office_no_21.pdf",
  "fileName": "document_1709811639580_1709811803998_Office_no_21.pdf",
  "id": "892142",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
```



```
"isHardCopy": false,
"displayStatus": false,
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709811762084_1709811930466_Office_no_18.pdf",
"fileName": "document_1709811762084_1709811930466_Office_no_18.pdf",
"id": "573963",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811783090_1709811949540_Office_no_14.pdf",
  "fileName": "document_1709811783090_1709811949540_Office_no_14.pdf",
  "id": "548796",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811804701_1709811971355_Office_no_161st_floor.pdf",
  "fileName":
"document_1709811804701_1709811971355_Office_no_161st_floor.pdf",
  "id": "396861",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811831923_1709811998691_Office_no_07.pdf",
```



```
"fileName": "document_1709811831923_1709811998691_Office_no_07.pdf",
"id": "300806",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811860159_1709812028667_Office_no_22.pdf",
"fileName": "document_1709811860159_1709812028667_Office_no_22.pdf",
"id": "547639",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811905844_1709812072097_Office_no_26.pdf",
"fileName": "document_1709811905844_1709812072097_Office_no_26.pdf",
"id": "516908",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811939133_1709812105575_Office_no_24.pdf",
"fileName": "document_1709811939133_1709812105575_Office_no_24.pdf",
"id": "908713",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
}
```

```
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811967253_1709812135608_Office_no_23.pdf",
  "fileName": "document_1709811967253_1709812135608_Office_no_23.pdf",
  "id": "583173",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709811991306_1709812157736_Office_no_25.pdf",
  "fileName": "document_1709811991306_1709812157736_Office_no_25.pdf",
  "id": "247239",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812017795_1709812186385_Office_no_28.pdf",
  "fileName": "document_1709812017795_1709812186385_Office_no_28.pdf",
  "id": "439112",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
```

```
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812043192_1709812211788_Office_no_04.pdf",
  "fileName": "document_1709812043192_1709812211788_Office_no_04.pdf",
  "id": "778033",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812084329_1709812252580_Office_no_6.pdf",
  "fileName": "document_1709812084329_1709812252580_Office_no_6.pdf",
  "id": "824202",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812110984_1709812279550_Office_no_15_1st_floor.pdf",
  "fileName":
"document_1709812110984_1709812279550_Office_no_15_1st_floor.pdf",
  "id": "256906",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
```

```
"displayStatus": false,
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709812143137_1709812311357_Office_no_15_1st_floor.pdf",
"fileName":
"document_1709812143137_1709812311357_Office_no_15_1st_floor.pdf",
"id": "260368",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": " Agreement",
"value": "652d16a0316e1359cebd3c15"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709812191716_1709812360157_Office_no_05.pdf",
"fileName": "document_1709812191716_1709812360157_Office_no_05.pdf",
"id": "806156",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": " Agreement",
"value": "652d16a0316e1359cebd3c15"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709812225674_1709812393803_Office_no_02.pdf",
"fileName": "document_1709812225674_1709812393803_Office_no_02.pdf",
"id": "317989",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": " Agreement",
"value": "652d16a0316e1359cebd3c15"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/65e9a62ef9222577acbf07b6/
document_1709812250776_1709812419288_Office_no_15_Ground_Floor.pdf",
```

```
"fileName":
"document_1709812250776_1709812419288_Office_no_15_Ground_Floor.pdf",
  "id": "194384",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812277346_1709812445742_Office_no_30.pdf",
  "fileName": "document_1709812277346_1709812445742_Office_no_30.pdf",
  "id": "947610",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812306957_1709812475640_Office_no_1.pdf",
  "fileName": "document_1709812306957_1709812475640_Office_no_1.pdf",
  "id": "206927",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812330972_1709812499583_Office_no_1.pdf",
  "fileName": "document_1709812330972_1709812499583_Office_no_1.pdf",
  "id": "454203",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
```

```
"createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812353799_1709812520557_Shop_no_16.pdf",
  "fileName": "document_1709812353799_1709812520557_Shop_no_16.pdf",
  "id": "105087",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812377353_1709812544047_Office_no_03.pdf",
  "fileName": "document_1709812377353_1709812544047_Office_no_03.pdf",
  "id": "497015",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812405617_1709812572424_Office_no_29.pdf",
  "fileName": "document_1709812405617_1709812572424_Office_no_29.pdf",
  "id": "667063",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65e9a62ef9222577acbf07b6/
document_1709812441058_1709812609299_Office_no_31.pdf",
  "fileName": "document_1709812441058_1709812609299_Office_no_31.pdf",
  "id": "642318",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Mar 07 2024 17:24:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007544",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "741896",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 07 2024 17:04:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Amit Ashok Teckchandam ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "964016"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  },
  "_id": "65ec2090f9222577acc29c70",
  "area": "182",
  "providedByName": "Amit Ashok Teckchandam ",
```

```
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "965822",
    "name": "Unit Area",
    "length": "200.00",
    "length1": "200",
    "length2": "00",
    "width": "500.00",
    "width1": "500",
    "width2": "00",
    "totalArea": "100000.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "100000.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d5c",
    "name": "externalImg_1709973789747_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/externalImg_1709973789747_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d5d",
    "name": "externalImg_1709973790167_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/externalImg_1709973790167_image.jpeg",
    "orientation": "portrait"
  }
]
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d5e",
    "name": "externallmg_1709973790602_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973790602_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d5f",
    "name": "externallmg_1709973791182_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973791182_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d60",
    "name": "externallmg_1709973791387_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973791387_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d61",
    "name": "externallmg_1709973791577_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973791577_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d62",
    "name": "externallmg_1709973792213_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973792213_image.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ec2128f9222577acc29d63",
  "name": "externallmg_1709973792442_image.jpeg",
  "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973792442_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ec2128f9222577acc29d64",
  "name": "externallmg_1709973792522_image.jpeg",
  "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973792522_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ec2128f9222577acc29d65",
  "name": "externallmg_1709973793027_image.jpeg",
  "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973793027_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ec2128f9222577acc29d66",
  "name": "externallmg_1709973794048_image.jpeg",
  "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973794048_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ec2128f9222577acc29d67",
  "name": "externallmg_1709973794372_image.jpeg",
  "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973794372_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d68",
    "name": "externallmg_1709973794547_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973794547_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d69",
    "name": "externallmg_1709973794752_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973794752_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d6a",
    "name": "externallmg_1709973794967_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973794967_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d6b",
    "name": "externallmg_1709973795107_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973795107_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d6c",
    "name": "externallmg_1709973795277_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externallmg_1709973795277_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65ec2128f9222577acc29d6d",
    "name": "externalImg_1709973795647_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externalImg_1709973795647_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ec2128f9222577acc29d6e",
    "name": "externalImg_1709973795837_image.jpeg",
    "path": "cases/65e9a62ef9222577acbf07b6/
externalImg_1709973795837_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-07T11:34:06.406Z",
"updatedAt": "2024-03-09T08:47:02.721Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65829f7c65d49d78457ec7be",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Shop No. Basement Floor, Commercial Complex,, Village -
Belapur, Navi Mumbai",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Amit Ashok Teckchandani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "Unit Area",
"carpetTotal": "100000",
```

"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"

}

Name	Length	Width	Total
Composition :			
Unit Area	200'00"	500'00"	100000.00
Other Composition :			