

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "65eedaa8857bdc098a99701c",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Beryl Dsouza",
"displayname": "Beryl Dsouza",
"initial": "B"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "64d09914dc9f3034f3008833",
    "role": "SITEENGINEER+MAKAR",
    "firstName": "Meetali",
    "email": "meetalirasal@gmail.com",
    "lastName": "Rasal",
    "mobileNo": "7397882283",
    "designation": "Junior Architect",
    "shortName": "MR",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
```

```
"valuersRegistrationNumber": [
  {
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
```

```
    ],
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.247938903341478",
  "longitude": "72.85500484300466"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "11/03/2024 03:45 pm"
    },
    {
      "dateTime": "11/03/2024 12:00 am"
    },
    {
      "dateTime": "11/03/2024 12:00 am"
    },
    {
      "dateTime": "11/03/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mandpeshwar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",

```

```
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "5",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Villa Ferdinand ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
```

```
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "13",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "Mumbai",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
"igrFinalRate": {
```

```
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65eedaa8857bdc098a997022",
"ownerName": "Beryl Dsouza",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9819543024",
"contactPersonName": "Mr Mark",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Beryl Dsouza",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "308192"
  }
],
"caseReferredBy": "",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential Flat No. 13, 1st Floor, Villa Ferdinand , Plot No. 5, Village -
Mandpeshwar, Borivali, Mumbai, State - Maharashtra, India",
"remark": "2010 Value Required",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1710152389820_Adobe_Scan_28Feb2024.pdf",
    "path": "cases/65eedaa8857bdc098a997022/
document_1710152389820_Adobe_Scan_28Feb2024.pdf",
    "id": "363502",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Mon Mar 11 2024 15:49:52 GMT+0530 (India Standard Time)"
  }
]
```



```
},
{
  "documentType": {
    "value": "60ae12a0aa6d152c1801b483",
    "label": "site Details"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1710305726490_Beryl_DSouza__402_Fortune_Exotica_Bo
rivali_West.pdf",
  "path": "cases/65eedaa8857bdc098a997022/
document_1710305726490_Beryl_DSouza__402_Fortune_Exotica_Borivali_West.pdf",
  "id": "966094",
  "uploadedBy": "64d09914dc9f3034f3008833",
  "createdAt": "Wed Mar 13 2024 10:25:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1710305737176_Light_bill_maintenance_Beryl_DSouza_Document.pdf",
  "path": "cases/65eedaa8857bdc098a997022/
document_1710305737176_Light_bill_maintenance_Beryl_DSouza_Document.pdf",
  "id": "509114",
  "uploadedBy": "64d09914dc9f3034f3008833",
  "createdAt": "Wed Mar 13 2024 10:25:37 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "007593",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "149436",
    "title": "Create Case",
```

```
    "description": "Create Case",
    "datetime": "Mon Mar 11 2024 15:49:20 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13a6",
    "name":
"externalImg_1710305620196_WhatsApp_Image_20240313_at_95805_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externalImg_1710305620196_WhatsApp_Image_20240313_at_95805_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13a7",
    "name":
"externalImg_1710305620202_WhatsApp_Image_20240313_at_95806_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externalImg_1710305620202_WhatsApp_Image_20240313_at_95806_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13a8",
    "name":
"externalImg_1710305620206_WhatsApp_Image_20240313_at_95806_AM_2.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externalImg_1710305620206_WhatsApp_Image_20240313_at_95806_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65f13154857bdc098a9c13a9",
    "name":
"externallmg_1710305620210_WhatsApp_Image_20240313_at_95806_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620210_WhatsApp_Image_20240313_at_95806_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13aa",
    "name":
"externallmg_1710305620214_WhatsApp_Image_20240313_at_95807_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620214_WhatsApp_Image_20240313_at_95807_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13ab",
    "name":
"externallmg_1710305620218_WhatsApp_Image_20240313_at_95807_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620218_WhatsApp_Image_20240313_at_95807_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13ac",
    "name":
"externallmg_1710305620220_WhatsApp_Image_20240313_at_95830_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620220_WhatsApp_Image_20240313_at_95830_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13ad",
    "name":
"externallmg_1710305620222_WhatsApp_Image_20240313_at_95831_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620222_WhatsApp_Image_20240313_at_95831_AM_1.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f13154857bdc098a9c13ae",
      "name":
"externallmg_1710305620227_WhatsApp_Image_20240313_at_95832_AM_1.jpeg",
      "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620227_WhatsApp_Image_20240313_at_95832_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f13154857bdc098a9c13af",
      "name":
"externallmg_1710305620234_WhatsApp_Image_20240313_at_95832_AM.jpeg",
      "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620234_WhatsApp_Image_20240313_at_95832_AM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f13154857bdc098a9c13b0",
      "name":
"externallmg_1710305620240_WhatsApp_Image_20240313_at_95833_AM_1.jpeg",
      "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620240_WhatsApp_Image_20240313_at_95833_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f13154857bdc098a9c13b1",
      "name":
"externallmg_1710305620245_WhatsApp_Image_20240313_at_95833_AM_2.jpeg",
      "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620245_WhatsApp_Image_20240313_at_95833_AM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65f13154857bdc098a9c13b2",
      "name":
"externallmg_1710305620250_WhatsApp_Image_20240313_at_95833_AM.jpeg",
```

```
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620250_WhatsApp_Image_20240313_at_95833_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b3",
    "name":
"externallmg_1710305620255_WhatsApp_Image_20240313_at_95834_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620255_WhatsApp_Image_20240313_at_95834_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b4",
    "name":
"externallmg_1710305620259_WhatsApp_Image_20240313_at_95834_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620259_WhatsApp_Image_20240313_at_95834_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b5",
    "name":
"externallmg_1710305620262_WhatsApp_Image_20240313_at_95835_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620262_WhatsApp_Image_20240313_at_95835_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b6",
    "name":
"externallmg_1710305620263_WhatsApp_Image_20240313_at_95835_AM_2.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620263_WhatsApp_Image_20240313_at_95835_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65f13154857bdc098a9c13b7",
    "name":
"externallmg_1710305620265_WhatsApp_Image_20240313_at_95835_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620265_WhatsApp_Image_20240313_at_95835_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b8",
    "name":
"externallmg_1710305620266_WhatsApp_Image_20240313_at_95836_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620266_WhatsApp_Image_20240313_at_95836_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13154857bdc098a9c13b9",
    "name":
"externallmg_1710305620268_WhatsApp_Image_20240313_at_95837_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305620268_WhatsApp_Image_20240313_at_95837_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1522",
    "name":
"externallmg_1710305671397_WhatsApp_Image_20240313_at_95837_AM_2.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671397_WhatsApp_Image_20240313_at_95837_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1523",
    "name":
"externallmg_1710305671402_WhatsApp_Image_20240313_at_95838_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671402_WhatsApp_Image_20240313_at_95838_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1524",
    "name":
"externallmg_1710305671409_WhatsApp_Image_20240313_at_95838_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671409_WhatsApp_Image_20240313_at_95838_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1525",
    "name":
"externallmg_1710305671413_WhatsApp_Image_20240313_at_95839_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671413_WhatsApp_Image_20240313_at_95839_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1526",
    "name":
"externallmg_1710305671417_WhatsApp_Image_20240313_at_95839_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671417_WhatsApp_Image_20240313_at_95839_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1527",
    "name":
"externallmg_1710305671420_WhatsApp_Image_20240313_at_95840_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671420_WhatsApp_Image_20240313_at_95840_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1528",
```

```
    "name":
"externallmg_1710305671424_WhatsApp_Image_20240313_at_95840_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671424_WhatsApp_Image_20240313_at_95840_AM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1529",
    "name":
"externallmg_1710305671428_WhatsApp_Image_20240313_at_95841_AM_1.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671428_WhatsApp_Image_20240313_at_95841_AM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c152a",
    "name":
"externallmg_1710305671432_WhatsApp_Image_20240313_at_95841_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671432_WhatsApp_Image_20240313_at_95841_AM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c152b",
    "name":
"externallmg_1710305671435_WhatsApp_Image_20240313_at_95842_AM_2.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671435_WhatsApp_Image_20240313_at_95842_AM_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c152c",
    "name":
"externallmg_1710305671439_WhatsApp_Image_20240313_at_95842_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671439_WhatsApp_Image_20240313_at_95842_AM.jpeg",
    "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f13187857bdc098a9c152d",
  "name":
"externallmg_1710305671443_WhatsApp_Image_20240313_at_95843_AM_1.jpeg",
  "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671443_WhatsApp_Image_20240313_at_95843_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f13187857bdc098a9c152e",
  "name":
"externallmg_1710305671447_WhatsApp_Image_20240313_at_95844_AM.jpeg",
  "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671447_WhatsApp_Image_20240313_at_95844_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f13187857bdc098a9c152f",
  "name":
"externallmg_1710305671451_WhatsApp_Image_20240313_at_95845_AM_1.jpeg",
  "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671451_WhatsApp_Image_20240313_at_95845_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f13187857bdc098a9c1530",
  "name":
"externallmg_1710305671455_WhatsApp_Image_20240313_at_95847_AM.jpeg",
  "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671455_WhatsApp_Image_20240313_at_95847_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f13187857bdc098a9c1531",
  "name":
"externallmg_1710305671458_WhatsApp_Image_20240313_at_95848_AM_1.jpeg",
```

```
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671458_WhatsApp_Image_20240313_at_95848_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13187857bdc098a9c1532",
    "name":
"externallmg_1710305671462_WhatsApp_Image_20240313_at_95848_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305671462_WhatsApp_Image_20240313_at_95848_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13195857bdc098a9c15db",
    "name":
"externallmg_1710305685352_WhatsApp_Image_20240313_at_95849_AM_2.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305685352_WhatsApp_Image_20240313_at_95849_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f13195857bdc098a9c15dc",
    "name":
"externallmg_1710305685358_WhatsApp_Image_20240313_at_95849_AM.jpeg",
    "path": "cases/65eedaa8857bdc098a997022/
externallmg_1710305685358_WhatsApp_Image_20240313_at_95849_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-11T10:19:20.409Z",
"updatedAt": "2024-03-13T04:55:37.287Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "64d09914dc9f3034f3008833"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			