

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "95000000",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": 47500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.008046",
  "longitude": "72.832986"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.832986,
    19.008046
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-16",
      "remark": "9.50 Required\\n\\nTwo opinion "
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A2 ",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": " Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Lover Parel ",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "sky forest",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```

```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": " 1504",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
```

```
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
```

```
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
"isAdvanceInvoice": false,
status": true,
caseStatus": "SITEVISITCOMPLETED",
```



```
"invoices": [],
"paymentIds": [],
"_id": "65f3ef00857bdc098aa0c337",
"ownerName": "Mr Sanjay Ramesh Narang NRI",
"ownerPhoneNo": "7841033333",
"appAddress": "A2 1504\nnsky forest\nLover Parel\nMumbai ",
"remark": "9.50 Required\n\nTwo opinion ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f3ef00857bdc098aa0c337/document_1710485106810_1710485288901_A21504__AGREEMENT_FOR_SALE_2024.pdf",
    "fileName": "document_1710485106810_1710485288901_A21504__AGREEMENT_FOR_SALE_2024.pdf",
    "id": "721542",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Fri Mar 15 2024 12:17:28 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f3ef00857bdc098aa0c337/document_1710520177108_35588.pdf",
    "fileName": "document_1710520177108_35588.pdf",
    "id": "395315",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Fri Mar 15 2024 21:59:37 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007703",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "755539",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 15 2024 12:17:28 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr Sanjay Ramesh Narang NRI",
    "phone": "7841033333",
    "ownershipShare": "",
    "email": "",
    "id": "239098"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392f0",
    "name": "externallmg_1710580305492_1710580470046_image_0.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/externallmg_1710580305492_1710580470046_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392f1",
    "name": "externallmg_1710580319032_1710580470046_image_1.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/externallmg_1710580319032_1710580470046_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392f2",
    "name": "externallmg_1710580334471_1710580470046_image_2.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/externallmg_1710580334471_1710580470046_image_2.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56288857bdc098aa392f3",
  "name": "externallmg_1710580336909_1710580470046_image_3.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580336909_1710580470046_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56288857bdc098aa392f4",
  "name": "externallmg_1710580339288_1710580470046_image_4.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580339288_1710580470046_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56288857bdc098aa392f5",
  "name": "externallmg_1710580341429_1710580470046_image_5.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580341429_1710580470046_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56288857bdc098aa392f6",
  "name": "externallmg_1710580344010_1710580470046_image_6.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580344010_1710580470046_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56288857bdc098aa392f7",
  "name": "externallmg_1710580346636_1710580470046_image_7.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580346636_1710580470046_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392f8",
    "name": "externallmg_1710580348340_1710580470046_image_8.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580348340_1710580470046_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392f9",
    "name": "externallmg_1710580350217_1710580470046_image_9.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580350217_1710580470046_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392fa",
    "name": "externallmg_1710580352094_1710580470046_image_10.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580352094_1710580470046_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392fb",
    "name": "externallmg_1710580353419_1710580470046_image_11.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580353419_1710580470046_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56288857bdc098aa392fc",
    "name": "externallmg_1710580355559_1710580470046_image_12.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580355559_1710580470046_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65f56288857bdc098aa392fd",
  "name": "externallmg_1710580356989_1710580470046_image_13.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580356989_1710580470046_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56366857bdc098aa3985f",
  "name": "externallmg_1710580450842_1710580626751_image_0.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580450842_1710580626751_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56366857bdc098aa39860",
  "name": "externallmg_1710580453037_1710580626751_image_1.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580453037_1710580626751_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56366857bdc098aa39861",
  "name": "externallmg_1710580456367_1710580626751_image_2.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580456367_1710580626751_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f56366857bdc098aa39862",
  "name": "externallmg_1710580460637_1710580626751_image_3.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580460637_1710580626751_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65f56366857bdc098aa39863",
    "name": "externallmg_1710580465057_1710580626751_image_4.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580465057_1710580626751_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39864",
    "name": "externallmg_1710580466914_1710580626751_image_5.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580466914_1710580626751_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39865",
    "name": "externallmg_1710580468981_1710580626751_image_6.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580468981_1710580626751_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39866",
    "name": "externallmg_1710580470642_1710580626751_image_7.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580470642_1710580626751_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39867",
    "name": "externallmg_1710580475830_1710580626751_image_8.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580475830_1710580626751_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39868",
```

```
    "name": "externallmg_1710580476181_1710580626751_image_9.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580476181_1710580626751_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39869",
    "name": "externallmg_1710580479392_1710580626751_image_10.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580479392_1710580626751_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986a",
    "name": "externallmg_1710580481581_1710580626751_image_11.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580481581_1710580626751_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986b",
    "name": "externallmg_1710580482977_1710580626751_image_12.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580482977_1710580626751_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986c",
    "name": "externallmg_1710580485520_1710580626751_image_13.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580485520_1710580626751_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986d",
    "name": "externallmg_1710580531078_1710580626751_image_14.jpeg",
```

```
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580531078_1710580626751_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986e",
    "name": "externallmg_1710580531477_1710580626751_image_15.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580531477_1710580626751_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa3986f",
    "name": "externallmg_1710580533916_1710580626751_image_16.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580533916_1710580626751_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39870",
    "name": "externallmg_1710580541027_1710580626751_image_17.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580541027_1710580626751_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39871",
    "name": "externallmg_1710580555549_1710580626751_image_18.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580555549_1710580626751_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f56366857bdc098aa39872",
    "name": "externallmg_1710580564641_1710580626751_image_19.jpeg",
    "path": "cases/65f3ef00857bdc098aa0c337/
externallmg_1710580564641_1710580626751_image_19.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f5621f857bdc098aa391a6",
  "name": "externalImg_1710580133067_1710580309958_image_0.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externalImg_1710580133067_1710580309958_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f5621f857bdc098aa391a7",
  "name": "externalImg_1710580222360_1710580309958_image_1.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externalImg_1710580222360_1710580309958_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f5621f857bdc098aa391a8",
  "name": "externalImg_1710580238051_1710580309958_image_2.jpeg",
  "path": "cases/65f3ef00857bdc098aa0c337/
externalImg_1710580238051_1710580309958_image_2.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "DRAFT AGREEMENT.pdf",
    "filename": "1710501062353_DRAFT_AGREEMENT.pdf",
    "path": "cases/65f3ef00857bdc098aa0c337/
processingDocuments/1710501062353_DRAFT_AGREEMENT.pdf",
    "size": "646848",
    "createdAt": "Fri Mar 15 2024 16:41:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
```

```

    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "65f54848857bdc098aa3435a",
    "note": "Site Visit Pending",
    "taskId": "65f42cca857bdc098aa1c876",
    "createdAt": "2024-03-16T07:20:40.274Z"
  }
],
"createdAt": "2024-03-15T06:47:28.708Z",
"updatedAt": "2024-03-16T11:40:04.491Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1504, 15th Floor, Building No A2 , sky forest,
District - Mumbai, Lover Parel ",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr Sanjay Ramesh Narang NRI",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7841033333"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
