

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
```

```
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.245462255838895",
  "longitude": "72.87224627219616"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87224627219616,
    19.245462255838895
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "18/03/2024 06:05 pm"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-03-20",
```

```
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-03-21",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dahisar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
}
```

```
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "B",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Shree Suryodaya Apartment",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Rawalpada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Shiv Vallabh Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```



```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "162, Hissa No. 1 (Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2560-C",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "R/N Ward",
```

```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN code - 400 068",
  "label": false
},
"suburb": {
  "status": true,
```

```

    "name": "Suburb",
    "key": "suburb",
    "value": "Dahisar (East), Mumbai",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
},

```

```
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Laxmi Niwas CHSL",
  "west": "Shiv Vallabh Road",
  "south": "Girijabai Bhoir Chawl",
  "east": "Kumble Chawl"
},
"asPerDocumentAgreement": {
  "north": "Partly by S. No. 153, H. No. 3 & 5",
  "west": "D.P. Road",
  "south": "Survey No. 155",
  "east": "Partly by S. No. 162, H. No. 2 & 3"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Occupancy Certificate Document No. CHE / 8495 / BP (WS) / AR / OCC / 1 / New Dated 16.07.2021 issued by Municipal Corporation of Greater Mumbai",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
```

```
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "136750",
  "landRate": "57110",
  "igrImage": "cases/65f8290e857bdc098aa6ddd5/igr_1710827159594_Image.png",
  "squareMeterGuideLineRate": "136750.00",
  "squareFeetGuideLineRate": "12705.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "95",
  "rate": "12335.00",
  "squareMeterGuideLineRate": "132768.00",
  "squareFeetGuideLineRate": "12335.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "23,000/- Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
```

```
"marketabilityList": {
  "value": "Good",
  "label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2021",
    "fullDate": "1/1/2021"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  }
}
```

```
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
```

```
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "3",
"totalLifeBuilding": "60",
"estimatedAge": "57",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
"area": "491.70",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Metro_Station",
"label": "Metro Station"
}
},
"routeMapImg": "cases/65f8290e857bdc098aa6ddd5/
routeMap_1710999457847_Image.png",
"routeLat": "19.245031",
```



```
"routeLng": "72.872057",
"stationName": "Ovari Pada",
"routeDistance": "1.4 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "qu9llo",
    "name": "qu9llo",
    "image": "cases/65f8290e857bdc098aa6ddd5/
routeMap_1710999410034_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
```

```
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9387000.00",
"finalValue": "9387000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "6065120.00",
  "selectedBuildUpValue": "491.70",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65fba7c65ca1625e50591d3c",
      "name":
"externallmg_1710991301926_WhatsApp_Image_20240320_at_193728.jpeg",
      "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991301926_WhatsApp_Image_20240320_at_193728.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65fba8545ca1625e50591da7",
      "name":
"externallmg_1710991443922_WhatsApp_Image_20240320_at_193737.jpeg",
      "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443922_WhatsApp_Image_20240320_at_193737.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65fba7c65ca1625e50591d3e",
      "name":
"externallmg_1710991301941_WhatsApp_Image_20240320_at_193729.jpeg",
      "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991301941_WhatsApp_Image_20240320_at_193729.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
```

```
    "status": false,
    "_id": "65fba8545ca1625e50591daf",
    "name":
"externallmg_1710991443948_WhatsApp_Image_20240320_at_193740.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443948_WhatsApp_Image_20240320_at_193740.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "65fba8545ca1625e50591da2",
    "name": "Living Room",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443909_WhatsApp_Image_20240320_at_193735_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65fba8545ca1625e50591da5",
    "name": "Living Room",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443917_WhatsApp_Image_20240320_at_193736.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65fba8545ca1625e50591dad",
    "name": "Living Room",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443939_WhatsApp_Image_20240320_at_193739.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65fba8545ca1625e50591daa",
    "name": "Living Room",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443933_WhatsApp_Image_20240320_at_193738.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65fba8545ca1625e50591da6",
    "name": "Living Room",
```

```
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443919_WhatsApp_Image_20240320_at_193737_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20548",
    "max": "23786"
  },
  "builtUpRateRange": {
    "min": "18680",
    "max": "21625"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "447.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65f8290e857bdc098aa6ddd5",
"ownerName": "Mr. Parshuram Bhima Asolkar, Mrs. Padmavati Parshuram Asolkar &
```

```
Miss. Dipali Parshuram Asolkar",
"ownerPhoneNo": "7021231670",
"appAddress": "D- 403 4 th floor Suryoday Rawalpada Dahisar East 400068",
"remark": "(Furkan SSL Case ) other no - 9821962029 / 9870629477",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "inputs": {
    "documentDate": "14/05/2019",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s. Rohan Development",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Parshuram Bhima Asolkar, Mrs. Padmavati Parshuram Asolkar &
Miss. Dipali Parshuram Asolkar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "6456 / 2019"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "639597",
  "path": "cases/65f8290e857bdc098aa6ddd5/document_1710762077360_17107622
56914_SBI_Racpc_Borivali_Parshuram_B_Asolkar_SSL_Furak.pdf",
  "fileName": "document_1710762077360_1710762256914_SBI_Racpc_Borivali_Par
shuram_B_Asolkar_SSL_Furak.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/08/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
```

```
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51800004819"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711001219272_P51800004819.pdf",
"path": "cases/65f8290e857bdc098aa6ddd5/
document_1711001219272_P51800004819.pdf",
"id": "801936",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Mar 21 2024 11:36:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "27/04/1995",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CHE / 8495 / BP (WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "636522",
  "path": "cases/65f8290e857bdc098aa6ddd5/document_1711001260223_cc.pdf",
  "fileName": "document_1711001260223_cc.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
```

```
"documentDate": "16/07/2021",
"nameOfApprovingAuthority": {
  "value": "Municipal_Corporation_of_Greater_Mumbai",
  "label": "Municipal Corporation of Greater Mumbai"
},
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "CHE / 8495 / BP (WS) / AR / OCC / 1 / New"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711001340635_oc.pdf",
"path": "cases/65f8290e857bdc098aa6ddd5/document_1711001340635_oc.pdf",
"id": "766303",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Mar 21 2024 11:39:01 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007789",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "800268",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 18 2024 17:14:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Parshuram Bhima Asolkar, Mrs. Padmavati Parshuram Asolkar & Miss.
Dipali Parshuram Asolkar",
    "phone": "7021231670",
    "ownershipShare": "",
    "email": "",
    "id": "427999"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "362395",
  "name": "Living Room",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "17.83",
  "width1": "17",
  "width2": "10",
  "totalArea": "200.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "200.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "37.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "37.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.17",
  "length1": "6",
  "length2": "2",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
```

```
"totalArea": "24.15",
"images": [],
"extraAreas": [],
"finalArea": "24.15"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "37.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "37.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "10.58",
  "width1": "10",
  "width2": "7",
  "totalArea": "101.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "101.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "5",
"name": "Toilet",
"length": "4.17",
"length1": "4",
"length2": "2",
"width": "4.42",
"width1": "4",
"width2": "5",
"totalArea": "18.40",
"images": [],
"extraAreas": [],
"finalArea": "18.40"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "41.53",
  "totalAreaDocument": "447.00",
  "docBuiltpupPercentage": "10",
  "docFinalBuiltpup": "491.70",
  "docFinalBuiltpupSquareMeter": "45.68",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "459624"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65f92a6549003e142a8e159a",
  "property": "1 BHK Flat In River Park Complex For Sale In River Park Complex,
Ekta Nagar, Dahisar East",
  "area": "438.00",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "9000000",
"expectedRate": "20547.95",
"builtUpExpectedRate": "18679.95",
"image": "cases/65f8290e857bdc098aa6ddd5/
indicator_1710826249727_Image.png",
"squareMeter": "40.69",
"id": "675021"
},
{
  "printlnReport": true,
  "_id": "65f92a6549003e142a8e159b",
  "property": "1 RK Flat In Yamuna Society For Sale In Rawal Pada, Dahisar (",
  "area": "220",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "5000000.00",
  "expectedRate": "22727.27",
  "builtUpExpectedRate": "20661.16",
  "image": "cases/65f8290e857bdc098aa6ddd5/
indicator_1710826445332_Image.png",
  "squareMeter": "20.44",
  "id": "853031"
},
{
  "printlnReport": true,
  "_id": "65f92a6549003e142a8e159c",
  "property": "Shree Saurvoday CHSL, Dahisar (East), Mumbai",
  "area": "206",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "4900000.00",
  "expectedRate": "23786.41",
  "builtUpExpectedRate": "21624.01",
  "image": "cases/65f8290e857bdc098aa6ddd5/
indicator_1710826779528_Image.png",
```



```
    "squareMeter": "19.14",
    "id": "245069"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba7c65ca1625e50591d3c",
    "name":
"externallmg_1710991301926_WhatsApp_Image_20240320_at_193728.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991301926_WhatsApp_Image_20240320_at_193728.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba7c65ca1625e50591d3d",
    "name":
"externallmg_1710991301932_WhatsApp_Image_20240320_at_193729_1.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991301932_WhatsApp_Image_20240320_at_193729_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba7c65ca1625e50591d3e",
    "name":
"externallmg_1710991301941_WhatsApp_Image_20240320_at_193729.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991301941_WhatsApp_Image_20240320_at_193729.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591d9e",
    "name":
"externallmg_1710991443883_WhatsApp_Image_20240320_at_193731_1.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443883_WhatsApp_Image_20240320_at_193731_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591d9f",
    "name":
"externallmg_1710991443890_WhatsApp_Image_20240320_at_193731.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443890_WhatsApp_Image_20240320_at_193731.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da0",
    "name":
"externallmg_1710991443899_WhatsApp_Image_20240320_at_193733.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443899_WhatsApp_Image_20240320_at_193733.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da1",
    "name":
"externallmg_1710991443905_WhatsApp_Image_20240320_at_193734.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443905_WhatsApp_Image_20240320_at_193734.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da2",
    "name":
"externallmg_1710991443909_WhatsApp_Image_20240320_at_193735_1.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443909_WhatsApp_Image_20240320_at_193735_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da3",
    "name":
"externallmg_1710991443912_WhatsApp_Image_20240320_at_193735.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443912_WhatsApp_Image_20240320_at_193735.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da4",
    "name":
"externallmg_1710991443914_WhatsApp_Image_20240320_at_193736_1.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443914_WhatsApp_Image_20240320_at_193736_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da5",
    "name":
"externallmg_1710991443917_WhatsApp_Image_20240320_at_193736.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443917_WhatsApp_Image_20240320_at_193736.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da6",
    "name":
"externallmg_1710991443919_WhatsApp_Image_20240320_at_193737_1.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443919_WhatsApp_Image_20240320_at_193737_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da7",
    "name":
"externallmg_1710991443922_WhatsApp_Image_20240320_at_193737.jpeg",
    "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443922_WhatsApp_Image_20240320_at_193737.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fba8545ca1625e50591da8",
```

```
    "name":
"externallmg_1710991443928_WhatsApp_Image_20240320_at_193738_1.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443928_WhatsApp_Image_20240320_at_193738_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591da9",
  "name":
"externallmg_1710991443931_WhatsApp_Image_20240320_at_193738_2.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443931_WhatsApp_Image_20240320_at_193738_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591daa",
  "name":
"externallmg_1710991443933_WhatsApp_Image_20240320_at_193738.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443933_WhatsApp_Image_20240320_at_193738.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591dab",
  "name":
"externallmg_1710991443934_WhatsApp_Image_20240320_at_193739_1.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443934_WhatsApp_Image_20240320_at_193739_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591dac",
  "name":
"externallmg_1710991443937_WhatsApp_Image_20240320_at_193739_2.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443937_WhatsApp_Image_20240320_at_193739_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591dad",
  "name":
"externallmg_1710991443939_WhatsApp_Image_20240320_at_193739.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443939_WhatsApp_Image_20240320_at_193739.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591dae",
  "name":
"externallmg_1710991443941_WhatsApp_Image_20240320_at_193740_1.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443941_WhatsApp_Image_20240320_at_193740_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591daf",
  "name":
"externallmg_1710991443948_WhatsApp_Image_20240320_at_193740.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443948_WhatsApp_Image_20240320_at_193740.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fba8545ca1625e50591db0",
  "name":
"externallmg_1710991443952_WhatsApp_Image_20240320_at_193727.jpeg",
  "path": "cases/65f8290e857bdc098aa6ddd5/
externallmg_1710991443952_WhatsApp_Image_20240320_at_193727.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "plan.pdf",
  "filename": "1711003722694_plan.pdf",
```

```
"path": "cases/65f8290e857bdc098aa6ddd5/
processingDocuments/1711003722694_plan.pdf",
"size": "985823",
"createdAt": "Thu Mar 21 2024 12:18:44 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
"originalname": "7789.xlsx",
"filename": "1711004316690_7789.xlsx",
"path": "cases/65f8290e857bdc098aa6ddd5/
processingDocuments/1711004316690_7789.xlsx",
"size": "9714",
"createdAt": "Thu Mar 21 2024 12:28:36 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-18T11:44:14.717Z",
"updatedAt": "2024-03-22T05:36:04.891Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
},
"fullAddress": "Residential Flat No. 403, 4th Floor, Wing - D, Shree Suryodaya
Apartment, Plot No. B, Rawalpada, Shiv Vallabh Road, Village - Dahisar, Municipality
Ward No. R/N Ward, Dahisar (East), Mumbai, Taluka - Borivali, District - Mumbai
Suburban District, PIN code - 400 068, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Parshuram Bhima Asolkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "7021231670",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
```

```
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 447.00",
"flatRate": "21000",
"landOtherRate": "18200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "281.09",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "462.32",
"finalCarpetArea": "420.29",
"finalSalableArea": "508.55",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.",
"siteMeasurementRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Fri Mar 22 2024 11:55:04 GMT+0530 (India Standard Time)",
```

"siteVisitDate": "2024-03-21"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	11'3"	17'10"	200.62
Passage	3'6"	10'10"	37.92
Toilet	6'2"	3'11"	24.15
Kitchen	6'8"	5'8"	37.78
Bedroom	9'7"	10'7"	101.42
Toilet	4'2"	4'5"	18.40
Other Composition :			