

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d7"
    },
    "type": "CREDITOFFICER",
    "_id": "65f12f86857bdc098a9c08cb",
    "firstName": "Binay",
    "lastName": "Bhusan",
    "mobileNo": "",
    "workMobileNo": "9853558535",
    "email": "binu.pradha@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10061860",
    "discussWithPerson": "Binay",
    "expectedFees": 5030.93,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d7",
  "branchCode": "000032",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Malad (West)",
  "email": "team9.04107@sbi.co.in",
  "mobileNo": "022-28826408",
  "alternateMobileNo": "",
  "address": "Industrial Finance Branch, Near Chincholi Phatak Signal, S. V. Road,
Malad (West), Mumbai - 400 064, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA- IFB MALAD",
  "fax": "022-28827773",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.208851424940715",
  "longitude": "72.86380281456172"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86380281456172,
    19.208851424940715
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/03/2024 08:48 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Poisar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "MUmbai",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Thakurs Green Filed CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Thakur Complex",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "107",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
```

```
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65fb285a5ca1625e50590d36",
```



```
"ownerName": "Savita Kailash Agarwal ",
"ownerPhoneNo": "9833934339",
"appAddress": "Flat no 107 1 St floor B-wing Thakurs Green Field Co-op HSG Soc
Ltd Thakur Complex Kandivali East 400101",
"remark": "Sskh Harshul Contact Presan visit ",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65fb285a5ca1625e50590d36/
document_1710958305670_1710958486487_1pdf_107_Agreement_2005.pdf",
    "fileName":
"document_1710958305670_1710958486487_1pdf_107_Agreement_2005.pdf",
    "id": "844878",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 20 2024 23:48:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Occupation Certificate",
      "value": "60ae1293aa6d152c1801b447"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65fb285a5ca1625e50590d36/
document_1710958450354_1710958628312_occupancy_cert2.pdf",
    "fileName": "document_1710958450354_1710958628312_occupancy_cert2.pdf",
    "id": "320370",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 20 2024 23:48:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Share Certificate ",
      "value": "60ae1264aa6d152c1801b371"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65fb285a5ca1625e50590d36/
document_1710958514618_1710958694648_share_certificate1.pdf",
    "fileName": "document_1710958514618_1710958694648_share_certificate1.pdf",
    "id": "764621",
```

```
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Wed Mar 20 2024 23:48:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65fb285a5ca1625e50590d36/
document_1710958546652_1710958727643_plan_107_Agreement_Plan.pdf",
  "fileName":
"document_1710958546652_1710958727643_plan_107_Agreement_Plan.pdf",
  "id": "305521",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Wed Mar 20 2024 23:48:02 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007871",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "756652",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 20 2024 23:48:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Savita Kailash Agarwal ",
    "phone": "9833934339",
    "ownershipShare": "",
    "email": "",
    "id": "289508"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595580",
    "name":
"externalImg_1710997730470_WhatsApp_Image_20240321_at_103731_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externalImg_1710997730470_WhatsApp_Image_20240321_at_103731_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595581",
    "name":
"externalImg_1710997730476_WhatsApp_Image_20240321_at_103731_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externalImg_1710997730476_WhatsApp_Image_20240321_at_103731_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595582",
    "name":
"externalImg_1710997730481_WhatsApp_Image_20240321_at_103732_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externalImg_1710997730481_WhatsApp_Image_20240321_at_103732_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595583",
    "name":
"externalImg_1710997730486_WhatsApp_Image_20240321_at_103732_AM_2.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externalImg_1710997730486_WhatsApp_Image_20240321_at_103732_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595584",
    "name":
"externalImg_1710997730492_WhatsApp_Image_20240321_at_103732_AM.jpeg",
```

```
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730492_WhatsApp_Image_20240321_at_103732_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595585",
    "name":
"externallmg_1710997730498_WhatsApp_Image_20240321_at_103737_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730498_WhatsApp_Image_20240321_at_103737_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595586",
    "name":
"externallmg_1710997730502_WhatsApp_Image_20240321_at_103737_AM_2.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730502_WhatsApp_Image_20240321_at_103737_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595587",
    "name":
"externallmg_1710997730504_WhatsApp_Image_20240321_at_103737_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730504_WhatsApp_Image_20240321_at_103737_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595588",
    "name":
"externallmg_1710997730507_WhatsApp_Image_20240321_at_103738_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730507_WhatsApp_Image_20240321_at_103738_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65fbc0e25ca1625e50595589",
    "name":
"externallmg_1710997730509_WhatsApp_Image_20240321_at_103738_AM_2.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730509_WhatsApp_Image_20240321_at_103738_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558a",
    "name":
"externallmg_1710997730512_WhatsApp_Image_20240321_at_103738_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730512_WhatsApp_Image_20240321_at_103738_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558b",
    "name":
"externallmg_1710997730516_WhatsApp_Image_20240321_at_103739_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730516_WhatsApp_Image_20240321_at_103739_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558c",
    "name":
"externallmg_1710997730519_WhatsApp_Image_20240321_at_103739_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730519_WhatsApp_Image_20240321_at_103739_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558d",
    "name":
"externallmg_1710997730523_WhatsApp_Image_20240321_at_103740_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730523_WhatsApp_Image_20240321_at_103740_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558e",
    "name":
"externallmg_1710997730527_WhatsApp_Image_20240321_at_103740_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730527_WhatsApp_Image_20240321_at_103740_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e5059558f",
    "name":
"externallmg_1710997730531_WhatsApp_Image_20240321_at_103741_AM_1.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730531_WhatsApp_Image_20240321_at_103741_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595590",
    "name":
"externallmg_1710997730537_WhatsApp_Image_20240321_at_103741_AM_2.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730537_WhatsApp_Image_20240321_at_103741_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595591",
    "name":
"externallmg_1710997730540_WhatsApp_Image_20240321_at_103741_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730540_WhatsApp_Image_20240321_at_103741_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0e25ca1625e50595592",
```

```
"name":
"externallmg_1710997730713_WhatsApp_Image_20240321_at_103742_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997730713_WhatsApp_Image_20240321_at_103742_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a0",
  "name":
"externallmg_1710997753114_WhatsApp_Image_20240321_at_103739_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753114_WhatsApp_Image_20240321_at_103739_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a1",
  "name":
"externallmg_1710997753116_WhatsApp_Image_20240321_at_103739_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753116_WhatsApp_Image_20240321_at_103739_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a2",
  "name":
"externallmg_1710997753118_WhatsApp_Image_20240321_at_103740_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753118_WhatsApp_Image_20240321_at_103740_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a3",
  "name":
"externallmg_1710997753121_WhatsApp_Image_20240321_at_103740_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753121_WhatsApp_Image_20240321_at_103740_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a4",
  "name":
"externallmg_1710997753124_WhatsApp_Image_20240321_at_103741_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753124_WhatsApp_Image_20240321_at_103741_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a5",
  "name":
"externallmg_1710997753128_WhatsApp_Image_20240321_at_103741_AM_2.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753128_WhatsApp_Image_20240321_at_103741_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a6",
  "name":
"externallmg_1710997753133_WhatsApp_Image_20240321_at_103741_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753133_WhatsApp_Image_20240321_at_103741_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a7",
  "name":
"externallmg_1710997753135_WhatsApp_Image_20240321_at_103742_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753135_WhatsApp_Image_20240321_at_103742_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956a8",
  "name":
"externallmg_1710997753137_WhatsApp_Image_20240321_at_103742_AM.jpeg",
```



```
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753137_WhatsApp_Image_20240321_at_103742_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956a9",
    "name":
"externallmg_1710997753139_WhatsApp_Image_20240321_at_103743_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753139_WhatsApp_Image_20240321_at_103743_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956aa",
    "name":
"externallmg_1710997753142_WhatsApp_Image_20240321_at_103705_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753142_WhatsApp_Image_20240321_at_103705_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956ab",
    "name":
"externallmg_1710997753144_WhatsApp_Image_20240321_at_103707_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753144_WhatsApp_Image_20240321_at_103707_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956ac",
    "name":
"externallmg_1710997753147_WhatsApp_Image_20240321_at_103708_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753147_WhatsApp_Image_20240321_at_103708_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65fbc0f95ca1625e505956ad",
  "name":
"externallmg_1710997753151_WhatsApp_Image_20240321_at_103709_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753151_WhatsApp_Image_20240321_at_103709_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956ae",
  "name":
"externallmg_1710997753155_WhatsApp_Image_20240321_at_103709_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753155_WhatsApp_Image_20240321_at_103709_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956af",
  "name":
"externallmg_1710997753157_WhatsApp_Image_20240321_at_103714_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753157_WhatsApp_Image_20240321_at_103714_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956b0",
  "name":
"externallmg_1710997753162_WhatsApp_Image_20240321_at_103717_AM_1.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753162_WhatsApp_Image_20240321_at_103717_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fbc0f95ca1625e505956b1",
  "name":
"externallmg_1710997753168_WhatsApp_Image_20240321_at_103717_AM.jpeg",
  "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753168_WhatsApp_Image_20240321_at_103717_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956b2",
    "name":
"externallmg_1710997753173_WhatsApp_Image_20240321_at_103718_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753173_WhatsApp_Image_20240321_at_103718_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fbc0f95ca1625e505956b3",
    "name":
"externallmg_1710997753178_WhatsApp_Image_20240321_at_103730_AM.jpeg",
    "path": "cases/65fb285a5ca1625e50590d36/
externallmg_1710997753178_WhatsApp_Image_20240321_at_103730_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-20T18:18:02.855Z",
"updatedAt": "2024-03-21T05:09:13.274Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 107, 1st Floor, Wing - B, Thakurs Green Filed
CHSL, Thakur Complex\t, Village - Poisar, Kandivali East, MUmbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Savita Kailash Agarwal ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833934339"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			