

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "1sbi.14677@sbi.co.in",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9200000",
    "discussWithPerson": "Rushikesh",
    "expectedFees": 4600,
    "quotedAmount": "3540"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62550ed0aba01e0af98f2f75",
  "role": "SITEENGINEER",
  "firstName": "Chandan",
  "email": "chandan@vastukala.org",
  "lastName": "Singh",
  "mobileNo": "8454863607",
  "designation": "",
  "shortName": "CH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.662455417210666",
  "longitude": "73.70808189615491"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.70808189615491,
18.662455417210666
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "22/03/2024 04:35 pm"
    },
    {
      "dateTime": "22/03/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-26",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gahunje",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "6",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Pune",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahapilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Maval ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pebble Beach Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Lodha Belmondo",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "205(Part), 221(Part), 225(Part), 226(Part) & others ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 412 101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Pune_Metropolitan_Reginal_Development_Authority",
    "label": "Pune Metropolitan Reginal Development Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road ",
    "west": "Internal Road ",
    "south": "Tower No. 14",
    "east": "Tower No. 9 "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Part Occupancy Certificate is available it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "262.5",
  "depreciatedCostOfConstruction": "11037.50",
  "depreciatedBuildingRate": "2237.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "40940",
  "landRate": "3820",
  "igrImage": "cases/65fd537e5ca1625e505c5db3/igr_1711524873006_Image.png",
  "squareMeterGuideLineRate": "47081.00",
  "squareFeetGuideLineRate": "4374.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "93",
  "rate": "4093.00",
  "squareFeetGuideLineRate": "4093.00",
  "squareMeterGuideLineRate": "44053.00"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per local norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Along with One Open Car Parking Space No. S1 - 287",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
```



```
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "23",
"flatFloorNo": "21",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1156.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65fd537e5ca1625e505c5db3/
routeMap_1711538890416_Image.png",
    "routeLat": "18.662239",
    "routeLng": "73.708057",
    "stationName": "Dehu Road",
    "routeDistance": "8.2 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "oww3wx",
      "name": "oww3wx",
      "image": "cases/65fd537e5ca1625e505c5db3/
routeMap_1711538664813_Image.png"
```

```
}
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "10640632.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "10640632.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Mar 27 2024 17:42:12 GMT+0530 (India Standard Time)",
  "number": "2305766",
  "dayCount": "17",
  "monthCount": "514",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4734782.00",
  "selectedBuildUpValue": "1156.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6602a2d05ca1625e5060e633",
      "name":
"externalimg_1711448784014_WhatsApp_Image_20240326_at_154623_2.jpeg",
      "path": "cases/65fd537e5ca1625e505c5db3/
externalimg_1711448784014_WhatsApp_Image_20240326_at_154623_2.jpeg",
```

```
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e62a",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783975_WhatsApp_Image_20240326_at_154627.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e626",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783957_WhatsApp_Image_20240326_at_154626_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e628",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783967_WhatsApp_Image_20240326_at_154627_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e62d",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783984_WhatsApp_Image_20240326_at_154628.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e62c",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783983_WhatsApp_Image_20240326_at_154628_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6602a2c45ca1625e5060e5c9",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448772581_WhatsApp_Image_20240326_at_154625_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e630",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784004_WhatsApp_Image_20240326_at_154629.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e637",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784026_WhatsApp_Image_20240326_at_154624.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e636",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784025_WhatsApp_Image_20240326_at_154624_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6602a2d05ca1625e5060e633",
    "name": "Bedroom",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784014_WhatsApp_Image_20240326_at_154623_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "9820",
"max": "12651"
},
"builtUpRateRange": {
  "min": "8184",
  "max": "10543"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```



```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "964.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"invoices": [],
"paymentIds": [],
"_id": "65fd537e5ca1625e505c5db3",
"ownerName": "Mr. Praveen Prajapati & Mr. Lalit Kumar",
"ownerPhoneNo": "8010816536",
"appAddress": "flat no 2104 21 th floor Tower no 6 lodha Belmondo village Gahunje
Tal. maval pune ",
"remark": "sSI Rushikesh sir ",
```

```
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "19/03/2024",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Prashant Panday & Mrs. Anjana Panday ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Praveen Prajapati & Mr. Lalit Kumar",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "3347 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "872722",
    "path": "cases/65fd537e5ca1625e505c5db3/
document_1711099743262_1711099924341_DocScanner_22Mar2024_109_pm.pdf",
    "fileName":
"document_1711099743262_1711099924341_DocScanner_22Mar2024_109_pm.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "28/04/2017",
      "nameOfApprovingAuthority": {
        "value": "Pune_Metropolitan_Reginal_Development_Authority",
        "label": "Pune Metropolitan Reginal Development Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]
```

```

    },
    "No": "DP / BMA / Village - Gahunje / G. No. 205 & others / P. K. 7 / 16 - 17"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "630621",
  "path": "cases/65fd537e5ca1625e505c5db3/document_1711518007759_OC.pdf",
  "fileName": "document_1711518007759_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "01/06/2016",
    "nameOfApprovingAuthority": {
      "value": "Pune_Metropolitan_Reginal_Development_Authority",
      "label": "Pune Metropolitan Reginal Development Authority"
    },
    "remark": " (As downloaded from RERA site)",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "BMA / P.K. 7 / 15 - 16 / Village - Gahunje / G.No. 205 & others"
},
  "isHardCopy": false,
  "displayStatus": false,
  "id": "512215",
  "path": "cases/65fd537e5ca1625e505c5db3/document_1711519088330_CC.pdf",
  "fileName": "document_1711519088330_CC.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "15/07/2017",
    "remark": " (As downloaded from RERA site)",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P52100000350"
}

```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1711519130182_P52100000350.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/
document_1711519130182_P52100000350.pdf",
    "id": "716169",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Wed Mar 27 2024 11:28:50 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007915",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "862546",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 22 2024 15:16:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Praveen Prajapati & Mr. Lalit Kumar",
    "phone": "8010816536",
    "ownershipShare": "",
    "email": "",
    "id": "604498"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "8",
    "name": "Bedroom",
    "length": "11.92",
    "length1": "11",
    "length2": "11",
    "width": "11.67",
    "width1": "11",
    "width2": "8",
```

```
"totalArea": "139.03",
"images": [],
"finalArea": "139.03",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "11.92",
  "length1": "11",
  "length2": "11",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "137.04",
  "images": [],
  "finalArea": "137.04",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "6.17",
  "length1": "6",
  "length2": "2",
  "width": "4.92",
  "width1": "4",
  "width2": "11",
  "totalArea": "30.32",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6603f9185ca1625e506329ff",
      "name": "ExtrA",
```

```
    "extraAreaType": "Add",
    "length": "107.00",
    "length1": "107",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "107.00"
  }
],
"finalArea": "137.32"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "39.00",
  "length1": "39",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "39.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "36.00",
  "length1": "36",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "36.00",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "36.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "256.00",
  "length1": "256",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "256.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "256.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Store Room",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "23.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "74.00",
```



```
"length1": "74",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "74.00",
"images": [],
"extraAreas": [],
"finalArea": "74.00"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "64.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "64.17",
  "percentageBeforeTotal": "64.17",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
```

```
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "15.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.11",
  "percentageBeforeTotal": "15.11",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "901973",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "964",
    "squareMeterArea": "89.56",
    "docFinalBuiltUp": "1156.8",
    "docFinalBuiltUpSquareMeter": "107.47200000000001",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
```

```
{
  "printlnReport": true,
  "_id": "6603ccd65ca1625e50627337",
  "property": "Residential Flat",
  "area": "993",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "9751000",
  "expectedRate": "9819.74",
  "builtUpExpectedRate": "8183.12",
  "image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524637922_Image.jpeg",
  "squareMeter": "92.25",
  "id": "154225"
},
{
  "printlnReport": true,
  "_id": "6603ccd65ca1625e50627338",
  "property": "Residential Flat",
  "area": "1223",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "12221000",
  "expectedRate": "9992.64",
  "builtUpExpectedRate": "9084.22",
  "image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524671967_Image.jpeg",
  "squareMeter": "113.62",
  "id": "848383"
},
{
  "printlnReport": true,
  "_id": "6603ccd65ca1625e50627339",
  "property": "Residential Flat",
  "area": "1241",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
```

```
"expectedPrice": "15700000",
"expectedRate": "12651.09",
"builtUpExpectedRate": "10542.57",
"image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524697174_Image.png",
"squareMeter": "115.29",
"id": "951983"
},
{
  "printlnReport": true,
  "_id": "6603ccd65ca1625e5062733a",
  "property": "Residential Flat",
  "area": "1170",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "13500000",
  "expectedRate": "11538.46",
  "builtUpExpectedRate": "9615.38",
  "image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524713017_Image.png",
  "squareMeter": "108.70",
  "id": "986669"
},
{
  "printlnReport": true,
  "_id": "6603ccd65ca1625e5062733b",
  "property": "Residential Flat",
  "area": "1068",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "13200000",
  "expectedRate": "12359.55",
  "builtUpExpectedRate": "10299.63",
  "image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524736282_Image.png",
  "squareMeter": "99.22",
  "id": "155150"
},
{
  "printlnReport": true,
```

```
    "_id": "6603ccd65ca1625e5062733c",
    "property": "Residential Flat",
    "area": "980",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "11500000",
    "expectedRate": "11734.69",
    "builtUpExpectedRate": "9778.91",
    "image": "cases/65fd537e5ca1625e505c5db3/
indicator_1711524756536_Image.png",
    "squareMeter": "91.05",
    "id": "871844"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2c45ca1625e5060e5c8",
    "name":
"externallmg_1711448772576_WhatsApp_Image_20240326_at_154625_1.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448772576_WhatsApp_Image_20240326_at_154625_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2c45ca1625e5060e5c9",
    "name":
"externallmg_1711448772581_WhatsApp_Image_20240326_at_154625_2.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448772581_WhatsApp_Image_20240326_at_154625_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2c45ca1625e5060e5ca",
    "name":
"externallmg_1711448772583_WhatsApp_Image_20240326_at_154626_1.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448772583_WhatsApp_Image_20240326_at_154626_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e626",
    "name":
"externallmg_1711448783957_WhatsApp_Image_20240326_at_154626_2.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783957_WhatsApp_Image_20240326_at_154626_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e627",
    "name":
"externallmg_1711448783963_WhatsApp_Image_20240326_at_154626.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783963_WhatsApp_Image_20240326_at_154626.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e628",
    "name":
"externallmg_1711448783967_WhatsApp_Image_20240326_at_154627_1.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783967_WhatsApp_Image_20240326_at_154627_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e629",
    "name":
"externallmg_1711448783968_WhatsApp_Image_20240326_at_154627_2.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783968_WhatsApp_Image_20240326_at_154627_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e62a",
```

```
"name":
"externallmg_1711448783975_WhatsApp_Image_20240326_at_154627.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783975_WhatsApp_Image_20240326_at_154627.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e62b",
  "name":
"externallmg_1711448783982_WhatsApp_Image_20240326_at_154628_1.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783982_WhatsApp_Image_20240326_at_154628_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e62c",
  "name":
"externallmg_1711448783983_WhatsApp_Image_20240326_at_154628_2.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783983_WhatsApp_Image_20240326_at_154628_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e62d",
  "name":
"externallmg_1711448783984_WhatsApp_Image_20240326_at_154628.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448783984_WhatsApp_Image_20240326_at_154628.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e62e",
  "name":
"externallmg_1711448784000_WhatsApp_Image_20240326_at_154629_1.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784000_WhatsApp_Image_20240326_at_154629_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e62f",
  "name":
"externallmg_1711448784002_WhatsApp_Image_20240326_at_154629_2.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784002_WhatsApp_Image_20240326_at_154629_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e630",
  "name":
"externallmg_1711448784004_WhatsApp_Image_20240326_at_154629.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784004_WhatsApp_Image_20240326_at_154629.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e631",
  "name":
"externallmg_1711448784006_WhatsApp_Image_20240326_at_154620.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784006_WhatsApp_Image_20240326_at_154620.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e632",
  "name":
"externallmg_1711448784008_WhatsApp_Image_20240326_at_154623_1.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784008_WhatsApp_Image_20240326_at_154623_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6602a2d05ca1625e5060e633",
  "name":
"externallmg_1711448784014_WhatsApp_Image_20240326_at_154623_2.jpeg",
```



```
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784014_WhatsApp_Image_20240326_at_154623_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e634",
    "name":
"externallmg_1711448784018_WhatsApp_Image_20240326_at_154623.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784018_WhatsApp_Image_20240326_at_154623.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e635",
    "name":
"externallmg_1711448784022_WhatsApp_Image_20240326_at_154624_1.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784022_WhatsApp_Image_20240326_at_154624_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e636",
    "name":
"externallmg_1711448784025_WhatsApp_Image_20240326_at_154624_2.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784025_WhatsApp_Image_20240326_at_154624_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6602a2d05ca1625e5060e637",
    "name":
"externallmg_1711448784026_WhatsApp_Image_20240326_at_154624.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/
externallmg_1711448784026_WhatsApp_Image_20240326_at_154624.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6602a2d05ca1625e5060e638",
  "name":
"externalImg_1711448784027_WhatsApp_Image_20240326_at_154625.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/
externalImg_1711448784027_WhatsApp_Image_20240326_at_154625.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Valuation_Report_Praveen Prajapati & Mr. Lalit Kumar.pdf",
    "filename":
"1711546213981_Valuation_Report_Praveen Prajapati__Mr_Lalit_Kumar.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/externalDocuments/1711546213981_V
aluation_Report_Praveen Prajapati__Mr_Lalit_Kumar.pdf",
    "size": "1250308",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Wed Mar 27 2024 19:00:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "originalname": "Praveen Prajapati & Mr. Lalit Kumar.pdf",
    "filename": "1711546213999_Praveen Prajapati__Mr_Lalit_Kumar.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/
externalDocuments/1711546213999_Praveen Prajapati__Mr_Lalit_Kumar.pdf",
    "size": "3768737",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Wed Mar 27 2024 19:00:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "path": "../CDN/cases/65fd537e5ca1625e505c5db3/
externalDocuments/1711687296618_440195.pdf",
    "filename": "1711687296618_440195.pdf",
    "documentType": {
      "organization": {
        "status": true,
        "isdelete": false,
        "_id": "5f2bdee67813470eb443deb4",
```

```
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
"shortName": "VCIPL",
"type": "ORGANIZATION",
"city": "Mumbai",
"ownerEmail": "umang@vastukala.org",
"ownerName": "Umang Patel"
},
"_id": "60ae124daa6d152c1801b307",
"document": {
  "documentType": "Office Copy",
  "documentDate": true,
  "to": false,
  "from": false,
  "amount": false,
  "nameOfApprovingAuthority": false,
  "number": false,
  "remarks": true,
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
},
"createdAt": "2021-05-26T09:18:05.809Z",
"updatedAt": "2023-06-20T10:17:50.158Z",
"__v": 0,
"label": "Office Copy",
"value": "60ae124daa6d152c1801b307",
"Name": "Office Copy",
"Value": "60ae124daa6d152c1801b307",
"caseStatus": {
  "value": "DELIVERED",
  "label": "Delivered"
}
},
"createdAt": "Fri Mar 29 2024 10:11:36 GMT+0530 (India Standard Time)",
"uploadedBy": "63fda584ce84bf289baadaf6"
},
{
  "originalname": "Valuation_Report_Praveen Prajapati & Mr. Lalit Kumar.pdf",
  "filename":
  "1711784628815_Valuation_Report_Praveen_Prajapati__Mr_Lalit_Kumar.pdf",
```

```
"path": "cases/65fd537e5ca1625e505c5db3/externalDocuments/1711784628815_Valuation_Report_Praveen_Prajapati__Mr_Lalit_Kumar.pdf",
"size": "1263863",
"documentType": {
  "value": "640ece6024088f0f94ee4ea8",
  "label": "Final PDF Report"
},
"createdAt": "Sat Mar 30 2024 13:13:48 GMT+0530 (India Standard Time)",
"uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "Praveen Prajapati & Mr. Lalit Kumar.pdf",
  "filename": "1711784628838_Praveen_Prajapati__Mr_Lalit_Kumar.pdf",
  "path": "cases/65fd537e5ca1625e505c5db3/externalDocuments/1711784628838_Praveen_Prajapati__Mr_Lalit_Kumar.pdf",
  "size": "3772064",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Sat Mar 30 2024 13:13:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "path": "../CDN/cases/65fd537e5ca1625e505c5db3/externalDocuments/1712117148219_415204.pdf",
  "filename": "1712117148219_415204.pdf",
  "documentType": {
    "organization": {
      "status": true,
      "isdelete": false,
      "_id": "5f2bdee67813470eb443deb4",
      "name": "Vastukala Consultants India Pvt. Ltd.",
      "gstNo": "18AABCT3518Q1ZZ",
      "panNo": "ABCDE1234A",
      "email": "vastukalamumbai@vastukala.com",
      "phone": "9819670183",
      "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093",
      "shortName": "VCIPL",
      "type": "ORGANIZATION",
      "city": "Mumbai",
      "ownerEmail": "umang@vastukala.org",
      "ownerName": "Umang Patel"
    }
  },
  "_id": "60ae124daa6d152c1801b307",
```

```
"document": {
  "documentType": "Office Copy",
  "documentDate": true,
  "to": false,
  "from": false,
  "amount": false,
  "nameOfApprovingAuthority": false,
  "number": false,
  "remarks": true,
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
},
"createdAt": "2021-05-26T09:18:05.809Z",
"updatedAt": "2023-06-20T10:17:50.158Z",
"__v": 0,
"label": "Office Copy",
"value": "60ae124daa6d152c1801b307",
"Name": "Office Copy",
"Value": "60ae124daa6d152c1801b307",
"caseStatus": {
  "value": "DELIVERED",
  "label": "Delivered"
}
},
"createdAt": "Wed Apr 03 2024 09:35:48 GMT+0530 (India Standard Time)",
"uploadedBy": "63fda584ce84bf289baadaf6"
},
],
"processingDocuments": [
  {
    "originalname": "123456.pdf",
    "filename": "1711525103058_123456.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/processingDocuments/1711525103058_123456.pdf",
    "size": "56842675",
    "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1711448784006_WhatsApp_Image_20240326_at_154620.jpeg",
    "filename": "1711525104540_externallmg_1711448784006_WhatsApp_Image_20240326_at_154620.jpeg",
    "path": "cases/65fd537e5ca1625e505c5db3/processingDocuments/1711525104540
```

```
_externallmg_1711448784006_WhatsApp_Image_20240326_at_154620.jpeg",
  "size": "77117",
  "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1711448784018_WhatsApp_Image_20240326_at_154623.jpeg",
  "filename": "1711525104546_externallmg_1711448784018_WhatsApp_Image_202
40326_at_154623.jpeg",
  "path": "cases/65fd537e5ca1625e505c5db3/processingDocuments/1711525104546
_externallmg_1711448784018_WhatsApp_Image_20240326_at_154623.jpeg",
  "size": "75681",
  "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1711525104551_IGR01.pdf",
  "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711525104551_IGR01.pdf",
  "size": "154505",
  "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1711525104562_IGR02.pdf",
  "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711525104562_IGR02.pdf",
  "size": "160755",
  "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1711525104574_IGR03.pdf",
  "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711525104574_IGR03.pdf",
  "size": "152112",
  "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1711525104586_IGR04.pdf",
```

```
    "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711525104586_IGR04.pdf",
    "size": "165117",
    "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=PRAVEEN.xlsx",
    "filename": "1711525104596_Summary_NewPRAVEEN.xlsx",
    "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711525104596_Summary_NewPRAVEEN.xlsx",
    "size": "4693764",
    "createdAt": "Wed Mar 27 2024 13:08:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1711539303531_CC.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711539303531_CC.pdf",
    "size": "581853",
    "createdAt": "Wed Mar 27 2024 17:05:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "P52100000350.pdf",
    "filename": "1711539303547_P52100000350.pdf",
    "path": "cases/65fd537e5ca1625e505c5db3/
processingDocuments/1711539303547_P52100000350.pdf",
    "size": "155871",
    "createdAt": "Wed Mar 27 2024 17:05:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
profilePhoto_1626255068979_Shym_Photo.jpg"
    }
  }
],
```

```
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "6602b1855ca1625e5061269d",
"note": "Pending for value confirmation",
"taskId": "65fd65465ca1625e505c9a95",
"createdAt": "2024-03-26T11:29:09.600Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "PRINT",
  "display": true,
  "status": true,
  "_id": "6607a7245ca1625e50686725",
  "note": "Branch Change (Task Reopen)",
  "taskId": "660412325ca1625e5063ba8f",
  "createdAt": "2024-03-30T05:46:12.276Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "DELIVERY",
  "display": true,
  "status": true,
  "_id": "6607a7295ca1625e5068673b",
  "note": "Branch Change (Task Reopen)",
  "taskId": "66041fa25ca1625e5063ebd1",
  "createdAt": "2024-03-30T05:46:17.071Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
```



```
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "SIGNED_REPORT_UPLOAD",
  "display": true,
  "status": true,
  "_id": "6607a72d5ca1625e5068678a",
  "note": "Branch Change (Task Reopen)",
  "taskId": "6604137d5ca1625e5063bff7",
  "createdAt": "2024-03-30T05:46:21.237Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "PREPARE_INVOICE",
  "display": true,
  "status": true,
  "_id": "6607a7385ca1625e506867b8",
  "note": "Branch Change make 1000+GST Bill (Task Reopen)",
  "taskId": "66040de75ca1625e5063aa85",
  "createdAt": "2024-03-30T05:46:32.388Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6607a73d5ca1625e506867fb",
  "note": "Branch Change (Task Reopen)",
  "taskId": "660404b55ca1625e50636cff",
  "createdAt": "2024-03-30T05:46:37.442Z"
```

```
    },
    {
      "createdBy": {
        "_id": "64dc7184ccaf1e7b7f637f47",
        "role": "FRONTDESK",
        "firstName": "Binumon",
        "lastName": "Moozhickal",
        "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
      },
      "workType": "CHECKER",
      "display": true,
      "status": true,
      "_id": "662f29b2e9ac4776383940c8",
      "note": "Typing error (Task Reopen)",
      "taskId": "660404b55ca1625e50636cff",
      "createdAt": "2024-04-29T05:01:38.843Z"
    },
    {
      "createdBy": {
        "_id": "64dc7184ccaf1e7b7f637f47",
        "role": "FRONTDESK",
        "firstName": "Binumon",
        "lastName": "Moozhickal",
        "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
      },
      "workType": "PRINT",
      "display": true,
      "status": true,
      "_id": "662f29c7e9ac47763839412e",
      "note": "Typing Error (Task Reopen)",
      "taskId": "660412325ca1625e5063ba8f",
      "createdAt": "2024-04-29T05:01:59.876Z"
    }
  ],
  "createdAt": "2024-03-22T09:46:38.341Z",
  "updatedAt": "2024-04-29T05:04:29.432Z",
  "__v": 0,
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "fullAddress": "Residential Flat No. 2104, 21st Floor, Building No 6, Pebble Beach Co-
Op. Hsg. Soc. Ltd. , Lodha Belmondo, Village - Gahunje, Taluka - Maval , District -
Pune , Pune, PIN - 412 101, State - Maharashtra, Country - India",
```

```
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Miss. Pooja ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Friend ",
"siteVisitContactNo": "9145018873",
"builtupPercentage": "10",
"carpetTotal": "841.89",
"extendOfSiteRemark": "\nAll the above areas are 4% of the Agreement for Sale Area.
The above calculations and detail measurements taken by us prove that the Agreement
for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for
Sale area",
"finalBuiltupArea": "1013.29",
"finalCarpetArea": "921.17",
"finalSalableArea": "1114.62",
"otherCarpetTotal": "79.28",
"salablePercentage": "10",
"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 842.00\nBalcony Area in Sq.
Ft. = 64.00\nDry Balcony Area in Sq. Ft. = 15.00\n\n",
"toBeAdded": "",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 964.00",
"flatRate": "11300",
"landOtherRate": "8800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet +
Store Room",
"otherCompositionBuiltUpTotal": "0.00",
```

```

"otherCompositionCarpetTotal": "79.28",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Mar 27 2024 15:44:51 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-26"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	11'11"	11'8"	139.03
Bedroom	11'11"	11'6"	137.04
Passage	6'2"	4'11"	30.32
Toilet	39'00"	1'00"	39.00
Toilet	36'00"	1'00"	36.00
Living Room	256'00"	1'00"	256.00
Store Room	6'00"	3'11"	23.50
Kitchen	74'00"	1'00"	74.00
Other Composition :			
Balcony Area	11'8"	5'6"	64.17

Dry Balcony Area

5'8"

2'8"

15.11
