

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63fd9d80ce84bf289baac3d6"
    },
    "type": "CREDITOFFICER",
    "_id": "650189eea8e9b70221e22779",
    "firstName": "Sumedha",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9967730169",
    "email": "Sumedha.trivedi@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63fd9d80ce84bf289baac3d6",
  "name": "Ghodbandar Road",
  "branchCode": "",
  "mobileNo": "02225896996",
  "alternateMobileNo": "",
  "email": "abhijit.panchpor@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 4, Cosmos Heritage, Tikujini Wadi, Off Ghodbandar Road,
Manpada, Thane West 400 610"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6572cc17d4a67a1d0041f807",
  "role": "SITEENGINEER",
  "firstName": "Laxmi ",
  "email": "wadkarlaxmi1009@gmail.com",
  "lastName": "Salvi (Wadkar)          ",
  "mobileNo": "7057004925",
  "designation": "Site Engg",
  "shortName": "LS",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.19170997830898",
  "longitude": "73.22199321691998"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chikhli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B - 09",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
```

```
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Srushti Hill Complex ",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "6",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Gulmohar Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "128/1 (Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```



```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "303",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
```



```
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6602a9625ca1625e5061062a",
"ownerName": "Vijaylaxmi Keshav Kulkarni & Keshav Shrinavasrao Kulkarni ",
"ownerPhoneNo": "9921076298",
"fullAddress": "Residential Flat No. 303, 3rd Floor, Building No B - 09, Srushti Hill
Complex , Gulmohar Co.-Op. Hsg. Soc. Ltd., Sector 6, Village - Chikhholi, Taluka -
Ambernath, State - Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "inputs": {
    "documentDate": "02/06/2011",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "Laxmandas Dalvani & Mina Laxmandas Dalvani",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Vijaylaxmi Keshav Kulkarni & Keshav Shrinavasrao Kulkarni ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "2964/2011"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "890740",
  "path": "cases/6602a9625ca1625e5061062a/
document_1711450461637_133696.pdf",
  "fileName": "document_1711450461637_133696.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  }
}
```

```
},
"inputs": {
  "documentDate": "04/03/1996",
  "nameOfApprovingAuthority": {
    "value": "Ambernath_Municipal_Council",
    "label": "Ambernath Municipal Council"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "ANP / NRV / BP / 1995 – 1996 / 1162 -310 "
},
"isHardCopy": false,
"displayStatus": true,
"id": "351613",
"path": "cases/6602a9625ca1625e5061062a/
document_1711624548988_Keshav_kulkarni_doc.pdf",
"fileName": "document_1711624548988_Keshav_kulkarni_doc.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "24/04/2003",
    "nameOfApprovingAuthority": {
      "value": "Ambernath_Municipal_Council",
      "label": "Ambernath Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "ANP / NRV / 2003 – 2004 / 55 - 05"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "360397",
  "path": "cases/6602a9625ca1625e5061062a/
document_1712745309221_Occupation_Certificate.pdf",
  "fileName": "document_1712745309221_Occupation_Certificate.pdf"
}
],
"assignmentType": {
```

```
"value": "Retail",
"label": "Retail"
},
"caseNumber": "007974",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "719242",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 26 2024 16:24:26 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vijaylaxmi Keshav Kulkarni & Keshav Shrinavasrao Kulkarni ",
    "phone": "9921076298",
    "ownershipShare": "",
    "email": "",
    "id": "331294"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e5064615e",
    "name":
"externallmg_1711603138342_WhatsApp_Image_20240328_at_94048_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138342_WhatsApp_Image_20240328_at_94048_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e5064615f",
    "name":
"externallmg_1711603138349_WhatsApp_Image_20240328_at_94050_AM.jpeg",
```

```
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138349_WhatsApp_Image_20240328_at_94050_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646160",
    "name":
"externallmg_1711603138368_WhatsApp_Image_20240328_at_94051_AM_1.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138368_WhatsApp_Image_20240328_at_94051_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646161",
    "name":
"externallmg_1711603138382_WhatsApp_Image_20240328_at_94051_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138382_WhatsApp_Image_20240328_at_94051_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646162",
    "name":
"externallmg_1711603138398_WhatsApp_Image_20240328_at_94052_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138398_WhatsApp_Image_20240328_at_94052_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646163",
    "name":
"externallmg_1711603138414_WhatsApp_Image_20240328_at_94053_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138414_WhatsApp_Image_20240328_at_94053_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6604fdc25ca1625e50646164",
    "name":
"externallmg_1711603138433_WhatsApp_Image_20240328_at_94054_AM_1.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138433_WhatsApp_Image_20240328_at_94054_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646165",
    "name":
"externallmg_1711603138457_WhatsApp_Image_20240328_at_94054_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138457_WhatsApp_Image_20240328_at_94054_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646166",
    "name":
"externallmg_1711603138481_WhatsApp_Image_20240328_at_94055_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138481_WhatsApp_Image_20240328_at_94055_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646167",
    "name":
"externallmg_1711603138492_WhatsApp_Image_20240328_at_94058_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138492_WhatsApp_Image_20240328_at_94058_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646168",
    "name":
"externallmg_1711603138501_WhatsApp_Image_20240328_at_94059_AM_1.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138501_WhatsApp_Image_20240328_at_94059_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdc25ca1625e50646169",
    "name":
"externallmg_1711603138516_WhatsApp_Image_20240328_at_94059_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603138516_WhatsApp_Image_20240328_at_94059_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdd95ca1625e50646316",
    "name":
"externallmg_1711603159651_WhatsApp_Image_20240328_at_94100_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159651_WhatsApp_Image_20240328_at_94100_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdd95ca1625e50646317",
    "name":
"externallmg_1711603159671_WhatsApp_Image_20240328_at_94101_AM_1.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159671_WhatsApp_Image_20240328_at_94101_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdd95ca1625e50646318",
    "name":
"externallmg_1711603159684_WhatsApp_Image_20240328_at_94101_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159684_WhatsApp_Image_20240328_at_94101_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdd95ca1625e50646319",
```

```
    "name":
"externallmg_1711603159687_WhatsApp_Image_20240328_at_94102_AM.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159687_WhatsApp_Image_20240328_at_94102_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631a",
  "name":
"externallmg_1711603159705_WhatsApp_Image_20240328_at_94104_AM_1.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159705_WhatsApp_Image_20240328_at_94104_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631b",
  "name":
"externallmg_1711603159724_WhatsApp_Image_20240328_at_94104_AM_2.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159724_WhatsApp_Image_20240328_at_94104_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631c",
  "name":
"externallmg_1711603159750_WhatsApp_Image_20240328_at_94104_AM.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159750_WhatsApp_Image_20240328_at_94104_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631d",
  "name":
"externallmg_1711603159769_WhatsApp_Image_20240328_at_94105_AM_1.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159769_WhatsApp_Image_20240328_at_94105_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631e",
  "name":
"externallmg_1711603159807_WhatsApp_Image_20240328_at_94105_AM_2.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159807_WhatsApp_Image_20240328_at_94105_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e5064631f",
  "name":
"externallmg_1711603159837_WhatsApp_Image_20240328_at_94105_AM.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159837_WhatsApp_Image_20240328_at_94105_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e50646320",
  "name":
"externallmg_1711603159861_WhatsApp_Image_20240328_at_94106_AM_1.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159861_WhatsApp_Image_20240328_at_94106_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e50646321",
  "name":
"externallmg_1711603159881_WhatsApp_Image_20240328_at_94106_AM.jpeg",
  "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159881_WhatsApp_Image_20240328_at_94106_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6604fdd95ca1625e50646322",
  "name":
"externallmg_1711603159911_WhatsApp_Image_20240328_at_95741_AM_1.jpeg",
```



```
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603159911_WhatsApp_Image_20240328_at_95741_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6604fdd95ca1625e50646323",
    "name":
"externallmg_1711603160783_WhatsApp_Image_20240328_at_95741_AM.jpeg",
    "path": "cases/6602a9625ca1625e5061062a/
externallmg_1711603160783_WhatsApp_Image_20240328_at_95741_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "3700.pdf",
    "filename": "1711781787010_3700.pdf",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1711781787010_3700.pdf",
    "size": "164145",
    "createdAt": "Sat Mar 30 2024 12:26:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "dsafffff.jpg",
    "filename": "1711781787016_dsafffff.jpg",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1711781787016_dsafffff.jpg",
    "size": "227490",
    "createdAt": "Sat Mar 30 2024 12:26:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "proige .jpg",
    "filename": "1711781787029_proige_.jpg",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1711781787029_proige_.jpg",
    "size": "237617",
    "createdAt": "Sat Mar 30 2024 12:26:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "sadf.jpg",
```

```
    "filename": "1711781787057_sadf.jpg",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1711781787057_sadf.jpg",
    "size": "217236",
    "createdAt": "Sat Mar 30 2024 12:26:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "Untitled.jpg",
    "filename": "1711781787061_Untitled.jpg",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1711781787061_Untitled.jpg",
    "size": "206318",
    "createdAt": "Sat Mar 30 2024 12:26:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "Book1.xlsx",
    "filename": "1712985762368_Book1.xlsx",
    "path": "cases/6602a9625ca1625e5061062a/
processingDocuments/1712985762368_Book1.xlsx",
    "size": "9757",
    "createdAt": "Sat Apr 13 2024 10:52:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60092304a16fab0f2af9b0c2",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Nitesh",
      "lastName": "Khedekar",
      "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6607b45e5ca1625e5068a98f",
    "note": "value confirmation pending",
    "taskId": "6602a96d5ca1625e506106ca",
    "createdAt": "2024-03-30T06:42:38.565Z"
  }
]
```

```
],
"createdAt": "2024-03-26T10:54:26.864Z",
"updatedAt": "2024-04-13T11:01:55.453Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Vijaylaxmi Keshav Kulkarni & Keshav Shrinavasrao Kulkarni ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9921076298"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			