

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64e58e18daae6a1c980f9e1e"
    },
    "type": "CREDITOFFICER",
    "_id": "64e58e18daae6a1c980f9e20",
    "firstName": "S.K",
    "lastName": "Sushil",
    "mobileNo": "912532463482",
    "workMobileNo": "9168590072",
    "email": "nasikr@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64e58e18daae6a1c980f9e1e",
  "name": "Nashik Road 2",
  "branchCode": "BARB0NASIKR",
  "mobileNo": "91 2535463482",
  "alternateMobileNo": "9168590072",
  "email": "nasikr@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "03 & 04 Icon Plaza, Near Punjab Colony Nashik Pune Road, Datta
Mandir Rd, near Titan Showroom At, Nashik, Maharashtra 422101"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
```

```
    "designation": "",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.941209719767265",
  "longitude": "73.83517786759887"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-31",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
```

```
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Deolali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "10",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Veershaiv",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Lingayat colony Devlali Gaon",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Mouje Deolali",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```

```
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "38/10",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "14",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```



```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422401",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
```

```
"unitBoundaries": {
  "isDisplay": false
},
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sun Mar 31 2024 16:49:58 GMT+0530 (India Standard Time)",
  "number": "2305854",
  "dayCount": "14",
  "monthCount": "602",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "660945d6f50cbc6699c9fb29",
"ownerName": "Swapnil Zarekar",
"ownerPhoneNo": "9420827551",
"fullAddress": "Residential Amalgamated Flats No. 14, 1st Floor, Veershaiv, Plot No.
10, New/Current Survey No. 38/10, Lingayat colony Devlali Gaon, Mouje Deolali,
Village - Deolali, District - Nashik, Nashik, 422401, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1711883723713_swapnil_Zarekar__Aditya_Zarekar.pdf",
    "path": "cases/660945d6f50cbc6699c9fb29/
document_1711883723713_swapnil_Zarekar__Aditya_Zarekar.pdf",
    "id": "736005",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sun Mar 31 2024 16:45:34 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "6077c791395bc80714864a30",
      "label": "Electricity Bill"
    }
  }
]
```



```
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "049084032408"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1712571774467_LT_Energy_Bill.pdf",
    "path": "cases/660945d6f50cbc6699c9fb29/
document_1712571774467_LT_Energy_Bill.pdf",
    "id": "254278",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Mon Apr 08 2024 15:52:54 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008067",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "904699",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Mar 31 2024 16:45:34 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Swapnil Zarekar",
    "phone": "9420827551",
    "ownershipShare": "",
    "email": "",
    "id": "640982"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c2433",
    "name":
"externalImg_1712571647423_WhatsApp_Image_20240408_at_120008_PM.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externalImg_1712571647423_WhatsApp_Image_20240408_at_120008_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c2434",
    "name":
"externalImg_1712571647587_WhatsApp_Image_20240408_at_120009_PM.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externalImg_1712571647587_WhatsApp_Image_20240408_at_120009_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c2435",
    "name":
"externalImg_1712571647751_WhatsApp_Image_20240408_at_120013_PM_1.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externalImg_1712571647751_WhatsApp_Image_20240408_at_120013_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c2436",
    "name":
"externalImg_1712571647818_WhatsApp_Image_20240408_at_120013_PM.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externalImg_1712571647818_WhatsApp_Image_20240408_at_120013_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6613c501834794131c1c2437",
  "name":
"externallmg_1712571647964_WhatsApp_Image_20240408_at_120014_PM_1.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571647964_WhatsApp_Image_20240408_at_120014_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2438",
  "name":
"externallmg_1712571648006_WhatsApp_Image_20240408_at_120014_PM_2.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648006_WhatsApp_Image_20240408_at_120014_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2439",
  "name":
"externallmg_1712571648046_WhatsApp_Image_20240408_at_120014_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648046_WhatsApp_Image_20240408_at_120014_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c243a",
  "name":
"externallmg_1712571648104_WhatsApp_Image_20240408_at_120015_PM_1.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648104_WhatsApp_Image_20240408_at_120015_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c243b",
  "name":
"externallmg_1712571648134_WhatsApp_Image_20240408_at_120015_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648134_WhatsApp_Image_20240408_at_120015_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c243c",
    "name":
"externallmg_1712571648220_WhatsApp_Image_20240408_at_120016_PM_1.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648220_WhatsApp_Image_20240408_at_120016_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c243d",
    "name":
"externallmg_1712571648319_WhatsApp_Image_20240408_at_120016_PM_2.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648319_WhatsApp_Image_20240408_at_120016_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c243e",
    "name":
"externallmg_1712571648376_WhatsApp_Image_20240408_at_120016_PM.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648376_WhatsApp_Image_20240408_at_120016_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c243f",
    "name":
"externallmg_1712571648497_WhatsApp_Image_20240408_at_120017_PM_1.jpeg",
    "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648497_WhatsApp_Image_20240408_at_120017_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6613c501834794131c1c2440",
```

```
    "name":
"externallmg_1712571648556_WhatsApp_Image_20240408_at_120017_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648556_WhatsApp_Image_20240408_at_120017_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2441",
  "name":
"externallmg_1712571648612_WhatsApp_Image_20240408_at_120018_PM_1.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648612_WhatsApp_Image_20240408_at_120018_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2442",
  "name":
"externallmg_1712571648843_WhatsApp_Image_20240408_at_120018_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648843_WhatsApp_Image_20240408_at_120018_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2443",
  "name":
"externallmg_1712571648921_WhatsApp_Image_20240408_at_120019_PM_1.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648921_WhatsApp_Image_20240408_at_120019_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2444",
  "name":
"externallmg_1712571648987_WhatsApp_Image_20240408_at_120019_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571648987_WhatsApp_Image_20240408_at_120019_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2445",
  "name":
"externallmg_1712571649063_WhatsApp_Image_20240408_at_120020_PM.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_1712571649063_WhatsApp_Image_20240408_at_120020_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6613c501834794131c1c2446",
  "name": "externallmg_r_1712571648712_WhatsApp_Image_20240408_at_120018_
PM_2.jpeg",
  "path": "cases/660945d6f50cbc6699c9fb29/
externallmg_r_1712571648712_WhatsApp_Image_20240408_at_120018_PM_2.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"document_1711883723713_swapnil_Zarekar__Aditya_Zarekar.pdf",
    "filename":
"1711883982757_document_1711883723713_swapnil_Zarekar__Aditya_Zarekar.pdf",
    "path": "cases/660945d6f50cbc6699c9fb29/processingDocuments/1711883982757_
document_1711883723713_swapnil_Zarekar__Aditya_Zarekar.pdf",
    "size": "17385704",
    "createdAt": "Sun Mar 31 2024 16:49:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "Swapnil Zarekar.xlsx",
    "filename": "1712571696737_Swapnil_Zarekar.xlsx",
    "path": "cases/660945d6f50cbc6699c9fb29/
processingDocuments/1712571696737_Swapnil_Zarekar.xlsx",
    "size": "609526",
    "createdAt": "Mon Apr 08 2024 15:51:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  }
],
"leadRemarks": [],
"audioRemarks": [],
```

```
"remarks": [
  {
    "createdBy": {
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",
      "firstName": "Rushikesh",
      "lastName": "Pingle",
      "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "6613c4d0834794131c1c2150",
    "note": "VISIT (Task Reopen)",
    "taskId": "660945e5f50cbc6699c9fc2d",
    "createdAt": "2024-04-08T10:20:00.830Z"
  },
  {
    "createdBy": {
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",
      "firstName": "Rushikesh",
      "lastName": "Pingle",
      "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "6613c54e834794131c1c2661",
    "note": "draft word (Task Reopen)",
    "taskId": "6609465bf50cbc6699ca0033",
    "createdAt": "2024-04-08T10:22:06.708Z"
  }
],
"createdAt": "2024-03-31T11:15:34.404Z",
"updatedAt": "2024-04-08T10:22:54.952Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Swapnil Zarekar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9420827551",
"reportGeneratedDate": "Sun Mar 31 2024 16:59:36 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-03-31"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			