

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
    "city": "Thane",
    "shortName": "VCIPL/Thane"
  },
  "client": {
```

```
"_id": "66161d2b834794131c1cce9b",
"type": "PRIVATE_CLIENT",
"name": "UTI Asset Management Company Limited",
"displayName": "UTI Asset Management Company Limited",
"initial": "U"
},
"branch": "",
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
    "firstName": "Priyanka",
    "email": "thane@vastukala.org",
    "lastName": "Pawar",
    "mobileNo": "8928414480",
    "shortName": "PCP",
    "workWithDocumentMaker": "627222afafd7d55eddeddd82"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62720b21afd7d55eddedc545",
    "role": "MAKER+CHECKER",
    "firstName": "Avinash",
    "email": "avinash.pandey@vastukala.org",
    "lastName": "Pandey",
    "mobileNo": "9021605621",
    "designation": "",
    "shortName": "AV",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
```

```
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "18.93101508630537",
  "longitude": "72.82622096419735"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
    0,  
    0  
  ]  
},  
"siteVisit": {  
  "siteVisitStatus": false,  
  "schedule": [],  
  "visitedDate": []  
},  
"marketAnalysisAndRemark": {  
  "audioNotes": []  
},  
"externalReportDetails": {  
  "finalAreaType": "Built_Up",  
  "finalMeasurementType": "Sq. Ft.",  
  "underConstruction": false  
},  
"address": {  
  "state": {  
    "status": true,  
    "name": "State",  
    "key": "state",  
    "value": "Maharashtra",  
    "label": true  
  },  
  "country": {  
    "status": true,  
    "name": "Country",  
    "key": "country",  
    "value": "India",  
    "label": false  
  },  
  "village": {  
    "status": false,  
    "name": "Village",  
    "key": "village",  
    "value": "",  
    "label": true  
  },  
  "floorNo": {  
    "status": true,  
    "name": "Floor No",  
    "key": "floorNo",  
    "value": "Ground",  
    "label": false  
  },  
}
```

```
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Churchgate",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "196",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
```

```
"value": "Lotus Court",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "Fort Division",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Backbay Reclamation",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Jamshedji Tata Road",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "Commercial Showroom ",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
```

```
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1632 ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
```



```
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 020",
  "label": false
},
"suburb": {
  "status": false,
```

```
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6616692e834794131c1dc70e",
"ownerName": "UTI Asset Management Company Limited",
"ownerPhoneNo": "9818897130",
"fullAddress": "Commercial Unit No. Ground Floor, Wing - Commercial Showroom ,
Lotus Court, Jamshedji Tata Road, Plot No. 196, Sector Fort Division, CTS No. 1632 ,
Backbay Reclamation, District - Mumbai, Churchgate, PIN Code - 400 020, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "16/03/2023",
      "remark": "issued by Vastukala Consultants (I) Pvt. Ltd."
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "807040",
    "path": "cases/6616692e834794131c1dc70e/document_1712744746957_Valuation_
Report_UTI_Asset_Management_Company_Limited_Showroom_Plot_No_196.pdf",
    "fileName": "document_1712744746957_Valuation_Report_UTI_Asset_Managemen
```



```
t_Company_Limited_Showroom_Plot_No_196.pdf"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008180",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "949461",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Apr 10 2024 15:55:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "UTI Asset Management Company Limited",
    "phone": "9818897130",
    "ownershipShare": "",
    "email": "",
    "id": "918888"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de30b",
    "name":
"externalmg_1712746635043_WhatsApp_Image_20240404_at_33449_PM_1.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externalmg_1712746635043_WhatsApp_Image_20240404_at_33449_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de30c",
    "name":
"externallmg_1712746635054_WhatsApp_Image_20240404_at_33449_PM_2.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635054_WhatsApp_Image_20240404_at_33449_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de30d",
    "name":
"externallmg_1712746635064_WhatsApp_Image_20240404_at_33449_PM_3.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635064_WhatsApp_Image_20240404_at_33449_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de30e",
    "name":
"externallmg_1712746635075_WhatsApp_Image_20240404_at_33449_PM_4.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635075_WhatsApp_Image_20240404_at_33449_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de30f",
    "name":
"externallmg_1712746635085_WhatsApp_Image_20240404_at_33449_PM_5.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635085_WhatsApp_Image_20240404_at_33449_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de310",
    "name":
"externallmg_1712746635104_WhatsApp_Image_20240404_at_33449_PM.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635104_WhatsApp_Image_20240404_at_33449_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de311",
    "name":
"externallmg_1712746635128_WhatsApp_Image_20240404_at_33450_PM_1.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635128_WhatsApp_Image_20240404_at_33450_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de312",
    "name":
"externallmg_1712746635141_WhatsApp_Image_20240404_at_33450_PM_2.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635141_WhatsApp_Image_20240404_at_33450_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de313",
    "name":
"externallmg_1712746635155_WhatsApp_Image_20240404_at_33450_PM_3.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635155_WhatsApp_Image_20240404_at_33450_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de314",
    "name":
"externallmg_1712746635174_WhatsApp_Image_20240404_at_33450_PM_4.jpeg",
    "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635174_WhatsApp_Image_20240404_at_33450_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6616708b834794131c1de315",
```

```
    "name":
"externallmg_1712746635200_WhatsApp_Image_20240404_at_33450_PM_5.jpeg",
  "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635200_WhatsApp_Image_20240404_at_33450_PM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6616708b834794131c1de316",
  "name":
"externallmg_1712746635218_WhatsApp_Image_20240404_at_33450_PM_6.jpeg",
  "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635218_WhatsApp_Image_20240404_at_33450_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6616708b834794131c1de317",
  "name":
"externallmg_1712746635230_WhatsApp_Image_20240404_at_33450_PM_7.jpeg",
  "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635230_WhatsApp_Image_20240404_at_33450_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6616708b834794131c1de318",
  "name":
"externallmg_1712746635254_WhatsApp_Image_20240404_at_33450_PM.jpeg",
  "path": "cases/6616692e834794131c1dc70e/
externallmg_1712746635254_WhatsApp_Image_20240404_at_33450_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "IGR-01.pdf",
  "filename": "1712745233996_IGR01.pdf",
  "path": "cases/6616692e834794131c1dc70e/
processingDocuments/1712745233996_IGR01.pdf",
  "size": "139831",
  "createdAt": "Wed Apr 10 2024 16:03:54 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1712745233999_IGR02.pdf",
  "path": "cases/6616692e834794131c1dc70e/
processingDocuments/1712745233999_IGR02.pdf",
  "size": "167485",
  "createdAt": "Wed Apr 10 2024 16:03:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Previous Report - Showroom.doc",
  "filename": "1712745234003_Previous_Report__Showroom.doc",
  "path": "cases/6616692e834794131c1dc70e/
processingDocuments/1712745234003_Previous_Report__Showroom.doc",
  "size": "7398400",
  "createdAt": "Wed Apr 10 2024 16:03:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=Showroom-05.04.2024.xlsx",
  "filename": "1712745234166_Summary_NewShowroom05042024.xlsx",
  "path": "cases/6616692e834794131c1dc70e/
processingDocuments/1712745234166_Summary_NewShowroom05042024.xlsx",
  "size": "7679187",
  "createdAt": "Wed Apr 10 2024 16:03:54 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-10T10:25:50.504Z",
"updatedAt": "2024-04-10T12:09:40.283Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "UTI Asset Management Company Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": ""
```

"relationWithOwner": "self",  
"siteVisitContactNo": "9818897130"

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---