

Structural Stability Report

Residential Land and Bungalow On Plot No. 04, Basement + Ground + First Floor, Survey No. 7/ 4/ 1, Near Sacred Heart Convent High School, Kalpataru Nagar, Jaydeep Nagar, Wadala Road, Village - Wadala, Taluka - Nashik, District - Nashik, PIN Code - 422 006, State - Maharashtra, Country - India. belongs to Name of Owner: **Shri. Shaikh Niyaz Ahmed Abdul Vahid.**

This is to certify that on visual inspection, it appears that the structure of Plot No. 04 is in Normal condition and the future life can be reasonably takes under Average condition and with proper periodic repairs & maintenance is about 35years.

General Information:

A.	Introduction	
1	Name of Building	Residential Land and Bungalow on Plot No. 04
2	Property Address	Residential Land and Bungalow On Plot No. 04, Basement + Ground + First Floor, Survey No. 7/ 4/ 1, Near Sacred Heart Convent High School, Kalpataru Nagar, Jaydeep Nagar, Wadala Road, Village - Wadala, Taluka - Nashik, District - Nashik, PIN Code - 422 006, State - Maharashtra, Country - India.
3	Type of Building	Residential Land and Bungalow on Plot No. 04
4	No. of Floors	Basement + Ground + First Floor
5	Whether stilt / podium / open parking provided	Covered Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1999 (As per Occupancy Certificate)
11	Present age of building	25 years
12	Residual age of the building	35years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of Bungalow	Independent Residential Bungalow
14	Methodology adopted	As per visual site inspection



Nashik: 4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra Nandu Naka Link Road, Adgaon, Nashik-422003 (M.S.), INDIA
Email: nashik@vastukala.co.in | Tel : +91 253 4068262/98903 80564

Our Pan India Presence at :

📍 Nanded 📍 Thane 📍 Ahmedabad 📍 Delhi NCR
📍 Mumbai 📍 Nashik 📍 Rajkot 📍 Raipur
📍 Aurangabad 📍 Pune 📍 Indore 📍 Jaipur

Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai** :400072, (M.S), India

📞 +91 22 47495919

✉️ mumbai@vastukala.co.in

🌐 www.vastukala.co.in

B. External Observation of the Building		
1	Plaster	Normal
2	Chajjas	Normal
3	Plumbing	Normal
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	The external condition of the structure is in Normal condition
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	-

E Conclusion	
<p>The captioned Flat is having Ground floor which are constructed in year 1999 (As per Part Occupancy Certificate). Estimated future life under present circumstances is about 35 years' subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 20.04.2024 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Average structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

**Manoj
Chalikwar**
Director

Digitally signed by Manoj Chalikwar
DN: cn=Manoj Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai,
email=manoj@vastukala.org, c=IN
Date: 2024.04.23 17:50:22 +05'30'

Auth. Sign

Manoj B. Chalikwar
Registered Valuer
Chartered Engineer (India)
Reg. No. CAT-I-F-1763
Reg. No. IBBI/RV/07/2018/10366
BOB Empanelment No.: ZO:MZ:ADV:46:941
Encl: Valuation Report.



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



1. ACTUAL SITE PHOTOGRAPHS

