

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "type": "CREDITOFFICER",
    "_id": "6360c7aee363ef22db2f6945",
    "firstName": "SAVITA ",
    "lastName": "GAWARI",
    "mobileNo": "",
    "email": "savita.gawari@sbi.co.in",
    "workMobileNo": "9619121336"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "40000000",
    "discussWithPerson": "SAVITA ",
    "expectedFees": 20000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.065824084877036",
  "longitude": "72.86370555869787"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86370555869787,
    19.065824084877036
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-04-24",
      "remark": "contact person - Manisha "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "BKC",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Bharat Diamond Bourse",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "EC-9020",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6628acbafb52ee7d9c395d3b",
"ownerName": "K Girdharilal International Private Limited",
"ownerPhoneNo": "9867437410",
"appAddress": "BMC, BDB, EC 9020 & 9030",
"remark": "contact person - Manisha ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6628acbafb52ee7d9c395d3b/
document_1713941480300_.1713941276662_ec_9020",
    "fileName": "document_1713941480300_.1713941276662_ec_9020",
    "id": "117988",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6628acbafb52ee7d9c395d3b/
document_1713941496705_1713941293207_EC_9020.pdf",
    "fileName": "document_1713941496705_1713941293207_EC_9020.pdf",
    "id": "732650",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
```

```
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6628acbafb52ee7d9c395d3b/
document_1713941587542_.1713941380013_ec_9030",
  "fileName": "document_1713941587542_.1713941380013_ec_9030",
  "id": "180604",
  "uploadedBy": "62723addafd7d55eddeddfe4",
  "createdAt": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6628acbafb52ee7d9c395d3b/
document_1713941605263_1713941401977_EC_9030_VENUS_TO_KG.pdf",
  "fileName":
"document_1713941605263_1713941401977_EC_9030_VENUS_TO_KG.pdf",
  "id": "359948",
  "uploadedBy": "62723addafd7d55eddeddfe4",
  "createdAt": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6628acbafb52ee7d9c395d3b/
document_1713941682911_.1713941479326_insurance_giridharlal_",
  "fileName": "document_1713941682911_.1713941479326_insurance_giridharlal_",
  "id": "828686",
  "uploadedBy": "62723addafd7d55eddeddfe4",
  "createdAt": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008375",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "925412",
```

```
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Apr 24 2024 12:24:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "K Girdharilal International Private Limited",
    "phone": "9867437410",
    "ownershipShare": "",
    "email": "",
    "id": "881229"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6628e867ee7b0c1701ec6af7",
    "name": "externalImg_1713956812781_1713956607276_image_0.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externalImg_1713956812781_1713956607276_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6628e845ee7b0c1701ec6a0b",
    "name": "externalImg_1713956792396_1713956587347_image_0.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externalImg_1713956792396_1713956587347_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a24f",
    "name":
"externalImg_1714021278197_WhatsApp_Image_20240424_at_155629.jpeg",
```

```
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278197_WhatsApp_Image_20240424_at_155629.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a250",
    "name":
"externallmg_1714021278203_WhatsApp_Image_20240424_at_155630.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278203_WhatsApp_Image_20240424_at_155630.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a251",
    "name":
"externallmg_1714021278209_WhatsApp_Image_20240424_at_155631_1.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278209_WhatsApp_Image_20240424_at_155631_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a252",
    "name":
"externallmg_1714021278214_WhatsApp_Image_20240424_at_155631.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278214_WhatsApp_Image_20240424_at_155631.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a253",
    "name":
"externallmg_1714021278235_WhatsApp_Image_20240424_at_155638_1.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278235_WhatsApp_Image_20240424_at_155638_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6629e39ef231a32fc747a254",
    "name":
"externallmg_1714021278240_WhatsApp_Image_20240424_at_155638.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externallmg_1714021278240_WhatsApp_Image_20240424_at_155638.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a255",
    "name":
"externallmg_1714021278255_WhatsApp_Image_20240424_at_155639_1.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externallmg_1714021278255_WhatsApp_Image_20240424_at_155639_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a256",
    "name":
"externallmg_1714021278279_WhatsApp_Image_20240424_at_155639_2.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externallmg_1714021278279_WhatsApp_Image_20240424_at_155639_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a257",
    "name":
"externallmg_1714021278282_WhatsApp_Image_20240424_at_155639.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externallmg_1714021278282_WhatsApp_Image_20240424_at_155639.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e39ef231a32fc747a258",
    "name":
"externallmg_1714021278285_WhatsApp_Image_20240424_at_155640_1.jpeg",
    "path": "cases/6628acbabf52ee7d9c395d3b/
externallmg_1714021278285_WhatsApp_Image_20240424_at_155640_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e39ef231a32fc747a259",
  "name":
  "externallmg_1714021278288_WhatsApp_Image_20240424_at_155640_2.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278288_WhatsApp_Image_20240424_at_155640_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e39ef231a32fc747a25a",
  "name":
  "externallmg_1714021278290_WhatsApp_Image_20240424_at_155640.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278290_WhatsApp_Image_20240424_at_155640.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e39ef231a32fc747a25b",
  "name":
  "externallmg_1714021278292_WhatsApp_Image_20240424_at_155641_1.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278292_WhatsApp_Image_20240424_at_155641_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e39ef231a32fc747a25c",
  "name":
  "externallmg_1714021278295_WhatsApp_Image_20240424_at_155641_2.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021278295_WhatsApp_Image_20240424_at_155641_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2e5",
```

```
    "name":
"externallmg_1714021308344_WhatsApp_Image_20240424_at_155641.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021308344_WhatsApp_Image_20240424_at_155641.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2e6",
  "name":
"externallmg_1714021311983_WhatsApp_Image_20240424_at_155642.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021311983_WhatsApp_Image_20240424_at_155642.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2e7",
  "name":
"externallmg_1714021312093_WhatsApp_Image_20240424_at_155643_1.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312093_WhatsApp_Image_20240424_at_155643_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2e8",
  "name":
"externallmg_1714021312348_WhatsApp_Image_20240424_at_155643.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312348_WhatsApp_Image_20240424_at_155643.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2e9",
  "name":
"externallmg_1714021312357_WhatsApp_Image_20240424_at_155644_1.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312357_WhatsApp_Image_20240424_at_155644_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2ea",
  "name":
"externallmg_1714021312360_WhatsApp_Image_20240424_at_155644_2.jpeg",
  "path": "cases/6628acbaf52ee7d9c395d3b/
externallmg_1714021312360_WhatsApp_Image_20240424_at_155644_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2eb",
  "name":
"externallmg_1714021312368_WhatsApp_Image_20240424_at_155644.jpeg",
  "path": "cases/6628acbaf52ee7d9c395d3b/
externallmg_1714021312368_WhatsApp_Image_20240424_at_155644.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2ec",
  "name":
"externallmg_1714021312457_WhatsApp_Image_20240424_at_155645_1.jpeg",
  "path": "cases/6628acbaf52ee7d9c395d3b/
externallmg_1714021312457_WhatsApp_Image_20240424_at_155645_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2ed",
  "name":
"externallmg_1714021312464_WhatsApp_Image_20240424_at_155645_2.jpeg",
  "path": "cases/6628acbaf52ee7d9c395d3b/
externallmg_1714021312464_WhatsApp_Image_20240424_at_155645_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6629e3c2f231a32fc747a2ee",
  "name":
"externallmg_1714021312471_WhatsApp_Image_20240424_at_155645.jpeg",
```



```
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312471_WhatsApp_Image_20240424_at_155645.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e3c2f231a32fc747a2ef",
    "name":
"externallmg_1714021312477_WhatsApp_Image_20240424_at_155646_1.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312477_WhatsApp_Image_20240424_at_155646_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e3c2f231a32fc747a2f0",
    "name":
"externallmg_1714021312480_WhatsApp_Image_20240424_at_155646.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312480_WhatsApp_Image_20240424_at_155646.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e3c2f231a32fc747a2f1",
    "name":
"externallmg_1714021312484_WhatsApp_Image_20240424_at_155841.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312484_WhatsApp_Image_20240424_at_155841.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6629e3c2f231a32fc747a2f2",
    "name":
"externallmg_1714021312488_WhatsApp_Image_20240424_at_155842.jpeg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
externallmg_1714021312488_WhatsApp_Image_20240424_at_155842.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [
  {
    "originalname": "AGR-EC-9020.pdf",
    "filename": "1714021246482_AGREC9020.pdf",
    "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021246482_AGREC9020.pdf",
    "size": "15283880",
    "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR-EC-9030.pdf",
    "filename": "1714021246921_AGREC9030.pdf",
    "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021246921_AGREC9030.pdf",
    "size": "10988669",
    "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "INSURANCE.pdf",
    "filename": "1714021247136_INSURANCE.pdf",
    "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247136_INSURANCE.pdf",
    "size": "151389",
    "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "KGIPL-COI consequent to pvt company.jpg",
    "filename": "1714021247140_KGIPLCOI_consequent_to_pvt_company.jpg",
    "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247140_KGIPLCOI_consequent_to_pvt_company.jpg",
    "size": "197215",
    "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "KGIPL-COI consequent to pvt company.pdf",
    "filename": "1714021247144_KGIPLCOI_consequent_to_pvt_company.pdf",
    "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247144_KGIPLCOI_consequent_to_pvt_company.pdf",
    "size": "24487",
    "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
]
```

```
{
  "originalname": "MB-EC-9020.pdf",
  "filename": "1714021247144_MBEC9020.pdf",
  "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247144_MBEC9020.pdf",
  "size": "510915",
  "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "MB-EC-9030.pdf",
  "filename": "1714021247152_MBEC9030.pdf",
  "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247152_MBEC9030.pdf",
  "size": "508952",
  "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Previous Valuation Report.pdf",
  "filename": "1714021247185_Previous_Valuation_Report.pdf",
  "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247185_Previous_Valuation_Report.pdf",
  "size": "958379",
  "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=K. Girdharilal.xlsx",
  "filename": "1714021247209_Summary_NewK_Girdharilal.xlsx",
  "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247209_Summary_NewK_Girdharilal.xlsx",
  "size": "3471625",
  "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "WhatsApp Image 2024-04-24 at 15.56.18.jpeg",
  "filename": "1714021247285_WhatsApp_Image_20240424_at_155618.jpeg",
  "path": "cases/6628acbafb52ee7d9c395d3b/
processingDocuments/1714021247285_WhatsApp_Image_20240424_at_155618.jpeg",
  "size": "173390",
  "createdAt": "Thu Apr 25 2024 10:30:47 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-04-24T06:54:50.189Z",
"updatedAt": "2024-04-25T05:01:54.414Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Industrial Unit No. EC-9020, 9th Floor, Bharat Diamond Bourse, Village
- BKC, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "K Girdharilal International Private Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9867437410",
"siteVisitDate": "2024-04-24"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			