

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6410712a319ffa48baa54078"
    },
    "type": "CREDITOFFICER",
    "_id": "6410712a319ffa48baa5407a",
    "firstName": "Shreekant ",
    "lastName": "patil",
    "mobileNo": "",
    "workMobileNo": "9712282388",
    "email": "ambadnasik@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3540"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6410712a319ffa48baa54078",
  "name": "Ambad Branch, Nashik",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "ambadnasik@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ramashray Apartment Sector C Plot No 283 Near Sambhaji Stadium
Bhadrapada Nasik\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chauthari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.927916239954502",
  "longitude": "73.81244587745479"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Deolali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  }
}
```

```
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Srushti Phase-1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
```

```
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vadner Dumala Road, Vadner Dumala , Deolali Cantonment Board",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B-1",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```



```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422401",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
```

```
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
}
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6634ca5a52e3aa36c81b0867",
"ownerName": "Bijay Pandey",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 2, Ground Floor, Wing - B-1, Sai Srushti Phase-1,
Vadner Dumala Road, Vadner Dumala , Deolali Cantonment Board, Village - Deolali,
Taluka - nashik, District - Nashik, Nashik, 422401",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1714735655069_1_Building_Plan_Approval__NA_Order_f
or_plotted_development.pdf",
    "path": "cases/6634ca5a52e3aa36c81b0867/document_1714735655069_1_Building
_Plan_Approval__NA_Order_for_plotted_development.pdf",
    "id": "394880",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri May 03 2024 16:58:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
```



```
"displayStatus": false,
"fileName": "document_1714735660878_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/6634ca5a52e3aa36c81b0867/document_1714735660878_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "772102",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Fri May 03 2024 16:58:26 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae124aaa6d152c1801b2f7",
"label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1714735666136_Adobe_Scan_30_Apr_2024_1.pdf",
"path": "cases/6634ca5a52e3aa36c81b0867/document_1714735666136_Adobe_Scan_30_Apr_2024_1.pdf",
"id": "666945",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Fri May 03 2024 16:58:26 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae124aaa6d152c1801b2f7",
"label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1714735686411_vijay_Pandey_Notary__Rera.pdf",
"path": "cases/6634ca5a52e3aa36c81b0867/document_1714735686411_vijay_Pandey_Notary__Rera.pdf",
"id": "607491",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Fri May 03 2024 16:58:26 GMT+0530 (India Standard Time)"
}
},
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"caseNumber": "008530",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
{
```

```
"id": "221108",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Fri May 03 2024 16:58:26 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Bijay Pandey",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "285426"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce08",
    "name":
"externalImg_1714735896874_WhatsApp_Image_20240430_at_30059_PM.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externalImg_1714735896874_WhatsApp_Image_20240430_at_30059_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce09",
    "name":
"externalImg_1714735896958_WhatsApp_Image_20240430_at_30120_PM.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externalImg_1714735896958_WhatsApp_Image_20240430_at_30120_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6634cb1b4511fa6f226fce0a",
  "name":
"externallmg_1714735897075_WhatsApp_Image_20240430_at_30121_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897075_WhatsApp_Image_20240430_at_30121_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce0b",
  "name":
"externallmg_1714735897250_WhatsApp_Image_20240430_at_30122_PM_1.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897250_WhatsApp_Image_20240430_at_30122_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce0c",
  "name":
"externallmg_1714735897413_WhatsApp_Image_20240430_at_30122_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897413_WhatsApp_Image_20240430_at_30122_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce0d",
  "name":
"externallmg_1714735897531_WhatsApp_Image_20240430_at_30123_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897531_WhatsApp_Image_20240430_at_30123_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce0e",
  "name":
"externallmg_1714735897643_WhatsApp_Image_20240430_at_30124_PM_1.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897643_WhatsApp_Image_20240430_at_30124_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce0f",
    "name":
"externallmg_1714735897739_WhatsApp_Image_20240430_at_30124_PM.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897739_WhatsApp_Image_20240430_at_30124_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce10",
    "name":
"externallmg_1714735897851_WhatsApp_Image_20240430_at_30125_PM_1.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897851_WhatsApp_Image_20240430_at_30125_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce11",
    "name":
"externallmg_1714735897980_WhatsApp_Image_20240430_at_30125_PM_2.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735897980_WhatsApp_Image_20240430_at_30125_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce12",
    "name":
"externallmg_1714735898134_WhatsApp_Image_20240430_at_30125_PM.jpeg",
    "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898134_WhatsApp_Image_20240430_at_30125_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6634cb1b4511fa6f226fce13",
```

```
"name":
"externallmg_1714735898214_WhatsApp_Image_20240430_at_30126_PM_1.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898214_WhatsApp_Image_20240430_at_30126_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce14",
  "name":
"externallmg_1714735898427_WhatsApp_Image_20240430_at_30126_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898427_WhatsApp_Image_20240430_at_30126_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce15",
  "name":
"externallmg_1714735898616_WhatsApp_Image_20240430_at_30127_PM_1.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898616_WhatsApp_Image_20240430_at_30127_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce16",
  "name":
"externallmg_1714735898733_WhatsApp_Image_20240430_at_30127_PM_2.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898733_WhatsApp_Image_20240430_at_30127_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce17",
  "name":
"externallmg_1714735898860_WhatsApp_Image_20240430_at_30127_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898860_WhatsApp_Image_20240430_at_30127_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce18",
  "name":
"externallmg_1714735898990_WhatsApp_Image_20240430_at_30128_PM_1.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735898990_WhatsApp_Image_20240430_at_30128_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce19",
  "name":
"externallmg_1714735899118_WhatsApp_Image_20240430_at_30128_PM_2.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735899118_WhatsApp_Image_20240430_at_30128_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6634cb1b4511fa6f226fce1a",
  "name":
"externallmg_1714735899286_WhatsApp_Image_20240430_at_30128_PM.jpeg",
  "path": "cases/6634ca5a52e3aa36c81b0867/
externallmg_1714735899286_WhatsApp_Image_20240430_at_30128_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-03T11:28:27.034Z",
"updatedAt": "2024-05-03T11:31:39.775Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Bijay Pandey",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0000000000"
```

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			