

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "KAUSHUIK",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.00399189660537",
  "longitude": "72.84992535295669"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84992535295669,
    19.00399189660537
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/05/2024 12:08 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhoiwada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "31",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "T06",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Crescent Bay",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "3102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Parel",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "663b1a04d34acf0916e27468",
"ownerName": "Ruchika Verma ",
"ownerPhoneNo": "9769722206",
"appAddress": "Flat no3102\ncrescent bay\nBhoiwada Parel \nMumbai ",
"remark": "contact Pooja BM \nwood house branch \n9769722206 Vastukala +
Yogesh Vankar\n\ntwo opinion ",
"documents": [
  {
    "documentType": {
      "label": "Builder Possession Letter",
      "value": "60ae1260aa6d152c1801b35c"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/663b1a04d34acf0916e27468/document_1715149253561_17151490
40570_2d7957fd_b0ef_4659_9e4b_cac3e6a1100b.pdf",
    "fileName": "document_1715149253561_1715149040570_2d7957fd_b0ef_4659_9e
4b_cac3e6a1100b.pdf",
    "id": "622045",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Wed May 08 2024 11:51:56 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "008587",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "952656",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 08 2024 11:51:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ruchika Verma ",
    "phone": "9769722206",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "379461"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "663c51fdd34acf0916e2c124",
    "name": "externallmg_1715229180437_1715228967982_image_0.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229180437_1715228967982_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "663c51fdd34acf0916e2c125",
    "name": "externallmg_1715229180599_1715228967982_image_1.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229180599_1715228967982_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c5215d34acf0916e2c168",
    "name": "externallmg_1715229201412_1715228989953_image_0.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229201412_1715228989953_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c5215d34acf0916e2c169",
    "name": "externallmg_1715229201588_1715228989953_image_1.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229201588_1715228989953_image_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16a",
  "name": "externallmg_1715229201828_1715228989953_image_2.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229201828_1715228989953_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16b",
  "name": "externallmg_1715229202054_1715228989953_image_3.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229202054_1715228989953_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16c",
  "name": "externallmg_1715229202550_1715228989953_image_4.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229202550_1715228989953_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16d",
  "name": "externallmg_1715229202879_1715228989953_image_5.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229202879_1715228989953_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16e",
  "name": "externallmg_1715229203151_1715228989953_image_6.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229203151_1715228989953_image_6.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c16f",
  "name": "externallmg_1715229203577_1715228989953_image_7.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229203577_1715228989953_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c170",
  "name": "externallmg_1715229203895_1715228989953_image_8.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229203895_1715228989953_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c171",
  "name": "externallmg_1715229204152_1715228989953_image_9.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229204152_1715228989953_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c172",
  "name": "externallmg_1715229204584_1715228989953_image_10.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229204584_1715228989953_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c5215d34acf0916e2c173",
  "name": "externallmg_1715229204821_1715228989953_image_11.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229204821_1715228989953_image_11.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcd4",
  "name": "externallmg_1715229223685_1715229012234_image_0.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229223685_1715229012234_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcd5",
  "name": "externallmg_1715229223972_1715229012234_image_1.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229223972_1715229012234_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcd6",
  "name": "externallmg_1715229224242_1715229012234_image_2.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229224242_1715229012234_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcd7",
  "name": "externallmg_1715229224698_1715229012234_image_3.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229224698_1715229012234_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcd8",
  "name": "externallmg_1715229225085_1715229012234_image_4.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229225085_1715229012234_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c522c1c6321090f29bcd9",
    "name": "externallmg_1715229225598_1715229012234_image_5.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229225598_1715229012234_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c522c1c6321090f29bcda",
    "name": "externallmg_1715229225979_1715229012234_image_6.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229225979_1715229012234_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c522c1c6321090f29bcdb",
    "name": "externallmg_1715229226200_1715229012234_image_7.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229226200_1715229012234_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c522c1c6321090f29bcdb",
    "name": "externallmg_1715229226753_1715229012234_image_8.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229226753_1715229012234_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c522c1c6321090f29bcdd",
    "name": "externallmg_1715229227122_1715229012234_image_9.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229227122_1715229012234_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "663c522c1c6321090f29bcde",
  "name": "externallmg_1715229227575_1715229012234_image_10.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229227575_1715229012234_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c522c1c6321090f29bcdf",
  "name": "externallmg_1715229228021_1715229012234_image_11.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229228021_1715229012234_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c52571c6321090f29bd4f",
  "name": "externallmg_1715229262967_1715229050713_image_0.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229262967_1715229050713_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c52571c6321090f29bd50",
  "name": "externallmg_1715229263245_1715229050713_image_1.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229263245_1715229050713_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c52571c6321090f29bd51",
  "name": "externallmg_1715229263627_1715229050713_image_2.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229263627_1715229050713_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "663c52571c6321090f29bd52",
    "name": "externallmg_1715229263947_1715229050713_image_3.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229263947_1715229050713_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd53",
    "name": "externallmg_1715229264363_1715229050713_image_4.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229264363_1715229050713_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd54",
    "name": "externallmg_1715229264977_1715229050713_image_5.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229264977_1715229050713_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd55",
    "name": "externallmg_1715229265490_1715229050713_image_6.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229265490_1715229050713_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd56",
    "name": "externallmg_1715229265918_1715229050713_image_7.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229265918_1715229050713_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd57",
```



```
    "name": "externallmg_1715229266353_1715229050713_image_8.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229266353_1715229050713_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd58",
    "name": "externallmg_1715229266675_1715229050713_image_9.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229266675_1715229050713_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd59",
    "name": "externallmg_1715229267252_1715229050713_image_10.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229267252_1715229050713_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd5a",
    "name": "externallmg_1715229267550_1715229050713_image_11.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229267550_1715229050713_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd5b",
    "name": "externallmg_1715229267982_1715229050713_image_12.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229267982_1715229050713_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd5c",
    "name": "externallmg_1715229269833_1715229050713_image_13.jpeg",
```

```
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229269833_1715229050713_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c52571c6321090f29bd5d",
    "name": "externallmg_1715229270282_1715229050713_image_14.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229270282_1715229050713_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c527f23ff7a08d340621e",
    "name": "externallmg_1715229303530_1715229091342_image_0.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229303530_1715229091342_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c527f23ff7a08d340621f",
    "name": "externallmg_1715229306062_1715229091342_image_1.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229306062_1715229091342_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c527f23ff7a08d3406220",
    "name": "externallmg_1715229306504_1715229091342_image_2.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229306504_1715229091342_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c527f23ff7a08d3406221",
    "name": "externallmg_1715229306912_1715229091342_image_3.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229306912_1715229091342_image_3.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406222",
  "name": "externallmg_1715229307157_1715229091342_image_4.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229307157_1715229091342_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406223",
  "name": "externallmg_1715229307567_1715229091342_image_5.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229307567_1715229091342_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406224",
  "name": "externallmg_1715229308245_1715229091342_image_6.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229308245_1715229091342_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406225",
  "name": "externallmg_1715229308648_1715229091342_image_7.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229308648_1715229091342_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406226",
  "name": "externallmg_1715229309017_1715229091342_image_8.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229309017_1715229091342_image_8.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406227",
  "name": "externallmg_1715229309269_1715229091342_image_9.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229309269_1715229091342_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406228",
  "name": "externallmg_1715229309521_1715229091342_image_10.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229309521_1715229091342_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d3406229",
  "name": "externallmg_1715229310128_1715229091342_image_11.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229310128_1715229091342_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d340622a",
  "name": "externallmg_1715229310702_1715229091342_image_12.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229310702_1715229091342_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d340622b",
  "name": "externallmg_1715229310928_1715229091342_image_13.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229310928_1715229091342_image_13.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c527f23ff7a08d340622c",
  "name": "externallmg_1715229311083_1715229091342_image_14.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229311083_1715229091342_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c529d1c6321090f29bdae",
  "name": "externallmg_1715229336973_1715229125381_image_0.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229336973_1715229125381_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c529d1c6321090f29bdaf",
  "name": "externallmg_1715229337395_1715229125381_image_1.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229337395_1715229125381_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c529d1c6321090f29bdb0",
  "name": "externallmg_1715229338092_1715229125381_image_2.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229338092_1715229125381_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663c529d1c6321090f29bdb1",
  "name": "externallmg_1715229339118_1715229125381_image_3.jpeg",
  "path": "cases/663b1a04d34acf0916e27468/
externallmg_1715229339118_1715229125381_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c529d1c6321090f29bdb2",
    "name": "externalImg_1715229339636_1715229125381_image_4.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externalImg_1715229339636_1715229125381_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c529d1c6321090f29bdb3",
    "name": "externalImg_1715229340010_1715229125381_image_5.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externalImg_1715229340010_1715229125381_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663c529d1c6321090f29bdb4",
    "name": "externalImg_1715229340579_1715229125381_image_6.jpeg",
    "path": "cases/663b1a04d34acf0916e27468/
externalImg_1715229340579_1715229125381_image_6.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-08T06:21:56.876Z",
"updatedAt": "2024-05-09T04:35:41.730Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 3102, 31st Floor, Building No T06, Crescent Bay,
Village - Bhoiwada, Parel, Mumbai",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Ruchika Verma ",
"email": "",
```

"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9769722206"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---