

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "firstName": "Priti",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhudurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
},
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.218022129911475",
  "longitude": "73.08735266668128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-09",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "G. B. Patharli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali East",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vij Prabha Complex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Patkar Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Office No. 18",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
```

```
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```



```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "663c5475d34acf0916e2c225",
"ownerName": "Mr. Prashant Vasant Suvarna",
"ownerPhoneNo": "9892591170",
"fullAddress": "Residential Office No. Office No. 18, 3rd Floor, Vij Prabha Complex,
Patkar Road, Village - G. B. Patharli, Taluka - Kalyan, District - Thane, Dombivali East",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "16/07/1997",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "Bhatt And Bhandari Associates",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Prashant Vasant Suvarna",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]
```

```
    },
    "No": "0000"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715229793877_Suvarna_Agr_cos_D.pdf",
  "path": "cases/663c5475d34acf0916e2c225/
document_1715229793877_Suvarna_Agr_cos_D.pdf",
  "id": "478818",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 10:13:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715229807590_57744.pdf",
  "path": "cases/663c5475d34acf0916e2c225/
document_1715229807590_57744.pdf",
  "id": "359724",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu May 09 2024 10:13:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/03/1996",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Mahanagarpalika",
      "label": "Kalyan Mahanagarpalika"
    }
  },
  "number": {
    "value": "No",
    "label": "No"
  }
}
```

```
    },
    "No": "KMC / NRV / BP / DOM / 614 - 167 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/663c5475d34acf0916e2c225/
document_1715774062348_274144.pdf",
  "fileName": "document_1715774062348_274144.pdf",
  "id": "140002",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed May 15 2024 17:29:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "19/03/1999",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KMC / NRV / CC / DOM / KMC / 536 "
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715774128309_118531.pdf",
  "path": "cases/663c5475d34acf0916e2c225/
document_1715774128309_118531.pdf",
  "id": "502765",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed May 15 2024 17:29:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/03/1996",
    "nameOfApprovingAuthority": {
```

```
    "value": "Kalyan_Mahanagarpalika",
    "label": "Kalyan Mahanagarpalika"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "KMC / NRV / BP / DOM / 614 - 167 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1715774219021_594916.pdf",
"path": "cases/663c5475d34acf0916e2c225/
document_1715774219021_594916.pdf",
"id": "883093",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Wed May 15 2024 17:29:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "26/09/2015",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "13"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715774360519_93419.pdf",
  "path": "cases/663c5475d34acf0916e2c225/
document_1715774360519_93419.pdf",
  "id": "544258",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed May 15 2024 17:29:21 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008608",
```

```
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "936422",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 09 2024 10:13:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Prashant Vasant Suvarna",
    "phone": "9892591170",
    "ownershipShare": "",
    "email": "",
    "id": "106758"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b7b",
    "name": "externalImg_1715265373768_1715265162717_image_0.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/externalImg_1715265373768_1715265162717_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b7c",
    "name": "externalImg_1715265374923_1715265162717_image_1.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/externalImg_1715265374923_1715265162717_image_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b7d",
    "name": "externallmg_1715265375837_1715265162717_image_2.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265375837_1715265162717_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b7e",
    "name": "externallmg_1715265376678_1715265162717_image_3.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265376678_1715265162717_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b7f",
    "name": "externallmg_1715265377642_1715265162717_image_4.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265377642_1715265162717_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b80",
    "name": "externallmg_1715265378096_1715265162717_image_5.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265378096_1715265162717_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663cdf64633fdd2360772b81",
    "name": "externallmg_1715265378592_1715265162717_image_6.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265378592_1715265162717_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "663cdf64633fdd2360772b82",
  "name": "externallmg_1715265379057_1715265162717_image_7.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265379057_1715265162717_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663cdf64633fdd2360772b83",
  "name": "externallmg_1715265379432_1715265162717_image_8.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265379432_1715265162717_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663cdf64633fdd2360772b84",
  "name": "externallmg_1715265379857_1715265162717_image_9.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265379857_1715265162717_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "663cdf3bba518823200572b1",
  "name": "externallmg_1715265338294_1715265128794_image_0.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265338294_1715265128794_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "663cdf3bba518823200572b2",
  "name": "externallmg_1715265338539_1715265128795_image_1.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/
externallmg_1715265338539_1715265128795_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "663cdf3bba518823200572b3",
    "name": "externalimg_1715265338723_1715265128795_image_2.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externalimg_1715265338723_1715265128795_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "663cdf3bba518823200572b4",
    "name": "externalimg_1715265339094_1715265128795_image_3.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
externalimg_1715265339094_1715265128795_image_3.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "area.pdf",
    "filename": "1715759075041_area.pdf",
    "path": "cases/663c5475d34acf0916e2c225/
processingDocuments/1715759075041_area.pdf",
    "size": "59003",
    "createdAt": "Wed May 15 2024 13:14:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1715759075044_igr1.pdf",
    "path": "cases/663c5475d34acf0916e2c225/
processingDocuments/1715759075044_igr1.pdf",
    "size": "194045",
    "createdAt": "Wed May 15 2024 13:14:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1715759075050_igr2.pdf",
    "path": "cases/663c5475d34acf0916e2c225/
processingDocuments/1715759075050_igr2.pdf",
    "size": "147012",
    "createdAt": "Wed May 15 2024 13:14:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
```



```
    "originalname": "PRevious value.jpeg",
    "filename": "1715759075055_PRevious_value.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/
processingDocuments/1715759075055_PRevious_value.jpeg",
    "size": "103153",
    "createdAt": "Wed May 15 2024 13:14:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - prashant.xlsx",
    "filename": "1715759075058_Summary__prashant.xlsx",
    "path": "cases/663c5475d34acf0916e2c225/
processingDocuments/1715759075058_Summary__prashant.xlsx",
    "size": "3164458",
    "createdAt": "Wed May 15 2024 13:14:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "WhatsApp Image 2024-05-11 at 11.37.46 AM (1).jpeg",
    "filename":
"1715759091652_WhatsApp_Image_20240511_at_113746_AM_1.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091652
_WhatsApp_Image_20240511_at_113746_AM_1.jpeg",
    "size": "594916",
    "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "WhatsApp Image 2024-05-11 at 11.37.46 AM (2).jpeg",
    "filename":
"1715759091664_WhatsApp_Image_20240511_at_113746_AM_2.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091664
_WhatsApp_Image_20240511_at_113746_AM_2.jpeg",
    "size": "340140",
    "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "WhatsApp Image 2024-05-11 at 11.37.46 AM.jpeg",
    "filename": "1715759091674_WhatsApp_Image_20240511_at_113746_AM.jpeg",
    "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091674
_WhatsApp_Image_20240511_at_113746_AM.jpeg",
    "size": "431004",
    "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
}
```

```
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.47 AM (1).jpeg",
  "filename":
"1715759091686_WhatsApp_Image_20240511_at_113747_AM_1.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091686
_WhatsApp_Image_20240511_at_113747_AM_1.jpeg",
  "size": "189971",
  "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.47 AM (2).jpeg",
  "filename":
"1715759091689_WhatsApp_Image_20240511_at_113747_AM_2.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091689
_WhatsApp_Image_20240511_at_113747_AM_2.jpeg",
  "size": "148113",
  "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.47 AM.jpeg",
  "filename": "1715759091692_WhatsApp_Image_20240511_at_113747_AM.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091692
_WhatsApp_Image_20240511_at_113747_AM.jpeg",
  "size": "262566",
  "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.48 AM (1).jpeg",
  "filename":
"1715759091698_WhatsApp_Image_20240511_at_113748_AM_1.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759091698
_WhatsApp_Image_20240511_at_113748_AM_1.jpeg",
  "size": "174649",
  "createdAt": "Wed May 15 2024 13:14:51 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.48 AM.jpeg",
  "filename": "1715759104542_WhatsApp_Image_20240511_at_113748_AM.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104542
_WhatsApp_Image_20240511_at_113748_AM.jpeg",
  "size": "293007",
  "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.49 AM.jpeg",
  "filename": "1715759104549_WhatsApp_Image_20240511_at_113749_AM.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104549_WhatsApp_Image_20240511_at_113749_AM.jpeg",
  "size": "623732",
  "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.50 AM.jpeg",
  "filename": "1715759104563_WhatsApp_Image_20240511_at_113750_AM.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104563_WhatsApp_Image_20240511_at_113750_AM.jpeg",
  "size": "308382",
  "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.51 AM (1).jpeg",
  "filename":
"1715759104569_WhatsApp_Image_20240511_at_113751_AM_1.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104569_WhatsApp_Image_20240511_at_113751_AM_1.jpeg",
  "size": "171774",
  "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.51 AM (2).jpeg",
  "filename":
"1715759104573_WhatsApp_Image_20240511_at_113751_AM_2.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104573_WhatsApp_Image_20240511_at_113751_AM_2.jpeg",
  "size": "203360",
  "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "WhatsApp Image 2024-05-11 at 11.37.51 AM.jpeg",
  "filename": "1715759104576_WhatsApp_Image_20240511_at_113751_AM.jpeg",
  "path": "cases/663c5475d34acf0916e2c225/processingDocuments/1715759104576_WhatsApp_Image_20240511_at_113751_AM.jpeg",
  "size": "187518",
```

```

    "createdAt": "Wed May 15 2024 13:15:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-09T04:43:33.811Z",
"updatedAt": "2024-05-15T11:59:21.165Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Prashant Vasant Suvarna",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892591170"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			