

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "type": "CREDITOFFICER",
    "_id": "64df02beccaf1e7b7f665818",
    "firstName": "Mayuri",
    "lastName": "Auti",
    "mobileNo": "",
    "workMobileNo": "9867745515",
    "email": "mayuri@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Mayuri",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
```

```
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.996500",
  "longitude": "72.829006"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.829006,
    18.9965
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "lower Parel - West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Manik co op hsg Ltd",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "sitaram jadhav Marg ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "218",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "664747de8a65804291e93f33",
"ownerName": "Sahadev Dasgaonkar",
"ownerPhoneNo": "9664282972",
"appAddress": "Flat no 218, 2nd floor, Manik co op hsg Ltd, sitaram jadhav Marg ,
lower Parel - West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    }
  },
  "isHardCopy": false,
```

```
"displayStatus": false,
"path": "cases/664747de8a65804291e93f33/
document_1715947474059_122633.pdf",
"fileName": "document_1715947474059_122633.pdf",
"id": "190591",
"uploadedBy": "62723addafd7d55eddeddfe4",
"createdAt": "Fri May 17 2024 17:34:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "23/05/2001",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "-"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1716982506218_1391526.pdf",
"path": "cases/664747de8a65804291e93f33/
document_1716982506218_1391526.pdf",
"id": "773360",
"uploadedBy": "60092304a16fab0f2af9b0c2",
"createdAt": "Wed May 29 2024 17:07:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "24/12/1999",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-",
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716982561430_1768988.pdf",
"path": "cases/664747de8a65804291e93f33/
document_1716982561430_1768988.pdf",
"id": "129010",
"uploadedBy": "60092304a16fab0f2af9b0c2",
"createdAt": "Wed May 29 2024 17:07:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1257aa6d152c1801b335",
    "label": "Society Registration Certificate"
  },
  "inputs": {
    "documentDate": "03/01/2003",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "-"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716982641714_1568542.pdf",
"path": "cases/664747de8a65804291e93f33/
document_1716982641714_1568542.pdf",
"id": "319245",
"uploadedBy": "60092304a16fab0f2af9b0c2",
"createdAt": "Wed May 29 2024 17:07:21 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008799",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "982004",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri May 17 2024 17:34:46 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Sahadev Dasgaonkar",
    "phone": "9664282972",
    "ownershipShare": "",
    "email": "",
    "id": "733259"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e67",
    "name": "externallmg_1716449619162_1716449455141_image_0.jpeg",
    "path": "cases/664747de8a65804291e93f33/externallmg_1716449619162_1716449455141_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e68",
    "name": "externallmg_1716449619934_1716449455141_image_1.jpeg",
    "path": "cases/664747de8a65804291e93f33/externallmg_1716449619934_1716449455141_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e69",
    "name": "externallmg_1716449620251_1716449455141_image_2.jpeg",
    "path": "cases/664747de8a65804291e93f33/externallmg_1716449620251_1716449455141_image_2.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e6a",
  "name": "externallmg_1716449620473_1716449455141_image_3.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449620473_1716449455141_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e6b",
  "name": "externallmg_1716449620517_1716449455141_image_4.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449620517_1716449455141_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e6c",
  "name": "externallmg_1716449620868_1716449455141_image_5.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449620868_1716449455141_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e6d",
  "name": "externallmg_1716449621317_1716449455141_image_6.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449621317_1716449455141_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e6e",
  "name": "externallmg_1716449621667_1716449455141_image_7.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449621667_1716449455141_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e6f",
    "name": "externallmg_1716449621859_1716449455141_image_8.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449621859_1716449455141_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e70",
    "name": "externallmg_1716449622022_1716449455141_image_9.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449622022_1716449455141_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e71",
    "name": "externallmg_1716449622266_1716449455141_image_10.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449622266_1716449455141_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e72",
    "name": "externallmg_1716449622423_1716449455141_image_11.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449622423_1716449455141_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e73",
    "name": "externallmg_1716449622624_1716449455141_image_12.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449622624_1716449455141_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "664ef157415afe1810494e74",
  "name": "externallmg_1716449623019_1716449455141_image_13.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623019_1716449455141_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e75",
  "name": "externallmg_1716449623035_1716449455141_image_14.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623035_1716449455141_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e76",
  "name": "externallmg_1716449623208_1716449455141_image_15.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623208_1716449455141_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e77",
  "name": "externallmg_1716449623331_1716449455141_image_16.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623331_1716449455141_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ef157415afe1810494e78",
  "name": "externallmg_1716449623337_1716449455141_image_17.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623337_1716449455141_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "664ef157415afe1810494e79",
    "name": "externallmg_1716449623344_1716449455141_image_18.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623344_1716449455141_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef157415afe1810494e7a",
    "name": "externallmg_1716449623392_1716449455141_image_19.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449623392_1716449455141_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed1",
    "name": "externallmg_1716449653935_1716449491151_image_0.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449653935_1716449491151_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed2",
    "name": "externallmg_1716449654156_1716449491151_image_1.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654156_1716449491151_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed3",
    "name": "externallmg_1716449654286_1716449491151_image_2.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654286_1716449491151_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed4",
```



```
    "name": "externallmg_1716449654426_1716449491151_image_3.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654426_1716449491151_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed5",
    "name": "externallmg_1716449654525_1716449491151_image_4.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654525_1716449491151_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed6",
    "name": "externallmg_1716449654666_1716449491151_image_5.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654666_1716449491151_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed7",
    "name": "externallmg_1716449654749_1716449491151_image_6.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654749_1716449491151_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed8",
    "name": "externallmg_1716449654892_1716449491151_image_7.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654892_1716449491151_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494ed9",
    "name": "externallmg_1716449654952_1716449491151_image_8.jpeg",
```

```
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654952_1716449491151_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494eda",
    "name": "externallmg_1716449654996_1716449491151_image_9.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449654996_1716449491151_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494edb",
    "name": "externallmg_1716449655034_1716449491151_image_10.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449655034_1716449491151_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494edc",
    "name": "externallmg_1716449655071_1716449491151_image_11.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449655071_1716449491151_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ef177415afe1810494edd",
    "name": "externallmg_1716449655097_1716449491151_image_12.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449655097_1716449491151_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "664ef11099e95b180a31c2e1",
    "name": "externallmg_1716449551950_1716449386685_image_0.jpeg",
    "path": "cases/664747de8a65804291e93f33/
externallmg_1716449551950_1716449386685_image_0.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "664ef11099e95b180a31c2e2",
  "name": "externalImg_1716449552324_1716449386685_image_1.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externalImg_1716449552324_1716449386685_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "664ef11099e95b180a31c2e3",
  "name": "externalImg_1716449552390_1716449386685_image_2.jpeg",
  "path": "cases/664747de8a65804291e93f33/
externalImg_1716449552390_1716449386685_image_2.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [
  {
    "originalname": "Sahadeo Gopal Dasgaonkar.doc",
    "filename": "1716982310984_Sahadeo_Gopal_Dasgaonkar.doc",
    "path": "cases/664747de8a65804291e93f33/
externalDocuments/1716982310984_Sahadeo_Gopal_Dasgaonkar.doc",
    "size": "7035392",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Wed May 29 2024 17:01:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"processingDocuments": [
  {
    "originalname": "Calculation sahadev.xlsx",
    "filename": "1716874623624_Calculation__sahadev.xlsx",
    "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716874623624_Calculation__sahadev.xlsx",
    "size": "15561",
    "createdAt": "Tue May 28 2024 11:07:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  }
],
```

```
{
  "originalname": "price .jpg",
  "filename": "1716874623626_price_.jpg",
  "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716874623626_price_.jpg",
  "size": "224669",
  "createdAt": "Tue May 28 2024 11:07:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "60092304a16fab0f2af9b0c2"
},
{
  "originalname": "price 2.jpg",
  "filename": "1716874623637_price_2.jpg",
  "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716874623637_price_2.jpg",
  "size": "232857",
  "createdAt": "Tue May 28 2024 11:07:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "60092304a16fab0f2af9b0c2"
},
{
  "originalname": "price 3.jpg",
  "filename": "1716874623644_price_3.jpg",
  "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716874623644_price_3.jpg",
  "size": "256939",
  "createdAt": "Tue May 28 2024 11:07:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "60092304a16fab0f2af9b0c2"
},
{
  "originalname": "8799.doc",
  "filename": "1716919511394_8799.doc",
  "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716919511394_8799.doc",
  "size": "6912512",
  "createdAt": "Tue May 28 2024 23:35:15 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "1716874623624_Calculation__sahadev.xlsx",
  "filename": "1716919515116_1716874623624_Calculation__sahadev.xlsx",
  "path": "cases/664747de8a65804291e93f33/
processingDocuments/1716919515116_1716874623624_Calculation__sahadev.xlsx",
  "size": "15049",
  "createdAt": "Tue May 28 2024 23:35:15 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
```

```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "627221f4afd7d55eddeddcb4",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Prajakta",
      "lastName": "Patil",
      "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "6655c03c9bc0d00b08d37acc",
    "note": "pending of OC",
    "taskId": "66556da605de72512028a4b3",
    "createdAt": "2024-05-28T11:30:04.085Z"
  },
  {
    "createdBy": {
      "_id": "627221f4afd7d55eddeddcb4",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Prajakta",
      "lastName": "Patil",
      "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "66561ce305de725120291df9",
    "note": "pending for oc",
    "taskId": "66556da605de72512028a4b3",
    "createdAt": "2024-05-28T18:05:23.548Z"
  }
],
"createdAt": "2024-05-17T12:04:46.080Z",
"updatedAt": "2024-05-29T11:37:21.842Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 218, 2nd Floor, Manik co op hsg Ltd, sitaram
```

jadhav Marg , lower Parel - West, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Sahadev Dasgaonkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9664282972",
"siteVisitDate": "2024-05-23"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
