

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b31",
    "email": "resham.kulkarni@cosmosbank.in",
    "firstName": "Resham ",
    "mobileNo": "9987780572",
    "workMobileNo": "9987780572",
    "lastName": "Kulkarni"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.227100385888413",
  "longitude": "72.96704165659233"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23",
      "remark": ""
    }
  ]
},
"schedule": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Majiwade",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "C - 29",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vasant Jai Jui Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pokhran Road No. 2",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vasant Vihar Complex",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "33",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 610",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```



```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "66487ffe6f40574290c1c5b6",
"ownerName": "Mr. Bijlesh Bhaskara Menon & Deepa Bijlesh Menon",
"ownerPhoneNo": "9833022224",
"fullAddress": "Residential Flat No. 33, 3rd Floor, Building No C - 29, Vasant Jai Jui
Co.-Op. Hsg. Soc. Ltd., Vasant Vihar Complex, Pokhran Road No. 2, Village - Majiwade,
Taluka - Thane, District - Thane, Thane West, PIN Code - 400 610, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/08/2007",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Poreyana Poovaiah Ramaiah",
      "to": {
        "value": "transferee",
        "label": "transferee"
      }
    }
  }
],
```

```
"transferee": "Mr. Bijlesh Bhaskara Menon & Deepa Bijlesh Menon",
"number": {
  "value": "No",
  "label": "No"
},
"No": "5855/2007"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716027203257_Cosmos_gb_road_brijesh_Menon_ref_cha
ndrakant_katkade.pdf",
"path": "cases/66487ffe6f40574290c1c5b6/document_1716027203257_Cosmos_gb
_road_brijesh_Menon_ref_chandrakant_katkade.pdf",
"id": "899400",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Sat May 18 2024 15:46:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1716027214571_Index_II.pdf",
"path": "cases/66487ffe6f40574290c1c5b6/
document_1716027214571_Index_II.pdf",
"id": "426216",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Sat May 18 2024 15:46:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "16/05/2023",
    "remark": "issued by Vastukala Consultants Pvt. Ltd. for BOI"
  }
},
```

```
"isHardCopy": false,
"displayStatus": true,
"id": "758789",
"path": "cases/66487ffe6f40574290c1c5b6/
document_1716027383294_Thane_Medical_Agency_reports.pdf",
"fileName": "document_1716027383294_Thane_Medical_Agency_reports.pdf"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "22/12/2022",
    "remark": "issued by Vastukala Consultants Pvt. Ltd. for Cosmos"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/66487ffe6f40574290c1c5b6/
document_1716635041537_CBValuation_Report_Bijesh_Menon__Sign_Report.pdf",
  "fileName":
"document_1716635041537_CBValuation_Report_Bijesh_Menon__Sign_Report.pdf",
  "id": "235854",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Sat May 25 2024 16:38:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/04/1972",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Not visible"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716635213647_254503.pdf",
```

```
    "path": "cases/66487ffe6f40574290c1c5b6/
document_1716635213647_254503.pdf",
    "id": "196902",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Sat May 25 2024 16:38:10 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "24/04/1990",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      },
      "number": {
        "value": "V.P._No._",
        "label": "V.P. No. "
      },
      "V.P._No._": "84 / 153"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1716635290850_259963.pdf",
    "path": "cases/66487ffe6f40574290c1c5b6/
document_1716635290850_259963.pdf",
    "id": "741006",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Sat May 25 2024 16:38:10 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "008819",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "427472",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat May 18 2024 15:46:30 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Bijlesh Bhaskara Menon & Deepa Bijlesh Menon",
    "phone": "9833022224",
    "ownershipShare": "",
    "email": "",
    "id": "520510"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2a5d7ce151854f3dec8",
    "name": "externallmg_1716441758808_1716441592666_image_0.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/externallmg_1716441758808_1716441592666_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2a5d7ce151854f3dec9",
    "name": "externallmg_1716441759090_1716441592666_image_1.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/externallmg_1716441759090_1716441592666_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2a5d7ce151854f3deca",
    "name": "externallmg_1716441759804_1716441592666_image_2.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/externallmg_1716441759804_1716441592666_image_2.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ed2a5d7ce151854f3decb",
  "name": "externallmg_1716441760321_1716441592666_image_3.jpeg",
  "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441760321_1716441592666_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ed2a5d7ce151854f3decc",
  "name": "externallmg_1716441761061_1716441592666_image_4.jpeg",
  "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441761061_1716441592666_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ed2a5d7ce151854f3decd",
  "name": "externallmg_1716441761305_1716441592666_image_5.jpeg",
  "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441761305_1716441592666_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ed2a5d7ce151854f3dece",
  "name": "externallmg_1716441761756_1716441592666_image_6.jpeg",
  "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441761756_1716441592666_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ed2a5d7ce151854f3decf",
  "name": "externallmg_1716441762480_1716441592666_image_7.jpeg",
  "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441762480_1716441592666_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664ed2a5d7ce151854f3ded0",
"name": "externallmg_1716441762826_1716441592666_image_8.jpeg",
"path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441762826_1716441592666_image_8.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664ed2a5d7ce151854f3ded1",
"name": "externallmg_1716441763325_1716441592666_image_9.jpeg",
"path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441763325_1716441592666_image_9.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664ed2a5d7ce151854f3ded2",
"name": "externallmg_1716441763759_1716441592666_image_10.jpeg",
"path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441763759_1716441592666_image_10.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664ed2a5d7ce151854f3ded3",
"name": "externallmg_1716441764200_1716441592666_image_11.jpeg",
"path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441764200_1716441592666_image_11.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664ed2a5d7ce151854f3ded4",
"name": "externallmg_1716441764676_1716441592666_image_12.jpeg",
"path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441764676_1716441592666_image_12.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "664ed2d199e95b180a31a262",
    "name": "externallmg_1716441801544_1716441636096_image_0.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441801544_1716441636096_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a263",
    "name": "externallmg_1716441802172_1716441636096_image_1.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441802172_1716441636096_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a264",
    "name": "externallmg_1716441803210_1716441636096_image_2.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441803210_1716441636096_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a265",
    "name": "externallmg_1716441803692_1716441636096_image_3.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441803692_1716441636096_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a266",
    "name": "externallmg_1716441804084_1716441636096_image_4.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441804084_1716441636096_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "664ed2d199e95b180a31a267",
    "name": "externallmg_1716441804392_1716441636096_image_5.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441804392_1716441636096_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a268",
    "name": "externallmg_1716441804925_1716441636096_image_6.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441804925_1716441636096_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a269",
    "name": "externallmg_1716441805102_1716441636096_image_7.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441805102_1716441636096_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26a",
    "name": "externallmg_1716441805818_1716441636096_image_8.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441805818_1716441636096_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26b",
    "name": "externallmg_1716441806035_1716441636096_image_9.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441806035_1716441636096_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26c",
```

```
    "name": "externallmg_1716441806515_1716441636096_image_10.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441806515_1716441636096_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26d",
    "name": "externallmg_1716441807616_1716441636096_image_11.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441807616_1716441636096_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26e",
    "name": "externallmg_1716441807836_1716441636096_image_12.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441807836_1716441636096_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ed2d199e95b180a31a26f",
    "name": "externallmg_1716441808209_1716441636096_image_13.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441808209_1716441636096_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "664ed2730a8d061847153a07",
    "name": "externallmg_1716441714927_1716441551252_image_0.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441714927_1716441551252_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "664ed2730a8d061847153a08",
    "name": "externallmg_1716441714985_1716441551252_image_1.jpeg",
```

```
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441714985_1716441551252_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "664ed2730a8d061847153a09",
    "name": "externallmg_1716441715354_1716441551252_image_2.jpeg",
    "path": "cases/66487ffe6f40574290c1c5b6/
externallmg_1716441715354_1716441551252_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "19000 - Vasant.pdf",
    "filename": "1716541494592_19000__Vasant.pdf",
    "path": "cases/66487ffe6f40574290c1c5b6/
processingDocuments/1716541494592_19000__Vasant.pdf",
    "size": "158743",
    "createdAt": "Fri May 24 2024 14:34:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname":
"1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "filename": "1716541494710_1711780572109_1703238797922_1701350330944_C
alculation_123_2.xlsx",
    "path": "cases/66487ffe6f40574290c1c5b6/processingDocuments/1716541494710_
1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "size": "4780269",
    "createdAt": "Fri May 24 2024 14:34:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Valuation_Report_Bijesh Menon.pdf",
    "filename": "1716541522629_Valuation_Report_Bijesh_Menon.pdf",
    "path": "cases/66487ffe6f40574290c1c5b6/
processingDocuments/1716541522629_Valuation_Report_Bijesh_Menon.pdf",
    "size": "1053765",
    "createdAt": "Fri May 24 2024 14:35:23 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
```

```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "664dee9de9ac0648dd0d81c0",
    "note": "Rate verification done, pending for visit",
    "taskId": "6648802abeacf042d5550f2e",
    "createdAt": "2024-05-22T13:09:49.845Z"
  },
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "664deec90444eb489e02632e",
    "note": "Rate verification done, pending for visit",
    "taskId": "6648802abeacf042d5550f2e",
    "createdAt": "2024-05-22T13:10:33.707Z"
  }
],
"createdAt": "2024-05-18T10:16:30.200Z",
"updatedAt": "2024-05-25T11:08:10.955Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Bijlesh Bhaskara Menon & Deepa Bijlesh Menon",
"email": ""
```

"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833022224"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
