

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b31",
    "email": "resham.kulkarni@cosmosbank.in",
    "firstName": "Resham ",
    "mobileNo": "9987780572",
    "workMobileNo": "9987780572",
    "lastName": "Kulkarni"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.26646655540411",
  "longitude": "72.96741574592187"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23",
      "remark": ""
    }
  ]
},
"schedule": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Owale",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "A-1",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Fenkin Belleza ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ghodbunder Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kasarvadavali",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Hypercity Mall",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "86/1/1",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "112/1/1",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "603",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 615",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```



```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6648938446d99f42db91ae1f",
"ownerName": "Mrs. Archana Chandrakant Katkade & Mr. Chandrakant R. Katkade",
"ownerPhoneNo": "9833022224",
"fullAddress": "Residential Flat No. 603, 6th Floor, Building No A-1, Fenkin Belleza ,
Hypercity Mall, Ghodbunder Road, Kasarvadavali, Village - Owale, Thane West, PIN
Code - 400 615, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "16/03/2017",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Fen-kin Developers ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Archana Chandrakant Katkade & Mr. Chandrakant R. Katkade",
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "2501/2017"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716032383574_Agreement.pdf",
"path": "cases/6648938446d99f42db91ae1f/
document_1716032383574_Agreement.pdf",
"id": "345761",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Sat May 18 2024 17:09:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/01/2017",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "2006 / 143 / TMC / TDD / 169"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716453794502_121175.pdf",
  "path": "cases/6648938446d99f42db91ae1f/
document_1716453794502_121175.pdf",
  "id": "693611",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu May 23 2024 14:17:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "08/02/2017",
  "nameOfApprovingAuthority": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "2006 / 143 / TMC / TDD / 188"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716453843873_112939.pdf",
"path": "cases/6648938446d99f42db91ae1f/
document_1716453843873_112939.pdf",
"id": "133714",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Thu May 23 2024 14:17:21 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "14/06/2017",
    "remark": " issued by Praksis Consultants & Valuers Pvt. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716454041099_72213.pdf",
  "path": "cases/6648938446d99f42db91ae1f/document_1716454041099_72213.pdf",
  "id": "808561",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu May 23 2024 14:17:21 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "008832",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
```

```
{
  "id": "689035",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat May 18 2024 17:09:48 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mrs. Archana Chandrakant Katkade & Mr. Chandrakant R. Katkade",
    "phone": "9833022224",
    "ownershipShare": "",
    "email": "",
    "id": "113405"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a0",
    "name": "externalimg_1716437622242_1716437456605_image_0.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externalimg_1716437622242_1716437456605_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a1",
    "name": "externalimg_1716437622301_1716437456605_image_1.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externalimg_1716437622301_1716437456605_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "664ec27a415afe18104913a2",
    "name": "externallmg_1716437622567_1716437456605_image_2.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437622567_1716437456605_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a3",
    "name": "externallmg_1716437623126_1716437456605_image_3.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437623126_1716437456605_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a4",
    "name": "externallmg_1716437623837_1716437456605_image_4.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437623837_1716437456605_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a5",
    "name": "externallmg_1716437623911_1716437456605_image_5.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437623911_1716437456605_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a6",
    "name": "externallmg_1716437624553_1716437456605_image_6.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437624553_1716437456605_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a7",
```

```
    "name": "externallmg_1716437625141_1716437456605_image_7.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437625141_1716437456605_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a8",
    "name": "externallmg_1716437625442_1716437456605_image_8.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437625442_1716437456605_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913a9",
    "name": "externallmg_1716437625727_1716437456605_image_9.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437625727_1716437456605_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913aa",
    "name": "externallmg_1716437626015_1716437456605_image_10.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437626015_1716437456605_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec27a415afe18104913ab",
    "name": "externallmg_1716437626218_1716437456605_image_11.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437626218_1716437456605_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b2c",
    "name": "externallmg_1716437687185_1716437520394_image_0.jpeg",
```

```
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437687185_1716437520394_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b2d",
    "name": "externallmg_1716437688114_1716437520394_image_1.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437688114_1716437520394_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b2e",
    "name": "externallmg_1716437688171_1716437520394_image_2.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437688171_1716437520394_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b2f",
    "name": "externallmg_1716437688600_1716437520394_image_3.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437688600_1716437520394_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b30",
    "name": "externallmg_1716437688776_1716437520394_image_4.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437688776_1716437520394_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b31",
    "name": "externallmg_1716437689345_1716437520394_image_5.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437689345_1716437520394_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b32",
  "name": "externallmg_1716437689811_1716437520394_image_6.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437689811_1716437520394_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b33",
  "name": "externallmg_1716437690284_1716437520394_image_7.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437690284_1716437520394_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b34",
  "name": "externallmg_1716437690868_1716437520394_image_8.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437690868_1716437520394_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b35",
  "name": "externallmg_1716437691132_1716437520394_image_9.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437691132_1716437520394_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b36",
  "name": "externallmg_1716437692307_1716437520394_image_10.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437692307_1716437520394_image_10.jpeg",
  "orientation": "portrait"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b37",
    "name": "externallmg_1716437693728_1716437520394_image_11.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437693728_1716437520394_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b38",
    "name": "externallmg_1716437693912_1716437520394_image_12.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437693912_1716437520394_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b39",
    "name": "externallmg_1716437694358_1716437520394_image_13.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437694358_1716437520394_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b3a",
    "name": "externallmg_1716437694570_1716437520394_image_14.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437694570_1716437520394_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664ec2c20a8d061847152b3b",
    "name": "externallmg_1716437694986_1716437520394_image_15.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437694986_1716437520394_image_15.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b3c",
  "name": "externallmg_1716437696187_1716437520394_image_16.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437696187_1716437520394_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b3d",
  "name": "externallmg_1716437697112_1716437520394_image_17.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437697112_1716437520394_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664ec2c20a8d061847152b3e",
  "name": "externallmg_1716437697349_1716437520394_image_18.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437697349_1716437520394_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "664ec25799e95b180a319532",
  "name": "externallmg_1716437590816_1716437428684_image_0.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437590816_1716437428684_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "664ec25799e95b180a319533",
  "name": "externallmg_1716437590864_1716437428684_image_1.jpeg",
  "path": "cases/6648938446d99f42db91ae1f/
externallmg_1716437590864_1716437428684_image_1.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "664ec25799e95b180a319534",
    "name": "externalImg_1716437591282_1716437428684_image_2.jpeg",
    "path": "cases/6648938446d99f42db91ae1f/
externalImg_1716437591282_1716437428684_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "17900 Fen kin.pdf",
    "filename": "1716443214200_17900_Fen_kin.pdf",
    "path": "cases/6648938446d99f42db91ae1f/
processingDocuments/1716443214200_17900_Fen_kin.pdf",
    "size": "174975",
    "createdAt": "Thu May 23 2024 11:16:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "19000 Fen kin.pdf",
    "filename": "1716443214331_19000_Fen_kin.pdf",
    "path": "cases/6648938446d99f42db91ae1f/
processingDocuments/1716443214331_19000_Fen_kin.pdf",
    "size": "153628",
    "createdAt": "Thu May 23 2024 11:16:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname":
"1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "filename": "1716443214470_1711780572109_1703238797922_1701350330944_C
alculation_123_2.xlsx",
    "path": "cases/6648938446d99f42db91ae1f/processingDocuments/1716443214470
_1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "size": "4566797",
    "createdAt": "Thu May 23 2024 11:16:58 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```

    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "664deea90444eb489e0262a7",
  "note": "Rate verification done, pending for visit",
  "taskId": "6648938b6f40574290c1da6e",
  "createdAt": "2024-05-22T13:10:01.453Z"
}
],
"createdAt": "2024-05-18T11:39:48.641Z",
"updatedAt": "2024-05-23T08:47:21.435Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mrs. Archana Chandrakant Katkade & Mr. Chandrakant R.
Katkade",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833022224"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			