

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "firstName": "Shivani ",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Shivani ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```

    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ]
    }
  ]
}

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.036586998118988",
  "longitude": " 72.87094657045589"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87094657045589,
    19.036586998118988
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "21/05/2024 01:46 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Sion Division",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "13",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Tower No. 1A, Phase 1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai City",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": false,
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Siddha Sky ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp. Shukla Hotel",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Raoli Camp, Khokri Agar, New 90 Feet Road, Hemant Manjrekar Road,
Sardar Nagar No.4",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "12 (part), 6 (part), 16 (part), 17 (part), 18 (part), 19 (part), 20(part) &
21(part)",
  "label": true
},
},
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "SSW / T1A / 1306",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "F/N Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 037",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sion Koliwada",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring"
  }
}
```

with Concealed."

```
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road & Under Construction Building",
    "west": "Nirmal Nagar",
    "south": "Slum Area",
    "east": "New MHADA Colony"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  }
}
```

```
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "As per Approved Plan, the composition of Residential Flat will be 3 Bedrooms + Living Room + Dining + Kitchen + 3 Toilets + Balcony Area.",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No.SRA / ENG / FN / STGOVT / 0064 / 20140719 / AP / SB - 2 Dated 16.11.2021 issued by Slum Rehabilitation Authority",
  "approvePlanVerified": "N.A., as the building is under construction",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal Site Inspection, Measurement & Photographs of the property. Details about the work progress status has been provided by Customer Relationship Manager - Mrs. Rekha Reddy (Contact No. 9867830833).",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "141250",
  "landRate": "58200",
  "igrImage": "cases/664c507fcc7f1e727bbec79f/igr_1716378726066_Image.png",
  "squareMeterGuideLineRate": "155375.00",
  "squareFeetGuideLineRate": "14435.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "141250.00",
```

```
"squareMeterGuideLineRate": "155375.00",
"squareFeetGuideLineRate": "14435.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "58,000/- Expected rental income per month after completion",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per SRA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
```

```
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Along with One (1) Car Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Yes",
"label": "Yes"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenancelssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
}
```



```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "2",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "39",
"flatFloorNo": "13",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
  "area": "954.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Monorail",
      "label": "Monorail"
    },
    "routeMapImg": "cases/664c507fcc7f1e727bbec79f/
routeMap_1716401725672_Image.png",
    "routeLat": "19.035917",
    "routeLng": "72.870028",
    "stationName": "GTB Nagar",
    "routeDistance": "150 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "54v38f",
```

```
    "name": "54v38f",
    "image": "cases/664c507fcc7f1e727bbec79f/
routeMap_1716401688818_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "23436000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "23436000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu May 23 2024 11:11:07 GMT+0530 (India Standard Time)",
  "number": "2306429",
  "dayCount": "2",
```

```
"monthCount": "289",
"generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "43",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "43",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "43",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "15",
    "percentage": "1.22",
```

```
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "43",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "8",
  "percentage": "1.86",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "70.58",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "13782538.00",
"selectedBuildUpValue": "954.80",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "664c915bcc7f1e727bbf1d2a",
"name":
"externalimg_1716293979595_WhatsApp_Image_20240521_at_173841.jpeg",
```

```
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979595_WhatsApp_Image_20240521_at_173841.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d27",
    "name":
"externallmg_1716293979586_WhatsApp_Image_20240521_at_173840.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979586_WhatsApp_Image_20240521_at_173840.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d26",
    "name":
"externallmg_1716293979582_WhatsApp_Image_20240521_at_173840_1.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979582_WhatsApp_Image_20240521_at_173840_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26000.00",
    "max": "28603.00"
  },
  "builtUpRateRange": {
    "min": "23637.00",
    "max": "26003.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
```



```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "868.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "664c507fcc7f1e727bbec79f",
"ownerName": "Mr. Rishikesh Vilas Pawar, Mrs. Priyanka Rishikesh Pawar & Mr. Vilas
Pandharinath Pawar",
"ownerPhoneNo": "9890061396",
"appAddress": "Flat no. SSW/T1A - 1306, 13th Floor, Tower no. 1A, Phase 1, Siddha
Sky, Sion",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "06/05/2024",
      "amount": " (5 Pages from documents)",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      }
    }
  }
]
```

```
    },
    "Promoter": "Sejal Shakti Realtors LLP",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Rishikesh Vilas Pawar, Mrs. Priyanka Rishikesh Pawar & Mr.
Vilas Pandharinath Pawar",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "9241/2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "196835",
  "path": "cases/664c507fcc7f1e727bbec79f/
document_1716277340368_1716277148710_Racpc_GHatkopar_Priyanka_Pawar.pdf",
  "fileName":
"document_1716277340368_1716277148710_Racpc_GHatkopar_Priyanka_Pawar.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "27/05/2019",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51900021027"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716437692470_P51900021027.pdf",
  "path": "cases/664c507fcc7f1e727bbec79f/
document_1716437692470_P51900021027.pdf",
  "id": "605088",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
```

```
"createdAt": "Thu May 23 2024 09:44:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "22/05/2019",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "F - N / STGOVT / 0064 / 20140719 / AP / SB - 2"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716437875408_cc.pdf",
  "path": "cases/664c507fcc7f1e727bbec79f/document_1716437875408_cc.pdf",
  "id": "630011",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu May 23 2024 09:47:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "16/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "SRA / ENG / FN / STGOVT / 0064 / 20140719 / AP / SB - 2 "
  },
  "isHardCopy": false,
  "displayStatus": true,

```

```
"fileName": "document_1716438587771_fLOOR_pLAN.pdf",
"path": "cases/664c507fcc7f1e727bbec79f/
document_1716438587771_fLOOR_pLAN.pdf",
"id": "971595",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu May 23 2024 09:59:49 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008854",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
  "id": "125646",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue May 21 2024 13:12:55 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Mr. Rishikesh Vilas Pawar, Mrs. Priyanka Rishikesh Pawar & Mr. Vilas
Pandharinath Pawar",
  "phone": "9890061396",
  "ownershipShare": "",
  "email": "",
  "id": "832415"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "80.64",
  "totalAreaDocument": "868",
```

```
"docBuiltpPercentage": "10",
"docFinalBuiltp": "954.80",
"docFinalBuiltpSquareMeter": "88.70",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "687781"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "717.00",
"squareMeterArea": "66.61",
"expectedRate": "27067.00",
"percentage": ""
},
"builtUpArea": {
"area": "788.70",
"squareMeterArea": "73.27",
"expectedRate": "24606.36",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "664ddc6f0444eb489e0252be",
"property": "Residential Flat",
"area": "717",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "19407039",
"expectedRate": "27067.00",
"builtUpExpectedRate": "24606.36",
"image": "cases/664c507fcc7f1e727bbec79f/indicator_1716378599609_Image.png",
"squareMeter": "66.61",
"id": "717386"
```

```
},
{
  "carpetArea": {
    "area": "717.00",
    "squareMeterArea": "66.61",
    "expectedRate": "26000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "788.70",
    "squareMeterArea": "73.27",
    "expectedRate": "23636.36",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "664ddc6f0444eb489e0252bf",
  "property": "Residential Flat",
  "area": "717",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "18642000",
  "expectedRate": "26000.00",
  "builtUpExpectedRate": "23636.36",
  "image": "cases/664c507fcc7f1e727bbec79f/indicator_1716378622458_Image.png",
  "squareMeter": "66.61",
  "id": "865014"
},
{
  "carpetArea": {
    "area": "911.00",
    "squareMeterArea": "84.63",
    "expectedRate": "27552.14",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1002.10",
```

```
"squareMeterArea": "93.10",
"expectedRate": "25047.40",
"percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "664ddc6f0444eb489e0252c0",
"property": "Residential Flat",
"area": "911",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "25100000",
"expectedRate": "27552.14",
"builtUpExpectedRate": "25047.40",
"image": "cases/664c507fcc7f1e727bbec79f/indicator_1716378640284_Image.png",
"squareMeter": "84.63",
"id": "151228"
},
{
  "carpetArea": {
    "area": "916.00",
    "squareMeterArea": "85.10",
    "expectedRate": "28602.62",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1007.60",
    "squareMeterArea": "93.61",
    "expectedRate": "26002.38",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
  "_id": "664ddc6f0444eb489e0252c1",
  "property": "Residential Flat",
  "area": "916",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "26200000",
  "expectedRate": "28602.62",
  "builtUpExpectedRate": "26002.38",
  "image": "cases/664c507fcc7f1e727bbec79f/indicator_1716378654387_Image.png",
  "squareMeter": "85.10",
  "id": "687207"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d24",
    "name":
"externallmg_1716293979576_WhatsApp_Image_20240521_at_173837.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979576_WhatsApp_Image_20240521_at_173837.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d25",
    "name":
"externallmg_1716293979578_WhatsApp_Image_20240521_at_173839.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979578_WhatsApp_Image_20240521_at_173839.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d26",
    "name":
"externallmg_1716293979582_WhatsApp_Image_20240521_at_173840_1.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979582_WhatsApp_Image_20240521_at_173840_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d27",
    "name":
"externallmg_1716293979586_WhatsApp_Image_20240521_at_173840.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979586_WhatsApp_Image_20240521_at_173840.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d28",
    "name":
"externallmg_1716293979589_WhatsApp_Image_20240521_at_173841_1.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979589_WhatsApp_Image_20240521_at_173841_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d29",
    "name":
"externallmg_1716293979592_WhatsApp_Image_20240521_at_173841_2.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979592_WhatsApp_Image_20240521_at_173841_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d2a",
    "name":
"externallmg_1716293979595_WhatsApp_Image_20240521_at_173841.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979595_WhatsApp_Image_20240521_at_173841.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d2b",
```

```
    "name":
"externallmg_1716293979598_WhatsApp_Image_20240521_at_173842_1.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979598_WhatsApp_Image_20240521_at_173842_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664c915bcc7f1e727bbf1d2c",
    "name":
"externallmg_1716293979600_WhatsApp_Image_20240521_at_173842.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/
externallmg_1716293979600_WhatsApp_Image_20240521_at_173842.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1716378759410_AGR.pdf",
    "path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716378759410_AGR.pdf",
    "size": "11441047",
    "createdAt": "Wed May 22 2024 17:22:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1716293979598_WhatsApp_Image_20240521_at_173842_1.jpeg",
    "filename": "1716378759582_externallmg_1716293979598_WhatsApp_Image_202
40521_at_173842_1.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/processingDocuments/1716378759582_
externallmg_1716293979598_WhatsApp_Image_20240521_at_173842_1.jpeg",
    "size": "106426",
    "createdAt": "Wed May 22 2024 17:22:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1716293979600_WhatsApp_Image_20240521_at_173842.jpeg",
    "filename": "1716378759624_externallmg_1716293979600_WhatsApp_Image_202
40521_at_173842.jpeg",
    "path": "cases/664c507fcc7f1e727bbec79f/processingDocuments/1716378759624_
externallmg_1716293979600_WhatsApp_Image_20240521_at_173842.jpeg",
```

```
"size": "87440",
"createdAt": "Wed May 22 2024 17:22:39 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=RISHIKESH.xlsx",
"filename": "1716378759647_Summary_NewRISHIKESH.xlsx",
"path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716378759647_Summary_NewRISHIKESH.xlsx",
"size": "970676",
"createdAt": "Wed May 22 2024 17:22:39 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "6 (1).pdf",
"filename": "1716438769652_6_1.pdf",
"path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438769652_6_1.pdf",
"size": "456057",
"createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
"originalname": "6.pdf",
"filename": "1716438770070_6.pdf",
"path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438770070_6.pdf",
"size": "593745",
"createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
"originalname": "cc.pdf",
"filename": "1716438770721_cc.pdf",
"path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438770721_cc.pdf",
"size": "454130",
"createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
"originalname": "fLOOR pLAN.pdf",
"filename": "1716438771216_fLOOR_pLAN.pdf",
"path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438771216_fLOOR_pLAN.pdf",
"size": "932021",
```

```
"createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "P51900021027.pdf",
  "filename": "1716438772030_P51900021027.pdf",
  "path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438772030_P51900021027.pdf",
  "size": "152136",
  "createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "Plan.pdf",
  "filename": "1716438772141_Plan.pdf",
  "path": "cases/664c507fcc7f1e727bbec79f/
processingDocuments/1716438772141_Plan.pdf",
  "size": "396265",
  "createdAt": "Thu May 23 2024 10:02:52 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-21T07:42:55.995Z",
"updatedAt": "2024-05-23T06:04:41.486Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. SSW / T1A / 1306, 13th Floor, Building No Tower
No. 1A, Phase 1, Siddha Sky , Opp. Shukla Hotel, Raoli Camp, Khokri Agar, New 90
Feet Road, Hemant Manjrekar Road, Sardar Nagar No.4, Village - Sion Division,
Municipality Ward No. F/N Ward, Sion Koliwada, District - Mumbai City, Mumbai, PIN
Code - 400 037, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Rekha Reddy ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "9867830833",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 868.00",
"flatRate": "27000",
"landOtherRate": "24000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 832.00\nEnclosed / Open Balcony
Area in Sq. Ft. = 36.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
```

"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"reportGeneratedDate": "Thu May 23 2024 09:39:48 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-05-22"
}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
