

```
{
  "typeOfReport": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Yogeesh",
    "expectedFees": 0,
    "quotedAmount": "10000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "665069344818a66bfbd4f4e2",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Yogeesh Ramchandra Pandir",
"displayname": "Yogeesh Ramchandra Pandir",
"initial": "Y"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "shortName": "JB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc575ece84bf289ba9e82d",
    "role": "SITEENGINEER",
    "firstName": "Deepak ",
    "email": "daksh7831@gmail.com",
    "lastName": "Jain ",
    "mobileNo": "9022815908",
    "designation": "",
    "shortName": "DJ",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
```

```
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
```

```
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.206683438915427",
  "longitude": "72.8444545022859"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "24/05/2024 03:39 pm"
    }
  ],
}
```

```
{
  "dateTime": "24/05/2024 12:00 am"
},
{
  "dateTime": "24/05/2024 12:00 am"
},
{
  "dateTime": "24/05/2024 12:00 am"
},
{
  "dateTime": "24/05/2024 12:00 am"
},
{
  "dateTime": "24/05/2024 12:00 am"
}
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",

```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "16",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Saikrupa ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pandurang Wadi",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sixth Road, Near lyover",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Nemish CHSL",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "7",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
```



```
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "665069344818a66bfbd4f4e8",
"ownerName": "Yogeesh Ramchandra Pandit",
"ownerPhoneNo": "9082699055",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9082699055",
"contactPersonName": "Yogeesh Ramchandra Pandit",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Yogeesh Ramchandra Pandit",
    "phone": "9082699055",
    "ownershipShare": "",
    "email": "",
    "id": "848535"
  }
],
"caseReferredBy": "6006d4ce5080a310ac1fdfc2",
"relationWithOwner": "self",
"fullAddress": "Residential Capital Gain No. 7, 2nd Floor, Shree Saikrupa , Nemish
CHSL, Plot No. 16, Pandurang Wadi, Sixth Road, Near Iyover, Goregaon East, Mumbai,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1716545809224_Sale_Agreement.pdf",
    "path": "cases/665069344818a66bfbd4f4e8/
document_1716545809224_Sale_Agreement.pdf",
    "id": "938556",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Fri May 24 2024 15:47:24 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1716545821727_Gift_Deed.pdf",
"path": "cases/665069344818a66bfbd4f4e8/
document_1716545821727_Gift_Deed.pdf",
"id": "965300",
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Fri May 24 2024 15:47:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1716787286796_yogesh.pdf",
  "path": "cases/665069344818a66bfbd4f4e8/
document_1716787286796_yogesh.pdf",
  "id": "306393",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Mon May 27 2024 10:51:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae128daa6d152c1801b42e",
    "label": "Society Demand Notice"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1717407896847_Notice.pdf",
  "path": "cases/665069344818a66bfbd4f4e8/document_1717407896847_Notice.pdf",
  "id": "457883",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9",
  "createdAt": "Mon Jun 03 2024 15:16:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af71e62ffdf65bcd65862c",
    "label": "NOC"
  },
  "inputs": {
```

```
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "a"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1717407966121_PVR.pdf",
  "path": "cases/665069344818a66bfbd4f4e8/document_1717407966121_PVR.pdf",
  "id": "119503",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9",
  "createdAt": "Mon Jun 03 2024 15:16:06 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "008904",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "386948",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri May 24 2024 15:47:24 GMT+0530 (India Standard Time)"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896a",
  }
]
```

```
    "name": "externallmg_1716811419896_IMG20240527WA0001.jpg",
    "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419896_IMG20240527WA0001.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896b",
    "name": "externallmg_1716811419900_IMG20240527WA0003.jpg",
    "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419900_IMG20240527WA0003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896c",
    "name": "externallmg_1716811419903_IMG20240527WA0004.jpg",
    "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419903_IMG20240527WA0004.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896d",
    "name": "externallmg_1716811419908_IMG20240527WA0005.jpg",
    "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419908_IMG20240527WA0005.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896e",
    "name": "externallmg_1716811419911_IMG20240527WA0006.jpg",
    "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419911_IMG20240527WA0006.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f896f",
    "name": "externallmg_1716811419918_IMG20240527WA0008.jpg",
```

```
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419918_IMG20240527WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f8970",
    "name": "externallmg_1716811419921_IMG20240527WA0009.jpg",
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419921_IMG20240527WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f8971",
    "name": "externallmg_1716811419923_IMG20240527WA0010.jpg",
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419923_IMG20240527WA0010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f8972",
    "name": "externallmg_1716811419926_IMG20240527WA0011.jpg",
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419926_IMG20240527WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f8973",
    "name": "externallmg_1716811419928_IMG20240527WA0012.jpg",
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419928_IMG20240527WA0012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6654769c1f66eb51479f8974",
    "name": "externallmg_1716811419930_IMG20240527WA0013.jpg",
    "path": "cases/665069344818a66bfd4f4e8/
externallmg_1716811419930_IMG20240527WA0013.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6654769c1f66eb51479f8975",
  "name": "externallmg_1716811419933_IMG20240527WA0016.jpg",
  "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419933_IMG20240527WA0016.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6654769c1f66eb51479f8976",
  "name": "externallmg_1716811419935_IMG20240527WA0018.jpg",
  "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419935_IMG20240527WA0018.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6654769c1f66eb51479f8977",
  "name": "externallmg_1716811419938_IMG20240527WA0019.jpg",
  "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419938_IMG20240527WA0019.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6654769c1f66eb51479f8978",
  "name": "externallmg_1716811419941_IMG20240527WA0020.jpg",
  "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419941_IMG20240527WA0020.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6654769c1f66eb51479f8979",
  "name": "externallmg_1716811419943_IMG20240527WA0021.jpg",
  "path": "cases/665069344818a66bfbd4f4e8/
externallmg_1716811419943_IMG20240527WA0021.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6654769c1f66eb51479f897a",
      "name": "externalImg_1716811419945_IMG20240527WA0022.jpg",
      "path": "cases/665069344818a66bfd4f4e8/
externalImg_1716811419945_IMG20240527WA0022.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6654769c1f66eb51479f897b",
      "name": "externalImg_1716811419946_IMG20240527WA0023.jpg",
      "path": "cases/665069344818a66bfd4f4e8/
externalImg_1716811419946_IMG20240527WA0023.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6654769c1f66eb51479f897c",
      "name": "externalImg_1716811419948_IMG20240527WA0024.jpg",
      "path": "cases/665069344818a66bfd4f4e8/
externalImg_1716811419948_IMG20240527WA0024.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6654769c1f66eb51479f897d",
      "name": "externalImg_1716811419950_IMG20240527WA0025.jpg",
      "path": "cases/665069344818a66bfd4f4e8/
externalImg_1716811419950_IMG20240527WA0025.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "5fc78e26625ecd20ec1f88e9",
```

```

    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66557b639bc0d00b08d33bae",
  "note": "payment not recd",
  "taskId": "6650693511aa646c01a5c612",
  "createdAt": "2024-05-28T06:36:19.141Z"
}
],
"createdAt": "2024-05-24T10:17:24.729Z",
"updatedAt": "2024-06-03T09:46:06.237Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "5fc78e26625ecd20ec1f88e9"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			