

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report / SBI / Sharanpur Road Branch / Sau. Shobha Supdu Patil (008988/2306506) Page 1 of 3

www.vastukala.co.in

Vastu/Nashik/05/2024/008988/2306506 29/4-366-RPBS Date: 29.05.2024

Structural Stability Report

Residential Unit No. Six-Pearls-1, Ground + Stilt + First Floor, "Six-Pearls", Survey No. 712/2-A + 2-D, Plot No. 45 + 46, Opp. Colony Garden & Genius Tots Preschool, D-Souza Colony, Gangapur Road, Village - Nashik City-3, Taluka & District - Nashik, PIN Code - 422 005, State - Maharashtra, Country - India belongs Shri. Suresh Choithram Gurnani Name of Proposed Purchaser: Sau. Shobha Supadu Patil.

This is to certify that on visual inspection, it appears that the structure of "Six-Pearls" is in normal condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 40 years.

General Information:

Name of Building Property Address	"Six-Pearls"
Property Address	
Troperty Address	Residential Unit No. Six-Pearls-1, Ground + Stilt + First Floor, "Six-Pearls", Survey No. 712/2-A + 2-D, Plot No. 45 + 46, Opp. Colony Garden & Genius Tots Preschool, D-Souza Colony, Gangapur Road, Village – Nashik City-3, Taluka & District - Nashik, PIN Code - 422 005, State - Maharashtra, Country – India.
Type of Building	Residential Unit No. Six-Pearls-1
No. of Floors	Ground + Stilt + First Floor
Whether stilt / podium / open parking provided	Covered Car Parking
Type of Construction	R.C.C. Framed Structure
Type of Foundation	R.C.C. Footing
Thickness of the External Walls	6' thick brick walls both sides plastered
Type of Compound	Brick Masonry Walls
Year of Construction	1995 (As per Full Occupancy Certificate)
Present age of building	29 years
Residual age of the building	31 years Subject to proper, preventive periodic maintenance & structural repairs.
No. of Units	6 Row Bungalows
Methodology adopted	As per visual site inspection
	No. of Floors Whether stilt / podium / open parking provided Type of Construction Type of Foundation Thickness of the External Walls Type of Compound Year of Construction Present age of building Residual age of the building No. of Units

Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra Nandu Naka Link Road, Adgaon, Nashik-422003 (M.S.), INDIA Email: nashik@vastukala..co.in| Tel : +91 253 4068262/98903 80564

Our Pan India Presence at:

Nanded Mumbai

Nashik Rajkot

Raipur

Indore



B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India



