

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6666d4671386b87b142d7324"
    },
    "type": "CREDITOFFICER",
    "_id": "6666d4671386b87b142d7326",
    "firstName": "Bhagyashree",
    "lastName": " Madam",
    "mobileNo": "",
    "workMobileNo": "9820486454",
    "email": "veebom@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6666d4671386b87b142d7324",
  "name": "Veena Nagar (Mulund West Branch)\t",
  "branchCode": "",
  "mobileNo": "02221614131",
  "alternateMobileNo": "02221647379",
  "email": "veebom@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "New Krishna Dham Building No A2 B-13, Lal Bahadur Shastri Rd, Veena
Nagar, Mulund West, Mumbai, Maharashtra 400080"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  }
]
```

```
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.118324065276223",
  "longitude": "72.92543718968453"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
```

```
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Hariali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  }
}
```

```
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kailash Commercial Complex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "LBS Marg, Vikhroli West",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Gala Udyog Premises Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
```

```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "22.22/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit No. 12",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```



```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 083",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6666e54d2ae3637b0ee92d4f",
"ownerName": "M/s. H. S. Enterprises",
"ownerPhoneNo": "9869663096",
"fullAddress": "Residential Unit No. Unit No. 12, 1st Floor, Kailash Commercial
Complex, Gala Udyog Premises Co.-Op. Hsg. Soc. Ltd., CTS No. 22.22/1, LBS Marg,
Vikhroli West, Village - Hariali, Taluka - Kurla, District - Mumbai, Mumbai, PIN Code -
400 083",
"remark": "",
```



```
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/11/2011",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "M/s. Sethi Capital",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "M/s. H. S. Enterprises",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "4201/2015"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718019397482_Bob_Veena_Nagar_Gala_112.pdf",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
document_1718019397482_Bob_Veena_Nagar_Gala_112.pdf",
    "id": "140726",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Mon Jun 10 2024 17:06:45 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009204",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "917344",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 10 2024 17:06:45 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "M/s. H. S. Enterprises",
    "phone": "9869663096",
    "ownershipShare": "",
    "email": "",
    "id": "324512"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6669210f09a0de7b00a44709",
    "name": "externalImg_1718165773734_1718165629598_image_0.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externalImg_1718165773734_1718165629598_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6669210f09a0de7b00a4470a",
    "name": "externalImg_1718165773758_1718165629598_image_1.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externalImg_1718165773758_1718165629598_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6669210f09a0de7b00a4470b",
    "name": "externalImg_1718165774050_1718165629598_image_2.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externalImg_1718165774050_1718165629598_image_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c4",
  "name": "externallmg_1718165809593_1718165662214_image_0.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165809593_1718165662214_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c5",
  "name": "externallmg_1718165810017_1718165662214_image_1.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165810017_1718165662214_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c6",
  "name": "externallmg_1718165811006_1718165662214_image_2.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165811006_1718165662214_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c7",
  "name": "externallmg_1718165811790_1718165662214_image_3.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165811790_1718165662214_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c8",
  "name": "externallmg_1718165812639_1718165662214_image_4.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165812639_1718165662214_image_4.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519c9",
  "name": "externallmg_1718165813189_1718165662214_image_5.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165813189_1718165662214_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519ca",
  "name": "externallmg_1718165814050_1718165662214_image_6.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165814050_1718165662214_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519cb",
  "name": "externallmg_1718165814581_1718165662214_image_7.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165814581_1718165662214_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519cc",
  "name": "externallmg_1718165814830_1718165662214_image_8.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165814830_1718165662214_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66692138f605307b019519cd",
  "name": "externallmg_1718165815335_1718165662214_image_9.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165815335_1718165662214_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66692138f605307b019519ce",
    "name": "externallmg_1718165815775_1718165662214_image_10.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165815775_1718165662214_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66692138f605307b019519cf",
    "name": "externallmg_1718165816173_1718165662214_image_11.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165816173_1718165662214_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a4473f",
    "name": "externallmg_1718165862017_1718165713630_image_0.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165862017_1718165713630_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44740",
    "name": "externallmg_1718165862351_1718165713630_image_1.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165862351_1718165713630_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44741",
    "name": "externallmg_1718165862783_1718165713630_image_2.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165862783_1718165713630_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6669216a09a0de7b00a44742",
    "name": "externallmg_1718165863334_1718165713630_image_3.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165863334_1718165713630_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44743",
    "name": "externallmg_1718165863658_1718165713630_image_4.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165863658_1718165713630_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44744",
    "name": "externallmg_1718165864181_1718165713630_image_5.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165864181_1718165713630_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44745",
    "name": "externallmg_1718165864403_1718165713630_image_6.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165864403_1718165713630_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44746",
    "name": "externallmg_1718165864633_1718165713630_image_7.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165864633_1718165713630_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6669216a09a0de7b00a44747",
    "name": "externallmg_1718165864993_1718165713630_image_8.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165864993_1718165713630_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44748",
    "name": "externallmg_1718165865222_1718165713630_image_9.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165865222_1718165713630_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a44749",
    "name": "externallmg_1718165865700_1718165713630_image_10.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165865700_1718165713630_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6669216a09a0de7b00a4474a",
    "name": "externallmg_1718165865885_1718165713630_image_11.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165865885_1718165713630_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d53",
    "name": "externallmg_1718165897341_1718165749798_image_0.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165897341_1718165749798_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d54",
```

```
    "name": "externallmg_1718165897993_1718165749798_image_1.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165897993_1718165749798_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d55",
    "name": "externallmg_1718165899202_1718165749798_image_2.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165899202_1718165749798_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d56",
    "name": "externallmg_1718165899435_1718165749798_image_3.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165899435_1718165749798_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d57",
    "name": "externallmg_1718165900214_1718165749798_image_4.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165900214_1718165749798_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d58",
    "name": "externallmg_1718165901366_1718165749798_image_5.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165901366_1718165749798_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d59",
    "name": "externallmg_1718165902446_1718165749798_image_6.jpeg",
```



```
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165902446_1718165749798_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d5a",
    "name": "externallmg_1718165903183_1718165749798_image_7.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165903183_1718165749798_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d5b",
    "name": "externallmg_1718165903619_1718165749798_image_8.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165903619_1718165749798_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d5c",
    "name": "externallmg_1718165904459_1718165749798_image_9.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165904459_1718165749798_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d5d",
    "name": "externallmg_1718165905227_1718165749798_image_10.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165905227_1718165749798_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666921931386b87b142e1d5e",
    "name": "externallmg_1718165905475_1718165749798_image_11.jpeg",
    "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165905475_1718165749798_image_11.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666921931386b87b142e1d5f",
  "name": "externallmg_1718165905924_1718165749798_image_12.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165905924_1718165749798_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666921931386b87b142e1d60",
  "name": "externallmg_1718165906282_1718165749798_image_13.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165906282_1718165749798_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666921931386b87b142e1d61",
  "name": "externallmg_1718165906612_1718165749798_image_14.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165906612_1718165749798_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666921931386b87b142e1d62",
  "name": "externallmg_1718165906929_1718165749798_image_15.jpeg",
  "path": "cases/6666e54d2ae3637b0ee92d4f/
externallmg_1718165906929_1718165749798_image_15.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-10T11:36:45.731Z",
"updatedAt": "2024-06-12T04:18:27.838Z",
```

"__v": 0,
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "M/s. H. S. Enterprises",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9869663096"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			