

MSME Reg No: UDYAM-MH-18-008361 An ISO 9001 : 2015 Certified Company CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

# Valuation Report of the Immovable Property



Details of the property under consideration:

Name of Owner: Sau.Sunita Sanjay Kulkarni

Residential Land and Bungalow on **Plot No.33**, Ground + First Floor, Survey No.74A/1 Behind Chagan Bhujbal Office, Aurangabad Nashik Highway, At-Angangaon, Taluka- Yeola, District - Nashik, PIN Code – 423 401, State – Maharashtra, Country – India

# Latitude Longitude: 20°02'35.4"N 74°28'36.1"E

# Intended User: Union Bank of India Mumbai Naka Branch

Ground Floor of Dr. Torane Hospital Opp. Suyash Hospital Ahilyabai Holkar Marg, Behind Mahamarg Bus Stand, Mumbai Naka, Nashik - 422 001, State – Maharashtra, Country – India



#### Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra Nandu Naka Link Road, Adgaon, Nashik-422003 (M.S.), INDIA

Email: nashik@vastukala.co.in| Tel : +91 253 4068262/98903 80564

our rannu	14 1 1030	lice at .	
Nanded	♀ Thane	Ahmedabad      Ahmedabad     Ahmeda	<b>Q</b> Delhi NCR
Mumbai	<b>Nashik</b>	<b>Rojkot</b>	<b>Raipur</b>
Aurangabad	♀ Pune	Indore	💡 Jaipur

## **Regd. Office**

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai** :400072, (M.S), India

2 +91 22 47495919

mumbai@vastukala.co.in

🕀 www.vastukala.co.in



MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001 : 2015 Certified Company CIN: U74120MH2010PTC207869

# Vastukala Consultants (I) Pvt. Ltd.

Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 2 of 22

Vastu/Nashik/06/2024/009251/2306713 13/3-157-CCBS Date: 13.06.2024

# VALUATION OPINION REPORT

This is to certify that the property bearing Residential Land and Bungalow on **Plot No.33**, Ground + First Floor, Survey No.74A/1 Behind Chagan Bhujbal Office, Aurangabad Nashik Highway, At-Angangaon, Taluka- Yeola , District - Nashik, PIN Code – 423 401, State – Maharashtra, Country – India belongs to **Sau.Sunita Sanjay Kulkarni.** 

Boundaries of the property.

North	:	Plot No.32
South	:	Plot No.34
East	:	Colony Road
West	:	Plot No.26

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and valued for Fair Market Value purpose at ₹ 66,41,485.00 (Rupees Sixty-Six Lakh Forty-One Thousand Four Hundred Eighty-Five Only)

The valuation of the property is based on the documents produced by the concern. Legal aspects have not been taken into considerations while preparing this valuation report.

# Hence certified For VASTUKALA CONSULTANTS (I) PVT. LTD.

Digitally signed by Sharadkumar Chalikwar

Date: 2024.06.13 12:32:26 +05'30

DN: cn=Sharadkumar Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=Mumbai,

c=IN

Sharadkumar Chalikwar

Director

Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 Encl: Valuation report.

Auth. Sian



Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra Nandu Naka Link Road, Adgaon, Nashik-422003 (M.S.), INDIA Email: nashik@vastukala..co.in| Tel : +91 253 4068262/98903 80564

 Our Pan India Presence at :

 Nanded
 Image: Thane

 Anmedabad
 Delhi NCR

 Mumbai
 Nashik

 Rajkot
 Raipur

 Aurangabad
 Pune

#### **Regd. Office**

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**:400072, (M.S), India

+91 22 47495919
 mumbai@vastukala.co.in
 www.vastukala.co.in

Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 3 of 22

# Vastukala Consultants (I) Pvt. Ltd.

B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai, Andheri (East), Mumbai - 400 072

To,

## The Branch Manager Union Bank of India Mumbai Naka Branch

Ground Floor of Dr. Torane Hospital Opp. Suyash Hospital Ahilyabai Holkar Marg, Behind Mahamarg Bus Stand, Mumbai Naka, Nashik - 422 001, State - Maharashtra, Country - India

# VALUATION REPORT (IN RESPECT OF RESIDENTIAL LAND AND BUILDING)

1	General	1	<u> </u>		
1.	Purpose for which the valuation is made	:	As per the request from Union Bank of India, Mumba Naka Branch to assess Market value of the property for loan purpose.		
2.	a) Date of inspection	:	12.06.2024		
	b) Date on which the valuation is made	:	12.06.2024		
3	List of documents produced for perusal:	:			
	1. Copy of Sale deed Vide No.1029/2009 Dated.17.04.2009				
	Municipal Council, Yeola.		No.B156/09/10 dated 13.11.2009 issued by Yeola		
			.10.2009 issued by Yeola Municipal Council, Yeola. VS/156/09/10 dated 13.11.2009, issued by Yeola		
	6. Copy of NA Order Letter No.16/2004 Dated.22.07.2004 issued by Collector Office, Nashik				
	7. Copy of Electricity Bill vide Consumer No.061510046110 dated 10.05.2024 in the name of				
	Sau.Sunita Sanjay Kulkarni. issued by				
	(es) with Phone no. (details of share of ea owner in case of joint ownership)	ach	Sau.Sunita Sanjay Kulkarni. <u>Address</u> : Residential Land and Bungalow on Plo No.33, Ground + First Floor, Survey No.74A/1 Behind Chagan Bhujbal Office, Aurangabad Nashik Highway At-Angangaon , Taluka- Yeola , District - Nashik, PlN Code – 423 401,State – Maharashtra, Country – India. <u>Contact Person:</u> Mr.Kulkarni (Owner Representative ) Contact No.:+ 91 9423179566		
5.	Brief description of the property (Includi Leasehold / freehold etc.)	ing :	6 <u>2 4 6</u>		
	connected with road and train. The property Plot:	y is at '	esidential land and Bungalow standing thereof. It is wel 1.7 Km. travelling distance from nearest Bus Stop, Yeola and area is 150.00 Sq. M., which is considered for		
	valuation.	i the t	and area is 150.00 Sq. Mi, Which is considered to		



Since 1989



An ISO 9001 : 2015 Certified Company

td.

Vastukala Consultants (I) Pvt

3 % 10	The		CC framed structure	e is	Situated on Ground Floor + F	irst Floor. The composition	
	of B	ungalow is as under:					
		omposition (as per A					
	Gr	ound Floor-Living Ro	om + Kit + Din + Be	dro	om		
	+	Dressing + Toilet	+ Passage + Stai	irca	se.		
		rking.	Straffing Arns				
	First Floor-Formal Seating + Bedroom+ Dres + Toilet + Passage + Staircase+ Semi-Cov Terr						
		•				and units and the	
	AS	Floor	the Structure area is 131. Built Up Area ( in Sq.mtr )		31.26 Sq. M., Which is cons	idered for the valuation.	
		Ground Floor	65.63				
		First Floor	65.63				
	T	otal Built Up Area	131.26				
6.		ation of property		1:			
	a)	Plot No. / Survey N	0.	:	Survey No.74A/1, Plot No.3	33	
	b)	Door No.			Residential Land and Bunga		
	c)	T.S. No. / Village			At-Angangaon		
	d)	Ward / Taluka			Taluka- Yeola	- manager	
	e)	Mandal / District		1:	District – Nashik	a to chiese G	
7.		al address of the prop	ertv	•	Residential Land and Bunga	now on Plot No.33 Ground	
			leites.		Angangaon , Taluka- Yee Code – 423 401,State – Ma		
8.	City / Town		:	: At-Angangaon			
		dential area		:	Yes		
		mercial area		:	No		
		strial area		:	No		
9.		sification of the area		:			
		gh / Middle / Poor		:	Middle Class		
		ban / Semi Urban / Ru		:	Urban		
10.		ing under Corporati	on limit / Village	:	At-Angangaon		
		chayat / Municipality	Otata / Ocatal	-	Yeola Municipal Council, Yeo	bla	
11.		ther covered under a . enactments (e.g., L		:	No		
		or notified under agen			et a star set a star set a set a set a		
		/ cantonment area	cy area/ scheduled	1	1 10 m 1 M (1 & 1 , 2 K)		
12.		ase it is Agricultural la	nd any conversion		N.A.	o nothelague	
2.		buse site plots is conte		1	nidebilaar muuthibila ks		
13.		idaries of the property			As per the Site	As per Actual Deed	
	North		<u>.</u>	:	Plot No.32	Plot No.32	
	Sout	h	Correlation Antique Co	:	Plot No.34	Plot No.34	
T	East	unden pur Lang sp		:	Colony Road	Colony Road	
	West	t		:	Plot No.26	Plot No.26	



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 4 of 22

	Boundaries of the property (Bungalow)		As per the Documents As per Actual Site
14.2	Latitude, Longitude & Co-ordinates of Property	:	20°02'35.4"N 74°28'36.1"E
15.	Extent of the site	:	Plot Area =150.00 Sq. M.
			(Area As per Sale Deed, and Approved Plan)
			<u>Structure Area:</u> Built Up Area = 131.26 Sq. M. (Area as per Approved Plan)
16.	Extent of the site considered for Valuation	:	Plot Area =150.00 Sq. M. (Area As per Sale Deed, and Approved Plan)
		2	<u>Structure Area:</u> Built Up Area = 131.26 Sq. M.
			(Area as per Approved Plan)
17.	Whether occupied by the owner / tenant? If occupied by tenant since how long? Rent received per month.	:	Owner Occupied
11	CHARACTERSTICS OF THE SITE		LON LOOL
1.	Classification of locality	:	Middle Class
2.	Development of surrounding areas	:	Developing
3.	Possibility of frequent flooding/ sub-merging	:	No
4.	Feasibility to the Civic amenities like School, Hospital, Bus Stop, Market etc.	1	Available
5.	Level of land with topographical conditions	:	Regular
6.	Shape of land	:	Rectangular
7.	Type of use to which it can be put	:	For Residential purpose
8.	Any usage restriction	1	Residential
9.	Is plot in town planning approved layout?	:	Yes
10.	Corner plot or intermittent plot?	:	Intermittent
11.	Road facilities	:	Yes
12.	Type of road available at present	:	B.T. Road
13.	Width of road – is it below 20 ft. or more than 20 ft.	:	Below 20 ft
14.	Is it a Land – Locked land?	:	No
15.	Water potentiality	:	Available
16.	Underground sewerage system	:	Available
17.	Is Power supply is available in the site	:	Available
18.	Advantages of the site	:	Located in developing area
19.	Special remarks, if any like threat of acquisition of land for publics service purposes, road widening or applicability of CRZ provisions etc. (Distance from sea-	:	No
	cost / tidal level must be incorporated)		
Part -	A (Valuation of land)		
1	Size of plot	:	Plot Area =150.00 Sq. M. (Area As per Sale Deed, and Approved Plan)
	North & South	:	-
	East & West	:	
2	Total extent of the plot	:	-
3	Prevailing market rate (Along with details /	:	₹ 10,000.00 to ₹ 20,000.00 per Sq. M.





Since 1989



An ISO 9001: 2015 Certified Company

Vastukala Consultants (I) Pvt. Ltd.

	reference of at least two latest deals / transactions with respect to adjacent properties in the areas)		
4	Ready Reckoner rate obtained from the Register's for land	:	₹ 4,320.00 per Sq. M.
5	Assessed / adopted rate of valuation	:	₹ 16,000.00 per Sq. M.
6	Estimated value of land	:	₹ 24,00,000.00
Part	- B (Valuation of Building)		
1	Technical details of the building	:	The state is a state of the state of the
	a) Type of Building (Residential / Commercial / Industrial)	:	Residential
	<ul> <li>b) Type of construction (Load bearing / RCC / Steel Framed)</li> </ul>	:	RCC framed structure
	c) Year of construction	:	2009 (As per Occupancy Certificate)
	d) Age of the building		15 Years
	e) Life of the building estimated		45 Years (Subject to proper, preventive periodic maintenance & structural repairs.)
	<li>f) Number of floors and height of each floor including basement, if any</li>	:	Ground Floor + First Floor
	g) Plinth area floor-wise	:	Structure Area: Built Up Area = 131.26 Sq. M. (Area as per Approved Plan)
	Condition of the building	1	
	i) Exterior - Excellent, Good, Normal, Poor	:	Good
	ii) Interior – Excellent, Good, Normal, Poor	:	Good
	<ul> <li>h) Date of issue and validity of layout of approved map</li> </ul>		Copy of Approved Building Plan No.PWP/WS/156/09/10 dated 13.11.2009, issued by
	i) Approved map / plan issuing authority	-	Yeola Municipal Council,Yeola Yeola Municipal Council,Yeola
	<li>j) Whether genuineness or authenticity of approved map / plan is verified</li>		Yes
	<ul> <li>k) Any other comments by our empanelled valuers on authentic of approved plan</li> </ul>	••	No.

# Specifications of construction (floor-wise) in respect of

Since 1989

Sr. No.	Description		en owners and the second second
1.	Foundation	:	RCC
2.	Basement	:	N.A.
3.	Superstructure	:	B. B. Masonry
4.	Joinery / Doors & Windows (Please furnish details about size of frames, shutters, glazing, fitting etc. and specify the species of timber	:	Teak Wood door frame, Aluminum sliding windows
5.	RCC Works	:	Columns, Slab etc.
6.	Plastering	:	Cement Plastering.
7.	Flooring, Skirting, dado	:	Vitrified tile Flooring
8.	Special finish as marble, granite, wooden paneling, grills etc.	:	NA
9.	Roofing including weather proof course	:	RCC slab roofing
10.	Drainage	:	Underground Sewerage connected to Municipal drain





An ISO 9001 : 2015 Certified Company

Vastukala Consultants (I) Pvt. Ltd.

			lines
		15	, items states and the second states areas
2.	Compound Wall	:	Yes
	Height	:	NA
	Length	:	and in the set of the
	Type of construction	:	A A A A A A A A A A A A A A A A A A A
3.	Electrical installation	:	Provided as per requirement
	Type of wiring	:	Concealed
	Class of fittings (superior / ordinary / poor)	:	Ordinary
	Number of light points	:	Provided as per requirement
	Fan points	:	Provided as per requirement
	Spare plug points	:	Provided as per requirement
	Any other item	:	•
4.	Plumbing installation		Provided as per requirement
	a) No. of water closets and their type	:	Provided as per requirement

:

: |

:

:

:

Provided as per requirement

Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 7 of 22

Part – C (Extra Items)	:	Amount in `
1. Portico		Included in the Cost of Construction
2. Ornamental front door	:	Included in the Cost of Construction
3. Sit out / Verandah with steel grills	:	Included in the Cost of Construction
4. Overhead water tank	:	Included in the Cost of Construction
5. Extra steel / collapsible gates	States and a	Included in the Cost of Construction
Total		

Part -	- D (Amenities)	:	Amount in `
1.	Wardrobes	:	Included in the Cost of Construction
2.	Glazed tiles	:	Included in the Cost of Construction
3.	Extra sinks and bath tub	:	Included in the Cost of Construction
4.	Marble / ceramic tiles flooring	:	Included in the Cost of Construction
5.	Interior decorations	:	Included in the Cost of Construction
6.	Architectural elevation works		Included in the Cost of Construction
7.	Paneling works		Included in the Cost of Construction
8.	Aluminum works		Included in the Cost of Construction
9.	Aluminum hand rails		Included in the Cost of Construction
10.	False ceiling		Included in the Cost of Construction
	Total		

Part – E (Miscellaneous)	:	Amount in `
1. Separate toilet room	:	Included in the Cost of Construction
2. Separate lumber room	:	Included in the Cost of Construction
3. Separate water tank / sump	:	Included in the Cost of Construction
4. Trees, gardening	:	Included in the Cost of Construction
Total		

Vastukala Consultants (I) Pvt. Ltd.



Since 1989

No. of wash basins

No. of bath tubs

Any other fixtures

Water meters, taps etc.

No. of urinals

b)

c)

d)

e)

f)



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 8 of 22

Part – F (Services)			Amount in `	
1.	Water supply arrangements	:	Included in the Cost of Construction	
2.	Drainage arrangements		Included in the Cost of Construction	
3.	Compound wall	:	Included in the Cost of Construction	
4.	C.B. deposits, fittings etc.	:	Included in the Cost of Construction	
5.	Pavement		Included in the Cost of Construction	
	Total			

	Government Value			
Particulars	Area in Sq. M.	Rate in (₹)	Value in (₹)	
Land	150.00	4,320.00	6,48,000.00	
Structure	As per valu	ation table	21,87,185.00	
	Total		28.35.185.00	

### Structure

Particulars	Built Up Area	Year of Const.	Estimated Replacement Rate	Age of Building	Depreciated Rate	Depreciated Value	Estimated Replacement Cost / Insurable Value
	(Sq. M.)		(र)	In Years	(₹)	(₹)	(₹)
Ground + First Floor	131.26	2009	21,500.00	15	16,663.00	21,87,185.00	28,22,090.00
Total						21,87,185.00	28,22,090.00

# Abstract of the entire property

	Abattaci		the entire property
Part – A	Land	:	₹ 24,00,000.00
Part – B	Building	:	₹ 21,87,185.00
Part – C	Interior Decoration =1413 Sq.Ft X 1100 per Sq.Ft	:	₹ 15,54,300.00
Part - D	Compound Gate & Safty Door	:	₹ 2,00,000.00
Part – E	Gate	:	₹ 1,00,000.00
Part – F	Water Proofing	:	₹ 1,00,000.00
Part – G	Parking and Side Margin		₹ 1,00,000.00
	Market Value	:	₹ 66,41,485.00
	Realizable Value	:	₹ 63,09,411.00
	Distress Sale Value	:	₹ 53,13,188.00
	Total Insurable value (Full Replacement Cost - Subsoil Structure Cost (15%)	:	₹ 18,59,107.00
Remarks			<b>L</b>

The cost approach is a Real Property Valuation method which considers the value of a property as the cost of the land plus the replacement cost of the building (construction costs) minus the physical and functional depreciation.

This approach is most commonly used for real estate properties that are not easily sold like schools, hospitals, government buildings and above type of property. Land cost can be estimated using the Sales Comparison Approach by studying recent sales of land close to the subject property, and these sales should be comparable in size and

Vastukala Consultants (I) Pvt. Ltd.




Since 1989



#### Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 9 of 22

location with subject property. There are different ways to estimate replacement costs, the most common being finding out the cost to build a square foot of comparable properties multiplied by the total square footage of the building. The cost approach is commonly used for Residential Bungalow, Residential Building and properties mentioned above. As the property is an residential land and building thereof, we have adopted Cost approach / Land and Building Method for the purpose of valuation. The Price for similar type of property in the nearby vicinity is in the range of ₹ 10,000.00 to ₹ 20,000.00 per Sq. M. for land Considering the rate with attached report, current market conditions, demand and supply position, Land size, location, sustained demand for residential building / Plot, all round development of commercial and residential application in the locality etc.

We estimate ₹ 16,000.00 per Sq. M. for Land with appropriate cost of construction for valuation.





# Actual Site Photographs



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001: 2015 Certified Company



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 11 of 22



Latitude Longitude: 20°02'35.4"N 74°28'36.1"E Note: The Blue line shows the route to site from nearest Bus Stand (Yeola - 1.7. Km)





Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 12 of 22

# **Ready Reckoner Rate**

V2123100 None Kule Cudh		महाराष्ट्र शासन	
		"" Welcome to Valuation of Pr	operties in Maharashtra
ocation Details	pment Agreement Otenant Occupied Other	Division Name Nachik 🗸	Help on Division
District Name	নাহত 🗸 Taluka Name	धरता 🗸 Village/Zone Name स्रीव : आगणगव (भाग	v
Attribute	सई नवर ¥ 74	SubZone Name 7.4-मॉन आगणगार मध	<b>v</b>
Nahapalika Area	B Cleee Palika 🗸		
	Open Land Residence Offic 4320 25000 2702		
	4229 23900 27102	20 31250 d Square Neter	

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001: 2015 Certified Company



Since 1989



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 13 of 22

mer Property in Nate	ik 3. Plata in Norsek				Posted on Feb 15, 20	te l'asset
12125	l Re	esidential Land/Plot fo	or Sale			
	9 1,011 per sq.ft.	Yeste, Navek, Matter exists				
Imated EMI ₹9,58-	4					
RA STATUS 🔵 NOT	AVAILABLE   Website https	Umaharerait mañaomine g	ov.m/			
Overview	Owner Details	Registry Record	Explore Locality	Recommendations	Ar. >	
Property (8)						
			ot area 1186 sq.ft.v	Pris	te t+ Govt Charges & Tax	
			10.12 sq.m.)		per sq.ft.	
			Address	👩 Fac	10.0	
			cola, Nasik	East	*16 	
			Construction of the			
			Gated Society	Others	eriooking	
				softer a		
	Photos not shared by advertiser					
			Possession		ors Allowed For Construction	
	Request Photos	In	mmediate	2 Floors		
nsaction Type : Res perty Code : F4735 Marne: con/1473620	52917	operty Ownership : Free	hold 🖲 Gated Corr	smunity: <b>Yes</b>	Boundary Wall. No	
perty Code : F4735	52917	operty Ownership : Freel		smunity: Yes	Boundary Wall. No	
oerty Code : <b>F4735</b> Marris, com/1473620	52917		heid U Leaton Con	enunity: Yes	Selilent Property	a) 6'-
perty Code : <b>F4735</b> Marne, com/1473620	52917 877		hold U Lasten Con		Selifiant Property	3 e <sup>r,</sup>
perty Code : <b>F4735</b> Marne, com/1473620	52917 217 9° - Dhe Looig / Need / Soung Yun Honer Roong Noo	dmark - Pause mok		• • Q	Selivitents Property 📾	
perty Code : <b>F4735</b> Marne, com/14/362	52917 97. Bran Looky / Payed / Sovry / Las Home Pagety in No. <b>- 12 Lac</b> e	dmark o Passenal PESSencia Lan 11.011 per spit	oProt for Sale	• • Q	Selivitents Property 📾	∃ e <sup>r</sup> ∼
perty Code : <b>F4735</b> Marne, com/1473620	52917 91 - Dhar Looky / Poyed / Soory / Las Home Poyed / North Coord - <b>12 Loc</b> g Estimated Diri 12324	aman o Pusi e mai o Pusi e mai o Pusi e mai o mai a vana duri	aPitot for Sale	• • Q	Selivitents Property 📾	
oerty Code : <b>F4735</b> Marris, com/1473620	52917 91 - Dhe Looky / Payed / Servy / Les Honer Rooky in No. - <b>12 Lac</b> Bonnad 541 2035	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Neose kaps (malarentes)	dPilot for Sale scrims	Pased on Falls 11, 2224   R	Selivitents Property 📾	antari Owner *
berty Code : <b>F4735</b> Marses.com/1473620	52917 91 - Dhar Looky / Poyed / Soory / Las Home Poyety in Not - <b>12 Loc</b> y Estimated Diri 12324	aman o Pusi e mai o Pusi e mai o Pusi e mai o mai a vana duri	dPilot for Sale scrims	• • Q	Selivitents Property 📾	antari Owner *
erty Code : F4735 Places.com/1473520	52917 91 - Dhe Looky / Payed / Servy / Les Honer Rooky in No. - <b>12 Lac</b> Bonnad 541 2035	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Neose kaps (malarentes)	afflot for Sale calles animgaure coord Explore Locally Recor	Protect on Feb 15.2034	Selivitents Property	antari Owner *
erty Code : F4735 Places.com/1473520	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Neose kaps (malarentes)	aPitot for Sale extra entre grovi kond Explore Locality Recor Pot area 118 egit V	Process on Fair 15, 2024   Ar Process on Fair 15, 2024   Ar Process Art 2	Selivitents Property	antari Owner *
erty Code : F4735 Places.com/1473520	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Neose kaps (malarentes)	SPice for Sale exite exite point Koord Explore Locality Recor	Reserve File 12.2224 (k) mmendations Art. 2	Selivitents Property	antari Owner *
erty Code : F4735 Places.com/1473520	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	dPlot for Sale colors writergour cool Explore Locality Recor The area 1180 splt × ick Kauni CK Kauni	Reserver Fair 1, 2024 R Preserver Fair 1, 2024 R mmendations Art. 3 Proce 12 Later Cont Charges & Tax. 19 1,011 per so.t.	Selivitents Property	antari Owner *
erty Code : F4735 Places.com/1473520	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	diffect for Sale extra : antine gound cord Explore Locality Recor Englands The split ~ (51 Saun)	Process on Fair 15, 2024   Ar Process on Fair 15, 2024   Ar Process Art 2	Selivitents Property	antari Owner *
erty Code : F4735 Places.com/1473520	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	SPlot for Sale extre extre extre extre for an UB splore Locality Recor Prof an UB splore Record Prof an UB splore Record Prof an UB splore reals Nasak	Reserves Fair 1, 2224 (k) The stand of the stand of the stand The stand of the stand of t	Selivitents Property	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	dPlot for Sale colors writergour cool Explore Locality Recor The area 1180 splt × ick Kauni CK Kauni	Process Art 3 P	Selivitents Property	antari Owner *
berty Code : <b>F4735</b> Marses.com/1473620	52917 W* the Looky / Need / Servy / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	dPlot for Sale extens extens cord Explore Locality Recor Tot area TIB appt ~ Instance Tot area TIB appt ~ Instance Tot area TIB appt ~	Therefore the state of the stat	Selivitents Property	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 W* the Looky / Neper/ Sonry / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	eman - Anse total PLOTI per solt - Mediate kryschinderen schwa- Comer Decels Registy Re- - Re- - Registy Re- - Registy Re- - Registy	dPitot for Sale excites writergoury record Explore Locality Recor Prof and Filler sight → recisit rups) recisit Rups)	Monenciadores Art 2  Processors Art 2  Processors Art 2  Processors PLater Food Charges & Tax PLATE Food PLATE per solut.  Plate Parts Plate Pl	Selivitents Property	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 W* the Looky / Neper/ Sonry / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	dman. > Pasa e test > 1.011 per so fit. > Milli Matt. : Nesse kaps (malarentes)	aPlot for Sale colors writer gouv cord Epiper Locality Recor Pot area 118 topt ~ rest Real Pot Assis Pot Sales Core Scorey Yes	Therefore the state of the stat	Selivitents Property	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 W* the Looky / Neper/ Sonry / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	eman - Anse total PLOTI per solt - Mediate kryschinderen schwa- Comer Decels Registy Re- - Re- - Registy Re- - Registy Re- - Registy	dPitot for Sale excites writergoury record Explore Locality Recor Prof and Filler sight → recisit rups) recisit Rups)	Monenciadores Art 2  Processors Art 2  Processors Art 2  Processors PLater Food Charges & Tax PLATE Food PLATE per solut.  Plate Parts Plate Pl	Selivitents Property	antari Owner *
perty Code : <b>F4735</b> Marne, com/1473620	52917 W* the Looky / Neper/ Sonry / Lev Here: Rooky in Non 12 Lace Estimate Diri 2004 More Rooky in Non Overview	eman - Anse total PLOTI per solt - Mediate kryschinderen schwa- Comer Decels Registy Re- - Re- - Registy Re- - Registy Re- - Registy	dPitot for Sale excites writergoury record Explore Locality Recor Prof and Filler sight → recisit rups) recisit Rups)	Monenciadores Art 2  Processors Art 2  Processors Art 2  Processors PLater Food Charges & Tax PLATE Food PLATE per solut.  Plate Parts Plate Pl	Selivitents Property	antari Owner *
perty Code : <b>F4735</b> Marne, com/1473620	52917 y* the Looky / Report / Socrey / Lev 122 Lac 122 Lac 122 Lac 123 Lac 124 Lac 124 Lac 125 Marcel Divide 127 Marcel Divide 128 Marce	eman In Para In India 2011 per 1921. Besidencia Lan In India India MARIANSE India India Comer Decide Argumentations Comer Decide Argumentations Registre Produce Registre Produce	oPtor for Sale extrem anime ground correl Department Restances Table state → cost States Test Analik Protores Test Analik Test Analik Test Analik Test Analik Test Analik Test Analik	Transmissions Ar. 2  Processing Construction  Processing  Process	Selivitents Property	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 9* Drie Lawig / Payer / Sony / Le 12 Lac Emission (1235 Emission (1235 Emission (1235 Emission (1235 Emission (1235 Emission (1235) Emission (12	aman a Pasa e Mak 1 (1) 11 per so ft. Petidemotal Lani meta Assa Mak Meta Makata Petidemotal Hans. Owner Details Registry Re Registry Report Produce Registry Denomina Registry Denomina	oPtor for Sale extens anime grount corrid Explore Locality Recor Prot and 1188 splt → crist Rula Record Explore Locality Recor Prot and 1188 splt → crist Rula Record Sale Prot and Sale Record Sale	Trimendations Ar. 2  Processing Ar. 2  Processing Party Ar. 2  Party Ar.	Selivitents Property 📾	antari Owner *
oerty Code : <b>F4735</b> Marris, com/1473620	52917 9* Drie Lasie, / Payer / Soney / Le - 12 Lac Email Di 2355 Email Di 2355 Misson (100) Norrier Pageny (0) 1/anaston //or Miss Pageny (0)	aman a Pasa e Mak 1 (1) 11 per so ft. Petidemotal Lani meta Assa Mak Meta Makata Petidemotal Hans. Owner Details Registry Re Registry Report Produce Registry Denomina Registry Denomina	oPtor for Sale extens anime grount corrid Explore Locality Recor Prot and 1188 splt → crist Rula Record Explore Locality Recor Prot and 1188 splt → crist Rula Record Sale Prot and Sale Record Sale	Trimendations Ar. 2  Processing Ar. 2  Processing Party Ar. 2  Party Ar.	Selivitents Property 📾	antari Owner *
perty Code : <b>F4735</b> Marne, com/1473620	52917 9* Drie Lasie, / Payer / Soney / Le - 12 Lac Email Di 2355 Email Di 2355 Misson (100) Norrier Pageny (0) 1/anaston //or Miss Pageny (0)	aman a Pasa e Mak 1 (1) 11 per so ft. Petidemotal Lani meta Assa Mak Meta Makata Petidemotal Hans. Owner Details Registry Re Registry Report Produce Registry Denomina Registry Denomina	oPtor for Sale extens anime grount corrid Explore Locality Recor Prot and 1188 splt → crist Rula Record Explore Locality Recor Prot and 1188 splt → crist Rula Record Sale Prot and Sale Record Sale	Trimendations Ar. 2  Processing Ar. 2  Processing Party Ar. 2  Party Ar.	Selivitents Property 📾	antari Owner *

Price Indicators



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 14 of 22

As a result of my appraisal and analysis, it is my considered opinion that the present Market value of the above property in the prevailing condition with aforesaid specifications is ₹ 66,41,485.00 (Rupees Sixty-Six Lakh Forty-One Thousand Four Hundred Eighty-Five Only). The Realizable Value of the above property is ₹ 63,09,411.00 (Rupees Sixty-Three Lakh Nine Thousand Four Hundred Eleven Only) and The Distress Value is ₹ 53,13,188.00 (Rupees Fifty-Three Lakh Thirteen Thousand One Hundred Eighty-Eight Only).

Place: Nashik Date: 13.06.2024

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Chalikwar Digitally signed by Sharadkumar Chalikwar DN: cn=Sharadkumar Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=Mumbai, email=cmd@vastukala.org, c=IN Date: 2024.06.13 12:32:50 +05'30'

Director

Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

Auth. Sign.

# Certificate

This is to certify that Copy of **Approved Plan No.PWP/WS/156/09/10 dated 13.11.2009** is approved by Yeola Municipal Council, Yeola is genuine & construction is as per copy of Approved Building Plan furnished

The undersigned has inspected the property detailed in the Valuation Report dated

on	DE TRA	. We are satisfied that the fair and reasonable market value of the property is			
	al "shokesid"	(Rupees	VAN DAV	n el en ni arse adi	
		este con pren latinti stitucció	only).		

Date

Signature (Name of the Branch Manager with Official seal)

Enclosures		
Declaration From Valuers (Annexure- I)	Attached	
Model code of conduct for valuer - (Annexure II)	Attached	





Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 15 of 22

Annexure-II

## DECLARATION FROM VALUERS

- I, hereby declare that:
- a. The information furnished in my valuation report dated 13.06.2024 is true and correct to the best of my knowledge and belief and I have made an impartial and true valuation of the property.
- b. I have no direct or indirect interest in the property valued;
- c. I/ my authorized representative has personally inspected the property on 12.06.2024 The work is not sub - contracted to any other valuer and carried out by myself.
- d. I have not been convicted of any offence and sentenced to a term of Imprisonment;
- e. I have not been found guilty of misconduct in my professional capacity.
- f. I have read the Handbook on Policy, Standards and procedure for Real Estate Valuation, 2011 of the IBA and this report is in conformity to the "Standards" enshrined for valuation in the Part - B of the above handbook to the best of my ability.
- g. I have read the International Valuation Standards (IVS) and the report submitted to the Bank for the respective asset class is in conformity to the "Standards" as enshrined for valuation in the IVS in "General Standards" and "Asset Standards" as applicable. The valuation report is submitted in the prescribed format of the bank.
- h. I abide by the Model Code of Conduct for empanelment of valuer in the Bank. (Annexure III A signed copy of same to be taken and kept along with this declaration)
- i. I am registered under Section 34 AB of the Wealth Tax Act, 1957.
- j. I am Director of the company, who is competent to sign this valuation report.

Vastukala Consultants (I) P\

An ISO 9001: 2015 Certified Company

k. Further, I hereby provide the following information.

Since 1989





Sr. No.		Valuer comment
1.	Background information of the asset being valued;	The property under consideration is being purchased by Sau.Sunita Sanjay Kulkarni from Shri.Anil Bhavarlal Lodha as per vide Saledeed Dated.17.04.2009
2.	Purpose of valuation and appointing authority	As per the request from Union Bank of India Mumbai Naka Branch to assess Market value of the property for loan purpose.
3.	Identity of the valuer and any other experts involved in the valuation;	Sharadkumar B. Chalikwar- Regd. Valuer Manoj B. Chalikwar – Regd. Valuer Sanjay Phadol- Regional Technical Manager Swapnil Wagh –Valuation Engineer Binu Surendran – Technical Officer Chinatamani Chaudhari – Technical Manager
4.	Disclosure of valuer interest or conflict, if any;	We have no interest, either direct or indirect, in the property valued. Further to state that we do not have relation or any connection with property owner / applicant directly or indirectly. Further to state that we are an independent Valuer and in no way related to property owner / applicant
5.	Date of appointment, valuation date and date of report;	Date of Appointment – 12.06.2024 Valuation Date – 12.06.2024 Date of Report – 13.06.2024
6.	Inspections and/or investigations undertaken;	Physical Inspection done on 12.06.2024
7.	Nature and sources of the information used or relied upon;	<ul> <li>Market Survey at the time of site visit</li> <li>Ready Reckoner rates / Circle rates</li> <li>Online search for Registered Transactions</li> <li>Online Price Indicators on real estate portals</li> <li>Enquiries with Real estate consultants</li> <li>Existing data of Valuation assignments carried out by us</li> </ul>
8.	Procedures adopted in carrying out the valuation and valuation standards followed;	Land and Building Method
9.	Restrictions on use of the report, if any;	This valuation is for the use of the party to whom it is addressed and for no other purpose. No responsibility is accepted to any third party who may use or rely on the whole or any part of this valuation. The valuer has no pecuniary interest that would conflict with the proper valuation of the property.
0.	Major factors that were taken into account during the valuation;	current market conditions, demand and supply position, Commercial shop size, location, upswing in real estate prices, sustained
	e en anna an anna anna anna anna anna a	demand for Residential Plot, all round development of commercial and residential application in the locality etc.
1.	Caveats, limitations and disclaimers to the extent they explain or elucidate the limitations faced by valuer, which shall not be for the purpose of limiting his responsibility for the	Attached

Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 16 of 22



Since 1989



An ISO 9001: 2015 Certified Company

Vastukala Consultants (I) Pvt. Ltd.

Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 17 of 22

	valuation report.	
1		Set 1 attended

## Assumptions, Disclaimers, Limitations & Qualifications

#### Value Subject to Change

The subject appraisal exercise is based on prevailing market dynamics as on **13th June 2024** and does not take into account any unforeseeable developments which could impact the same in the future.

### **Our Investigations**

We are not engaged to carry out all possible investigations in relation to the subject property. Where in our report we identify certain limitations to our investigations, this is to enable the reliant party to instruct further investigations where considered appropriate or where we recommend as necessary prior to reliance. Vastukala Consultants India Pvt. Ltd. (VCIPL) is not liable for any loss occasioned by a decision not to conduct further investigations

#### Assumptions

Assumptions are a necessary part of undertaking valuations. VCIPL adopts assumptions for the purpose of providing valuation advise because some matters are not capable of accurate calculations or fall outside the scope of our expertise, or out instructions. The reliant party accepts that the valuation contains certain specific assumptions and acknowledge and accept the risk of that if any of the assumptions adopted in the valuation are incorrect, then this may have an effect on the valuation.

#### Information Supplied by Others

The appraisal is based on the information provided by the client. The same has been assumed to be correct and has been used for appraisal exercise. Where it is stated in the report that another party has supplied information to VCIPL, this information is believed to be reliable but VCIPL can accept no responsibility if this should prove not to be so.

#### **Future Matters**

To the extent that the valuation includes any statement as to a future matter, that statement is provided as an estimate and/or opinion based on the information known to VCIPL at the date of this document. VCIPL does not warrant that such statements are accurate or correct.

## Map and Plans

Any sketch, plan or map in this report is included to assist the reader while visualising the property and assume no responsibility in connection with such matters.

## Site Details

Based on inputs received from Client's representative and site visit conducted, we understand that the subject property is currently a contiguous land parcel admeasuring Plot Area =150.00 Sq. M. and structure Built up Area in Sq. M. =131.26 there of Name of Sau.Sunita Sanjay Kulkarni. Further, VCIPL has assumed that the subject property is free from any encroachment and is available as on the date of the appraisal.

Vastukala Consultants (I) Pvt



Since 1989



#### **Property Title**

Based on our discussion with the Client, we understand that the subject property is being Owner **Sau.Sunita Sanjay Kulkarni.** For the purpose of this appraisal exercise, we have assumed that the subject property has a clear title and is free from any encumbrances, disputes and claims. VCIPL has made no further enquiries with the relevant local authorities in this regard and does not certify the property as having a clear and marketable title. Further, no legal advice regarding the title and ownership of the subject property has been obtained for the purpose of this appraisal exercise. It has been assumed that the title deeds are clear and marketable.

## **Environmental Conditions**

We have assumed that the subject property is not contaminated and is not adversely affected by any existing or proposed environmental law and any processes which are carried out on the property are regulated by environmental legislation and are properly licensed by the appropriate authorities.

#### **Town Planning**

The permissible land use, zoning, achievable FSI, area statement adopted for purpose of this valuation is based on the information provided by the Client's representative and the same has been adopted for this valuation purpose. VCIPL has assumed the same to be correct and permissible. VCIPL has not validated the same from any authority.

#### Area

Based on the information provided by the Client's representative, we understand that the subject property is a owner occupied, contiguous land parcel admeasuring Plot Area =150.00 Sq. M. and structure Built up Area in Sq. M. =131.26

#### **Condition & Repair**

In the absence of any information to the contrary, we have assumed that there are no abnormal ground conditions, nor archaeological remains present which might adversely affect the current or future occupation, development or value of the property. The property is free from rat, infestation, structural or latent defect. No currently known deleterious or hazardous materials or suspect techniques will be used in the construction of or subsequent alteration or additions to the property and comments made in the property details do not purport to express an opinion about, or advise upon, the condition of uninspected parts and should not be taken as making an implied representation or statement about such parts

#### Valuation Methodology

For the purpose of this valuation exercise, the valuation methodology used is Direct Comparison Approach Method and proposed Current Use / Existing Use premise is considered for this assignment.

The Direct Comparison Approach involves a comparison of the property being valued to similar properties that have actually been sold in arms - length transactions or are offered for sale. This approach demonstrates what buyers have historically been willing to pay (and sellers willing to accept) for similar

Vastukala Consultants (I)



Since 1989



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 19 of 22

properties in an open and competitive market and is particularly useful in estimating the value of the land and properties that are typically traded on a unit basis.

In case of inadequate recent transaction activity in the subject micro-market, the appraiser would collate details of older transactions. Subsequently, the appraiser would analyse rental / capital value trends in the subject micro-market in order to calculate the percentage increase / decrease in values since the date of the identified transactions. This percentage would then be adopted to project the current value of the same.

Where reliance has been placed upon external sources of information in applying the valuation methodologies, unless otherwise specifically instructed by Client and/or stated in the valuation, VCIPL has not independently verified that information and VCIPL does not advise nor accept it as reliable. The person or entity to whom the report is addressed acknowledges and accepts the risk that if any of the unverified information in the valuation is incorrect, then this may have an effect on the valuation.

#### Not a Structural Survey

We state that this is a valuation report and not a structural survey

Other

All measurements, areas and ages quoted in our report are approximate

Legal

We have not made any allowances with respect to any existing or proposed local legislation relating to taxation on realization of the sale value of the subject property. VCIPL is not required to give testimony or to appear in court by reason of this appraisal report, with reference to the property in question, unless arrangement has been made thereof. Further, no legal advice on any aspects has been obtained for the purpose of this appraisal exercise

### Property specific assumptions

Based on inputs received from the client and site visit conducted, we understand that the subject property is currently in owner possession, contiguous land parcel admeasuring Plot Area =150.00 Sq. M. and structure Built up Area in Sq. M. =131.26

## ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.

Vastukala Consultants (I)

5. There is no direct/ indirect interest in the property valued.

Since 1989





Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 20 of 22

6.

The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates

#### Annexure - II

# MODEL CODE OF CONDUCT FOR VALUERS

## {Adopted in line with Companies (Registered Valuers and Valuation Rules, 2017)}

All valuers empanelled with bank shall strictly adhere to the following code of conduct:

### Integrity and Fairness

- 1. A valuer shall, in the conduct of his/its business, follow high standards of integrity and fairness in all his/its dealings with his/its clients and other valuers.
- 2. A valuer shall maintain integrity by being honest, straightforward, and forthright in all professional relationships.
- 3. A valuer shall endeavour to ensure that he/it provides true and adequate information and shall not misrepresent any facts or situations.
- 4. A valuer shall refrain from being involved in any action that would bring disrepute to the profession.
- 5. A valuer shall keep public interest foremost while delivering his services.

## Professional Competence and Due Care

- 6. A valuer shall render at all times high standards of service, exercise due diligence, ensure proper care and exercise independent professional judgment.
- 7. A valuer shall carry out professional services in accordance with the relevant technical and professional standards that may be specified from time to time.
- A valuer shall continuously maintain professional knowledge and skill to provide competent professional service based on up-to-date developments in practice, prevailing regulations / guidelines and techniques.
- 9. In the preparation of a valuation report, the valuer shall not disclaim liability for his/its expertise or deny his/its duty of care, except to the extent that the assumptions are based on statements of fact provided by the company or its auditors or consultants or information available in public domain and not generated by the valuer.
- 10. A valuer shall not carry out any instruction of the client insofar as they are incompatible with the requirements of integrity, objectivity and independence.
- 11. A valuer shall clearly state to his client the services that he would be competent to provide and the services for which he would be relying on other valuers or professionals or for which the client can have a separate arrangement with other valuers.

Vastukala Consultants (I)



Since 1989



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 21 of 22

### Independence and Disclosure of Interest

- 12. A valuer shall act with objectivity in his/its professional dealings by ensuring that his/its decisions are made without the presence of any bias, conflict of interest, coercion, or undue influence of any party, whether directly connected to the valuation assignment or not.
- 13. A valuer shall not take up an assignment if he/it or any of his/its relatives or associates is not independent in terms of association to the company.
- 14. A valuer shall maintain complete independence in his/its professional relationships and shall conduct the valuation independent of external influences.
- 15. A valuer shall wherever necessary disclose to the clients, possible sources of conflicts of duties and interests, while providing unbiased services.
- 16. A valuer shall not deal in securities of any subject company after any time when he/it first becomes aware of the possibility of his / its association with the valuation, and in accordance with the Securities and Exchange Board of India (Prohibition of Insider Trading)Regulations,2015 or till the time the valuation report becomes public, whichever is earlier.
- 17. A valuer shall not indulge in "mandate snatching" or offering "convenience valuations" in order to cater to a company or client's needs.
- 18. As an independent valuer, the valuer shall not charge success fee. (Success fees may be defined as a compensation / incentive paid to any third party for successful closure of transaction. In this case, approval of credit proposals).
- 19. In any fairness opinion or independent expert opinion submitted by a valuer, if there has been a prior engagement in an unconnected transaction, the valuer shall declare the association with the company during the last five years.

## Confidentiality

20. A valuer shall not use or divulge to other clients or any other party any confidential information about the subject company, which has come to his / its knowledge without proper and specific authority or unless there is a legal or professional right or duty to disclose.

### Information Management

- 21. A valuer shall ensure that he/ it maintains written contemporaneous records for any decision taken, the reasons for taking the decision, and the information and evidence in support of such decision. This shall be maintained so as to sufficiently enable a reasonable person to take a view on the appropriateness of his /its decisions and actions.
- 22. A valuer shall appear, co-operate and be available for inspections and investigations carried out by the authority, any person authorised by the authority, the registered valuers organisation with which he/it is registered or any other statutory regulatory body.
- 23. A valuer shall provide all information and records as may be required by the authority, the Tribunal,

An ISO 9001: 2015 Certified Company

Vastukala Consultants (I) Pvt. Ltd



Since 1989



Valuation Report : UBI / Mumbai Naka Branch / Sau.Sunita Sanjay Kulkarni (009251/2306713) Page 22 of 22

Appellate Tribunal, the registered valuers organisation with which he/it is registered, or any other statutory regulatory body.

24. A valuer while respecting the confidentiality of information acquired during the course of performing professional services, shall maintain proper working papers for a period of three years or such longer period as required in its contract for a specific valuation, for production before a regulatory authority or for a peer review. In the event of a pending case before the Tribunal or Appellate Tribunal, the record shall be maintained till the disposal of the case.

## Gifts and hospitality:

25. A valuer or his / its relative shall not accept gifts or hospitality which undermines or affects his independence as a valuer.

Explanation: For the purposes of this code the term 'relative' shall have the same meaning as defined in clause (77) of Section 2 of the Companies Act, 2013 (18 of 2013).

26. A valuer shall not offer gifts or hospitality or a financial or any other advantage to a public servant or any other person with a view to obtain or retain work for himself / itself, or to obtain or retain an advantage in the conduct of profession for himself / itself.

### Remuneration and Costs.

- 27. A valuer shall provide services for remuneration which is charged in a transparent manner, is a reasonable reflection of the work necessarily and properly undertaken, and is not inconsistent with the applicable rules.
- 28. A valuer shall not accept any fees or charges other than those which are disclosed in a written contract with the person to whom he would be rendering service.

## Occupation, employability and restrictions.

- 29. A valuer shall refrain from accepting too many assignments, if he/it is unlikely to be able to devote adequate time to each of his/ its assignments.
- A valuer shall not conduct business which in the opinion of the authority or the registered valuer organisation discredits the profession.

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

Since 1989

## Sharadkumar Chalikwar

Digitally signed by Sharadkumar Chalikwar DN: cn=Sharadkumar Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=Mumbal, email=cmd@vastukala.org, c=IN Date: 2024.06.13 12:33.01 +05'30'

## Director

Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

Auth, Sian,

Vastukala Consultants (I) Pvt. Ltd.



