

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64c4e1300950be569ff8a459"
    },
    "firstName": "Pratiksha",
    "type": "CREDITOFFICER",
    "_id": "64c4e1a30950be569ff8a4cf",
    "lastName": "Bhargava",
    "mobileNo": "",
    "workMobileNo": "7000442789",
    "email": "borivaliwestmumbai@unionbankofindia.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "65000000",
    "discussWithPerson": "Pratiksha",
    "expectedFees": 32500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64c4e1300950be569ff8a459",
  "name": "UMFB Branch",
  "branchCode": "",
  "mobileNo": "02228929306",
  "alternateMobileNo": "",
  "email": "borivaliwestmumbai@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shree Rasraj Heights, Rokadia Lane, Borivali West, Mumbai -400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720a36afd7d55eddedc4a7",
"role": "SITEENGINEER",
"firstName": "Anwar",
"email": "anwar21786@gmail.com",
"lastName": "Shaikh",
"mobileNo": "8552884500",
"designation": "",
"shortName": "AS",
"workWithDocumentMaker": "",
"profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.41513415011197",
  "longitude": "72.82453517983434"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82453517983434,
    19.41513415011197
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/06/2024 11:53 am"
    },
    {
      "dateTime": "13/06/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Achole",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "46",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "235",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": false,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "666a82d2d4bc7979fdcfcaf7",
"ownerName": "M/s Industrial Rubber Products pvt ltd ",
"ownerPhoneNo": "8010182240",
"appAddress": "plot no 46 Survey No 235 The Vasai Taluka industrial Co-op Estate
Dist & Tal Thane ",
"remark": "Tekover case ICICI (Contact Presan Priyanka Madam)",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/666a82d2d4bc7979fdcfcaf7/document_1718256033941_1718255889
827_Ms_Industrial_Rubber_Products_pvt_ltd_UMFB_Borivali_West.pdf",
    "fileName": "document_1718256033941_1718255889827_Ms_Industrial_Rubber_P
roducts_pvt_ltd_UMFB_Borivali_West.pdf",
    "id": "327430",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Thu Jun 13 2024 10:55:37 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/666a82d2d4bc7979fdcfcaf7/document_1718256090858_1718255945
420_Industrial_Rubber_Products_pvt_ltd_Plot_46_2003_Agreement.pdf",
    "fileName": "document_1718256090858_1718255945420_Industrial_Rubber_Produ
cts_pvt_ltd_Plot_46_2003_Agreement.pdf",
    "id": "857623",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Thu Jun 13 2024 10:55:37 GMT+0530 (India Standard Time)"
  },
  }
```

```
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/666a82d2d4bc7979fdcfcaf7/document_1718256239191_1718256067837_JR_Fibre_Glass_1_Agreement_UMFB_1991.pdf",
  "fileName": "document_1718256239191_1718256067837_JR_Fibre_Glass_1_Agreement_UMFB_1991.pdf",
  "id": "171490",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Thu Jun 13 2024 10:55:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/666a82d2d4bc7979fdcfcaf7/document_1718256297949_1718256153710_UMFB_Borivali_West_other_3.pdf",
  "fileName": "document_1718256297949_1718256153710_UMFB_Borivali_West_other_3.pdf",
  "id": "431456",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Thu Jun 13 2024 10:55:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1718364666399_UMFB_Plan_Lead_no_9263_.pdf",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/document_1718364666399_UMFB_Plan_Lead_no_9263_.pdf",
  "id": "818668",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Fri Jun 14 2024 17:01:07 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009263",
```

```
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "495053",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 13 2024 10:55:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s Industrial Rubber Products pvt ltd ",
    "phone": "8010182240",
    "ownershipShare": "",
    "email": "",
    "id": "151132"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fad0e137dd92c5a",
    "name":
"externallmg_1718594518138_WhatsApp_Image_20240615_at_172827_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518138_WhatsApp_Image_20240615_at_172827_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fad0e137dd92c5b",
    "name":
"externallmg_1718594518145_WhatsApp_Image_20240615_at_172827.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518145_WhatsApp_Image_20240615_at_172827.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c5c",
  "name":
"externallmg_1718594518152_WhatsApp_Image_20240615_at_172828_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518152_WhatsApp_Image_20240615_at_172828_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c5d",
  "name":
"externallmg_1718594518159_WhatsApp_Image_20240615_at_172828.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518159_WhatsApp_Image_20240615_at_172828.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c5e",
  "name":
"externallmg_1718594518164_WhatsApp_Image_20240615_at_172829.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518164_WhatsApp_Image_20240615_at_172829.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c5f",
  "name":
"externallmg_1718594518168_WhatsApp_Image_20240615_at_172830.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518168_WhatsApp_Image_20240615_at_172830.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c60",
  "name":
"externallmg_1718594518173_WhatsApp_Image_20240615_at_172832_1.jpeg",
```

```
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518173_WhatsApp_Image_20240615_at_172832_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fadc0e137dd92c61",
    "name":
"externallmg_1718594518178_WhatsApp_Image_20240615_at_172832_2.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518178_WhatsApp_Image_20240615_at_172832_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fadc0e137dd92c62",
    "name":
"externallmg_1718594518182_WhatsApp_Image_20240615_at_172832.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518182_WhatsApp_Image_20240615_at_172832.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fadc0e137dd92c63",
    "name":
"externallmg_1718594518188_WhatsApp_Image_20240615_at_172833_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518188_WhatsApp_Image_20240615_at_172833_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabd6fadc0e137dd92c64",
    "name":
"externallmg_1718594518193_WhatsApp_Image_20240615_at_172833_2.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518193_WhatsApp_Image_20240615_at_172833_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "666fabd6fadc0e137dd92c65",
  "name":
"externallmg_1718594518196_WhatsApp_Image_20240615_at_172833.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518196_WhatsApp_Image_20240615_at_172833.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c66",
  "name":
"externallmg_1718594518200_WhatsApp_Image_20240615_at_172835_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518200_WhatsApp_Image_20240615_at_172835_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c67",
  "name":
"externallmg_1718594518204_WhatsApp_Image_20240615_at_172835_2.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518204_WhatsApp_Image_20240615_at_172835_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabd6fadc0e137dd92c68",
  "name":
"externallmg_1718594518207_WhatsApp_Image_20240615_at_172835.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594518207_WhatsApp_Image_20240615_at_172835.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e516fc",
  "name":
"externallmg_1718594549018_WhatsApp_Image_20240615_at_172836_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549018_WhatsApp_Image_20240615_at_172836_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e516fd",
    "name":
"externallmg_1718594549025_WhatsApp_Image_20240615_at_172836.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549025_WhatsApp_Image_20240615_at_172836.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e516fe",
    "name":
"externallmg_1718594549030_WhatsApp_Image_20240616_at_154533.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549030_WhatsApp_Image_20240616_at_154533.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e516ff",
    "name":
"externallmg_1718594549033_WhatsApp_Image_20240616_at_154534.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549033_WhatsApp_Image_20240616_at_154534.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e51700",
    "name":
"externallmg_1718594549036_WhatsApp_Image_20240615_at_172552_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549036_WhatsApp_Image_20240615_at_172552_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e51701",
```

```
    "name":
"externallmg_1718594549039_WhatsApp_Image_20240615_at_172552.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549039_WhatsApp_Image_20240615_at_172552.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51702",
  "name":
"externallmg_1718594549041_WhatsApp_Image_20240615_at_172555.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549041_WhatsApp_Image_20240615_at_172555.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51703",
  "name":
"externallmg_1718594549044_WhatsApp_Image_20240615_at_172556_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549044_WhatsApp_Image_20240615_at_172556_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51704",
  "name":
"externallmg_1718594549047_WhatsApp_Image_20240615_at_172556.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549047_WhatsApp_Image_20240615_at_172556.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51705",
  "name":
"externallmg_1718594549050_WhatsApp_Image_20240615_at_172557_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549050_WhatsApp_Image_20240615_at_172557_1.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51706",
  "name":
"externallmg_1718594549052_WhatsApp_Image_20240615_at_172557.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549052_WhatsApp_Image_20240615_at_172557.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51707",
  "name":
"externallmg_1718594549056_WhatsApp_Image_20240615_at_172558_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549056_WhatsApp_Image_20240615_at_172558_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51708",
  "name":
"externallmg_1718594549058_WhatsApp_Image_20240615_at_172558_2.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549058_WhatsApp_Image_20240615_at_172558_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e51709",
  "name":
"externallmg_1718594549061_WhatsApp_Image_20240615_at_172558.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549061_WhatsApp_Image_20240615_at_172558.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fabf524f3ba1343e5170a",
  "name":
"externallmg_1718594549063_WhatsApp_Image_20240615_at_172559.jpeg",
```

```
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549063_WhatsApp_Image_20240615_at_172559.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e5170b",
    "name":
"externallmg_1718594549068_WhatsApp_Image_20240615_at_172814_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549068_WhatsApp_Image_20240615_at_172814_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e5170c",
    "name":
"externallmg_1718594549071_WhatsApp_Image_20240615_at_172814_2.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549071_WhatsApp_Image_20240615_at_172814_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e5170d",
    "name":
"externallmg_1718594549075_WhatsApp_Image_20240615_at_172814.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549075_WhatsApp_Image_20240615_at_172814.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fabf524f3ba1343e5170e",
    "name":
"externallmg_1718594549078_WhatsApp_Image_20240615_at_172815_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549078_WhatsApp_Image_20240615_at_172815_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "666fabf524f3ba1343e5170f",
    "name":
"externallmg_1718594549081_WhatsApp_Image_20240615_at_172815.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594549081_WhatsApp_Image_20240615_at_172815.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf49878",
    "name":
"externallmg_1718594575999_WhatsApp_Image_20240615_at_172815_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594575999_WhatsApp_Image_20240615_at_172815_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf49879",
    "name":
"externallmg_1718594576004_WhatsApp_Image_20240615_at_172815.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576004_WhatsApp_Image_20240615_at_172815.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987a",
    "name":
"externallmg_1718594576010_WhatsApp_Image_20240615_at_172817.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576010_WhatsApp_Image_20240615_at_172817.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987b",
    "name":
"externallmg_1718594576014_WhatsApp_Image_20240615_at_172819.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576014_WhatsApp_Image_20240615_at_172819.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987c",
    "name":
"externallmg_1718594576021_WhatsApp_Image_20240615_at_172820.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576021_WhatsApp_Image_20240615_at_172820.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987d",
    "name":
"externallmg_1718594576024_WhatsApp_Image_20240615_at_172821_1.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576024_WhatsApp_Image_20240615_at_172821_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987e",
    "name":
"externallmg_1718594576028_WhatsApp_Image_20240615_at_172821.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576028_WhatsApp_Image_20240615_at_172821.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf4987f",
    "name":
"externallmg_1718594576031_WhatsApp_Image_20240615_at_172822.jpeg",
    "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576031_WhatsApp_Image_20240615_at_172822.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666fac1059d44b137cf49880",
```

```
"name":
"externallmg_1718594576035_WhatsApp_Image_20240615_at_172823.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576035_WhatsApp_Image_20240615_at_172823.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49881",
  "name":
"externallmg_1718594576038_WhatsApp_Image_20240615_at_172824_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576038_WhatsApp_Image_20240615_at_172824_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49882",
  "name":
"externallmg_1718594576041_WhatsApp_Image_20240615_at_172824.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576041_WhatsApp_Image_20240615_at_172824.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49883",
  "name":
"externallmg_1718594576044_WhatsApp_Image_20240615_at_172826_1.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576044_WhatsApp_Image_20240615_at_172826_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49884",
  "name":
"externallmg_1718594576047_WhatsApp_Image_20240615_at_172826_2.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576047_WhatsApp_Image_20240615_at_172826_2.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49885",
  "name":
"externallmg_1718594576050_WhatsApp_Image_20240615_at_172826.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576050_WhatsApp_Image_20240615_at_172826.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666fac1059d44b137cf49886",
  "name":
"externallmg_1718594576053_WhatsApp_Image_20240615_at_172551.jpeg",
  "path": "cases/666a82d2d4bc7979fdcfcaf7/
externallmg_1718594576053_WhatsApp_Image_20240615_at_172551.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-13T05:25:38.065Z",
"updatedAt": "2024-06-17T03:22:56.279Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Basement Floor, Plot No. 46, New/
Current Survey No. 235, Village - Achole, Taluka - Vasai, District - Palghar, State -
Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "M/s Industrial Rubber Products pvt ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": ""
```

"relationWithOwner": "self",
"siteVisitContactNo": "8010182240"

}

Name

Length

Width

Total

Composition :

Other

Composition :
