

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "659fcfa402c44c777bb0fd30"
    },
    "firstName": "Dhananjay",
    "type": "CREDITOFFICER",
    "_id": "659fcfa402c44c777bb0fd32",
    "lastName": "Varande",
    "mobileNo": "",
    "workMobileNo": "8369188639",
    "email": "dhananjay.varande@janatabankpune.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5605800",
    "discussWithPerson": "Dhananjay",
    "expectedFees": 2802.9,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "645c92ba7f94762ec7884195",
  "type": "BANK",
  "name": "Janta Sahkari Bank LTD",
  "displayName": "Janta Sahkari Bank LTD\t",
  "initial": "JSB"
},
"branch": {
  "_id": "659fcfa402c44c777bb0fd30",
  "name": "kandivali West Branch",
  "branchCode": "",
  "mobileNo": "02228010063",
  "alternateMobileNo": "",
  "email": "kandivali@janatabankpune.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 1, Veena Royale Villa, Near Varahi Mata Mandir, Shankar Lane,
Kandivali West"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "645c93d47f94762ec788472a",
  "zoneName": "Mumbai Metro"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
```

```
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": ""
```

```
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.20231713182685",
  "longitude": "72.83824429290314"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83824429290314,
    19.20231713182685
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "14/06/2024 03:51 pm"
    },
    {
      "dateTime": "14/06/2024 12:00 am"
    },
    {
      "dateTime": "14/06/2024 12:00 am"
    }
  ],
}
```

```
{
  "dateTime": "14/06/2024 12:00 am"
},
{
  "dateTime": "14/06/2024 12:00 am"
},
{
  "dateTime": "14/06/2024 12:00 am"
}
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Charkop",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "BD - 729, RSC - 68",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Charkop (3) Shilp Datta Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "7",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-4",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
}
```

```
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West), Mumbai ",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "48",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "1344",
  "depreciatedCostOfConstruction": "16856.00",
  "depreciatedBuildingRate": "1456"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "134700",
  "landRate": "58260",
  "igrImage": "cases/666c12b2772310133b1fc30a/igr_1718433091240_Image.png",
```

```
"squareMeterGuideLineRate": "134700.00",
"squareFeetGuideLineRate": "12514.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "68",
  "rate": "10242.00",
  "squareFeetGuideLineRate": "10242.00",
  "squareMeterGuideLineRate": "110239.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1992",
    "fullDate": "1/1/1992"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
}
```

```
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "28",
"ageOfBuilding": "32",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "1",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "1"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
}
```

```
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Jun 15 2024 17:57:37 GMT+0530 (India Standard Time)",
  "number": "2306776",
  "dayCount": "11",
  "monthCount": "220",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```



```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "2755098.00",
  "selectedBuildUpValue": "269.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18157.00",
    "max": "21429.00"
  },
  "builtUpRateRange": {
    "min": "15097.00",
    "max": "17838.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "269.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [
  "666fef4324f3ba1343e5600d"
],
"paymentIds": [],
"_id": "666c12b2772310133b1fc30a",
"invoices": [],
"ownerName": "Sulochana Tanahi Karjavkar ",
"ownerPhoneNo": "0000000000",
"appAddress": "Room no B/4 Charkop 3 Shilpa datta Co-op HSG Soc Ltd Plot no BD
729 RSC 68 Municipal R Ward Charkop Kandivali West 400067",
"remark": "Plan copy nahi ahe ",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/666c12b2772310133b1fc30a/document_1718358747662_17183585
97195_Sulochana_Karjavkar_Janta_Kandivali_West.pdf",
    "fileName": "document_1718358747662_1718358597195_Sulochana_Karjavkar_Ja
nta_Kandivali_West.pdf",
    "id": "596049",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Jun 14 2024 15:24:15 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009304",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "757017",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 14 2024 15:21:46 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Sulochana Tanahi Karjavkar ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "505474"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "24.99",
    "totalAreaDocument": "269.00",
    "docBultupPercentage": "",
    "docFinalBultUp": "0.00",
    "docFinalBultUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "898438"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "500.00",
      "squareMeterArea": "46.45",
      "expectedRate": "20000.00",
      "percentage": ""
    }
  },

```

```
"builtUpArea": {
  "area": "600.00",
  "squareMeterArea": "55.74",
  "expectedRate": "16666.67",
  "percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "666d35aafadc0e137dd8dd10",
"property": "Tapodhan Society, Sector 9 Charkop, Kandivali West",
"area": "600",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "10000000.00",
"expectedRate": "20000.00",
"builtUpExpectedRate": "10000000.00",
"image": "cases/666c12b2772310133b1fc30a/
indicator_1718431219803_Image.png",
"squareMeter": "55.74",
"id": "655380"
},
{
  "carpetArea": {
    "area": "813.00",
    "squareMeterArea": "75.53",
    "expectedRate": "19680.20",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "975.00",
    "squareMeterArea": "90.58",
    "expectedRate": "16410.26",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
```

```
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666d35aafadc0e137dd8dd11",
  "property": "Independent House, Sector 5 Charkop,near Charkop Market",
  "area": "975.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "16000000.00",
  "expectedRate": "19680.20",
  "builtUpExpectedRate": "16000000.00",
  "image": "cases/666c12b2772310133b1fc30a/
indicator_1718431370927_Image.png",
  "squareMeter": "90.58",
  "id": "662052"
},
{
  "carpetArea": {
    "area": "224.00",
    "squareMeterArea": "20.81",
    "expectedRate": "21428.57",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "269.10",
    "squareMeterArea": "25",
    "expectedRate": "17837.24",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666d35aafadc0e137dd8dd12",
  "property": "Charkop (3) Shilp Datta Sector 7 Kandivali West, Mumbai",
  "area": "269.10",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
```

```
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4800000.00",
"expectedRate": "21428.57",
"builtUpExpectedRate": "4800000.00",
"image": "cases/666c12b2772310133b1fc30a/
indicator_1718432318064_Image.png",
"squareMeter": "25",
"id": "915497"
},
{
"carpetArea": {
"area": "358.00",
"squareMeterArea": "33.26",
"expectedRate": "18156.42",
"percentage": ""
},
"builtUpArea": {
"area": "430.56",
"squareMeterArea": "40",
"expectedRate": "15096.62",
"percentage": ""
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "666d35aafadc0e137dd8dd13",
"property": "Charkop (3) Shilp Datta Sector 7 Kandivali West, Mumbai",
"area": "430.56",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "6500000.00",
"expectedRate": "18156.42",
"builtUpExpectedRate": "6500000.00",
"image": "cases/666c12b2772310133b1fc30a/
indicator_1718432915082_Image.png",
```



```
    "squareMeter": "40",
    "id": "590834"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf4238c",
    "name": "externalImg_1718426496391_IMG20240615WA0008.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externalImg_1718426496391_IMG20240615WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf4238d",
    "name": "externalImg_1718426496394_IMG20240615WA0017.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externalImg_1718426496394_IMG20240615WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf4238e",
    "name": "externalImg_1718426496398_IMG20240615WA0009.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externalImg_1718426496398_IMG20240615WA0009.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf4238f",
    "name": "externalImg_1718426496402_IMG20240615WA0010.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externalImg_1718426496402_IMG20240615WA0010.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42390",
    "name": "externalImg_1718426496405_IMG20240615WA0011.jpg",
```

```
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496405_IMG20240615WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42391",
    "name": "externallmg_1718426496408_IMG20240615WA0013.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496408_IMG20240615WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42392",
    "name": "externallmg_1718426496413_IMG20240615WA0014.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496413_IMG20240615WA0014.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42393",
    "name": "externallmg_1718426496416_IMG20240615WA0015.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496416_IMG20240615WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42394",
    "name": "externallmg_1718426496421_IMG20240615WA0016.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496421_IMG20240615WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d1b8159d44b137cf42395",
    "name": "externallmg_1718426496427_IMG20240615WA0018.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496427_IMG20240615WA0018.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d1b8159d44b137cf42396",
  "name": "externallmg_1718426496434_IMG20240615WA0020.jpg",
  "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496434_IMG20240615WA0020.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d1b8159d44b137cf42397",
  "name": "externallmg_1718426496438_IMG20240615WA0021.jpg",
  "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496438_IMG20240615WA0021.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d1b8159d44b137cf42398",
  "name": "externallmg_1718426496441_IMG20240615WA0023.jpg",
  "path": "cases/666c12b2772310133b1fc30a/
externallmg_1718426496441_IMG20240615WA0023.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d1b8159d44b137cf42399",
  "name": "externallmg_r_1718426496300_20240615_095010.jpg",
  "path": "cases/666c12b2772310133b1fc30a/
externallmg_r_1718426496300_20240615_095010.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d1b8159d44b137cf4239a",
  "name": "externallmg_r_1718426496344_20240615_095014.jpg",
  "path": "cases/666c12b2772310133b1fc30a/
externallmg_r_1718426496344_20240615_095014.jpg",
  "orientation": "portrait"
}
```

```
}
],
"externalDocuments": [
  {
    "originalname": "Mrs. Sulochana Tanaji Karjavkar.doc",
    "filename": "1718446766022_Mrs_Sulochana_Tanaji_Karjavkar.doc",
    "path": "cases/666c12b2772310133b1fc30a/
externalDocuments/1718446766022_Mrs_Sulochana_Tanaji_Karjavkar.doc",
    "size": "6054912",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Sat Jun 15 2024 15:49:26 GMT+0530 (India Standard Time)",
    "uploadedBy": "62691c48afd7d55eddecfda3"
  },
  {
    "originalname": "1718446766022_Mrs_Sulochana_Tanaji_Karjavkar.doc",
    "filename":
"1718454666307_1718446766022_Mrs_Sulochana_Tanaji_Karjavkar.doc",
    "path": "cases/666c12b2772310133b1fc30a/externalDocuments/1718454666307_1
718446766022_Mrs_Sulochana_Tanaji_Karjavkar.doc",
    "size": "6054400",
    "documentType": {
      "value": "64058cdff10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Sat Jun 15 2024 18:01:06 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "Sulochana_Tanaji_Karjavkar.pdf",
    "filename": "1718616428373_Sulochana_Tanaji_Karjavkar.pdf",
    "path": "cases/666c12b2772310133b1fc30a/
externalDocuments/1718616428373_Sulochana_Tanaji_Karjavkar.pdf",
    "size": "2441604",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Mon Jun 17 2024 14:57:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "originalname": "Valuation_report_Sulochana_Tanaji_Karjavkar.pdf",
    "filename": "1718616428429_Valuation_report_Sulochana_Tanaji_Karjavkar.pdf",
```

```
    "path": "cases/666c12b2772310133b1fc30a/externalDocuments/1718616428429_Valuation_report_Sulochana_Tanaji_Karjavkar.pdf",
    "size": "5389592",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Mon Jun 17 2024 14:57:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "path": "../CDN/cases/666c12b2772310133b1fc30a/externalDocuments/1718691375996_167826.pdf",
    "filename": "1718691375996_167826.pdf",
    "documentType": {
      "organization": {
        "status": true,
        "isdelete": false,
        "_id": "5f2bdee67813470eb443deb4",
        "name": "Vastukala Consultants India Pvt. Ltd.",
        "gstNo": "18AABCT3518Q1ZZ",
        "panNo": "ABCDE1234A",
        "email": "vastukalamumbai@vastukala.com",
        "phone": "9819670183",
        "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093",
        "shortName": "VCIPL",
        "type": "ORGANIZATION",
        "city": "Mumbai",
        "ownerEmail": "umang@vastukala.org",
        "ownerName": "Umang Patel"
      },
      "_id": "60ae124daa6d152c1801b307",
      "document": {
        "documentType": "Office Copy",
        "documentDate": true,
        "to": false,
        "from": false,
        "amount": false,
        "nameOfApprovingAuthority": false,
        "number": false,
        "remarks": true,
        "caseStatus": {
          "value": "DELIVERED",
          "label": "Delivered"
        }
      }
    }
  }
}
```

```
    },
    "createdAt": "2021-05-26T09:18:05.809Z",
    "updatedAt": "2023-06-20T10:17:50.158Z",
    "__v": 0,
    "label": "Office Copy",
    "value": "60ae124daa6d152c1801b307",
    "Name": "Office Copy",
    "Value": "60ae124daa6d152c1801b307",
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "Tue Jun 18 2024 11:46:16 GMT+0530 (India Standard Time)",
  "uploadedBy": "60af6ae22ffdf65bcd65861d"
},
"processingDocuments": [
  {
    "originalname": "15000.pdf",
    "filename": "1718435547354_15000.pdf",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547354_15000.pdf",
    "size": "156526",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "17800.pdf",
    "filename": "1718435547359_17800.pdf",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547359_17800.pdf",
    "size": "152532",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "Mrs sulochana.doc",
    "filename": "1718435547362_Mrs_sulochana.doc",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547362_Mrs_sulochana.doc",
    "size": "100352",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
```

```
    "originalname": "PRICE 2.jpg",
    "filename": "1718435547365_PRICE_2.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547365_PRICE_2.jpg",
    "size": "132993",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "PRIVE .jpg",
    "filename": "1718435547370_PRIVE_.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547370_PRIVE_.jpg",
    "size": "137346",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "RR.jpg",
    "filename": "1718435547373_RR.jpg",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547373_RR.jpg",
    "size": "141256",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  },
  {
    "originalname": "SULO.xlsx",
    "filename": "1718435547376_SULO.xlsx",
    "path": "cases/666c12b2772310133b1fc30a/
processingDocuments/1718435547376_SULO.xlsx",
    "size": "9488",
    "createdAt": "Sat Jun 15 2024 12:42:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdcf2",
      "role": "ADMIN",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
```

```
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "667d498da572a71913377ee5",
  "note": "Bank Name Change (Task Reopen)",
  "taskId": "666d6ab559d44b137cf476d2",
  "createdAt": "2024-06-27T11:14:21.950Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "PRINT",
  "display": true,
  "status": true,
  "_id": "667d499324d5fa190dda2185",
  "note": "Bank Name Change (Task Reopen)",
  "taskId": "666fc11a772310133b208048",
  "createdAt": "2024-06-27T11:14:27.678Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "SIGNED_REPORT_UPLOAD",
  "display": true,
  "status": true,
  "_id": "667d4998a572a71913377efd",
  "note": "Bank Name Change (Task Reopen)",
  "taskId": "666fcfc4fadcf0e137dd94667",
  "createdAt": "2024-06-27T11:14:32.532Z"
},
{
  "createdBy": {
```



```
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "DELIVERY",
  "display": true,
  "status": true,
  "_id": "667d499ca572a71913377f0f",
  "note": "Bank Name Change (Task Reopen)",
  "taskId": "667001c6fadcf0e137dd96e68",
  "createdAt": "2024-06-27T11:14:36.504Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "COLLECT_OC_COPY",
  "display": true,
  "status": true,
  "_id": "667d49a024d5fa190dda2199",
  "note": "Bank Name Change (Task Reopen)",
  "taskId": "6671263259d44b137cf5239a",
  "createdAt": "2024-06-27T11:14:40.572Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "667e36870201c575892b1844",
  "note": "Bank Name Change (Task Reopen)",
```

```
"taskId": "666d1b8659d44b137cf423a8",
"createdAt": "2024-06-28T04:05:27.543Z"
},
{
  "createdBy": {
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "lastName": "Bhatt",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "667e36930201c575892b184c",
  "note": "Banke Name Change (Task Reopen)",
  "taskId": "666c1a3759d44b137cf3ee26",
  "createdAt": "2024-06-28T04:05:39.828Z"
}
],
"createdAt": "2024-06-14T09:51:46.874Z",
"updatedAt": "2024-06-28T04:24:44.470Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60092304a16fab0f2af9b0c2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B-4, Ground Floor, Charkop (3) Shilp Datta Co-op.
Hsg. Soc. Ltd., Plot No. BD - 729, RSC - 68, Sector 7, Village - Charkop, Kandivali
(West), Mumbai , Taluka - Borivali, District - Mumbai Suburban , PIN - 400 067, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Ms Rupali",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"siteVisitContactNo": "9870525170",
"buildingServicesRate": "2800",
```

```

"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 269.00",
"flatRate": "18200",
"landOtherRate": "15400",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": ""

```

Name	Length	Width	Total
Composition :			
Other Composition :			