

```
{
  "typeOfReport": {
    "label": "Lenders_Engineers Report (LIE)",
    "value": "Lenders_Engineers_Report_(LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fe"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "660bb8fad91ed25cfbe74ed7",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9962158950",
    "email": "krabhishek0910@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "945464546",
    "discussWithPerson": "Abhishek",
    "expectedFees": 472732.273,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fe",
  "branchCode": "000072",
  "type": "BRANCH",
  "name": "Shivsagar Estate Branch Worli (South) ",
  "email": "sbi.01154@sbi.co.in",
  "mobileNo": "24921772 / 24980675 ",
  "alternateMobileNo": "24937708 / 24968939",
  "address": "Devchand House, Ground Floor, Dr. Annie Besant Road, Worli, Mumbai -
400 018, State - Maharashtra, Country - India\r\n",
  "ledgerName": "STATE BANK OF INDIA - WORLI SHIVSAGAR",
  "fax": "24973911",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
```

```
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "(N) CCIT/1-14/52/2008-09",
        "label": "IBBI"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ff3ead28cda966090eacbbe",
    "role": "VALUER",
    "firstName": "Umang ",
    "fatherName": "Ashwin Bhai",
    "PANNo": "AMKPP9341F",
    "email": "umang@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9819670183",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "607e6f3fa104d6723e0d7b22",
        "number": "(N) CCIT/1-14/52/2008-09"
      },
      {
        "title": {
          "label": "WealthTax"
        },
        "_id": "607e6f3fa104d6723e0d7b23",
        "number": "(N) CCIT/1-14/52/2008-09"
      }
    ]
  }
]
```

```
    ],
    "shortName": "umang",
    "workWithDocumentMaker": "5fc75d341095af19d8b34239",
    "designation": "",
    "profilePhoto": "users/5ff3ead28cda966090eacbbe/
profilePhoto_1678667749982_image.jpeg"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "20.449506411766066",
  "longitude": "75.77582709606799"
},
"geo": {
  "type": "Point",
  "coordinates": [
    75.77582709606799,
    20.449506411766066
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/06/2024 12:25 pm"
    },
    {
      "dateTime": "19/06/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Maharashtra",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Maharashtra",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```



```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  }
}
```

```
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "finalLatLng": {
      "coordinates": []
    },
    "locationMapImg": []
  },
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66726c6824f3ba1343e64309",
"invoices": [],
"ownerName": "E urja ",
"ownerPhoneNo": "7777035659",
"appAddress": "Maharashtra location & Ranchi ( zarkhand )\nBoth locations ",
"remark": "contact person - Prashant Tiwari \n\nUmang sir is coordinating with the customer\n",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
```

```
    "value": "60ae1248aa6d152c1801b2ee"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66726c6824f3ba1343e64309/document_1718774744896_17187746
04095_LIE_Report_of_Eurja23082022__REv.pdf",
  "fileName": "document_1718774744896_1718774604095_LIE_Report_of_Eurja230
82022__REv.pdf",
  "id": "368314",
  "uploadedBy": "62723addafd7d55eddeddfe4",
  "createdAt": "Wed Jun 19 2024 10:58:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009366",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "818993",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 19 2024 10:58:08 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "E urja ",
    "phone": "7777035659",
    "ownershipShare": "",
    "email": "",
    "id": "485372"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669651f59b7289714abe6444",
    "name":
"externallmg_1721127410940_WhatsApp_Image_20240711_at_10406_PM_1.jpeg",
```

```
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127410940_WhatsApp_Image_20240711_at_10406_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669651f59b7289714abe6445",
    "name":
"externallmg_1721127411018_WhatsApp_Image_20240711_at_10406_PM_2.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411018_WhatsApp_Image_20240711_at_10406_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669651f59b7289714abe6446",
    "name":
"externallmg_1721127411180_WhatsApp_Image_20240711_at_10406_PM.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411180_WhatsApp_Image_20240711_at_10406_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669651f59b7289714abe6447",
    "name":
"externallmg_1721127411242_WhatsApp_Image_20240711_at_10409_PM_1.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411242_WhatsApp_Image_20240711_at_10409_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669651f59b7289714abe6448",
    "name":
"externallmg_1721127411415_WhatsApp_Image_20240711_at_10409_PM_2.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411415_WhatsApp_Image_20240711_at_10409_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "669651f59b7289714abe6449",
  "name":
"externallmg_1721127411487_WhatsApp_Image_20240711_at_10409_PM.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411487_WhatsApp_Image_20240711_at_10409_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644a",
  "name":
"externallmg_1721127411595_WhatsApp_Image_20240711_at_10411_PM_1.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411595_WhatsApp_Image_20240711_at_10411_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644b",
  "name":
"externallmg_1721127411770_WhatsApp_Image_20240711_at_10411_PM_2.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411770_WhatsApp_Image_20240711_at_10411_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644c",
  "name":
"externallmg_1721127411841_WhatsApp_Image_20240711_at_10411_PM_3.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411841_WhatsApp_Image_20240711_at_10411_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644d",
  "name":
"externallmg_1721127411897_WhatsApp_Image_20240711_at_10411_PM_4.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411897_WhatsApp_Image_20240711_at_10411_PM_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644e",
  "name":
"externallmg_1721127411985_WhatsApp_Image_20240711_at_10411_PM_5.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127411985_WhatsApp_Image_20240711_at_10411_PM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe644f",
  "name":
"externallmg_1721127412111_WhatsApp_Image_20240711_at_10411_PM_6.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127412111_WhatsApp_Image_20240711_at_10411_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe6450",
  "name":
"externallmg_1721127412267_WhatsApp_Image_20240711_at_10411_PM_7.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127412267_WhatsApp_Image_20240711_at_10411_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe6451",
  "name":
"externallmg_1721127412457_WhatsApp_Image_20240711_at_10411_PM_8.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127412457_WhatsApp_Image_20240711_at_10411_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669651f59b7289714abe6452",
```

```
    "name":  
    "externallmg_1721127412552_WhatsApp_Image_20240711_at_10411_PM_9.jpeg",  
    "path": "cases/66726c6824f3ba1343e64309/  
externallmg_1721127412552_WhatsApp_Image_20240711_at_10411_PM_9.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "669651f59b7289714abe6453",  
    "name":  
    "externallmg_1721127412791_WhatsApp_Image_20240711_at_10411_PM_10.jpeg",  
    "path": "cases/66726c6824f3ba1343e64309/  
externallmg_1721127412791_WhatsApp_Image_20240711_at_10411_PM_10.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "669651f59b7289714abe6454",  
    "name":  
    "externallmg_1721127412861_WhatsApp_Image_20240711_at_10411_PM_11.jpeg",  
    "path": "cases/66726c6824f3ba1343e64309/  
externallmg_1721127412861_WhatsApp_Image_20240711_at_10411_PM_11.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6696520a78a9b1710bff963a",  
    "name":  
    "externallmg_1721127431579_WhatsApp_Image_20240711_at_10411_PM_12.jpeg",  
    "path": "cases/66726c6824f3ba1343e64309/  
externallmg_1721127431579_WhatsApp_Image_20240711_at_10411_PM_12.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6696520a78a9b1710bff963b",  
    "name":  
    "externallmg_1721127431614_WhatsApp_Image_20240711_at_10411_PM_13.jpeg",  
    "path": "cases/66726c6824f3ba1343e64309/  
externallmg_1721127431614_WhatsApp_Image_20240711_at_10411_PM_13.jpeg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696520a78a9b1710bff963c",
  "name":
"externallmg_1721127431762_WhatsApp_Image_20240711_at_10411_PM_14.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127431762_WhatsApp_Image_20240711_at_10411_PM_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696520a78a9b1710bff963d",
  "name":
"externallmg_1721127431916_WhatsApp_Image_20240711_at_10411_PM.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127431916_WhatsApp_Image_20240711_at_10411_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696520a78a9b1710bff963e",
  "name":
"externallmg_1721127432002_WhatsApp_Image_20240711_at_10412_PM_1.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432002_WhatsApp_Image_20240711_at_10412_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696520a78a9b1710bff963f",
  "name":
"externallmg_1721127432166_WhatsApp_Image_20240711_at_10412_PM_2.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432166_WhatsApp_Image_20240711_at_10412_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696520a78a9b1710bff9640",
  "name":
"externallmg_1721127432317_WhatsApp_Image_20240711_at_10412_PM_3.jpeg",
```

```
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432317_WhatsApp_Image_20240711_at_10412_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9641",
    "name":
"externallmg_1721127432403_WhatsApp_Image_20240711_at_10412_PM_4.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432403_WhatsApp_Image_20240711_at_10412_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9642",
    "name":
"externallmg_1721127432586_WhatsApp_Image_20240711_at_10412_PM_5.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432586_WhatsApp_Image_20240711_at_10412_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9643",
    "name":
"externallmg_1721127432655_WhatsApp_Image_20240711_at_10412_PM_6.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432655_WhatsApp_Image_20240711_at_10412_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9644",
    "name":
"externallmg_1721127432772_WhatsApp_Image_20240711_at_10412_PM_7.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432772_WhatsApp_Image_20240711_at_10412_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "6696520a78a9b1710bff9645",
    "name":
"externallmg_1721127432857_WhatsApp_Image_20240711_at_10412_PM_8.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432857_WhatsApp_Image_20240711_at_10412_PM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9646",
    "name":
"externallmg_1721127432991_WhatsApp_Image_20240711_at_10412_PM_9.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127432991_WhatsApp_Image_20240711_at_10412_PM_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9647",
    "name":
"externallmg_1721127433298_WhatsApp_Image_20240711_at_10412_PM_10.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127433298_WhatsApp_Image_20240711_at_10412_PM_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9648",
    "name":
"externallmg_1721127433514_WhatsApp_Image_20240711_at_10412_PM_11.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127433514_WhatsApp_Image_20240711_at_10412_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff9649",
    "name":
"externallmg_1721127433786_WhatsApp_Image_20240711_at_10412_PM_12.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127433786_WhatsApp_Image_20240711_at_10412_PM_12.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696520a78a9b1710bff964a",
    "name":
"externallmg_1721127433979_WhatsApp_Image_20240711_at_10412_PM_13.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127433979_WhatsApp_Image_20240711_at_10412_PM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696521e78a9b1710bff96fd",
    "name":
"externallmg_1721127452479_WhatsApp_Image_20240711_at_10412_PM_14.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127452479_WhatsApp_Image_20240711_at_10412_PM_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696521e78a9b1710bff96fe",
    "name":
"externallmg_1721127452542_WhatsApp_Image_20240711_at_10412_PM_15.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127452542_WhatsApp_Image_20240711_at_10412_PM_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696521e78a9b1710bff96ff",
    "name":
"externallmg_1721127452687_WhatsApp_Image_20240711_at_10412_PM_16.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127452687_WhatsApp_Image_20240711_at_10412_PM_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696521e78a9b1710bff9700",
```

```
"name":
"externallmg_1721127452871_WhatsApp_Image_20240711_at_10412_PM_18.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127452871_WhatsApp_Image_20240711_at_10412_PM_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9701",
  "name":
"externallmg_1721127453116_WhatsApp_Image_20240711_at_10412_PM_19.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453116_WhatsApp_Image_20240711_at_10412_PM_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9702",
  "name":
"externallmg_1721127453380_WhatsApp_Image_20240711_at_10412_PM_20.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453380_WhatsApp_Image_20240711_at_10412_PM_20.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9703",
  "name":
"externallmg_1721127453452_WhatsApp_Image_20240711_at_10412_PM_22.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453452_WhatsApp_Image_20240711_at_10412_PM_22.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9704",
  "name":
"externallmg_1721127453654_WhatsApp_Image_20240711_at_10412_PM_24.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453654_WhatsApp_Image_20240711_at_10412_PM_24.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9705",
  "name":
"externallmg_1721127453733_WhatsApp_Image_20240711_at_10412_PM_25.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453733_WhatsApp_Image_20240711_at_10412_PM_25.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9706",
  "name":
"externallmg_1721127453770_WhatsApp_Image_20240711_at_10412_PM_26.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453770_WhatsApp_Image_20240711_at_10412_PM_26.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9707",
  "name":
"externallmg_1721127453839_WhatsApp_Image_20240711_at_10412_PM_28.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453839_WhatsApp_Image_20240711_at_10412_PM_28.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9708",
  "name":
"externallmg_1721127453898_WhatsApp_Image_20240711_at_10412_PM_29.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453898_WhatsApp_Image_20240711_at_10412_PM_29.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696521e78a9b1710bff9709",
  "name":
"externallmg_1721127453952_WhatsApp_Image_20240711_at_10412_PM_30.jpeg",
```

```
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127453952_WhatsApp_Image_20240711_at_10412_PM_30.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e87e",
    "name":
"externallmg_1721127474517_WhatsApp_Image_20240711_at_10412_PM_31.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474517_WhatsApp_Image_20240711_at_10412_PM_31.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e87f",
    "name":
"externallmg_1721127474599_WhatsApp_Image_20240711_at_10412_PM_33.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474599_WhatsApp_Image_20240711_at_10412_PM_33.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e880",
    "name":
"externallmg_1721127474657_WhatsApp_Image_20240711_at_10412_PM_34.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474657_WhatsApp_Image_20240711_at_10412_PM_34.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e881",
    "name":
"externallmg_1721127474701_WhatsApp_Image_20240711_at_10412_PM_36.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474701_WhatsApp_Image_20240711_at_10412_PM_36.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66965234e1007a714979e882",
  "name":
"externallmg_1721127474743_WhatsApp_Image_20240711_at_10412_PM_38.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474743_WhatsApp_Image_20240711_at_10412_PM_38.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66965234e1007a714979e883",
  "name":
"externallmg_1721127474864_WhatsApp_Image_20240711_at_10412_PM_39.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127474864_WhatsApp_Image_20240711_at_10412_PM_39.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66965234e1007a714979e884",
  "name":
"externallmg_1721127475028_WhatsApp_Image_20240711_at_10412_PM_41.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127475028_WhatsApp_Image_20240711_at_10412_PM_41.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66965234e1007a714979e885",
  "name":
"externallmg_1721127475220_WhatsApp_Image_20240711_at_10412_PM_43.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127475220_WhatsApp_Image_20240711_at_10412_PM_43.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66965234e1007a714979e886",
  "name":
"externallmg_1721127475362_WhatsApp_Image_20240711_at_10412_PM_45.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127475362_WhatsApp_Image_20240711_at_10412_PM_45.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e887",
    "name":
"externallmg_1721127475401_WhatsApp_Image_20240711_at_10412_PM_46.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127475401_WhatsApp_Image_20240711_at_10412_PM_46.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66965234e1007a714979e888",
    "name":
"externallmg_1721127475557_WhatsApp_Image_20240711_at_10412_PM_47.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127475557_WhatsApp_Image_20240711_at_10412_PM_47.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696524878a9b1710bff97a3",
    "name":
"externallmg_1721127494878_WhatsApp_Image_20240711_at_10412_PM_48.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127494878_WhatsApp_Image_20240711_at_10412_PM_48.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696524878a9b1710bff97a4",
    "name":
"externallmg_1721127495003_WhatsApp_Image_20240711_at_10412_PM_50.jpeg",
    "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495003_WhatsApp_Image_20240711_at_10412_PM_50.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6696524878a9b1710bff97a5",
```

```
"name":
"externallmg_1721127495279_WhatsApp_Image_20240711_at_10412_PM.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495279_WhatsApp_Image_20240711_at_10412_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97a6",
  "name":
"externallmg_1721127495389_WhatsApp_Image_20240711_at_10413_PM_1.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495389_WhatsApp_Image_20240711_at_10413_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97a7",
  "name":
"externallmg_1721127495455_WhatsApp_Image_20240711_at_10413_PM_2.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495455_WhatsApp_Image_20240711_at_10413_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97a8",
  "name":
"externallmg_1721127495562_WhatsApp_Image_20240711_at_10413_PM_3.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495562_WhatsApp_Image_20240711_at_10413_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97a9",
  "name":
"externallmg_1721127495709_WhatsApp_Image_20240711_at_10413_PM_4.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495709_WhatsApp_Image_20240711_at_10413_PM_4.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97aa",
  "name":
"externallmg_1721127495794_WhatsApp_Image_20240711_at_10413_PM_5.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495794_WhatsApp_Image_20240711_at_10413_PM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97ab",
  "name":
"externallmg_1721127495945_WhatsApp_Image_20240711_at_10413_PM_6.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127495945_WhatsApp_Image_20240711_at_10413_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6696524878a9b1710bff97ac",
  "name":
"externallmg_1721127496077_WhatsApp_Image_20240711_at_10413_PM.jpeg",
  "path": "cases/66726c6824f3ba1343e64309/
externallmg_1721127496077_WhatsApp_Image_20240711_at_10413_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-19T05:28:08.629Z",
"updatedAt": "2024-07-16T10:58:16.300Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Basement Floor,
Village - Maharashtra, Maharashtra, State - Maharashtra, India",
"updatedBy": "62720b21afd7d55eddedc545",
```

```
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "E urja ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7777035659"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			