

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64d752c872fe957847117f2d"
    },
    "firstName": "Pooja ",
    "type": "CREDITOFFICER",
    "_id": "64d752c872fe957847117f2f",
    "lastName": "Gujar",
    "mobileNo": "",
    "workMobileNo": "9152800052",
    "email": "gujarpp@svcbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64d752c872fe957847117f2d",
  "name": "Louiswadi Branch",
  "branchCode": "",
  "mobileNo": "9152800052",
  "alternateMobileNo": "",
  "email": "louiswadiou@svcbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Unit No. 5, Sun Magnetica, Louiswadi, Near LIC Office, Service Road,
Thane (West) - 400604 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.16482888176689",
  "longitude": "72.96321205189666"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.96321205189666,
    19.16482888176689
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-19",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-19",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swastik Divine",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Navghar Road",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "78, 80, 82",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "1405",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "T",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 400 081",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MHADA",
  "label": "MHADA"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Wing - A",
  "west": "Veer Savarkar Road\n",
  "south": "Other Residential Building",
  "east": "Eastern Express Highway\n"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
```

```
"buses": {
  "title": "Buses"
},
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": " As per Approved Plan , the composition of flat will be 2
Bedrooms + Living Room + Kitchen + 2 Toilets + Passage Area, (i.e. 2 BHK + 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Plan Document No. Mhada / 12 /
1056 / 2022 dated 21.02.2022 issued by MHADA",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "Building is under construction",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "28000.00",
  "depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "133330",
  "landRate": "67520",
  "igrImage": "cases/6672902c59d44b137cf5a9cb/igr_1718868474767_Image.png",
  "squareMeterGuideLineRate": "146663.00",
  "squareFeetGuideLineRate": "13625.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "133330.00",
```

```
"squareMeterGuideLineRate": "146663.00",
"squareFeetGuideLineRate": "13625.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MHADA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in develeod area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
```

```
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed One Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenancelssues": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_per_RERA_Certificate",
"label": "As per RERA Certificate"
```



```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "1",
"noOfAmenityFloors": "1",
"noOfFloors": "20",
"flatFloorNo": "14",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "729.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6672902c59d44b137cf5a9cb/
routeMap_1718877393732_Image.png",
    "routeLat": "19.164677",
    "routeLng": "72.859722",
    "stationName": "Mulund ",
    "routeDistance": "1.2 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "9158jm",
```

```
    "name": "9158jm",
    "image": "cases/6672902c59d44b137cf5a9cb/
routeMap_1718877311479_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18564000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "18564000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jun 20 2024 15:41:41 GMT+0530 (India Standard Time)",
  "number": "2306835",
  "dayCount": "13",
```

```
"monthCount": "279",
"generatedBy": "64cde526dc9f3034f3fef49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "24",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "16",
    "percentage": "4.67",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "16",
    "percentage": "4.67",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "16",
    "percentage": "2.33",
```

```
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "16",
  "percentage": "2.33",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "14",
  "percentage": "1.46",
  "isHideFloor": false,
  "status": true
},
>window": {
  "label": "Window",
  "floorsCompleted": "14",
  "percentage": "1.46",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "66.92",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "9936713.00",
"selectedBuildUpValue": "729.30",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "6672fdab24f3ba1343e6c76b",
"name": "externalimg_1718812074932_1718811924345_image_7.jpeg",
```

```
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812074932_1718811924345_image_7.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "6672fdab24f3ba1343e6c769",
    "name": "externallmg_1718812072964_1718811924345_image_5.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812072964_1718811924345_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6672fdab24f3ba1343e6c76a",
    "name": "externallmg_1718812073859_1718811924345_image_6.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812073859_1718811924345_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6672fdab24f3ba1343e6c76b",
    "name": "externallmg_1718812074932_1718811924345_image_7.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812074932_1718811924345_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6672fdab24f3ba1343e6c768",
    "name": "externallmg_1718812072512_1718811924345_image_4.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812072512_1718811924345_image_4.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "26591.00",
"max": "29261.00"
},
"builtUpRateRange": {
  "min": "24174.00",
  "max": "26601.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "663.00",
"empanelmentNo": [
  "CO/Tec/BUS/526/ 20-21(L&B)"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6672902c59d44b137cf5a9cb",
"ownerName": "Mrs. Minal Milind Gadkari & Mr. Milind Balkrishna Gadkari ",
"ownerPhoneNo": "9223225799",
"fullAddress": "Residential Flat No. 1405, 14th Floor, Wing - B, Swastik Divine,
Navghar Road, Village - Mulund, Municipality Ward No. T, Mulund (East), Taluka -
Kurla , District - Mumbai Suburban , PIN - 400 081, State - Maharashtra, Country -
India",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/06/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Swastik Realtors",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Minal Milind Gadkar & Mr. Milind Balkrishna Godkar",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "15925/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718783987729_Agreement.pdf",
    "path": "cases/6672902c59d44b137cf5a9cb/
document_1718783987729_Agreement.pdf",
    "id": "102967",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Wed Jun 19 2024 13:30:44 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "21/02/2022",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "MH / EE / BP Cell / GM / MHADA - 12/ 1056 / 2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1718873635897_647978.pdf",
"path": "cases/6672902c59d44b137cf5a9cb/
document_1718873635897_647978.pdf",
"id": "260276",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 20 2024 14:23:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/02/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MHADA / 12 / 1056 / 2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1718873741471_Plan.pdf",
"path": "cases/6672902c59d44b137cf5a9cb/document_1718873741471_Plan.pdf",
"id": "500230",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 20 2024 14:25:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "10/09/2022",
```

```
"nameOfApprovingAuthority": {
  "value": "Maharashtra_Real_Estate_Regulatory_Authority",
  "label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "P51800046801"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1718873824941_649385.pdf",
"path": "cases/6672902c59d44b137cf5a9cb/
document_1718873824941_649385.pdf",
"id": "908939",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 20 2024 14:27:05 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009370",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "655853",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 19 2024 13:30:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Minal Milind Gadkari & Mr. Milind Balkrishna Gadkari ",
    "phone": "9223225799",
    "ownershipShare": "",
    "email": "",
    "id": "221736"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "61.59",
    "totalAreaDocument": "663",
    "docBultupPercentage": "10",
    "docFinalBultUp": "729.30",
    "docFinalBultUpSquareMeter": "67.75",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "575385"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "974.00",
      "squareMeterArea": "90.49",
      "expectedRate": "28747.43",
      "percentage": ""
    },
    "bultUpArea": {
      "area": "1071.40",
      "squareMeterArea": "99.54",
      "expectedRate": "26134.03",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
```

```
"_id": "6673da2d772310133b21fd62",
"property": "Residential Flat",
"area": "974",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "28000000",
"expectedRate": "28747.43",
"builtUpExpectedRate": "26134.03",
"image": "cases/6672902c59d44b137cf5a9cb/
indicator_1718868128347_Image.png",
"squareMeter": "90.49",
"id": "437372"
},
{
  "carpetArea": {
    "area": "974.00",
    "squareMeterArea": "90.49",
    "expectedRate": "29260.78",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1071.40",
    "squareMeterArea": "99.54",
    "expectedRate": "26600.71",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6673da2d772310133b21fd63",
  "property": "Residential Flat",
  "area": "974",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
```

```
"expectedPrice": "28500000",
"expectedRate": "29260.78",
"builtUpExpectedRate": "26600.71",
"image": "cases/6672902c59d44b137cf5a9cb/
indicator_1718868193226_Image.png",
"squareMeter": "90.49",
"id": "909014"
},
{
  "carpetArea": {
    "area": "974.00",
    "squareMeterArea": "90.49",
    "expectedRate": "26590.89",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1071.40",
    "squareMeterArea": "99.54",
    "expectedRate": "24173.54",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6673da2d772310133b21fd64",
  "property": "Residential Flat",
  "area": "974",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "25899530",
  "expectedRate": "26590.89",
  "builtUpExpectedRate": "24173.54",
  "image": "cases/6672902c59d44b137cf5a9cb/
indicator_1718868228573_Image.png",
  "squareMeter": "90.49",
  "id": "705852"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672fdab24f3ba1343e6c764",
    "name": "externalimg_1718812068837_1718811924345_image_0.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externalimg_1718812068837_1718811924345_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672fdab24f3ba1343e6c765",
    "name": "externalimg_1718812069847_1718811924345_image_1.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externalimg_1718812069847_1718811924345_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672fdab24f3ba1343e6c766",
    "name": "externalimg_1718812071072_1718811924345_image_2.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externalimg_1718812071072_1718811924345_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672fdab24f3ba1343e6c767",
    "name": "externalimg_1718812071824_1718811924345_image_3.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externalimg_1718812071824_1718811924345_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672fdab24f3ba1343e6c768",
    "name": "externalimg_1718812072512_1718811924345_image_4.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externalimg_1718812072512_1718811924345_image_4.jpeg",
    "orientation": "portrait"
  },
]
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672fdab24f3ba1343e6c769",
  "name": "externallmg_1718812072964_1718811924345_image_5.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812072964_1718811924345_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672fdab24f3ba1343e6c76a",
  "name": "externallmg_1718812073859_1718811924345_image_6.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812073859_1718811924345_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672fdab24f3ba1343e6c76b",
  "name": "externallmg_1718812074932_1718811924345_image_7.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812074932_1718811924345_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6672fd81772310133b21c835",
  "name": "externallmg_1718812027555_1718811887605_image_0.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812027555_1718811887605_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6672fd81772310133b21c836",
  "name": "externallmg_1718812029560_1718811887605_image_1.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812029560_1718811887605_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6672fd81772310133b21c837",
    "name": "externallmg_1718812030283_1718811887605_image_2.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812030283_1718811887605_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6672fd81772310133b21c838",
    "name": "externallmg_1718812030786_1718811887605_image_3.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812030786_1718811887605_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6672fd81772310133b21c839",
    "name": "externallmg_1718812031154_1718811887605_image_4.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812031154_1718811887605_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6672fd81772310133b21c83a",
    "name": "externallmg_1718812031552_1718811887605_image_5.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812031552_1718811887605_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6672fd81772310133b21c83b",
    "name": "externallmg_1718812031856_1718811887605_image_6.jpeg",
    "path": "cases/6672902c59d44b137cf5a9cb/
externallmg_1718812031856_1718811887605_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "6672fd81772310133b21c83c",
  "name": "externalImg_1718812032229_1718811887605_image_7.jpeg",
  "path": "cases/6672902c59d44b137cf5a9cb/
externalImg_1718812032229_1718811887605_image_7.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1718868524278_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6672902c59d44b137cf5a9cb/
processingDocuments/1718868524278_Calculation_Sheet_NEW.xlsx",
    "size": "1837126",
    "createdAt": "Thu Jun 20 2024 12:58:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Reference Report -
Swati_Sameer_Shirodkar__Mr_Sameer_Trivikram_Shirodkar.pdf",
    "filename": "1718868524319_Reference_Report__Swati_Sameer_Shirodkar__Mr_S
ameer_Trivikram_Shirodkar.pdf",
    "path": "cases/6672902c59d44b137cf5a9cb/processingDocuments/1718868524319
_Reference_Report__Swati_Sameer_Shirodkar__Mr_Sameer_Trivikram_Shirodkar.pdf"
    ,
    "size": "3592437",
    "createdAt": "Thu Jun 20 2024 12:58:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1718877602460_CC.pdf",
    "path": "cases/6672902c59d44b137cf5a9cb/
processingDocuments/1718877602460_CC.pdf",
    "size": "182536",
    "createdAt": "Thu Jun 20 2024 15:30:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1718877602486_Plan.pdf",
    "path": "cases/6672902c59d44b137cf5a9cb/
processingDocuments/1718877602486_Plan.pdf",
    "size": "28847442",
```

```
"createdAt": "Thu Jun 20 2024 15:30:03 GMT+0530 (India Standard Time)",
"uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6673d4ea59d44b137cf6143f",
    "note": "Value given for confirmation",
    "taskId": "6672903459d44b137cf5aa4d",
    "createdAt": "2024-06-20T07:06:18.441Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6673d4ed59d44b137cf61442",
    "note": "Value given for confirmation",
    "taskId": "6672903459d44b137cf5aa4d",
    "createdAt": "2024-06-20T07:06:21.473Z"
  }
],
"createdAt": "2024-06-19T08:00:44.204Z",
"updatedAt": "2024-06-20T10:13:17.232Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
```

```
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Pravin Jadhav ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person ",
"siteVisitContactNo": "7796817993",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 663.00",
"flatRate": "28000",
"landOtherRate": "25000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2024-06-19",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
```

```
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Thu Jun 20 2024 14:53:10 GMT+0530 (India Standard Time)"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			